



## Electrical Specifications

### Ranges and Resolution

abs: Absolute reference (atmospheric pressure to zero at full vacuum)

vac: Vacuum gauge, minus sign not used unless specified

Resolution is fixed as indicated in table below

Contact factory for engineering units not listed

-30.0 inHg/15.0 psig	120.0 inHg	1600 mmHg	35.0 bar	1.000 kg/cm <sup>2</sup> abs
-30.0 inHg/100.0 psig	199.9 inHg abs	760 torr abs	70.0 bar	1.000 kg/cm <sup>2</sup> vac
-30.0 inHg/199.9 psig	199.9 inHg	1600 torr abs	140.0 bar	±1.000 kg/cm <sup>2</sup>
3.00 psig	50.0 oz/in <sup>2</sup>	2100 mmH <sub>2</sub> O	199.9 bar	1.000 kg/cm <sup>2</sup>
5.00 psig	80.0 oz/in <sup>2</sup>	3500 mmH <sub>2</sub> O	350 bar	1.999 kg/cm <sup>2</sup> abs
15.00 psi abs	240 oz/in <sup>2</sup> abs	199.9 cmH <sub>2</sub> O	19.99 kPa	1.999 kg/cm <sup>2</sup>
15.00 psig vac	240 oz/in <sup>2</sup> vac	350 cmH <sub>2</sub> O	35.0 kPa	4.00 kg/cm <sup>2</sup>
±15.0 psig	±240 oz/in <sup>2</sup>	1000 cmH <sub>2</sub> O	100.0 kPa abs	7.00 kg/cm <sup>2</sup> abs
15.00 psig	240 oz/in <sup>2</sup>	2100 cmH <sub>2</sub> O	100.0 kPa vac	7.00 kg/cm <sup>2</sup>
30.0 psi abs	85.0 inH <sub>2</sub> O	199.9 mbar	±100.0 kPa	14.00 kg/cm <sup>2</sup>
30.0 psig	140.0 inH <sub>2</sub> O	350 mbar	100.0 kPa	19.99 kg/cm <sup>2</sup>
60.0 psig	400 inH <sub>2</sub> O abs	1000 mbar abs	199.9 kPa abs	35.0 kg/cm <sup>2</sup>
100.0 psi abs	400 inH <sub>2</sub> O vac	1000 mbar vac	199.9 kPa	70.0 kg/cm <sup>2</sup>
100.0 psig	±400 inH <sub>2</sub> O	±1000 mbar	400 kPa	140.0 kg/cm <sup>2</sup>
199.9 psig	400 inH <sub>2</sub> O	1000 mbar	700 kPa abs	199.9 kg/cm <sup>2</sup>
300 psig	850 inH <sub>2</sub> O	1999 mbar abs	700 kPa	350 kg/cm <sup>2</sup>
500 psig	7.00 ftH <sub>2</sub> O	1999 mbar	1500 kPa	1.000 atm abs
1000 psig	12.00 ftH <sub>2</sub> O	4000 mbar	1999 kPa	±1.000 atm
1999 psig	35.0 ftH <sub>2</sub> O	1.000 bar abs	3500 kPa	1.000 atm
3000 psig	70.0 ftH <sub>2</sub> O	1.000 bar vac	5000 kPa	4.00 atm
5000 psig	140.0 ftH <sub>2</sub> O	±1.000 bar	3.50 MPa	7.00 atm
6.00 inHg	230 ftH <sub>2</sub> O	1.000 bar	7.00 MPa	14.00 atm
10.00 inHg	480 ftH <sub>2</sub> O	1.999 bar abs	14.00 MPa	19.99 atm
30.0 inHg abs	150.0 mmHg	1.999 bar	19.99 MPa	35.0 atm
30.0 inHg vac	260 mmHg	4.00 bar	35.0 MPa	70.0 atm
±30.0 inHg	760 mmHg abs	7.00 bar abs	1000 g/cm <sup>2</sup> abs	135.0 atm
30.0 inHg	760 mmHg vac	7.00 bar	1000 g/cm <sup>2</sup>	199.9 atm
60.0 inHg abs	760 mmHg	14.00 bar	2100 g/cm <sup>2</sup> abs	340 atm
60.0 inHg	1600 mmHg abs	19.99 bar	2100 g/cm <sup>2</sup>	

### Accuracy (linearity, hysteresis, repeatability)

Standard: ±0.25% of full scale ±1 least significant digit

Optional: **-HA** ±0.1% FS ±1LSD (most ranges)

**CD** Factory calibration data

**NC** NIST traceable test report and calibration data

### Display

3 readings per second nominal display update rate

Ranges up to 1999: 3½ digit LCD, 0.5" digit height

3000 psi, 5000 psi: 4½ digit LCD, 0.5" digit height, lower display for units

**BBL** models: Red LED backlight

### Controls

**B** ranges up to 1999: Front pushbutton turns gauge on/off

**BBL** ranges up to 1999: Front pushbutton turns gauge & backlighting on/off

Front calibration potentiometers, non-interactive zero and span, ±10% range

**B**, **BBL** ranges of 3000 psi, 5000 psi

Front button turns gauge on, starts auto shutoff timer, and provides zero function for gauge reference ranges

Internal calibration pushbuttons

**BBL** ranges of 3000 psi, 5000 psi

Press button to activate backlighting for one minute while gauge is on

### Auto Shutoff

5 minutes standard

Ranges up to 1999: Factory settable to 5, 10, 30 minutes, or on/off

3000 psi, 5000 psi: Factory settable to any number of minutes or hours

### Batteries and Battery Life

Two AA alkaline

**B** ranges up to 1999: Approx. 2500 hours

**B** 3000 psi, 5000 psi: Approx. 2000 hours

**BBL** ranges up to 1999: Approx. 180 hours

**BBL** 3000 psi, 5000 psi: 150 to 1500 hrs depending on backlight usage

### Low Battery Indication

Low battery symbol on display when batteries must be replaced

- ±0.25% Test Gauge Accuracy
- 316 Stainless Steel Wetted Parts
- Battery Life up to 2500 Hours
- Pressure, Vacuum, Absolute or Compound
- BBL Includes Backlit Display

DPG1000B100PSIG-5  
0 to 100.0 psig range



DPG1000B5000PSIG-5  
0 to 5000 psig range



## Mechanical Specifications

### Size

3.38" W x 2.88" H x 1.65" D housing

Add approximately 0.75" to height for pressure fitting

### Weight

Gauge: 9 ounces (approx)

Shipping weight: 1 pound (approx)

### Material and Color

Extruded aluminum case, epoxy powder coated

Polycarbonate cover, front and rear gaskets

Light gray body, light gray/blue front

### Pressure/Vacuum Connection and Material

¼" NPT male, 316 stainless steel

### Media Compatibility

All wetted parts are 316 SS

Compatible with most liquids and gases

### Overpressure

3000 psig range and metric equivalents: 5000 psig

5000 psig range and metric equivalents: 7500 psig

3000 psi, 5000 psi: 112.5% out-of-range display

| - - - or | - . - . -

All others 2x rated pressure minimum

### Burst Pressure

4x rated pressure minimum or 10,000 psi, whichever is less

### Environmental

Storage Temperature -40 to 203°F (-40 to 95°C)

Operating Temperature -4 to 185°F (-20 to 85°C)

Compensated Temperature 32 to 158°F (0 to 70°C)



RB Rubber Boot  
Not for NEMA 4X models

# Cecomp Electronics

cecomp.com



## INSTALLATION AND PRECAUTIONS

Install or remove gauge using wrench on hex fitting only. Do not attempt to tighten by turning housing or any other part of the gauge. Use fittings appropriate for the pressure range of the gauge. Do not apply vacuum to gauges not designed for vacuum operation.

Due to the hardness of 316 stainless steel, it is recommended that a thread sealant be used to ensure leak-free operation.

NEVER insert objects into the gauge port or blow out with compressed air. Permanent damage not covered by warranty will result to the sensor.

## OPERATION - RANGES UP TO 1999

Press the round button on the front of the gauge to activate the display. The gauge will stay on for a period of time determined by the auto-shutoff time. The gauge can be shut off at any time by pressing the button again. Display backlighting on **DPG1000BBL** models is on whenever the gauge is on. If the gauge was ordered without auto shutoff it will stay on until the button is pressed or until the batteries are depleted. Turn gauge off when not in use to conserve battery.

## OPERATION - 3000 PSI, 5000 PSI RANGES

Press and hold the pushbutton for approx. 1 second. The full-scale range is indicated, display segments are tested, and the reading and units are displayed.

### Power-Up With One-Touch Zero (Gauge reference models only)

1. Make absolutely certain no pressure is applied to the gauge. The gauge port should be exposed to normal atmospheric pressure. Note that the zeroing function may only be activated at power-up and the stored zero correction is erased when the gauge is shut off.
2. Press and hold the pushbutton.
3. The full-scale range is indicated and the display segments are tested.
4. Continue to press the pushbutton until **0 0 0 0** is displayed and then release the button. This indicates that the gauge has been zeroed.
5. The actual pressure is displayed.

Attempting to zero the gauge with pressure greater than approximately 3% of full-scale applied will result in an error condition, and the display will alternately indicate **E r r 0** and the actual measured pressure. The gauge must be powered down to reset the error condition.

Absolute reference gauges do not use the zero feature since they read atmospheric pressure under normal conditions.

### Normal Operation

Following the start-up initialization, the display indicates the pressure reading updated approximately 3 times per second and the units. The auto shutoff timer starts when the gauge is powered up or whenever the button is pushed, unless the gauge was ordered without an auto shutoff time (-ON option).

If excessive vacuum is applied to a pressure-only gauge, the display will indicate **- E r r** until the vacuum is released. Applying vacuum to a gauge designed for pressure may damage the pressure sensor. If excessive pressure is applied (112.5% over range), an out-of-range indication of **l - - -** or **l -.-.-** will be displayed depending on model.

### Display Backlighting (BBL models only)

Display backlighting can be turned on by momentarily pressing the button whenever the gauge is on. The backlighting will turn on for one minute and then automatically shut off. This also restarts the auto shutoff timer.

### Shut-Down

To shut off the gauge manually at any time, press and hold the pushbutton until the display indicates **0 F F** (about 5 seconds) and then release.

For gauges with auto shutoff, the display indicates **0 F F** five seconds prior to auto shutoff. The pushbutton can be pressed to keep the gauge on. The auto shutoff and backlight (if equipped) timers are reset whenever the pushbutton is pressed and released.

If the gauge was ordered without auto shutoff (-ON option) it will stay on until manually shut off or until the batteries are depleted. Turn gauge off when not in use to conserve battery life.

## CALIBRATION

All Falcon gauges are factory calibrated on NIST traceable calibration equipment. No calibration is required before placing the gauge into service.

**Ranges up to 1999:** Remove the calibration potentiometer covers on the front of the unit to access the zero and span controls. Gauge reference units may be re-zeroed without affecting the span calibration. The gauge port must be open to the ambient with no pressure or vacuum applied. Adjust the Zero control until the gauge reads zero with the minus (-) sign occasionally flashing.

## CALIBRATION (CONTINUED)

Span calibration should only be attempted if the user has access to a pressure reference of known accuracy. The quality of the calibration is only as good as the accuracy of the calibration equipment and ideally should be at least four times the gauge accuracy. Zero calibration must be done before span calibration. Record readings at three to five points over the range of gauge and adjust span control to minimize error and meet specifications.

**3000 psi and 5000 psi ranges** – The calibration adjustments are internal on these models. The procedure is available from **cecomp.com** or by calling to request the "F16" calibration instructions.

**Absolute Reference** – These models display atmospheric pressure if the gauge port is open to the ambient. It is normal for the reading to constantly change in response to atmospheric pressure changes. Vacuum generation and atmospheric pressure measurement equipment for accurate calibration and thus these are more difficult to calibrate in the field.

Gauges can be returned to Cecomp Electronics for factory certified recalibration, repairs and refurbishment. NIST traceability is available. Gauges can also be recalibrated by any metrology lab with pressure calibration equipment at least four times more accurate than the gauge.

## BATTERY REPLACEMENT

A low battery indication will be shown in the upper left-hand corner of the display when the battery voltage falls sufficiently. The battery should be replaced soon after the indicator comes on or unreliable readings may result.

Remove the 6 Phillips head screws on the back of the unit.


Carefully remove batteries from the holders by lifting up the positive end of the battery (opposite the spring). Take care not to bend or distort the battery retention springs.

DO NOT discard the old battery into fire, any other sources of extreme heat, or in any other hazardous manner. Please consult local authorities if there is any question about proper disposal.

Always replace both batteries at the same time with high quality alkaline batteries. Observe the polarity of the batteries when replacing them. The negative (flat) end of each battery should be inserted first, and should face the spring in the battery holder.


Replace the back cover, including the rubber sealing gasket.

## DIMENSIONS



## PART NUMBERS

**DPG1000B range units reference - shutoff**



### Unit Abbreviations

psi	= PSI
inHg	= INHG
oz/in <sup>2</sup>	= ZIN
inH <sub>2</sub> O	= INH2O
ftH <sub>2</sub> O	= FTH2O
mmHg	= MMHG
torr	= TORR
mmH <sub>2</sub> O	= MMH2O
kg/cm <sup>2</sup>	= KGCM
g/cm <sup>2</sup>	= GCM
kPa	= KPA
MPa	= MPA
mbar	= MBAR
bar	= BAR
cmH <sub>2</sub> O	= CMH2O
atm	= ATM

Cecomp maintains a constant effort to upgrade and improve its products. Specifications are subject to change without notice. Consult factory for your specific requirements.

**Example:** **DPG1000B100PSIG-5** = Battery powered, 100.0 psig, 5 minute shutoff



## Electrical Specifications

### Ranges and Resolution

abs: Absolute reference (atmospheric pressure to zero at full vacuum)  
 vac: Vacuum gauge, minus sign not used unless specified  
 Resolution is fixed as indicated in table below  
 Contact factory for engineering units not listed

-30.0 inHg/15.0 psig	120.0 inHg	1600 mmHg	35.0 bar	1.000 kg/cm <sup>2</sup> abs
-30.0 inHg/100.0 psig	199.9 inHg abs	760 torr abs	70.0 bar	1.000 kg/cm <sup>2</sup> vac
-30.0 inHg/199.9 psig	199.9 inHg	1600 torr abs	140.0 bar	±1.000 kg/cm <sup>2</sup>
3.00 psig	50.0 oz/in <sup>2</sup>	2100 mmH <sub>2</sub> O	199.9 bar	1.000 kg/cm <sup>2</sup>
5.00 psig	80.0 oz/in <sup>2</sup>	3500 mmH <sub>2</sub> O	350 bar	1.999 kg/cm <sup>2</sup> abs
15.00 psi abs	240 oz/in <sup>2</sup> abs	199.9 cmH <sub>2</sub> O	19.99 kPa	1.999 kg/cm <sup>2</sup>
15.00 psig vac	240 oz/in <sup>2</sup> vac	350 cmH <sub>2</sub> O	35.0 kPa	4.00 kg/cm <sup>2</sup>
±15.0 psig	±240 oz/in <sup>2</sup>	1000 cmH <sub>2</sub> O	100.0 kPa abs	7.00 kg/cm <sup>2</sup> abs
15.00 psig	240 oz/in <sup>2</sup>	2100 cmH <sub>2</sub> O	100.0 kPa vac	7.00 kg/cm <sup>2</sup>
30.0 psi abs	85.0 inH <sub>2</sub> O	199.9 mbar	±100.0 kPa	14.00 kg/cm <sup>2</sup>
30.0 psig	140.0 inH <sub>2</sub> O	350 mbar	100.0 kPa	19.99 kg/cm <sup>2</sup>
60.0 psig	400 inH <sub>2</sub> O abs	1000 mbar abs	199.9 kPa abs	35.0 kg/cm <sup>2</sup>
100.0 psi abs	400 inH <sub>2</sub> O vac	1000 mbar vac	199.9 kPa	70.0 kg/cm <sup>2</sup>
100.0 psig	±400 inH <sub>2</sub> O	±1000 mbar	400 kPa	140.0 kg/cm <sup>2</sup>
199.9 psig	400 inH <sub>2</sub> O	1000 mbar	700 kPa abs	199.9 kg/cm <sup>2</sup>
300 psig	850 inH <sub>2</sub> O	1999 mbar abs	700 kPa	350 kg/cm <sup>2</sup>
500 psig	7.00 ftH <sub>2</sub> O	1999 mbar	1500 kPa	1.000 atm abs
1000 psig	12.00 ftH <sub>2</sub> O	4000 mbar	1999 kPa	±1.000 atm
1999 psig	35.0 ftH <sub>2</sub> O	1.000 bar abs	3500 kPa	1.000 atm
3000 psig	70.0 ftH <sub>2</sub> O	1.000 bar vac	5000 kPa	4.00 atm
5000 psig	140.0 ftH <sub>2</sub> O	±1.000 bar	3.50 MPa	7.00 atm
6.00 inHg	230 ftH <sub>2</sub> O	1.000 bar	7.00 MPa	14.00 atm
10.00 inHg	480 ftH <sub>2</sub> O	1.999 bar abs	14.00 MPa	19.99 atm
30.0 inHg abs	150.0 mmHg	1.999 bar	19.99 MPa	35.0 atm
30.0 inHg vac	260 mmHg	4.00 bar	35.0 MPa	70.0 atm
±30.0 inHg	760 mmHg abs	7.00 bar abs	1000 g/cm <sup>2</sup> abs	135.0 atm
30.0 inHg	760 mmHg vac	7.00 bar	1000 g/cm <sup>2</sup>	199.9 atm
60.0 inHg abs	760 mmHg	14.00 bar	2100 g/cm <sup>2</sup> abs	340 atm
60.0 inHg	1600 mmHg abs	19.99 bar	2100 g/cm <sup>2</sup>	

### Accuracy (linearity, hysteresis, repeatability)

Standard: ±0.25% of full scale ±1 least significant digit  
 Optional: **-HA** ±0.1% FS ±1LSD (most ranges)  
**CD** Factory calibration data  
**NC** NIST traceable test report and calibration data

### Display

3 readings per second nominal display update rate  
 Ranges up to 1999: 3½ digit LCD, 0.5" digit height  
 3000 psi, 5000 psi: 4½ digit LCD, 0.5" digit height,  
 lower alphanumeric display for engineering units  
**BBL** models: Red LED backlight

### Controls

**B** ranges up to 1999: Front pushbutton turns gauge on/off  
**BBL** ranges up to 1999: Front pushbutton turns gauge & backlighting on/off  
 Front calibration potentiometers, non-interactive zero and span, ±10% range  
**B & BBL** 3000 psi, 5000 psi, 4-digit ranges  
 Front button turns gauge on, starts auto shutoff timer, and provides zero function for gauge reference ranges  
 Internal calibration pushbuttons, non-interactive zero and span, ±10% range  
**BBL** 3000 psi, 5000 psi, 4-digit ranges  
 Press button to activate backlighting for one minute while gauge is on

### Auto Shutoff

5 minutes standard)  
 Ranges up to 1999: Factory settable to 5, 10, 30 minutes, or on/off  
 3000 psi, 5000 psi: Factory settable to any number of minutes or hours

### Batteries and Battery Life

Two AA alkaline  
**B** ranges up to 1999: Approx. 2500 hours  
**B** 3000 psi, 5000 psi, 4-digit: Approx. 2000 hours  
**BBL** ranges up to 1999: Approx. 180 hours  
**BBL** 3000 psi, 5000 psi, 4-digit: Approx. 150 to 1500 hrs depending on backlight usage

### Low Battery Indication

Low battery symbol on display when batteries must be replaced

- ±0.25% Test Gauge Accuracy
- 316 Stainless Steel Wetted Parts
- Battery Life up to 2500 Hours
- Pressure, Vacuum, Absolute or Compound
- BBL Includes Backlit Display

F4B100PSIG-5  
0 to 100.0 psig range



F4B5000PSIG-5  
0 to 5000 psig range

## Mechanical Specifications

### Size

3.5" W x 3.0" H x 2.0" D housing  
 Add approximately 0.75" to height for pressure fitting

### Weight

Gauge: 9 ounces (approx)  
 Shipping weight: 1 pound (approx)

### Housing

NEMA 4X  
 UV stabilized polycarbonate/ABS case, light gray color  
 Clear polycarbonate window to protect display  
 Gasketed rear cover, six captive stainless steel screws

### Pressure/Vacuum Connection and Material

¼" NPT male, 316 stainless steel

### Media Compatibility

All wetted parts are 316 SS  
 Compatible with most liquids and gases

### Overpressure

3000 psig range and metric equivalents: 5000 psig  
 5000 psig range and metric equivalents: 7500 psig  
 3000 psi, 5000 psi, 4-digit: 112.5% out-of-range display | - - - - or | - . - . - .  
 All others 2x rated pressure minimum

### Burst Pressure

4x rated pressure minimum or 10,000 psi, whichever is less

### Environmental

Storage Temperature -40 to 203°F (-40 to 95°C)  
 Operating Temperature -4 to 185°F (-20 to 85°C)  
 Compensated Temperature 32 to 158°F (0 to 70°C)



cecomp.com

1220 American Way Libertyville, IL 60048  
 Phone: 800-942-0315 Fax: 800-949-7502

api-usa.com



## INSTALLATION AND PRECAUTIONS

Install or remove gauge using wrench on hex fitting only. Do not attempt to tighten by turning housing or any other part of the gauge. Use fittings appropriate for the pressure range of the gauge. Do not apply vacuum to gauges not designed for vacuum operation.

Due to the hardness of 316 stainless steel, it is recommended that a thread sealant be used to ensure leak-free operation.

**NEVER** insert objects into the gauge port or blow out with compressed air. Permanent damage not covered by warranty will result to the sensor.

## OPERATION – RANGES UP TO 1999

Press the round button on the front of the gauge to activate the display. The gauge will stay on for a period of time determined by the auto-shutoff time. The gauge can be shut off at any time by pressing the button again. Display backlighting on DPG1000BBL models is on whenever the gauge is on. If the gauge was ordered without auto shutoff it will stay on until the button is pressed or until the batteries are depleted. The display backlighting will not be apparent under bright lighting conditions. Turn gauge off when not in use to conserve battery.

## OPERATION – 3000 PSI, 5000 PSI, 4-DIGIT RANGES

Press and hold the pushbutton for approx. 1 second. The full-scale range is indicated, display segments are tested, and the reading and units are displayed.

### Power-Up With One-Touch Zero (Gauge reference models only)

1. Make absolutely certain no pressure is applied to the gauge. The gauge port should be exposed to normal atmospheric pressure. Note that the zeroing function may only be activated at power-up and the stored zero correction is erased when the gauge is shut off.
2. Press and hold the pushbutton.
3. The full-scale range is indicated and the display segments are tested.
4. Continue to press the pushbutton until **0 0 0 0** is displayed and then release the button. This indicates that the gauge has been zeroed.
5. The actual pressure is displayed.

Attempting to zero the gauge with pressure greater than approximately 3% of full-scale applied will result in an error condition, and the display will alternately indicate **E r r 0** and the actual measured pressure. The gauge must be powered down to reset the error condition.

Absolute reference gauges do not use the zero feature since they read atmospheric pressure under normal conditions.

### Normal Operation

Following the start-up initialization, the display indicates the pressure reading updated approximately 3 times per second. The auto shutoff timer starts when the gauge is powered up or whenever the button is pushed, unless the gauge was ordered without an auto shutoff time (-ON option).

If excessive vacuum is applied to a pressure-only gauge, the display will indicate **- E r r** until the vacuum is released. Applying vacuum to a gauge designed for pressure may damage the pressure sensor. If excessive pressure is applied (112.5% over range), an out-of-range indication of **1 - - -** or **1 - . - . -** will be displayed depending on model.

### Display Backlighting (BBL models only)

Display backlighting can be turned on by momentarily pressing the button whenever the gauge is on. The backlighting will turn on for one minute and then automatically shut off. This also restarts the auto shutoff timer. The display backlighting will not be apparent under bright lighting conditions.

### Shut-Down

To shut off the gauge manually at any time, press and hold the pushbutton until the display indicates **0 F F** (about 5 seconds) and then release.

For gauges with auto shutoff, the display indicates **0 F F** five seconds prior to auto shutoff. The pushbutton can be pressed to keep the gauge on. The auto shutoff and backlight (if equipped) timers are reset whenever the pushbutton is pressed and released.

If the gauge was ordered without auto shutoff (-ON option) it will stay on until manually shut off or until the batteries are depleted. Turn gauge off when not in use to conserve battery life.

## CALIBRATION

All gauges are factory calibrated on NIST traceable calibration equipment. No calibration is required before placing the gauge into service.

**Ranges up to 1999:** Remove the calibration potentiometer covers on the front of the unit to access the zero and span controls.

Gauge reference units may be re-zeroed without affecting the span calibration. The gauge port must be open to the ambient with no pressure or vacuum applied. Adjust the Zero control until the gauge reads zero with the minus (-) sign occasionally flashing.

## CALIBRATION (CONTINUED)

Span calibration should only be attempted if the user has access to a pressure reference of known accuracy. The quality of the calibration is only as good as the accuracy of the calibration equipment and ideally should be at least four times the gauge accuracy. Zero calibration must be done before span calibration. Record readings at three to five points over the range of gauge and adjust span control to minimize error and meet specifications.

**3000 psi, 5000 psi and 4-digit Ranges** – The calibration adjustments are internal on these models. The calibration instructions are available at [www.cecomp.com](http://www.cecomp.com).

**Absolute Reference** – These models display atmospheric pressure if the gauge port is open to the ambient. It is normal for the reading to constantly change in response to atmospheric pressure changes. Vacuum generation and atmospheric pressure measurement equipment for accurate calibration and thus these are more difficult to calibrate in the field.

Gauges can be returned to Cecomp Electronics for factory certified recalibration, repairs and refurbishment. NIST traceability is available. Gauges can also be recalibrated by any metrology lab with pressure calibration equipment at least four times more accurate than the gauge.

## BATTERY REPLACEMENT

A low battery indication will be shown in the upper left-hand corner of the display when the battery voltage falls sufficiently. The battery should be replaced soon after the indicator comes on or unreliable readings may result.

Remove the 6 Phillips head screws on the back of the unit.

Carefully remove batteries from the holders by lifting up the positive end of the battery (opposite the spring). Take care not to bend or distort the battery retention springs.


DO NOT discard the old battery into fire, any other sources of extreme heat, or in any other hazardous manner. Please consult local authorities if there is any question about proper disposal.

Always replace both batteries at the same time with high quality alkaline batteries.

Observe the polarity of the batteries when replacing them. The negative (flat) end of each battery should be inserted first, and should face the spring in the battery holder.

Replace the back cover, including the rubber sealing gasket.

## DIMENSIONS



## PART NUMBERS

F4B range units reference - shutoff

- B** or **BBL** →
- Range (see table) →
- Units (see table) →
- Reference (see table) →
- G**=Gauge, **A**=Absolute, **VAC**=Vacuum
- Auto shutoff time →
- 5** = 5 minutes
- 10** = 10 minutes
- 30** = 30 minutes
- ON** = on/off, no auto shutoff

### Unit Abbreviations

- psi = PSI
- inHg = INHG
- oz/in<sup>2</sup> = ZIN
- inH<sub>2</sub>O = INH2O
- ftH<sub>2</sub>O = FTH2O
- mmHg = MMHG
- torr = TORR
- mmH<sub>2</sub>O = MMH2O
- kg/cm<sup>2</sup> = KGCM
- g/cm<sup>2</sup> = GCM
- kPa = KPA
- MPa = MPA
- mbar = MBAR
- bar = BAR
- cmH<sub>2</sub>O = CMH2O
- atm = ATM

**Example:** DPG1000B100PSIG-5 = Battery powered, 100.0 psig, 5 minute shutoff

[www.cecomp.com](http://www.cecomp.com)

Cecomp maintains a constant effort to upgrade and improve its products. Specifications are subject to change without notice. Consult factory for your specific requirements.



- F16B**      *Battery Powered*
- F16BN**    *Battery Powered, NEMA 4X*
- F16BBL**   *Battery Powered, Backlit Display*
- F16BNBL**   *Battery Powered, NEMA 4X, Backlit Display*

## Electrical Specifications

### Ranges and Resolution

abs: Absolute reference (atmospheric pressure to zero at full vacuum)

vac: Vacuum gauge, minus sign not used unless specified

Resolution is fixed as indicated in table below

Contact factory for engineering units not listed

-30.0 inHg/15.0 psig	120.0 inHg	1600 mmHg	35.00 bar	1.000 kg/cm <sup>2</sup> abs
-30.0 inHg/100.0 psig	200.0 inHg abs	760.0 torr abs	70.00 bar	1.000 kg/cm <sup>2</sup> vac
-30.0 inHg/200.0 psig	200.0 inHg	1600 torr abs	140.0 bar	±1.000 kg/cm <sup>2</sup>
3.000 psig	50.00 oz/in <sup>2</sup>	2100 mmH <sub>2</sub> O	200.0 bar	1.000 kg/cm <sup>2</sup>
5.000 psig	80.0 oz/in <sup>2</sup>	3500 mmH <sub>2</sub> O	350.0 bar	2.000 kg/cm <sup>2</sup> abs
15.00 psi abs	240.0 oz/in <sup>2</sup> abs	210.0 cmH <sub>2</sub> O	20.00 kPa	2.000 kg/cm <sup>2</sup>
15.00 psig vac	240.0 oz/in <sup>2</sup> vac	350.0 cmH <sub>2</sub> O	35.00 kPa	4.000 kg/cm <sup>2</sup>
±15.00 psig	±240.0 oz/in <sup>2</sup>	1000 cmH <sub>2</sub> O	100.0 kPa abs	7.000 kg/cm <sup>2</sup> abs
15.00 psig	240.0 oz/in <sup>2</sup>	2100 cmH <sub>2</sub> O	100.0 kPa vac	7.000 kg/cm <sup>2</sup>
30.00 psi abs	85.0 inH <sub>2</sub> O	200.0 mbar	±100.0 kPa	14.00 kg/cm <sup>2</sup>
30.00 psig	140.0 inH <sub>2</sub> O	350.0 mbar	100.0 kPa	20.00 kg/cm <sup>2</sup>
60.00 psig	400.0 inH <sub>2</sub> O abs	1000 mbar abs	200.0 kPa abs	35.00 kg/cm <sup>2</sup>
100.0 psi abs	400.0 inH <sub>2</sub> O vac	1000 mbar vac	200.0 kPa	70.00 kg/cm <sup>2</sup>
100.0 psig	±400 inH <sub>2</sub> O	±1000 mbar	400.0 kPa	140.0 kg/cm <sup>2</sup>
200.0 psig	400.0 inH <sub>2</sub> O	1000 mbar	700.0 kPa abs	200.0 kg/cm <sup>2</sup>
300.0 psig	850 inH <sub>2</sub> O	2000 mbar abs	700.0 kPa	350.0 kg/cm <sup>2</sup>
500.0 psig	7.000 ftH <sub>2</sub> O	2000 mbar	1500 kPa	1.000 atm abs
1000 psig	12.00 ftH <sub>2</sub> O	4000 mbar	2000 kPa	±1.000 atm
2000 psig	35.00 ftH <sub>2</sub> O	1.000 bar abs	3500 kPa	1.000 atm
3000 psig	70.00 ftH <sub>2</sub> O	1.000 bar vac	5000 kPa	4.000 atm
5000 psig	140.0 ftH <sub>2</sub> O	±1.000 bar	3.500 MPa	7.000 atm
6.000 inHg	230.0 ftH <sub>2</sub> O	1.000 bar	7.000 MPa	14.00 atm
10.00 inHg	480.0 ftH <sub>2</sub> O	2.000 bar abs	14.00 MPa	20.00 atm
30.00 inHg abs	150.0 mmHg	2.000 bar	20.00 MPa	35.00 atm
30.00 inHg vac	260.0 mmHg	4.000 bar	35.00 MPa	70.00 atm
±30.00 inHg	760.0 mmHg abs	7.000 bar abs	1000 g/cm <sup>2</sup> abs	135.0 atm
30.00 inHg	760.0 mmHg vac	7.000 bar	1000 g/cm <sup>2</sup>	200.0 atm
60.00 inHg abs	760.0 mmHg	14.00 bar	2100 g/cm <sup>2</sup> abs	340.0 atm
60.00 inHg	1600 mmHg abs	20.00 bar	2100 g/cm <sup>2</sup>	

### Accuracy (linearity, hysteresis, repeatability)

Standard: ±0.25% of full scale ±1 least significant digit

Optional: -HA ±0.1% FS ±1LSD (most ranges)

CD Factory calibration data

NC NIST traceable test report and calibration data

### Display

3 readings per second nominal display update rate

4½ digit LCD, 0.5" H, 5 character 0.25" H alphanumeric lower display

BL models: Red LED backlight

### Controls & Functions

Front pushbutton turns gauge on or off and cycles through functions

BL: Press pushbutton to activate 1 minute backlighting when gauge is on

Function	Pushbutton	Prompt (Release Button)	Result
On	Press 1 sec	Gauge Range/Display Test	Actual Pressure
One Touch Zero	Press/hold	0000	Zeroed Actual Pressure
Hi Reading	Press/hold	HI	HI & max. reading
Lo Reading	Press/hold	LO	LO & min. reading
Exit Hi/Lo	Press/hold	AP	Actual Pressure
Clear Hi/Lo	Press/hold	HI / LO / AP	Actual Pressure
Clear Zero, Off	Press/hold	HI / LO / AP	Clear Zero, Gauge Off

### Calibration

Internal calibration pushbuttons, non-interactive zero, span, & linearity, ±10% range

### Auto Shutoff

5 minutes standard (-5), factory settable to on/off (-ON) or specified custom time

### Batteries, Battery Life, Low Battery Indication

B: 2 AA alkaline, approx. 2000 hours

BL: 2 AA alkaline, approx. 150 to 1500 hrs depending on backlight usage

Low battery symbol on display when batteries must be replaced

- ±0.25% Test Gauge Accuracy
- 316 Stainless Steel Wetted Parts
- Capture Minimum and Maximum Readings
- Push Button Zero



**F16B300PSIG-5**  
0 to 300.0 psig range

**F16BN300PSIG-5**  
0 to 300.0 psig  
NEMA 4X

## Mechanical Specifications

### Size

F16B: 3.38" W x 2.88" H x 1.65" D housing

F16BN: 3.5" W x 3.0" H x 2.0" D housing

Add approximately 0.75" to height for pressure fitting

### Weight

Gauge: 9 ounces (approx)

Shipping weight: 1 pound (approx)

### Material & Color

F16B: Extruded aluminum case, light gray epoxy powder coated, black ABS/polycarbonate bezel (aluminum bezel optional), front and rear gaskets, black/gold label

F16BN: Light gray ABS/polycarbonate NEMA 4X case, rear gasket, black/gold label

### Pressure/Vacuum Connection Size, Material, Media Compatibility

¼" NPT male, all wetted parts are 316 SS, compatible with most liquids and gases

### Overpressure

3000 psig range and metric equivalents: 5000 psig

5000 psig range and metric equivalents: 7500 psig

All others: 2 x sensor pressure

112.5% out-of-range display: | - - - or | - . - . -

depending on model

### Burst Pressure

4 times sensor pressure rating, or 10,000 psi, whichever is less

### Environmental

Storage Temperature -40 to 203°F (-40 to 95°C)

Operating Temperature -4 to 185°F (-20 to 85°C)

Compensated Temperature 32 to 158°F (0 to 70°C)



**RB Rubber Boot**  
Not for NEMA 4X models



[cecomp.com](http://cecomp.com)

1220 American Way Libertyville, IL 60048

Phone: 800-942-0315 Fax: 800-949-7502

[api-usa.com](http://api-usa.com)



## INSTALLATION AND PRECAUTIONS

Install or remove gauge using wrench on hex fitting only. Do not attempt to tighten by turning housing or any other part of the gauge.

Use fittings appropriate for the pressure range of the gauge.

Do not apply vacuum to gauges not designed for vacuum operation.

Due to the hardness of 316 stainless steel, it is recommended that a thread sealant be used to ensure leak-free operation.

**NEVER** insert objects into the gauge port or blow out with compressed air. Permanent damage not covered by warranty will result to the sensor.

## POWER-UP

1. Press and hold the pushbutton for approximately 1 second.
2. The full-scale range is indicated and the display segments are tested.
3. The actual pressure and units are displayed.

### Power-Up With Zero (Gauge reference models only)

1. Be sure the gauge port is exposed to normal atmospheric pressure and no pressure is applied. The zeroing function is only activated at each power-up and the stored zero correction is erased when the gauge is shut off.
2. Press and hold the pushbutton.
3. The full-scale range is indicated and the display segments are tested.
4. Continue to press the pushbutton until **0 0 0 0** is displayed and then release the button. This indicates that the gauge has been zeroed.
5. The actual pressure is displayed.

Attempting to zero the gauge with pressure greater than approximately 3% of full-scale applied will result in an error condition, and the display will alternately indicate **E r r 0** and the actual measured pressure. The gauge must be powered down to reset the error condition.

Absolute reference gauges do not use the zero feature since they read atmospheric pressure under normal conditions.

## NORMAL OPERATION

Following the start-up initialization, the display indicates the pressure reading updated approximately 3 times per second. The auto shutoff timer starts when the gauge is powered up or whenever the button is pushed, unless the gauge was ordered without an auto shutoff time (-ON option).

If excessive vacuum is applied to a pressure-only gauge, the display will indicate **- E r r** until the vacuum is released. Applying vacuum to a gauge designed for pressure may damage the pressure sensor. If excessive pressure is applied (112.5% over range), an out-of-range indication of **l - - -** or **l - . - . -** will be displayed depending on model.

## MINIMUM AND MAXIMUM READINGS

Minimum and maximum readings are continuously stored and updated whenever gauge is on. The stored readings can be manually cleared if desired. The **HI** and **LO** memory is also cleared whenever the gauge is off.

Press and hold the pushbutton for about 1 second until **HI** is displayed. The maximum stored value is displayed.

After **HI** is displayed, press and hold the pushbutton again for about 1 second until **LO** is displayed. The minimum stored value is displayed.

After **LO** is displayed, press and hold the pushbutton again for about 1 second until **AP** (Applied Pressure) is displayed. The **HI** and **LO** memory is not erased and the gauge returns to normal operation with the display indicating the current pressure.

Press and continue to hold the pushbutton until the display indicates **clr HI/LO** (about 3 seconds total) and then release the pushbutton. Both **HI** and **LO** values are cleared and the gauge returns to the normal mode and displays the current pressure.

## DISPLAY BACKLIGHTING (BBL MODELS ONLY)

Display backlighting can be turned on by momentarily pressing the button whenever the gauge is on. The backlighting will turn on for one minute and then automatically shut off. This also restarts the auto shutoff timer. The display backlighting will not be apparent under bright lighting conditions.

## SHUT-DOWN

To shut off the gauge manually at any time, press and hold the pushbutton until the display indicates **OFF** (about 5 seconds) and then release.

For gauges with auto shutoff, the display indicates **OFF** five seconds prior to auto shutoff. The pushbutton can be pressed to keep the gauge on. The auto shutoff and backlight (if equipped) timers are reset whenever the pushbutton is pressed and released.

If the gauge was ordered without auto shutoff (-ON option) it will stay on until manually shut off or until the batteries are depleted. Turn gauge off when not in use to conserve battery life.

## CALIBRATION


**F16-series** gauges use internal controls for calibration. The calibration instructions are available at [cecomp.com](http://cecomp.com). Gauges can be recalibrated by any metrology lab with pressure calibration equipment at least 4 times more accurate than the gauge. Gauges may also be returned for factory recalibration and refurbishment. NIST traceability is available.

## BATTERY REPLACEMENT


A low battery indication will be shown in the upper left-hand corner of the display when the battery voltage falls sufficiently. The battery should be replaced soon after the indicator comes on or unreliable readings may result.

1. Remove the 6 Phillips head screws on the back of the unit.
2. Remove batteries by lifting up the positive end of the battery (opposite the spring) taking care not to bend the battery holder spring.
3. Discard old batteries properly, DO NOT discard into fire, sources of extreme heat, or in any other hazardous manner.
4. Always replace both batteries at the same time with high quality alkaline batteries. Install batteries with correct orientation. The negative (flat) end of each battery should be inserted first facing the battery holder spring.
6. Replace the back cover, including the rubber sealing gasket.

## DIMENSIONS



## PART NUMBERS



**Unit Abbreviations**

oz/in <sup>2</sup>	= ZIN
inH <sub>2</sub> O	= INH2O
ftH <sub>2</sub> O	= FTH2O
mmH <sub>2</sub> O	= MMH2O
kg/cm <sup>2</sup>	= KGCM
g/cm <sup>2</sup>	= GCM
cmH <sub>2</sub> O	= CMH2O

**Example: F16B100PSIG-10**  
F16, Battery powered, 100.0 psig, 10 minute shutoff

Cecomp maintains a constant effort to upgrade and improve its products. Specifications are subject to change without notice. Consult factory for your specific requirements.

[www.cecomp.com](http://www.cecomp.com)

- ±0.25% Test Gauge Accuracy
- 316 Stainless Steel Wetted Parts
- Capture Minimum and Maximum Readings

- Selectable Units
- Selectable Auto Shutoff Times
- Zero Function

**Specifications**

**Ranges and Resolution**

See table below. Any engineering units equivalent to the PSI range can be ordered as the default range. Resolution is fixed for each engineering unit

**Accuracy**

Includes linearity, hysteresis, repeatability  
Standard: ±0.25% of full scale ±1 least significant digit  
-HA: ±0.1% FS ±1 LSD (see Options for availability)

**Display**

3 readings per second nominal display update rate  
4 digit LCD, 0.5" H and 5 character 0.25" H alphanumeric  
BL models: red LED backlight

**Batteries, Battery Life, Low Battery Indication**

B: 2 AA alkaline, approx. 2000 hours  
BL: 2 AA alkaline, approx. 150 to 1500 hours depending on backlight usage  
Low battery symbol on display

**Controls & Functions**

Front button turns gauge on or off, zeros gauge reference gauges, and cycles through min/max functions  
Internal push buttons for calibration and selection of engineering units and auto shutoff times  
BL: Front button activates backlighting for 1 minute

**Min/Max Functions**

Minimum and maximum readings stored 4 times per second  
Front button cycles through min display, max display, clear  
Configurable for min only, max only, both, or none  
Configure to clear min/max at power off or retain min/max at power off

**Calibration**

Pass code protected calibration  
Non-interactive zero, span, and linearity, ±10% of range

**Auto Shutoff**

User selectable 1 minute to 8 hours or front button on/off  
Factory default 5 minutes, unless other time is specified

**Weight**

Gauge: 9 ounces (approximately)  
Shipping: 1 pound (approximately)

**Material**

F18B: Extruded aluminum case, epoxy powder coated, ABS/ polycarbonate bezel (aluminum bezel optional), front and rear gaskets, polycarbonate label  
F18BN: ABS/polycarbonate NEMA 4X case, rear gasket, polycarbonate label

**Connection, Material, Media Compatibility**

1/4" NPT male fitting, 316L stainless steel  
All wetted parts are 316L stainless steel  
Compatible with most liquids and gases

**Overpressure**

3000 psig range: 5000 psig  
5000 psig range: 7500 psig  
All others: 2 X pressure range  
112.5% FS out-of-range display: i --- or i ---

**Burst Pressure**

4 X sensor pressure rating, or 10,000 psi, whichever is less

**Storage Temperature**


-40 to 203°F (-40 to 95°C)

**Operating Temperature**

-4 to 185°F (-20 to 85°C)

**Compensated Temperature**

32 to 158°F (0 to 70°C)



**How to Order**

**Please Specify**

**Model Range - Shutoff\* - Options**

Specify pressure or vacuum range and units. Include gauge or absolute reference as applicable.

If vacuum gauge requires a minus sign, please specify.

\*Only specify if default time is to be other than 5 minutes

Model	Features
F18B	Standard housing
F18BBL	Standard housing, backlit display
F18BN	NEMA 4X housing
F18BNBL	NEMA 4X housing, backlit display

**Options—add to end of model number**

- HA High accuracy, ±0.1% FS ±1 LSD. Not available with vacuum, compound, bipolar, absolute, or 3 psi sensor ranges.
- PM Panel mount, 4.1" x 4.1". Not available with NEMA 4X models.
- MC Metal front cover. Machined aluminum, epoxy powder coated. Synthetic oil resistant. Not available with NEMA 4X models.
- CS Case stiffener strengthens case bottom for tire pressure applications.
- CC Conformal coating on circuit board for moisture resistance.
- SM Surface mount plate. Battery gauges only. Not available with NEMA 4X models.
- TP Top port, gauge port on top of case. Used primarily for tire pressure applications.

**Accessories**

- RB Protective rubber boot. Not for NEMA 4X models.
- CD Calibration data, 5 test points, test date.
- NC NIST certificate with traceability documentation, 5 test points and date.

Range Code	Default Range	Selectable Engineering Units. See table on next page for specific ranges.															
-30V15PSIG *	-30.0 inHg to 15.0 PSIG	±PSIG	±inHg	±inH <sub>2</sub> O	±oz/in <sup>2</sup>	±g/cm <sup>2</sup>	±mmHg	±torr	±mbar	±bar	±inH <sub>2</sub> O	±cmH <sub>2</sub> O	±kPa	±MPa	±kg/cm <sup>2</sup>	±atm	
-30V100PSIG *	-30.0 inHg to 100.0 PSIG	±PSIG	±inHg	±inH <sub>2</sub> O	±oz/in <sup>2</sup>		±mmHg	±torr	±bar				±kPa	±MPa	±kg/cm <sup>2</sup>	±atm	
-30V200PSIG *	-30.0 inHg to 200.0 PSIG	±PSIG	±inHg	±inH <sub>2</sub> O	±oz/in <sup>2</sup>				±bar				±kPa	±MPa	±kg/cm <sup>2</sup>	±atm	
3PSIG	0 to 3.000 PSIG		inHg	inH <sub>2</sub> O	oz/in <sup>2</sup>	g/cm <sup>2</sup>	mmHg	torr	mbar	bar	mmH <sub>2</sub> O	cmH <sub>2</sub> O	ftH <sub>2</sub> O	kPa		atm	
5PSIG	0 to 5.000 PSIG		inHg	inH <sub>2</sub> O	oz/in <sup>2</sup>	g/cm <sup>2</sup>	mmHg	torr	mbar	bar	mmH <sub>2</sub> O	cmH <sub>2</sub> O	ftH <sub>2</sub> O	kPa		atm	
15PSIA	15.00 to 0 PSIA		inHg	inH <sub>2</sub> O	oz/in <sup>2</sup>	g/cm <sup>2</sup>	mmHg	torr	mbar	bar		cmH <sub>2</sub> O		kPa	MPa	atm	
15PSIVAC	0 to -15.00 PSIG		inHg	inH <sub>2</sub> O	oz/in <sup>2</sup>	g/cm <sup>2</sup>	mmHg	torr	mbar	bar		cmH <sub>2</sub> O	ftH <sub>2</sub> O	kPa	MPa	atm	
±15PSIG	±15.00 PSIG		±inHg	±inH <sub>2</sub> O	±oz/in <sup>2</sup>	±g/cm <sup>2</sup>	±mmHg	±torr	±mbar	±bar		±cmH <sub>2</sub> O	±ftH <sub>2</sub> O	±kPa	±MPa	±atm	
15PSIG	0 to 15.00 PSIG		inHg	inH <sub>2</sub> O	oz/in <sup>2</sup>	g/cm <sup>2</sup>	mmHg	torr	mbar	bar		cmH <sub>2</sub> O	ftH <sub>2</sub> O	kPa	MPa	atm	
30PSIA	0 to 30.00 PSIA		inHg	inH <sub>2</sub> O	oz/in <sup>2</sup>	g/cm <sup>2</sup>	mmHg	torr	mbar	bar		cmH <sub>2</sub> O		kPa	MPa	atm	
30PSIG	0 to 30.00 PSIG		inHg	inH <sub>2</sub> O	oz/in <sup>2</sup>	g/cm <sup>2</sup>	mmHg	torr	mbar	bar		cmH <sub>2</sub> O	ftH <sub>2</sub> O	kPa	MPa	atm	
60PSIG	0 to 60.00 PSIG		inHg	inH <sub>2</sub> O	oz/in <sup>2</sup>	g/cm <sup>2</sup>	mmHg	torr	mbar	bar		cmH <sub>2</sub> O	ftH <sub>2</sub> O	kPa	MPa	atm	
100PSIA	0 to 100.0 PSIA		inHg	inH <sub>2</sub> O	oz/in <sup>2</sup>	g/cm <sup>2</sup>	mmHg	torr	mbar	bar		cmH <sub>2</sub> O		kPa	MPa	atm	
100PSIG	0 to 100.0 PSIG		inHg	inH <sub>2</sub> O	oz/in <sup>2</sup>	g/cm <sup>2</sup>	mmHg	torr	mbar	bar		cmH <sub>2</sub> O	ftH <sub>2</sub> O	kPa	MPa	atm	
200PSIG	0 to 200.0 PSIG		inHg	inH <sub>2</sub> O	oz/in <sup>2</sup>					bar		ftH <sub>2</sub> O	kPa	MPa	kg/cm <sup>2</sup>	atm	
300PSIG	0 to 300.0 PSIG		inHg		oz/in <sup>2</sup>					bar		ftH <sub>2</sub> O	kPa	MPa	kg/cm <sup>2</sup>	atm	
500PSIG	0 to 300.0 PSIG		inHg							bar		ftH <sub>2</sub> O	kPa	MPa	kg/cm <sup>2</sup>	atm	
1000PSIG	0 to 1000 PSIG		inHg							bar		ftH <sub>2</sub> O	kPa	MPa	kg/cm <sup>2</sup>	atm	
2000PSIG	0 to 2000 PSIG		inHg							bar		ftH <sub>2</sub> O	kPa	MPa	kg/cm <sup>2</sup>	atm	
3000PSIG	0 to 3000 PSIG		inHg							bar		ftH <sub>2</sub> O	kPa	MPa	kg/cm <sup>2</sup>	atm	
5000PSIG	0 to 5000 PSIG		inHg							bar		ftH <sub>2</sub> O	kPa	MPa	kg/cm <sup>2</sup>	atm	

\*Compound ranges can be set up as either compound (inHg/psig only) or bipolar (±) with selectable units in pass code protected user configuration mode only.

**Range Codes**

The range code is part of the gauge model number and indicates the default range when the gauge is ordered. Consult factory with special requirements or engineering units.

**Selectable Ranges**

Engineering units may be changed to any of those listed in the same Selectable Units group as shown in the table below.

**Conversion**

Engineering units are calculated from the factory default unit to the newly selected units. The ranges listed under Selectable Units are rounded off.

Range Codes	Selectable Units	Range Codes	Selectable Units	Range Codes	Selectable Units	Range Codes	Selectable Units
3PSIG	0 to 3.000 psig	100MBARG	0 to 1000 mbar <i>continued ▲</i>	4100MBARG	0 to 4100 mbar <i>continued ▲</i>	200PSIG	0 to 200.0 psig
6INHG	0 to 6.000 inHg	1000CMH2OG	0 to 1000 cmH2O	4200CMH2OG	0 to 4200 cmH2O	400INHG	0 to 400.0 inHg
85INH2OG	0 to 85.0 inH2O	35FTH2O	0 to 35.00 ftH2O	140FTH2O	0 to 140.0 ftH2O	5500INH2OG	0 to 5500 inH2O
5OZING	0 to 50.00 oz/in <sup>2</sup>	100KPAG	0 to 100.0 kPa	400KPAG	0 to 400.0 kPa	320OZING	0 to 3200 oz/in <sup>2</sup>
210GCMG	0 to 210.0 g/cm <sup>2</sup>	0.1MPAG	0 to .1000 MPa	0.4MPAG	0 to .4000 MPa	480FTH2O	0 to 480.0 ftH2O
150MMHGG	0 to 150.0 mmHg	1BARG	0 to 1000 bar	4BARG	0 to 4.000 bar	1400KPAG	0 to 1400 kPa
150TORR	0 to 150.0 torr	1KGCMMG	0 to 1000 kg/cm <sup>2</sup>	4KGCMMG	0 to 4.000 kg/cm <sup>2</sup>	1.4MPAG	0 to 1.400 MPa
200MBARG	0 to 200.0 mbar	1ATMG	0 to 1000 atm	4ATMG	0 to 4.000 atm	14BARG	0 to 14.00 bar
200CMH2OG	0 to 200.0 cmH2O	<b>Range Codes</b> <b>Selectable Units</b>		<b>Range Codes</b> <b>Selectable Units</b>		<b>Range Codes</b> <b>Selectable Units</b>	
2000MMH2OG	0 to 2000 mmH2O	±15PSIG	-15.00 to 15.00 psig	100PSIA	100.0 to 0 psia	14KGCMMG	0 to 14.00 kg/cm <sup>2</sup>
7FTH2O	0 to 7.000 ftH2O	-30INHG/15PSIG	-30.00 inHg to 15.00 psig	200INHGA	200.0 to 0 inHg abs	14ATMG	0 to 14.00 atm
20KPAG	0 to 20.00 kPa	±30INHGG	-30.00 to 30.00 inHg	2770INH20A	2770 to 0 inH2O abs	<b>Range Codes</b> <b>Selectable Units</b>	
<b>Range Codes</b> <b>Selectable Units</b>		±400INH2OG	-400 to 400 inH2O	1600ZINA	1600 to 0 oz/in <sup>2</sup> abs	300PSIG	0 to 300.0 psig
5PSIG	0 to 5.000 psig	±24OZING	-240.0 to 240.0 oz/in <sup>2</sup>	7000GMA	7000 to 0 g/cm <sup>2</sup> abs	610INHGG	0 to 610.0 inHg
10INHGG	0 to 10.00 inHg	±1000GCMG	-1000 to 1000 g/cm <sup>2</sup>	5200GMA	5200 to 0 mmHg abs	480OZING	0 to 4800 oz/in <sup>2</sup>
140INH2OG	0 to 140.0 inH2O	±760MMHGG	-760 to 760 mmHg	5200TORRA	5200 to 0 torr abs	700FTH2O	0 to 700.0 ftH2O
80ZING	0 to 80.0 oz/in <sup>2</sup>	±760TORR	-760 to 760 torr	7000MBARA	7000 to 0 mbar abs	2000KPAG	0 to 2000 kPa
350GCMG	0 to 350.0 g/cm <sup>2</sup>	±1000MBAR	-1000 to 1000 mbar	7000CMH2OA	7000 to 0 cmH2O abs	2MPAG	0 to 2.000 MPa
260MMHGG	0 to 260.0 mmHg	±1000CMH2OG	-1000 to 1000 cmH2O	700KPAA	700.0 to 0 kPa abs	20BARG	0 to 20.00 bar
260TORR	0 to 260.0 torr	±100KPAG	-100.0 to 100.0 kPa	0.7MPAA	0 to .7000 to 0 MPa abs	20KGCMMG	0 to 20.00 kg/cm <sup>2</sup>
350MBARG	0 to 350.0 mbar	±0.1MPAG	-.1000 to .1000 MPa	7BAR	0 to 7.000 to 0 bar abs	20ATMG	0 to 20.00 atm
350CMH2OG	0 to 350.0 cmH2O	±1BARG	-1.000 to 1.000 bar	7KGCMA	0 to 7.000 to 0 kg/cm <sup>2</sup> abs	<b>Range Codes</b> <b>Selectable Units</b>	
3500MMH2OG	0 to 3500 mmH2O	±1KGCMMG	-1.000 to 1.000 kg/cm <sup>2</sup>	7ATMA	0 to 7.000 to 0 atm abs	500PSIG	0 to 500.0 psig
12FTH2O	0 to 12.00 ftH2O	±1ATMG	-1.000 to 1.000 atm	<b>Range Codes</b> <b>Selectable Units</b>		1020INHGG	0 to 1020 inHg
35KPAG	0 to 35.00 kPa	<b>Range Codes</b> <b>Selectable Units</b>		15V100PSIG	-15.0 to 100.0 psig	1150FTH2O	0 to 1150 ftH2O
<b>Range Codes</b> <b>Selectable Units</b>		30PSIA	30.00 to 0 psia	-30INHG/100PSIG	-30.0 inHg to 100.0 psig	3500KPAG	0 to 3500 kPa
15PSIA	15.00 to 0 psia	60INHGA	60.00 to 0 inHg abs	-30V200INHGG	-30.0 to 200.0 inHg	3.5MPAG	0 to 3.500 MPa
30INHGA	30.00 to 0 inHg abs	850INH2OA	850 to 0 inH2O abs	-400V2770INH2OG	-400 to 2770 inH2O	35BARG	0 to 35.00 bar
400INH2OA	400.0 to 0 inH2O abs	480ZINA	480.0 to 0 oz/in <sup>2</sup> abs	240V1600ZING	-240 to 1600 oz/in <sup>2</sup>	35KGCMMG	0 to 35.00 kg/cm <sup>2</sup>
240ZINA	240.0 to 0 oz/in <sup>2</sup> abs	2100GMA	2100 to 0 g/cm <sup>2</sup> abs	760V5200MMHGG	-760 to 5200 mmHg	35ATMG	0 to 35.00 atm
1000GMA	1000 to 0 g/cm <sup>2</sup> abs	1600MMHGA	1600 to 0 mmHg abs	760V5200TORR	-760 to 5200 torr	<b>Range Codes</b> <b>Selectable Units</b>	
760MMHGA	760.0 to 0 mmHg abs	1600TORRA	1600 to 0 torr abs	-100V700KPAG	-100 to 700 kPa	1000PSIG	0 to 1000 psig
760TORRA	760.0 to 0 torr abs	2000MBARA	2000 to 0 mbar abs	-0.1V0.7MPAG	-1.00 to .700 MPa	2040INHGG	0 to 2040 inHg
1000MBARA	1000 to 0 mbar abs	2100CMH2OA	2100 to 0 cmH2O abs	-1V7BARG	-1.00 to 7.00 bar	2300FTH2O	0 to 2300 ftH2O
1000CMH2OA	1000 to 0 cmH2O abs	200KPAA	200.0 to 0 kPa abs	-1V7KGCMMG	-1.00 to 7.00 kg/cm <sup>2</sup>	7000KPAG	0 to 7000 kPa
100KPAA	100.0 to 0 kPa abs	0.2MPAA	0 to .2000 to 0 MPa abs	-1V7ATMG	-1.00 to 7.00 atm	7MPAG	0 to 7.000 MPa
0.1MPAA	.1000 to 0 MPa abs	2BAR	0 to 2.000 to 0 bar abs	<b>Range Codes</b> <b>Selectable Units</b>		70BARG	0 to 70.00 bar
1BAR	1.000 to 0 bar abs	2KGCMA	0 to 2.000 to 0 kg/cm <sup>2</sup> abs	100PSIG	0 to 100.0 psig	70KGCMMG	0 to 70.00 kg/cm <sup>2</sup>
1KGCMA	1.000 to 0 kg/cm <sup>2</sup> abs	2ATMA	0 to 2.000 to 0 atm abs	200INHGG	0 to 200.0 inHg	70ATMG	0 to 70.00 atm
1ATMA	1.000 to 0 atm abs	<b>Range Codes</b> <b>Selectable Units</b>		2770INH2OG	0 to 2770 inH2O	<b>Range Codes</b> <b>Selectable Units</b>	
<b>Range Codes</b> <b>Selectable Units</b>		30PSIG	0 to 30.00 psig	1600ZING	0 to 1600 oz/in <sup>2</sup>	2000PSIG	0 to 2000 psig
15PSIVAC	0 to 15.00 psig vacuum	60INHGG	0 to 60.00 inHg	7000GCMG	0 to 7000 g/cm <sup>2</sup>	4070INHGG	0 to 4070 inHg
30INHG	0 to 30.00 inHg vacuum	850INH2OG	0 to 850 inH2O	5200MMHGG	0 to 5200 mmHg	4600FTH2O	0 to 4600 ftH2O
400INH2OVAC	0 to 400 inH2O vacuum	480ZING	0 to 480.0 oz/in <sup>2</sup>	5200TORR	0 to 5200 torr	14MPAG	0 to 14.00 MPa
240ZINVAC	0 to 240.0 oz/in <sup>2</sup> vacuum	2100GCMG	0 to 2100 g/cm <sup>2</sup>	7000MBARG	0 to 7000 mbar	140BARG	0 to 140.0 bar
1000GCMVAC	0 to 1000 g/cm <sup>2</sup> vacuum	1600MMHGG	0 to 1600 mmHg	7000CMH2OG	0 to 7000 cmH2O	140KGCMMG	0 to 140.0 kg/cm <sup>2</sup>
760MMHGVAC	0 to 760.0 mmHg vacuum	1600TORR	0 to 1600 torr	230FTH2O	0 to 230.0 ftH2O	140ATMG	0 to 140.0 atm
760TORRVAC	0 to 760.0 torr vacuum	2000MBARG	0 to 2000 mbar	700KPAG	0 to 700.0 kPa	<b>Range Codes</b> <b>Selectable Units</b>	
1000MBARVAC	0 to 10000 mbar vacuum	2100CMH2OG	0 to 2100 cmH2O	0.7MPAG	0 to .7000 MPa	3000PSIG	0 to 3000 psig
1000CMH2OVAC	0 to 10000 cmH2O vacuum	70FTH2O	0 to 70.00 ftH2O	7BARG	0 to 7.000 bar	6100INHGG	0 to 6100 inHg
100KPAVAC	0 to 100.0 kPa vacuum	200KPAG	0 to 200.0 kPa	7KGCMMG	0 to 7.000 kg/cm <sup>2</sup>	6900FTH2O	0 to 6900 ftH2O
0.1MPAVAC	0 to .1000 MPa vacuum	0.2MPAG	0 to .2000 MPa	7ATMG	0 to 7.000 atm	20MPAG	0 to 20.00 MPa
1BARVAC	0 to 1.000 bar vacuum	2BARG	0 to 2.000 bar	<b>Range Codes</b> <b>Selectable Units</b>		200BARG	0 to 200.0 bar
1KGCMMVAC	0 to 35.00 kg/cm <sup>2</sup> vacuum	2KGCMMG	0 to 2.000 kg/cm <sup>2</sup>	15V200PSIG	-15.0 to 200.0 psig	200KGCMMG	0 to 200.0 kg/cm <sup>2</sup>
1ATMVAC	0 to 1.000 atm vacuum	2ATMG	0 to 2.000 atm	-30INHG/200PSIG	-30.0 inHg to 200.0 psig	200ATMG	0 to 200.0 atm
<b>Range Codes</b> <b>Selectable Units</b>		<b>Range Codes</b> <b>Selectable Units</b>		<b>Range Codes</b> <b>Selectable Units</b>		<b>Range Codes</b> <b>Selectable Units</b>	
15PSIG	0 to 15.00 psig	60PSIG	0 to 60.00 psig	400V5500INH2OG	-400 to 5500 inH2O	5000PSIG	0 to 5000 psig
30INHGG	0 to 30.00 inHg	120INHGG	0 to 120.0 inHg	240V3200ZING	-240 to 3200 oz/in <sup>2</sup>	35MPAG	0 to 35.00 MPa
400INH2OG	0 to 400.0 inH2O	1660INH2OG	0 to 1660 inH2O	-100V1400KPAG	-100 to 1400 kPa	350BARG	0 to 350.0 bar
240ZING	0 to 240.0 oz/in <sup>2</sup>	960ZING	0 to 960 oz/in <sup>2</sup>	-0.1V1.4MPAG	-1.00 to 1.400 MPa	350KGCMMG	0 to 350.0 kg/cm <sup>2</sup>
1000GCMG	0 to 1000 g/cm <sup>2</sup>	4200GCMG	0 to 4200 g/cm <sup>2</sup>	-1V14BARG	-1.00 to 14.00 bar	340ATMG	0 to 340.0 atm
760MMHGG	0 to 760.0 mmHg	3100MMHGG	0 to 3100 mmHg	-1V14KGCMMG	-1.00 to 14.00 kg/cm <sup>2</sup>		
760TORR	0 to 760.0 torr <i>continued ▲</i>	3100TORR	0 to 3100 torr <i>continued ▲</i>	-1V14ATMG	-1.00 to 14.00 atm		

**Installation Precautions**

- ✓ Read these instructions before installing the gauge. The configuration options may be easier to set up before the gauge is installed.
- ✓ Due to the hardness of 316 stainless steel, it is recommended that a thread sealant be used to ensure leak-free operation.
- ✓ Install or remove gauge using a wrench on the hex fitting only.
- ✓ For contaminated media use an appropriate screen or filter to keep debris out of gauge port.
- ✗ Do not attempt to turn by forcing the housing.
- ▲ Use fittings appropriate for the pressure range of the gauge.
- ✗ Do not apply vacuum to gauges not designed for vacuum operation.
- ✗ NEVER insert objects into the gauge port or blow out with compressed air. Permanent damage not covered by warranty will result to the sensor.

**Power-Up**

Press and hold the front button for approximately 1 second.

The display segments are tested.

The full-scale range is indicated and the display segments are briefly shown again.

The actual pressure and units are displayed.

**Power-Up With Zero**

This applies to gauge reference models only. Absolute reference gauges do not use the zero feature since they read atmospheric pressure under normal conditions.

Be sure the gauge port is exposed to normal atmospheric pressure and no pressure is applied. The zeroing function is only activated at each power-up and the stored zero correction is erased when the gauge is shut off.

Press and hold the front button.

The display segments are tested.

Continue to press the button until 0000 is displayed.

Release the button. The gauge is now zeroed.

The full-scale range is indicated and the display segments are briefly shown again.

The actual pressure and units are displayed.

Attempting to zero the gauge with pressure greater than approximately 3% of full-scale pressure or vacuum applied will result in an error condition, and the display will alternately indicate Err 0 and the actual measured pressure. The gauge must be powered down to reset the error condition.

**Normal Operation**

Following the start-up initialization, the display indicates the pressure reading updated approximately 3 times per second. The auto shutoff timer starts when the gauge is powered up or whenever the button is pushed, unless the gauge shutoff time was set to zero for on/off operation.

If excessive vacuum is applied to a pressure-only gauge, the display will indicate -Err until the vacuum is released.

Applying vacuum to a gauge designed for pressure may damage the pressure sensor. If excessive pressure is applied (112.5% over range), an out-of-range indication of 1 --- or 1.-- will be displayed depending on model.

**Display Backlighting (BL models only)**

Display backlighting can be turned on by momentarily pressing the front button whenever the gauge is on. The backlighting will turn on for one minute and then automatically shut off. This also restarts the auto shutoff timer. The display backlighting will not be apparent under bright lighting conditions.

**Minimum and Maximum Readings**

Gauges are normally configured with minimum and maximum capture functions enabled. One or both can be disabled in the User Configuration mode.

Minimum and maximum readings are continuously stored and updated whenever the gauge is on. The stored readings can be manually cleared if desired. The MAX and MIN memory is also cleared whenever the gauge is off unless configured to save the readings.

Press and hold the button for about 1 second until MAX is displayed alternating with the units. The maximum reading will be continuously updated. The gauge may be left in this mode.

After MAX is displayed, press and hold the button for about 1 second until MIN is displayed alternating with the units. The minimum reading will be continuously updated. The gauge may be left in this mode. If excessive vacuum is applied to a pressure-only gauge while in this mode, the display will indicate -Err until the MAX/MIN readings are cleared.

After MIN is displayed, press and hold the button again for about 1 second until \* \* \* \* is displayed. The MAX and MIN memory is not erased and the gauge returns to normal operation with the display indicating the current reading.


Press and continue to hold the button until the display indicates clr MX/MN (about 3 seconds total) and then release the button. Both maximum and minimum values are cleared and the gauge returns to the normal mode and displays the current pressure.

**Shut-Down**

To shut off the gauge manually at any time, press and hold the button until the display indicates OFF (about 5 seconds) and then release.

When an auto shutoff timer is used, the display indicates OFF five seconds prior to auto shutoff. The button can be pressed to keep the gauge on. The auto shutoff and backlight (if equipped) timers are reset whenever the button is pressed and released.

If the gauge set up without auto shutoff (on/off operation) it will stay on until manually shut off or until the batteries are depleted. Turn gauge off when not in use to conserve battery life.

**Engineering Unit Selection**

Engineering unit selection is done via internal buttons to help prevent accidental or unauthorized changes. The selected engineering unit is stored in non-volatile memory and will be retained even with the gauge off or batteries removed. The available engineering units depend on the sensor range and display resolution.

Compound (inHg/PSIG) gauges must be changed to display single-unit vacuum/pressure readings in the Advanced Configuration mode before different engineering units can be selected.

The default engineering units are mathematically converted to the newly selected engineering unit. When the gauge is powered up, the originally configured range is displayed and then the conversion with the selected engineering unit is displayed.

To change engineering units remove the rear cover to gain access to the two internal buttons located near the lower right and left corners of the circuit board.

With the gauge powered up, press and hold the UP button. Release the button when the engineering units begin to flash.

Use the UP and DOWN buttons to scroll through the list of engineering units available for the pressure range of the sensor.

When the desired units are displayed, press and release the front button to save the selection and return to normal operation.

Note: The gauge will automatically revert to normal operation if no buttons are operated for approximately 15 seconds.

Replace the rear cover taking care not to pinch the power wires between the cover and the case.

**Auto Shutoff Time Selection**

Auto shutoff time selection is done via internal buttons to help prevent accidental or unauthorized changes. The selected shut off time is stored in non-volatile memory and will be retained even with the battery off or batteries removed.

Remove the rear cover to gain access to the two internal buttons located near the lower right and left corners of the circuit board.

With the gauge powered up, press and hold the DOWN button. Release the button when the auto shutoff time is displayed on the upper section.

The lower display segments will indicate AST M if the time displayed is in minutes, and AST H if it is in hours.

An auto shutoff time of 0 signifies that the auto shutoff feature is disabled and the front button turns the gauge on and off.

Use the UP and DOWN buttons to select 0, 1, 2, 5, 10, 15, 20 or 30 minutes, or 1, 2, 4, or 8 hours.

When the desired time is displayed, press and release the front button to save the selection and return to normal operation.

Note: The gauge will automatically revert to normal operation if no buttons are operated for approximately 15 seconds.

Replace the rear cover taking care not to pinch the power wires between the cover and the case.

**Advanced Configuration****User Configuration**

User configuration allows requires a pass code for access and allows more features to be configured.

Remove the rear cover to gain access to the buttons located near the lower right and left corners of the circuit board.

With the gauge off, press and hold the UP button. Then press the front button. Release all buttons when the display indicates CFG and the program version then the full-scale range is indicated and the display segments are tested.

The display then indicates \_ \_ \_ \_ with the first underscore blinking, and with CFGPC (configuration pass code) on the character segments.

Note: The gauge will automatically revert to normal operation if no buttons are operated for approximately 15 seconds. To cancel and return to normal operation, press and release the front button without entering any pass code characters.

**User Configuration Pass Code Entry**

The factory default is 3510, but this may be changed by the user under the Pass Code Configuration section.

1. Use the UP or DOWN buttons to set the left-most digit to 3.
2. Press and release the front button to move to the next position. The 3 will remain, and the second position will be blinking.
3. Use the UP or DOWN buttons to select 5.
4. Press and release the front button to index to the next position. 35 will remain, and the third position will be blinking.

5. Use the UP or DOWN buttons to select 1.
6. Press and release the front button to index to the next position. 351 will remain, and the fourth position will be blinking.
7. Use the UP or DOWN buttons to select 0.
8. Press and release the front button to proceed with configuration procedures.

If an incorrect pass code is entered, the gauge will return to the start of the pass code entry sequence.

**Factory/User Configuration**

The upper display section will be blank, and the lower section will display either USER\_ or FCTRY.

If USER\_ is selected, the user configuration can be modified as described in the following steps.

To select USER\_, press and release the DOWN button.

The lower display will indicate USER\_.

Press and release the front button to continue.

If FCTRY is selected, the existing user configuration will be replaced by the original factory configuration.

To select FCTRY, press and release the UP button.

The lower display will indicate FCTRY.

Press and release the front button to restore the factory configuration and restart the gauge.

**Max/Min Configuration**

Use the UP and DOWN buttons to select from the following:

MX/MN Both highest and lowest values will be captured

MX/-- Only highest value will be captured

--/MN Only lowest value will be captured

--/-- Capture feature is disabled

Press and release the front button to move to the next parameter.

**Max/Min Memory**

The upper display section will indicate clr.

Use the UP and DOWN buttons to select from the following:

AUTO Automatically clear max. and min. values when the gauge is powered off

MAN Manually clear max. and min. values

Press and release the front button to move to the next parameter.

**Gauge Type Configuration**

This will only appear with 15, 100, or 200 psig ranges that were originally ordered as compound gauges.

Use the UP and DOWN buttons to select from the following:

-/+EU Vacuum is indicated as negative pressure in the selected engineering units

CMPND Vacuum is negative INHG, pressure is PSIG. This setting will disable engineering unit selection.

Press and release the front button to save the user configuration and restart the gauge.

Replace the rear cover taking care not to pinch the power wires between the cover and the case.

## Battery Replacement

A low battery indication will be shown in the upper left-hand corner of the display when the battery voltage falls sufficiently. The battery should be replaced soon after the indicator comes on or unreliable readings may result.

1. Remove the 6 Phillips screws on the back of the unit.

2. Remove batteries by lifting up the positive end of the battery (opposite the spring) taking care not to bend the battery holder spring.
3. Discard old batteries properly, do not discard into fire, sources of extreme heat, or in any hazardous manner.

4. Always replace both batteries at the same time with high quality alkaline batteries. Install batteries with correct orientation. The negative (flat) end of each battery should be inserted first facing the battery holder spring.
6. Replace the back cover, including the rubber gasket.

## Calibration

### Setup

Gauges are calibrated at the factory using equipment traceable to NIST. There is no need to calibrate the gauge before putting it into service. Calibration intervals depend on your quality control program requirements, although many customers calibrate annually.

Calibration should only be performed by qualified individuals using appropriate calibration standards and procedures. The calibration equipment should be at least four times more accurate than the gauge being calibrated.


The calibration system must be able to generate and measure pressure/vacuum over the full range of the gauge.

A vacuum pump able to produce a vacuum of 10 microns (0.01 torr or 10 millitorr) or lower is required for vacuum gauges. Warning: application of vacuum to non-vacuum models may result in irreparable damage to the sensor.

Allow the gauge to acclimate to ambient temperature for 20 minutes.

Install fresh batteries.

Remove the rear cover to gain access to the UP and DOWN buttons located near the lower right and left corners of the circuit board.



### Entering Calibration Mode

With the gauge off, press and hold the DOWN button. Then press the front button. Release all buttons when the display indicates CAL.

The display begins by indicating the full-scale positive pressure rating of the gauge in the engineering units as configured by the factory, and then shows all display segments.

Before the gauge enters the Calibration Mode, the display initially indicates ' \_ \_ \_ \_ ' with the first underscore blinking, and with CALPC (calibration pass code) on the lower display.

Note: The gauge will automatically revert to normal operation if no buttons are operated for approximately 15 seconds. To cancel and return to normal operation, press and release the front button without entering any pass code characters.

### Enter the User-Modifiable Pass Code

The factory default is 3510, but this is user changeable.

1. Use the UP or DOWN buttons to set the left-most digit to 3.

2. Press and release the front button to move to the next position. The 3 will remain, and the second position will be blinking.
3. Use the UP or DOWN buttons to select 5.
4. Press and release the front button to index to the next position. 35 will remain, and the third position will be blinking.
5. Use the UP or DOWN buttons to select 1.
6. Press and release the front button to index to the next position. 351 will remain, and the fourth position will be blinking.
7. Use the UP or DOWN buttons to select 0.
8. Press and release the front button to proceed with configuration procedures.

If an incorrect pass code is entered, the gauge will return to the start of the pass code entry sequence.

### Calibration Mode

The gauge enters and remains in the calibration mode until restarted manually or power is removed. Features not related to calibration are disabled and compound range models are set for the same engineering units for pressure and for vacuum.

The calibration may be performed in any of the available engineering units as well as percent (PCT). For greatest accuracy, use the UP and DOWN buttons to select engineering units for calibration with highest resolution (highest number of display counts). Press and release the front button when the appropriate engineering units are displayed. Suggested units are listed below.

Sensor	Suggested units for calibration
5 PSI	5.000 PSI
15 PSI	775.7 MMHG (TORR)
30 PSI	61.08 INHG
50 PSI	50.00 PSI
60 PSI	60.00 PSI
100 PSI	7.031 KG/CM2
200 PSI	407.2 INHG
300 PSI	610.8 INHG
500 PSI	500.0 PSI
1000 PSI	70.31 KG/CM2
2000 PSI	4072 INHG
3000 PSI	6108 INHG
5000 PSI	5000 PSI
Any	100.00 PCT (percent)

The display will then indicate the currently applied pressure in the engineering units selected for calibration.

### UP and DOWN Button Operation

Each time one of the calibration buttons is pressed and released quickly, a small change is made to the digitized pressure signal. It may take more than one of these small changes to result in a single digit change on the display.

To make larger changes, press and hold the appropriate calibration button. After about one second, the display will begin to change continuously. Release the button to stop. Then make fine adjustments by pressing and quickly releasing the calibration buttons as previously described.

### Gauge Reference Pressure Gauges

Apply zero pressure by venting the gauge port to atmosphere. The character display will alternate between ZERO and CAL. Adjust for a display indication of zero using the UP and the DOWN buttons.

Apply full-scale pressure. The character display will alternate between +SPAN and CAL. Adjust for a display indication of full-scale pressure using the UP and the DOWN buttons.

Apply 50% full-scale pressure. The character display will alternate between +MID and CAL. Adjust for a display indication equal to 50% of full-scale pressure using the UP and the DOWN buttons.

### Gauge Reference Vacuum Gauges

Apply zero pressure by venting the gauge port to atmosphere. The character display will alternate between ZERO and CAL. Adjust for a display indication of zero using the UP and the DOWN buttons.

Apply full-scale vacuum. The character display will alternate between +SPAN and CAL. Adjust for a display indication of full-scale vacuum using the UP and the DOWN buttons.

Apply 50% full-scale vacuum. The character display will alternate between +MID and CAL. Adjust for a display indication equal to 50% of full-scale vacuum using the UP and the DOWN buttons.

### Absolute Reference Gauges

Apply full vacuum to the gauge. The character display will alternate between ZERO and CAL. Press the UP and DOWN buttons to obtain a display indication of zero.

Apply full-scale pressure. The character display will alternate between +SPAN and CAL. Press the UP and DOWN buttons to obtain a display indication equal to full-scale pressure.

Apply 50% of full-scale pressure. The lower display will alternate between +MID and CAL. Press the UP and DOWN buttons to obtain an indication equal to 50% of full-scale pressure.

### Compound and Bipolar Gauges

In addition to the steps described above for pressure gauges, apply full-scale vacuum. The character display will alternate between -SPAN and CAL. Adjust for a display indication of actual applied vacuum using the UP and the DOWN buttons.

For bipolar and -30.00inHg/+15.00psig compound range models only, apply 50% full-scale vacuum. The character display will alternate between -MID and CAL. Adjust for a display indication equal to 50% of full-scale vacuum using the UP and the DOWN buttons.

### Save Calibration

Once the adjustments are complete, press and hold the front button until the display indicates ---- then release the button to store the calibration parameters in non-volatile memory and restart the gauge.

Verify the pressure indications at 0%, 25%, 50%, 75% and 100% of full scale.

Replace the rear cover taking care not to pinch the wires between the cover and the case.

## User-Defined Pass Code Configuration

Remove the rear cover to access the buttons located near the lower right and left corners of the circuit board.

View or change user configuration pass code

With the unit off, press and hold the UP button, then press the front button.

Release all buttons when the display indicates CFG.

View or change user calibration pass code

With the unit off, press and hold the DOWN button, then press the front button.

Release all buttons when the display indicates CAL.

Enter access code 1220

Before the unit enters the view or change pass code mode, the display initially indicates ' \_ \_ \_ \_ ' with the first underscore blinking, and with CFGPC or CALPC on the character display.

Note: The gauge will automatically revert to normal operation if no

buttons are operated for approximately 15 seconds.

To cancel and return to normal operation, press and release the POWER button without entering any pass code characters.

1. Use the UP and DOWN buttons to set the left-most digit to 1.
2. Press and release the front button to move to the next position. The 1 will remain, and the second position will be blinking.
3. Use the UP and DOWN buttons to select 2.
4. Press and release the front button to index to the next position. 12 will remain, and the third position will be blinking.
5. Use the UP and DOWN buttons to select 2.
6. Press and release the front button to move to the next position. 1 2 2 will remain, and the fourth position will be blinking.
7. Use the UP and DOWN buttons to select 0.
8. Press and release the front button to proceed.

Note: If an incorrect access code was entered, the gauge will return to the start of the access code entry sequence.

Once the access code has been entered correctly, the display will indicate the existing user-defined pass code with CFGPC or CALPC on the character segments.

1. Operate the UP or DOWN button to select the first character of the new pass code.
2. When the correct first character is being displayed, press and release the front button to proceed to the next pass code character.
3. Repeat above until the entire pass code is complete.
4. To exit, press and hold the front button. Release the button when the display indicates ---- to restart the gauge.
5. Replace the rear cover taking care not to pinch the power wires between the cover and the case.



- $\pm 0.25\%$  Test Gauge Accuracy
- 316 Stainless Steel Wetted Parts
- 760 to 0 Torr Absolute
- BBL Includes Backlit Display

## Applications

- Replace Mercury Manometers in Fume Hoods
- Monitor Vacuum Systems and Pumps
- Vacuum Packaging



Model	Version	Power
ARM760AD	DC powered	115 VAC/12 VDC adapter
ARM760ADBL	DC powered, backlit display	115 VAC/12 VDC adapter
ARM760B	Battery-powered	2 AA batteries
ARM760BBL	Battery, backlit display	2 AA batteries

## Electrical Specifications

### Range and Resolution

760 to 0 torr absolute, 1 torr resolution

### Optional Units and Ranges

Visit [cecomp.com](http://cecomp.com) or consult factory or for a complete list of models and ranges

### Display

3½ digit LCD (3 digits are used for this range), 0.5" digit height  
3 readings per second nominal display update rate

### Controls and Location

Front On/Off pushbutton  
Display zero/span, non-interactive,  $\pm 10\%$  range  
Front-accessible multiturn potentiometers

### Accuracy (linearity, hysteresis, repeatability)

Standard:  $\pm 0.25\%$  of full scale  $\pm 1$  least significant digit  
Optional: **CD** Factory calibration data  
**NC** NIST traceable test report and calibration data

### Power ARM760AD and ARM760ADBL

Includes 115VAC/12VDC wall mount power supply  
Gauge will operate on any DC source of 9 to 32 VDC or any AC source of 8 to 24 VAC 50/60 Hz

**ARM760AD** power consumption approximately 5 mA

**ARM760ADBL** power consumption approximately 75 mA

### Electrical Connection ARM760AD and ARM760ADBL

6 foot long, 2-conductor cable with female 3.5 mm socket  
Power supply; 6 foot long, 2-conductor cable with male 3.5 mm plug

### Power ARM760B and ARM760BBL

Includes 2 AA alkaline batteries  
**ARM760B** battery life is approximately 2500 hours  
**ARM760BBL** battery life is approximately 180 hours  
30 minute auto shutoff

### Environmental

Storage Temperature -40 to 203°F (-40 to 95°C)  
Operating Temperature -4 to 185°F (-20 to 85°C)  
Compensated Temperature 32 to 158°F (0 to 70°C)



**RB Rubber Boot**  
Not for NEMA 4X models



## Mechanical Specifications

### Size

3.38" W x 2.88" H x 1.65" D housing  
Add approximately 0.75" to height for pressure fitting  
Add approximately 1" to depth for strain relief and wire clearance.

### Weight

Gauge: 9 ounces (approx)  
Shipping weight: 1 pound (approx)

### Material and Color

Extruded aluminum case, epoxy powder coated, light gray  
Polycarbonate cover, blue, Polycarbonate front label  
Front and rear gaskets

### Pressure/Vacuum Connection and Material

¼" NPT male, 316 stainless steel

### Media Compatibility

All wetted parts are 316 SS, Compatible with most liquids and gases

### Overpressure

2x rated pressure minimum

### Burst Pressure

4x rated pressure minimum



[cecomp.com](http://cecomp.com)



## DESCRIPTION

The **ARM760AD** and **ARM760ADBL** models are designed for applications where a continuous display of vacuum is required. This makes it ideal for monitoring vacuum systems and pumps.

The **ARM760B** and **ARM760BBL** models are designed for portable applications such as monitoring portable vacuum pumps or for vacuum packaging applications.

## INSTALLATION AND PRECAUTIONS

Install or remove gauge using a wrench on the hex fitting only. Do not attempt to tighten by turning housing or any other part of the gauge.

Due to the hardness of 316 stainless steel, it is recommended that a thread sealant be used to ensure leak-free operation.

**NEVER** insert objects into the gauge port or blow out with compressed air. Permanent damage not covered by warranty will result to the sensor.

## ELECTRICAL CONNECTION ARM760AD AND ARM760ADBL

The **ARM760AD** and **ARM760ADBL** models include 6 feet of cable with a female connector and a 115VAC/12VDC adapter with 6 feet of cable with plug. After the gauge is installed, route the wires away from heat sources and moving equipment and connect the AC adapter's plug to the gauge cable connector. Lastly, plug the AC adapter into a 115 VAC outlet.

**NEVER** connect the gauge wires directly to 115 VAC or permanent damage not covered by warranty will result.

The **ARM760AD** and **ARM760ADBL** models can operate on any AC source of 8 to 24 VAC 50/60 Hz, or any DC source of 9 to 32 VDC. These models can be used with inexpensive unregulated low voltage AC or DC power sources. The type and magnitude of the supply voltage have negligible effects on the gauge calibration as long as it is within the voltage ranges stated above. No polarity needs to be observed when connecting a DC supply.

The only important consideration is to ensure that the gauge supply voltage does not fall below 8 VAC RMS if AC power is used, or 9 VDC if DC power is used. Operation with less than these values may cause erratic or erroneous readings.

If your application requires operation of several gauges from the same power supply, consult factory for wiring recommendations.

## OPERATION ARM760AD AND ARM760ADBL

If the gauge display is off, press the center button to power up the gauge.

If the gauge was in the power-on state when the power was disconnected, the gauge will automatically turn on when power is reapplied.

If the gauge was turned off using the push button and then the power was turned off, the gauge will not power up until the power is reapplied and the center button is pressed again.

## OPERATION ARM760B AND ARM760BBL

When the center button is pressed, the gauge will power up and be ready to use. The gauge will stay on for 30 minutes or until the button is pushed again.

To conserve battery life, turn gauge off when not needed. This is especially important with the **ARM760BBL** model with display backlighting. The display backlighting will not be apparent under bright lighting conditions.

## BATTERY REPLACEMENT ARM760B AND ARM760BBL

A low battery indication will be shown in the upper left-hand corner of the display when the battery voltage falls sufficiently. The battery should be replaced soon after the indicator comes on or unreliable readings may result.

Remove the 6 Phillips head screws on the back of the unit.

Carefully remove batteries from the holders by lifting up the positive end of the battery (opposite the spring). Take care not to bend or distort the battery retention springs.

DO NOT discard the old battery into fire, any other sources of extreme heat, or in any other hazardous manner. Please consult local authorities if there is any question about proper disposal.

Always replace both batteries at the same time with high quality alkaline batteries. Observe the polarity of the batteries when replacing them. The negative (flat) end of each battery should be inserted first, and should face the spring in the battery holder.

Replace the back cover, including the rubber sealing gasket.

## CALIBRATION

All Cecomp gauges are factory calibrated on NIST traceable calibration equipment. No calibration is required before placing the gauge into service.

An absolute reference gauge will display atmospheric pressure if the gauge port is open to the ambient. It is normal for the reading to constantly change in response to atmospheric pressure changes.

Absolute reference gauges require vacuum generation and atmospheric pressure measurement equipment for accurate calibration and thus are more difficult to calibrate in the field. Calibration should only be attempted if the user has access to an absolute pressure reference of known accuracy. The quality of the calibration is only as good as the accuracy of the calibration equipment and ideally should be at least four times the gauge accuracy.

Calibration intervals depend on the severity of the application, the user's quality guidelines, and calibration history of the product as established by the user. For many applications a six month or an annual calibration interval may be found to be adequate.


If recalibration is required, remove the calibration plugs from the front of the gauge to access the individual zero and span controls. Allow the gauge to adjust to ambient temperature if needed.

The gauge may be re-zeroed without affecting the span calibration. The gauge must be connected to a vacuum pump with the ability to maintain 0.1 torr absolute vacuum or less. Adjust the Zero control until the gauge reads zero with the minus (-) sign occasionally flashing.

Span calibration should only be attempted if the user has access to an absolute pressure reference of known accuracy. Zero calibration must be done before span calibration. Record readings at three or more points over the range of the gauge and adjust span control to minimize error over the range of the gauge.

Gauges may be returned to Cecomp Electronics for factory certified recalibration. NIST traceability is available.

## DIMENSIONS



[www.cecomp.com](http://www.cecomp.com)

Cecomp maintains a constant effort to upgrade and improve its products. Specifications are subject to change without notice. Consult factory for your specific requirements.