



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

Subject: New blown fuse indicator design change for FLNR 35-400 Amp Fuses.

Document#LFPCN_PG0023

Date: 7/24/2012

This letter is to inform Littelfuse Sales, Sales Support & Customers of a design change to the fuse status indicator feature for Series FLNR 35 thru 400 amp ratings.

The change will update the subject fuse ratings to incorporate our most recent indicator design. This is the current platform for all new products with the indicating feature.

The design change will further enhance the integrity of our supply chain for these products, supporting our commitment to customer satisfaction and quality. There will be no discernable effect on published performance specifications. There is no change to product part numbers and no updates are required to ordering systems as this will be a running change incorporated in all production after 8/01/2012.

There will be a slight visual change to the components behind the indicator window, but the indicator functionality will remain the same. When a fault occurs the indicator window will turn black from its operational (no-fault) color, white.



OLD

Indicator
Window



NEW



Expertise Applied | Answers Delivered

8755 W. Higgins Road
Suite 500
Chicago, IL 60631

www.littelfuse.com

The following part numbers will be affected:

FLNR035.TXID	FLNR070.VXID	FLNR125.XXID	FLNR250.XXID
FLNR040.TXID	FLNR080.VXID	FLNR150.XXID	FLNR300.XXID
FLNR045.TXID	FLNR090.VXID	FLNR175.XXID	FLNR350.XXID
FLNR050.TXID	FLNR100.VXID	FLNR200.XXID	FLNR400.XXID
FLNR060.TXID	FLNR110.XXID	FLNR225.XXID	

Sincerely,

Jim McGuire
Assistant Product Manager
Littelfuse Powr-Gard Products
773-628-0708