🗙 FSL Logo

PRODUCT BULLETIN Generic Copy

ISSUE DATE:12-Jun-2013NOTIFICATION:15655TITLE:I.MX 6DUALLITE6SOLO DOCUMENTATION UPDATEEFFECTIVE DATE:13-Jun-2013

DEVICE(S)

MPN
MCIMX6S1AVM08AB
MCIMX6S1AVM08ABR
MCIMX6S4AVM08AB
MCIMX6S4AVM08ABR
MCIMX6S5DVM10AB
MCIMX6S5DVM10ABR
MCIMX6S5EVM10AB
MCIMX6S5EVM10ABR
MCIMX6S6AVM08AB
MCIMX6S6AVM08ABR
MCIMX6S7CVM08AB
MCIMX6S8DVM10AB
MCIMX6U1AVM08AB
MCIMX6U1AVM08ABR
MCIMX6U4AVM08AB
MCIMX6U4AVM08ABR
MCIMX6U5DVM10AB
MCIMX6U5DVM10ABR
MCIMX6U5EVM10AB
MCIMX6U5EVM10ABR
MCIMX6U6AVM08AB
MCIMX6U6AVM08ABR
MCIMX6U7CVM08AB
MCIMX6U8DVM10AB

AFFECTED CHANGE CATEGORIES

DEVICE SPECIFICATION / ERRATA

DESCRIPTION OF CHANGE

Datasheets:

The datasheets have been updated to revision 2.1 for the i.MX 6DualLite/6Solo product lines.

The updated automotive grade datasheet can be found at: IMX6SDLAEC

The updated commercial/extended commercial grade datasheet can be found at: IMX6SDLCEC

The updated industrial grade datasheet can be found at: IMX6SDLIEC

The following substantive changes apply to all temperature grade datasheets:

- Incorporated standardized signal names. This change is extensive throughout.
- Added reference to EB792, i.MX Signal Name Mapping.
- Figures updated to align to standardized signal names.
- Updated references to eMMC standard to include 4.41.
- Figure 1 "Part Number Nomenclature": Updates to Part differentiator section to align with Table 1.

• Table 1 "Orderable Part Numbers": Options column Added ARM core information, 2x "ARM Cortex-A9" 64-bit for 6DualLite; Added 1x "ARM Cortex -A9" 32-bit to 6Solo. Removed "no EPD".

• Table 3 "i.MX 6Solo/6DualLite Modules List": Changed reference to Global Power Controller to read General Power Controller.

• Table 14 "Operating Ranges ": Added reference for information on product lifetime : i.MX 6DualLite/6Solo Product Usage Lifetime Estimates Application Note, AN4725.

- Table 17 "Maximum Supply Currents," updated footnote 2.
- Table 18 "Stop Mode Current and Power Consumption": Added SNVS Only mode
- Table 90 RGMII parameter TskewT minimum and maximum values corrected.
- Table 90 RGMII parameter TskewR units corrected.
 Table 135 Clarification of ENET_REF_CLK naming.
- Added Table 136, "Signals with Differing Before Reset and After Reset States," on page 227.
- Removed section, EIM Signal Cross Reference. Signal names are now aligned with reference manual.
- Removed table from Section 3.2, "Recommended Connections for Unused Analog Interfaces" and referenced the Hardware Development Guide
- Section 1.2, "Features": Added bulleted item regarding the SOC-level memory system.
 Section 1.2, "Features": Camera sensors: Corrected Camera ports to be up to 180 MHz peak.
- Added Section 1.3, "Updated Signal Naming Convention"

- Section 4.2.1, "Power-Up Sequence": updated wording.
 Section 4.3.2, "Regulators for Analog Modules": section updates.
 Added Section 4.6.1, "XTALI and RTC_XTALI (Clock Inputs) DC Parameters".
- Section 4.10, "General-Purpose Media Interface (GPMI) Timing": figures replaced, tables revised.

Refer to the document revision history for detailed information.

The following substantive changes apply to the commercial temperature grade datasheet:

- Added MediaLB (MLB) feature and DTCP module to the Commercial temperature grade version.
- Table 1 "Orderable Part Numbers": Added MLB as a Commercial option.

Reference Manual:

The reference manual has been updated to revision 1 for the i.MX 6DualLite/6Solo product lines.

The updated reference manual can be found at: IMX6SDLRM

- The following chapters have been updated:
- Architecture Overview
- Memory Maps
- External Signals
- Fusemap
- System Boot
- Multimedia
- System Security
- CCM
- CSI2IPU
- IOMUXC
- IPU
- MMDC
- SRC
- UART
- USB
- SDMA Scripts

Refer to the document revision history for detailed information.

Silicon Errata:

The silicon errata document has been updated to revision 2 for the i.MX 6DualLite/6Solo product lines.

The updated errata can be found at: IMX6SDLCE

Substantive changes in the errata are as follows:

- Deleted the following errata:
- ERR004353 "CAAM: SMC deallocates partition when zeroizing CSP pages in Fail State"
- Added the following errata:
- ERR006308 "USB: Host non-double word -aligned buffer address can cause host to hang on OUT Retry"
- ERR006358 "ENET: Write to Transmit Descriptor Active Register (ENET_TDAR) is ignored"
- ERR006687 "ENET: Only the ENET wake-up interrupt request can wake the system from Wait mode"
- Updated the following:
- ERR004446 "EIM: AUS mode is nonfunctional for devices larger than 32 MB"

- ERR005829 "FlexCAN: FlexCAN does not transmit a message that is enabled to be transmitted in a specific moment during the arbitration process"

Refer to the document revision history for detailed information.

REASON FOR CHANGE

Updated documentation

ANTICIPATED IMPACT OF PRODUCT CHANGE(FORM, FIT, FUNCTION, OR RELIABILITY)

No changes to form, fit, function or reliability

NOTE:

THE CHANGE(S) SPECIFIED IN THIS NOTIFICATION WILL BE IMPLEMENTED ON THE EFFECTIVE DATE LISTED ABOVE. To request further data or inquire about the notification, please enter a <u>Service Request</u>

For sample inquiries - please go to www.freescale.com

QUAL DATA AVAILABILITY DATE: 03-May-2013

QUALIFICATION STATUS: COMPLETED

QUALIFICATION PLAN:

N/A

RELIABILITY DATA SUMMARY:

N/A

ELECTRICAL CHARACTERISTIC SUMMARY:

https://www.freescale.com/files/shared/doc/pcn/PCN15655.htm

N/A

CHANGED PART IDENTIFICATION:

N/A

ATTACHMENT(S):

External attachment(s) FOR this notification can be viewed AT: <u>15655_IMX6SDLCE.pdf</u>