



| | |
|------------------------------|---|
| Title of Change: | Packaging change for TO263 products. |
| Effective date: | 24 May 2018 |
| Contact information: | Contact your local ON Semiconductor Sales Office or < Christian.remoreras@onsemi.com > |
| Type of notification: | This Product Bulletin is for notification purposes only. ON Semiconductor will proceed with implementation of this change upon publication of this Product Bulletin. |
| Change category: | <input type="checkbox"/> Wafer Fab Change <input type="checkbox"/> Assembly Change <input type="checkbox"/> Test Change <input checked="" type="checkbox"/> Other: <u>Packaging</u> |

| | |
|--------------------------------|--|
| Change Sub-Category(s): | <input type="checkbox"/> Material Change <input type="checkbox"/> Datasheet/Product Doc change <input type="checkbox"/> Manufacturing Site Change/Addition <input type="checkbox"/> Product specific change <input checked="" type="checkbox"/> Shipping/Packaging/Marking <input type="checkbox"/> Manufacturing Process Change <input type="checkbox"/> Other: _____ |
|--------------------------------|--|

| | | |
|------------------------|---|--|
| Sites Affected: | ON Semiconductor Sites: ON Cebu, Philippines | External Foundry/Subcon Sites: None |
|------------------------|---|--|

Description and Purpose:

ON Semiconductor, Cebu, Philippines announces the change in packaging for TO263 package in term of the number of empty for the leader and trailer tapes inside the reel.

This is to ensure that additional protection of the units near the reel hub from damage during mishandling of boxes (dropped) which result to lifted leads by increasing the number of empty pockets of the trailer tape.

| | Trailer Empty pockets | Leader Empty Pockets |
|-----------------|-----------------------|----------------------|
| Current | 55 | 70 |
| Proposed Change | 90 | 25 |

List of Affected Parts:

| | |
|-------------------|--------------------|
| FDB070AN06A0-F085 | FGB3040G2-F085 |
| FDB075N15A-F085 | HUF76419S3ST-F085 |
| FDB14AN06LA0-F085 | HUFA75639S3ST |
| FDB2532-F085 | HUFA76645S3ST-F085 |
| FDB7030BL | ISL9V2540S3ST |
| FDB8030L | ISL9V5036S3ST |
| FDB8442-F085 | NDB6020P |
| FDB86360-F085 | NDB6030PL |
| FDB8880 | NDB6060L |
| FDB9406-F085 | |

"Please be informed that there may be Customer Specific parts impacted by this Notification, thus MPN & CPN info will not be reflected in the parts list of this Generic document. Instead please click the link to the addendum PCN copy provided in the email notification to see full list of affected products specific to your company."