Würth Elektronik eiSos GmbH & Co. KG EMC & Inductive Solutions

$$\label{eq:max-ey} \begin{split} \text{Max-Eyth-Straße 1} & \cdot \text{74638 Waldenburg} \cdot \text{Germany} \\ \text{Tel.} & +49 \, (0) \, 79 \, 42 \, 945 \cdot 0 \cdot \text{Fax} \\ & +49 \, (0) \, 79 \, 42 \, 945 \cdot 400 \\ \text{eiSos@we-online.de} & \cdot \text{www.we-online.de} \end{split}$$



Product / Process Change Notification (PCN) ☐ Major change ☐ Minor change		
PCN #:	PCN_WIRL-PRO8_20190801	Change Category:
Affected Series:	WE-WIRL-PRO8; P/N 260702118100x	□ Equipment / Location⊠ General Data□ Material
PCN Date:	July 01, 2019	□ Process
Effective Date:	August 01, 2019	□ Product Design□ Shipping / Packaging□ Supplier□ Software
Contact:	Product Management	Data Sheet Change:
Phone:	+49 (0) 7942 - 945 5001	⊠ Yes □ No
Fax:	+49 (0) 7942 - 945 5179	Attachment:
E-Mail:	pcn.eismart@we-online.com	□ Yes ⊠ No
DESCRIPTION AND PURPOSE OF CHANGE:		
Because of a database mismatch, Würth Elektronik will correct the datasheet.		
All products since market launch, are affected by this change.		
There will be no change in form, fit, function, quality or reliability of the product.		

DETAIL OF CHANGE:


Pin 13 of the module was named as sleep pin but pin 13 is reserved for functions not yet implemented. Through the description in the product manual the pin function was explained correctly.

Even with the correct information in the user manual and the note in the datasheet that the user manual is binding a PCN information is created to explicitly inform customers and avoid errors in the design in phase.

Würth Elektronik eiSos GmbH & Co. KG EMC & Inductive Solutions

$$\label{eq:max-ey} \begin{split} \text{Max-Eyth-Straße 1} & \cdot \text{74638 Waldenburg} \cdot \text{Germany} \\ \text{Tel.} & +49 \, (0) \, 79 \, 42 \, 945 \cdot 0 \cdot \text{Fax} \\ & +49 \, (0) \, 79 \, 42 \, 945 \cdot 400 \\ \text{eiSos@we-online.de} & \cdot \text{www.we-online.de} \end{split}$$





RELIABILITY / QUALIFICATION SUMMARY:

There will be no change of the product, therefore no additional reliability or qualification testing will be performed.