



Product Change Notification - SYST-23YTHY335

Date:

25 Oct 2019

Product Category:

8-bit Microcontrollers

Affected CPNs:



Notification subject:

ERRATA - ATtiny212/412 Silicon Errata and Data Sheet Clarification

Notification text:

SYST-23YTHY335

Microchip has released a new Product Documents for the ATtiny212/412 Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [ATtiny212/412 Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change: 1) Updated document template. 2) The ADC errata, ADC Functionality Cannot be Ensured with ADCCLK Above 1.5 MHz for All Conditions, has been split into two separate erratas and rewritten.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 25 Oct 2019

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[ATtiny212/412 Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to [receive Microchip PCNs via email](#) please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to [change your PCN profile, including opt out](#), please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

ATTINY212-SSF

ATTINY212-SSFR

ATTINY212-SSN

ATTINY212-SSNR

ATTINY412-SSF

ATTINY412-SSFR

ATTINY412-SSN

ATTINY412-SSNR



ATtiny212/412

ATtiny212/412 Silicon Errata and Data Sheet Clarification

The ATtiny212/412 devices you have received conform functionally to the current device data sheet ([DS40001911](#)), except for the anomalies described in this document. The erratas described in this document will likely be addressed in future revisions of the ATtiny212/412 devices.

Note:

- This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current.
- Refer to the Device/Revision ID section in the current device data sheet ([DS40001911](#)) for more detailed information on Device Identification and Revision IDs for your specific device, or contact your local Microchip sales office for assistance.

1. Silicon Issue Summary

Legend

- Erratum is not applicable.
- X** Erratum is applicable.
- * This silicon revision was never released to production.

Peripheral	Short Description	Valid for Silicon Revision	
		Rev. A	Rev. B
Device	2.2.1 The Temperature Sensor is Not Calibrated on Parts with Date Code 727, 728 and 1728 (Year 2017, Week 27/28)	-	X
AC	2.3.1 AC Interrupt Flag Not Set Unless Interrupt is Enabled	X	-
	2.3.2 False Triggers May Occur Under Certain Conditions	X	-
ADC	2.4.1 One Extra Measurement Performed After Disabling ADC Free-Running Mode	X	X
	2.4.2 Changing ADC Control Bits During Free-Running Mode not Working	X	-
	2.4.3 ADC Wake-Up with WCOMP	X	-
	2.4.4 SAMPDLY and ASDV Does Not Work Together With SAMPLEN	X	-
	2.4.5 ADC Functionality Cannot be Ensured with CLKADC Above 1.5 MHz and a Setting of 25% Duty Cycle	X	X
	2.4.6 ADC Performance Degrades with CLKADC Above 1.5 MHz and VDD < 2.7V	X	X
CCL	2.5.1 Connecting LUTs in Linked Mode Require OUTEN Set to '1'	X	X
	2.5.2 D-latch is Not Functional	X	X
RTC	2.6.1 Any Write to the RTC.CTRLA Register Resets the RTC and PIT Prescaler	X	X
	2.6.2 Disabling the RTC Stops the PIT	X	X
TCB	2.7.1 Minimum Event Duration Must Exceed the Selected Clock Period	X	X
	2.7.2 The TCB Interrupt Flag is Cleared When Reading CCMPH	X	-
	2.7.3 TCB Input Capture Frequency and Pulse-Width Measurement Mode Not Working with Prescaled Clock	X	-
	2.7.4 The TCA Restart Command Does Not Force a Restart of TCB	X	X
TWI	2.8.1 TIMEOUT Bits in the TWI.MCTRLB Register are Not Accessible	X	-
	2.8.2 TWI Smart Mode Gives Extra Clock Pulse	X	-
	2.8.3 TWI Master Mode Wrongly Detects the Start Bit as a Stop Bit	X	-
	2.8.4 The TWI Master Enable Quick Command is Not Accessible	X	-
USART	2.9.1 TXD Pin Override Not Released When Disabling the Transmitter	X	X
	2.9.2 Frame Error on a Previous Message May Cause False Start Bit Detection	X	X

2. Silicon Errata Issues

2.1 Errata Details

- Erratum is not applicable.
- X** Erratum is applicable.
- * This silicon revision was never released to production.

2.2 Device

2.2.1 The Temperature Sensor is Not Calibrated on Parts with Date Code 727, 728 and 1728 (Year 2017, Week 27/28)

The temperature sensor is not calibrated on parts with date code 727/728 (used on QFN packages) and 1728 (used on SOIC packages).

Work around

If temperature sensor calibration data is required, devices with the affected date code may be returned through the Microchip RMA service. Devices with this date code are no longer shipped by Microchip.

Affected Silicon Revisions

Rev. A	Rev. B						
-	X						

2.3 AC - Analog Comparator

2.3.1 AC Interrupt Flag Not Set Unless Interrupt is Enabled

ACn.STATUS.CMP is not set if the ACn.INTCTRL.CMP is not set.

Work around

Enable ACn.INTCTRL.CMP or use ACn.STATUS.STATE for polling.

Affected Silicon Revisions

Rev. A	Rev. B						
X	-						

2.3.2 False Triggers May Occur Under Certain Conditions

False triggers may occur on falling input pin:

- For common-mode voltage below 0.5V
- For common-mode voltage above 0.5V if the slew rate is greater than 1 V/ μ s

Work around

None.

Affected Silicon Revisions

Rev. A	Rev. B						
X	-						

2.4 ADC - Analog-to-Digital Converter

2.4.1 One Extra Measurement Performed After Disabling ADC Free-Running Mode

The ADC may perform one additional measurement after clearing ADCn.CTRLA.FREERUN.

Work around

Write ADCn.CTRLA.ENABLE to '0' to stop the Free-Running mode immediately.

Affected Silicon Revisions

Rev. A	Rev. B						
X	X						

2.4.2 Changing ADC Control Bits During Free-Running Mode not Working

If control signals are changed during Free-Running mode, the new configuration is not properly taken into account in the next measurement. This is valid for the ADC.CTRLB, ADC.CTRLC, ADC.SAMPCTRL registers and the ADC.MUXPOS, ADC.WINLT and ADC.WINHT registers.

Work around

Disable ADC Free-Running mode before updating the ADC.CTRLB, ADC.CTRLC, ADC.SAMPCTRL, ADC.MUXPOS, ADC.WINLT or ADC.WINHT registers.

Affected Silicon Revisions

Rev. A	Rev. B						
X	-						

2.4.3 ADC Wake-Up with WCOMP

When waking up from STANDBY Sleep mode with ADC WCOMP interrupt, the ADC is disabled for a few cycles before the device enters ACTIVE mode. A new INITDLY is required before the next conversion.

Work around

Use INITDLY before the next conversion.

Affected Silicon Revisions

Rev. A	Rev. B						
X	-						

2.4.4 SAMPDLY and ASDV Does Not Work Together With SAMPLEN

Using SAMPCTRL.SAMPLEN at the same time as CTRLD.SAMPDLY or CTRLD.ASDV will cause an unpredictable sampling length.

Work around

When setting SAMPCTRL.SAMPLEN greater than 0x0, the CTRLD.SAMPDLY and CTRLD.ASDV must be cleared.

Affected Silicon Revisions

Rev. A	Rev. B						
X	-						

2.4.5 ADC Functionality Cannot be Ensured with CLK_{ADC} Above 1.5 MHz and a Setting of 25% Duty Cycle

The ADC functionality cannot be ensured if $CLK_{ADC} > 1.5$ MHz with ADCn.CALIB.DUTYCYC set to '1'.

Work around

If ADC is operated with $CLK_{ADC} > 1.5$ MHz, ADCn.CALIB.DUTYCYC must be set to '0' (50% duty cycle).

Affected Silicon Revisions

Rev. A	Rev. B						
X	X						

2.4.6 ADC Performance Degrades with CLK_{ADC} Above 1.5 MHz and $VDD < 2.7V$

The ADC INL performance degrades if $CLK_{ADC} > 1.5$ MHz and ADCn.CALIB.DUTYCYC set to '0' for $VDD < 2.7V$.

Work around

None.

Affected Silicon Revisions

Rev. A	Rev. B						
X	X						

2.5 CCL - Configurable Custom Logic

2.5.1 Connecting LUTs in Linked Mode Require OUTEN Set to '1'

Connecting the LUTs in linked mode require LUTnCTRLA.OUTEN set to '1' for the LUT providing the input source.

Work around

Use an event channel to link the LUTs or do not use the corresponding I/O pin for other purposes.

Affected Silicon Revisions

Rev. A	Rev. B						
X	X						

2.5.2 D-latch is Not Functional

The CCL D-latch is not functional.

Work around

None.

Affected Silicon Revisions

Rev. A	Rev. B						
X	X						

2.6 RTC - Real-Time Counter

2.6.1 Any Write to the RTC.CTRLA Register Resets the RTC and PIT Prescaler

Any write to the RTC.CTRLA register resets the RTC and PIT prescaler.

Work around

None.

Affected Silicon Revisions

Rev. A	Rev. B						
X	X						

2.6.2 Disabling the RTC Stops the PIT

Writing RTC.CTRLA.RTCEN to '0' will stop the PIT.

Writing RTC.PITCTRLA.PITEN to '0' will stop the RTC.

Work around

Do not disable the RTC or the PIT if any of the modules are used.

Affected Silicon Revisions

Rev. A	Rev. B						
X	X						

2.7 TCB - Timer/Counter B

2.7.1 Minimum Event Duration Must Exceed the Selected Clock Period

Event detection will fail if TCBn receives an input event with a high/low period shorter than the period of the selected clock source (CLKSEL in TCBn.CTRLA). This applies to the TCB modes (CNTMODE in TCBn.CTRLB) *Time-Out Check* and *Input Capture Frequency and Pulse-Width Measurement* mode.

Work around

Ensure that the high/low period of input events is equal to or longer than the period of the selected clock source (CLKSEL in TCBn.CTRLA).

Affected Silicon Revisions

Rev. A	Rev. B						
X	X						

2.7.2 The TCB Interrupt Flag is Cleared When Reading CCMPH

TCBn.INTFLAGS.CAPT is cleared when reading TCBn.CCMPH instead of CCMPL.

Work around

Read both TCBn.CCMPL and TCBn.CCMPH.

Affected Silicon Revisions

Rev. A	Rev. B						
X	-						

2.7.3 TCB Input Capture Frequency and Pulse-Width Measurement Mode Not Working with Prescaled Clock

The TCB Input Capture Frequency and Pulse-Width Measurement mode may lock to Freeze state if CLKSEL in TCB.CTRLA is set to any other value than 0x0.

Work around

Only use CLKSEL equal to 0x0 when using Input Capture Frequency and Pulse-Width Measurement mode.

Affected Silicon Revisions

Rev. A	Rev. B						
X	-						

2.7.4 The TCA Restart Command Does Not Force a Restart of TCB

The TCA restart command does not force a restart of the TCB when TCB is running in SYNCUPD mode. TCB is only restarted after a TCA OVF.

Work around

None.

Affected Silicon Revisions

Rev. A	Rev. B						
X	X						

2.8 TWI - Two-Wire Interface

2.8.1 TIMEOUT Bits in the TWI.MCTRLB Register are Not Accessible

The TIMEOUT bits in the TWI.MCTRLB register are not accessible from software.

Work around

When initializing TWI, BUSSTATE in TWI.MSTATUS should be brought into IDLE state by writing 0x1 to it.

Affected Silicon Revisions

Rev. A	Rev. B						
X	-						

2.8.2 TWI Smart Mode Gives Extra Clock Pulse

TWI Master with Smart mode enabled gives an extra clock pulse on the SCL line after sending NACK.

Work around

None.

Affected Silicon Revisions

Rev. A	Rev. B						
X	-						

2.8.3 TWI Master Mode Wrongly Detects the Start Bit as a Stop Bit

If TWI is enabled in Master mode followed by an immediate write to the MADDR register the bus monitor recognizes the Start bit as a Stop bit.

Work around

Wait for a minimum of two clock cycles from TWI.MCTRLA.ENABLE until TWI.MADDR is written.

Affected Silicon Revisions

Rev. A	Rev. B						
X	-						

2.8.4 The TWI Master Enable Quick Command is Not Accessible

TWI.MCTRLA.QCEN is not accessible from software.

Work around

None.

Affected Silicon Revisions

Rev. A	Rev. B						
X	-						

2.9 USART - Universal Synchronous and Asynchronous Receiver and Transmitter

2.9.1 TXD Pin Override Not Released When Disabling the Transmitter

The USART will not release the TXD pin override if:

- The USART transmitter is disabled by writing the TXEN bit in USART.CTRLB to '0' while the USART receiver is disabled (RXEN in USART.CTRLB is '0')
- Both the USART transmitter and receiver are disabled at the same time by writing the TXEN and RXEN bits in USART.CTRLB to '0'

Work around

There are two possible work arounds:

- Make sure the receiver is enabled (RXEN in USART.CTRLB is '1') while disabling the transmitter (writing TXEN in USART.CTRLB to '0')
- Writing to any register in the USART after disabling the transmitter will start the USART for long enough to release the pin override of the TXD pin

Affected Silicon Revisions

Rev. A	Rev. B						

X	X						
---	---	--	--	--	--	--	--

2.9.2 Frame Error on a Previous Message May Cause False Start Bit Detection

A false start bit detection will trigger if receiving a frame with RXDATAH.FERR set and reading the RXDATAL before the RxD line goes high.

Work around

Wait for the RxD pin to go high before reading RXDATA, for instance by polling the bit in PORTn.IN where the RxD pin is located.

Affected Silicon Revisions

Rev. A	Rev. B						
X	X						

3. Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet ([DS40001911](#)):

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

3.1 None

There are no known data sheet clarifications as of this publication date.

4. Document Revision History

Note: The data sheet clarification document revision is independent of the die revision and the device variant (last letter of the ordering number).

4.1 Revision History

Doc Rev.	Date	Comments
B	10/2019	<ul style="list-style-type: none">Updated document template.The ADC errata, ADC Functionality Cannot be Ensured with ADCCLK Above 1.5 MHz for All Conditions, has been split into two separate erratas and rewritten.
A	06/2019	<ul style="list-style-type: none">Initial document release.

The Microchip Website

Microchip provides online support via our website at <http://www.microchip.com/>. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to <http://www.microchip.com/pcn> and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: <http://www.microchip.com/support>

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

Legal Notice

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with

your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TempTrackr, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, Vite, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KleerNet, KleerNet logo, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2019, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-5139-6

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit <http://www.microchip.com/quality>.

Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
<p>Corporate Office 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Tel: 480-792-7277 Technical Support: http://www.microchip.com/support Web Address: http://www.microchip.com</p> <p>Atlanta Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455</p> <p>Austin, TX Tel: 512-257-3370</p> <p>Boston Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088</p> <p>Chicago Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075</p> <p>Dallas Addison, TX Tel: 972-818-7423 Fax: 972-818-2924</p> <p>Detroit Novi, MI Tel: 248-848-4000</p> <p>Houston, TX Tel: 281-894-5983</p> <p>Indianapolis Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380</p> <p>Los Angeles Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800</p> <p>Raleigh, NC Tel: 919-844-7510</p> <p>New York, NY Tel: 631-435-6000</p> <p>San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270</p> <p>Canada - Toronto Tel: 905-695-1980 Fax: 905-695-2078</p>	<p>Australia - Sydney Tel: 61-2-9868-6733</p> <p>China - Beijing Tel: 86-10-8569-7000</p> <p>China - Chengdu Tel: 86-28-8665-5511</p> <p>China - Chongqing Tel: 86-23-8980-9588</p> <p>China - Dongguan Tel: 86-769-8702-9880</p> <p>China - Guangzhou Tel: 86-20-8755-8029</p> <p>China - Hangzhou Tel: 86-571-8792-8115</p> <p>China - Hong Kong SAR Tel: 852-2943-5100</p> <p>China - Nanjing Tel: 86-25-8473-2460</p> <p>China - Qingdao Tel: 86-532-8502-7355</p> <p>China - Shanghai Tel: 86-21-3326-8000</p> <p>China - Shenyang Tel: 86-24-2334-2829</p> <p>China - Shenzhen Tel: 86-755-8864-2200</p> <p>China - Suzhou Tel: 86-186-6233-1526</p> <p>China - Wuhan Tel: 86-27-5980-5300</p> <p>China - Xian Tel: 86-29-8833-7252</p> <p>China - Xiamen Tel: 86-592-2388138</p> <p>China - Zhuhai Tel: 86-756-3210040</p>	<p>India - Bangalore Tel: 91-80-3090-4444</p> <p>India - New Delhi Tel: 91-11-4160-8631</p> <p>India - Pune Tel: 91-20-4121-0141</p> <p>Japan - Osaka Tel: 81-6-6152-7160</p> <p>Japan - Tokyo Tel: 81-3-6880-3770</p> <p>Korea - Daegu Tel: 82-53-744-4301</p> <p>Korea - Seoul Tel: 82-2-554-7200</p> <p>Malaysia - Kuala Lumpur Tel: 60-3-7651-7906</p> <p>Malaysia - Penang Tel: 60-4-227-8870</p> <p>Philippines - Manila Tel: 63-2-634-9065</p> <p>Singapore Tel: 65-6334-8870</p> <p>Taiwan - Hsin Chu Tel: 886-3-577-8366</p> <p>Taiwan - Kaohsiung Tel: 886-7-213-7830</p> <p>Taiwan - Taipei Tel: 886-2-2508-8600</p> <p>Thailand - Bangkok Tel: 66-2-694-1351</p> <p>Vietnam - Ho Chi Minh Tel: 84-28-5448-2100</p>	<p>Austria - Wels Tel: 43-7242-2244-39 Fax: 43-7242-2244-393</p> <p>Denmark - Copenhagen Tel: 45-4450-2828 Fax: 45-4485-2829</p> <p>Finland - Espoo Tel: 358-9-4520-820</p> <p>France - Paris Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79</p> <p>Germany - Garching Tel: 49-8931-9700</p> <p>Germany - Haan Tel: 49-2129-3766400</p> <p>Germany - Heilbronn Tel: 49-7131-72400</p> <p>Germany - Karlsruhe Tel: 49-721-625370</p> <p>Germany - Munich Tel: 49-89-627-144-0 Fax: 49-89-627-144-44</p> <p>Germany - Rosenheim Tel: 49-8031-354-560</p> <p>Israel - Ra'anana Tel: 972-9-744-7705</p> <p>Italy - Milan Tel: 39-0331-742611 Fax: 39-0331-466781</p> <p>Italy - Padova Tel: 39-049-7625286</p> <p>Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340</p> <p>Norway - Trondheim Tel: 47-72884388</p> <p>Poland - Warsaw Tel: 48-22-3325737</p> <p>Romania - Bucharest Tel: 40-21-407-87-50</p> <p>Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91</p> <p>Sweden - Gothenberg Tel: 46-31-704-60-40</p> <p>Sweden - Stockholm Tel: 46-8-5090-4654</p> <p>UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820</p>