

Customer Information Notification

Issue Date: 13-Aug-2020 Effective Date: 14-Aug-2020

Dear Gordon Love.

Here's your personalized quality information concerning products Premier Farnell PLC purchased from NXP.

For detailed information we invite you to <u>view this</u> notification online

This notice is NXP Company Proprietary.



Management Summary

There is a issue in SW L4.19 release. We should notice customers to use correct version and avoid issue.

Change Category

[] Wafer Fab Process	[] Assembly	[] Product Marking	[] Test Location	[] Design
[] Wafer Fab Materials	Process [] Assembly	[] Mechanical Specification	[]Test Process	[] Errata
[] Wafer Fab Location	Materials [] Assembly	[] Packing/Shipping/Labeling	[] Test	[] Electrica
[] Firmware	Location [X] Other -		, Equipinient	coverage

Wrong Voltage Setting and Risk Burning 845/815 on 4.19.xx and 5.4.xx Linux and Android Pre-build Demo Image

Description

LDO1/2 voltage of rohm,bd71847 are set wrong on L4.19 after kernel bootup:

<u>LDO1@3.0V</u> --NVCC_SNVS_1V8 <u>LDO2@0.9V</u> ----VDD_SNVS_0V8

With the below kernel print log:

[0.931167] Ido1: Bringing 1800000uV into 3000000-3000000uV

[0.938256] Ido2: Bringing 800000uV into 900000-900000uV

The issue is impacting 8MMINILPD4-EVK, MX8MMINID4-EVK and MX8MNANOD4-EVK boards. The wrong voltage is vialating the spec and might damage IOs.

The related SW release were set invalid in website after May. 28th

Suggesting customer use latest SW release or apply proper patches for these boards.

Since there are different bd71847 drivers/dts used on L4.14/L4.19/L5.4, there are different patches for this issue, please appy the correct patch on the right release branch:

1). imx_4.14.98_2.3.0:

0001-MLK-23275-1-ARM64-dts-freescale-fsl-imx8mm-evk-corre.patch

0002-MLK-23275-2-ARM64-dts-freescale-fsl-imx8mn-ddr4-evk-.patch

0003-MLK-23275-3-regulator-bd71837-correct-ldo1-ldo2-grou.patch

2). imx 4.19.35 1.1.0:

0001-MLK-23275-1-ARM64-dts-freescale-fsl-imx8mm-evk-corre.patch

0002-MLK-23275-2-ARM64-dts-freescale-fsl-imx8mn-ddr4-evk-.patch

0003-MLK-23846-ARM64-dts-freescale-fsl-imx8mn-ddr4-evk-co.patch

3). imx 5.4.3 2.0.0:

0001-MLK-23275-1-ARM64-dts-freescale-fsl-imx8mm-evk-corre.patch

0002-MLK-23275-2-ARM64-dts-freescale-imx8mn-ddr4-evk-corr.patch

0003-MLK-23844-1-ARM64-dts-freescale-imx8mn-ddr4-evk-clea.patch

0004-MLK-23844-2-ARM64-dts-freescale-imx8mm-correct-VDDAR.patch

Reason

Notice customers not using wrong SW version or download the correct SW version.

Identification of Affected Products

it is SW error, and No impact to Soc.

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No impact on form, fit, function, reliability or quality.

Data Sheet Revision

No impact to existing datasheet

Additional information

Affected products and sales history information: see attached file

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name Mcgregor Amanda

Position Marketing

e-mail address amanda.mcgregor@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

<u>View Notification</u> <u>Subscription</u> <u>Support</u>

NXP | Privacy Policy | Terms of Use

NXP Semiconductors High Tech Campus, 5656 AG Eindhoven, The Netherlands

@ 2006-2010 NXP Semiconductors. All rights reserved.