

Product Change Notification / SYST-15MAVS007

Date:

17-Sep-2021

Product Category:

8-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - ATtiny87/167 Automotive Silicon Errata and Data Sheet Clarifications

Affected CPNs:

SYST-15MAVS007_Affected_CPN_09172021.pdf SYST-15MAVS007_Affected_CPN_09172021.csv

Notification Text:

SYST-15MAVS007

Microchip has released a new Product Documents for the ATtiny87/167 Automotive Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at ATtiny87/167 Automotive Silicon Errata and Data Sheet Clarifications.

Notification Status: Final

Description of Change: Initial release of this document.

- 1. Errata content moved from the data sheet and restructured to the new document template
- 2. Data sheet clarifications added:
 - 3.1 Errata Section in Data Sheet is no Longer Valid
 - Interrupts: 3.2.1 Interrupt Vectors in ATtiny87/167 Automotive
 - LIN/UART: 3.3.1 Baud Rate Generator
 - Package Marking: 3.4 Package Marking Information

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 17 September 2021

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

ATtiny87/167 Automotive Silicon Errata and Data Sheet Clarifications

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our PCN home page select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the PCN FAQ section.

If you wish to <u>change your PCN profile, including opt out</u>, please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

ATTINY87-XU ATTINY87-SU ATTINY87-MU ATTINY87-A15XD ATTINY87-A15MD-VAO ATTINY87-XUR ATTINY87-SUR ATTINY87-MUR ATTINY87-A15XZ ATTINY87-A15SZ ATTINY87-A15MZ ATTINY167-W-NG ATTINY167-XU ATTINY167-SU ATTINY167-MU ATTINY167-MMU ATTINY167-A15XD ATTINY167-A15MD ATTINY167-XUR ATTINY167-SUR ATTINY167-MUR ATTINY167-MMUR ATTINY167-MMURB20 ATTINY167-A15XZ ATTINY167-A15SZ ATTINY167-A15MZ ATTINY167-A15MZ-V01 ATTINY167-A15MZ-V02 ATTINY167-A15MZ-V03



ATtiny87/167 Automotive

Automotive Silicon Errata and Data Sheet Clarifications

Introduction

The ATtiny87/167 Automotive devices you have received conform functionally to the current device data sheet (www.microchip.com/mymicrochip/filehandler.aspx?ddocname=en590544), except for the anomalies described in this document. The errata described in this document will likely be addressed in future revisions of the ATtiny87/167 Automotive devices.

Note:

• This document summarizes all the silicon errata issues from all revisions of silicon, previous and current.

1. Silicon Issue Summary

Legend

-	Erratum	is no	ot appl	icable

X Erratum is applicable.

Errata Overview

		Valid for Silicon Revision		
Peripheral	Short Description	Rev. A	Rev. B	Rev. C
	·	Date Code > 1207	Date Code > 1208	
System Clock and	2.2.1 Gain Control of the Crystal Oscillator	X	x	x
Clock Options	2.2.2 "Disable Clock Source" Command Remains Enabled	X	x	x
LIN-UART	2.3.1 CRC Calculation of Diagnostic Frames in LIN 2.x	X	-	-
	2.3.2 LIN Break Delimiter	X	X	-
	2.4.1 Comparison Between ADC Inputs and Voltage References	X	-	-
	2.4.2 Register Bits of DIDR1	X	-	-

2. Silicon Errata Issues

2.1 Errata Details

- Erratum is not applicable.
- X Erratum is applicable.

2.2 System Clock and Clock Options

2.2.1 Gain Control of the Crystal Oscillator

The crystal oscillator ($0.4 \rightarrow 16 \text{ MHz}$) doesn't latch its gain control (CKSEL/CSEL[2..0] bits):

- 1. The 'recover system clock source' command doesn't return CSEL[2..0] bits.
- 2. The gain control can be modified on the fly if CLKSELR changes.

Work Around

- 1. No work around.
- 2. As soon as possible, after any CLKSELR modification, re-write the appropriate crystal oscillator setting (CSEL[3]=1 and CSEL[2..0] / CSUT[1..0] bits) in CLKSELR.

Code example:

```
; Select crystal oscillator (16MHz crystal, fast rising power)
           ldi temp1,((0x0F<<CSEL0)|(0x02<<CSUT0))
sts CLKSELR, temp1</pre>
; Enable clock source (crystal oscillator)
            ldi temp2, (1<<CLKCCE)
            Iditemp3,(0x02<<CLKC0)</td>; CSEL = "0010"stsCLKCSR,temp2; Enable CLKCSR register accessstsCLKCSR,temp3; Enable crystal oscillator clock
; Clock source switch

    ldi
    temp3,(0x04<<CLKC0)</td>
    ; CSEL = "0100"

    sts
    CLKCSR,temp2
    ; Enable CLKCSR register access

    sts
    CLKCSR,temp3
    : Clock source switch

            sts
                     CLKCSR, temp3
                                                       ; Clock source switch
; Select watchdog clock (128KHz, fast rising power)
            ldi temp3,((0x03<<CSEL0)|(0x02<<CSUT0))
sts CLKSELR, temp3 ; (*)
; (*) !!! Loose gain control of crystal oscillator !!!
; ==> WORKAROUND ...
           sts CLKSELR, temp1
; ...
```

Affected Silicon Revisions

Rev. A	Rev. B	Rev. C
X	X	X

2.2.2 "Disable Clock Source" Command Remains Enabled

In the dynamic clock switch module, the 'disable clock source' command remains running after disabling the targeted clock source (the clock source is set in the CLKSELR register).

Work Around

After a 'disable clock source' command, reset the CLKCSR register by writing 0x80.

Code example:

```
; Select crystal oscillator
    ldi temp1,(0x0F<<CSEL0)
    sts CLKSELR, temp1
; Disable clock source (crystal oscillator)
    ldi temp2,(1<CLKCCE)
    ldi temp3,(0x01<<CLKCO) ; CSEL = "0001"
    sts CLKCSR,temp2 ; Enable CLKCSR register access
    sts CLKCSR,temp3 ; (*) Disable crystal oscillator clock
; (*) !!! At this moment, if any other clock source is selected by CLKSELR,
; this clock source will also stop !!!
; ==> WORKAROUND ...
    sts CLKCSR,temp2
```

Affected Silicon Revisions

Rev. A	Rev. B	Rev. C
X	x	x

2.3 LIN-UAT

2.3.1 CRC Calculation of Diagnostic Frames in LIN 2.x

Diagnostic frames of LIN 2.x use "classic checksum" calculation. Unfortunately, the setting of the checksum mode is enabled when the HEADER is transmitted/received. Usually, in LIN 2.x, the LIN/UART controller is initialized to process "enhanced checksums". A slave task does not know what kind of frame it will work on before checking the ID.

Work Around

This work around is to be implemented only in the case of transmission/reception of diagnostic frames.

- 1. Slave task of master node: Before enabling the HEADER, the master must set the appropriate LIN13 bit value in the LINCR register.
- 2. For slave nodes, the work around is in two parts:
 - a. Before enabling the RESPONSE, use the following function:

```
void lin_wa_head(void) {
unsigned char temp;
temp = LINBTR;
LINCR = 0x00; // It is not a RESET !
LINBTR = (1<<LDISR) | temp;
LINCR = (1<<LDISR) | temp;
LINCR = (1<<LIN13) | (1<<LENA) | (0<<LCMD2) | (0<<LCMD1) | (0<<LCMD0);
LINDLR = 0x88; // If it isn't already done
}</pre>
```

b. Once the RESPONSE is received or sent (having RxOK or TxOK as well as LERR), use the following function:

```
void lin wa_tail(void) {
LINCR = 0x00; // It is not a RESET !
LINBTR = 0x00;
LINCR = (0<<LIN13) | (1<<LENA) | (0<<LCMD2) | (0<<LCMD1) | (0<<LCMD0);
}</pre>
```

The time-out counter is disabled during the RESPONSE when this work around is set.

Affected Silicon Revisions

Rev. A	Rev. B	Rev. C

x	-	-

2.3.2 LIN Break Delimiter

In SLAVE MODE, a BREAK field detection error can occur under the following conditions.

The problem occurs if two conditions occur simultaneously:

- 1. The DOMINANT part of the BREAK is (N+0.5)*Tbit long with N=13, 14,15, ...
- 2. The RECESSIVE part of the BREAK (BREAK DELIMITER) is equal to 1*Tbit. (See the note below).

The BREAK_high is not detected, and the 2nd bit of the SYNC field is interpreted as the BREAK DELIMITER. The error is detected as a framing error on the first bits of the PID or subsequent Data or a Checksum error.

There is no error if BREAK_high is greater than 1 x Tbit + 18%.

There is no problem in Master mode.

Note: LIN2.1 protocol specification paragraph 2.3.1.1 Break field says (www.microchip.com/mymicrochip/ filehandler.aspx?ddocname=en590544): "A break field is always generated by the master task (in the master node) and it shall be at least 13 nominal bit times of dominant value, followed by a break delimiter, as shown in Figure 2-1. The break delimiter shall be at least one nominal bit time long."

Figure 2-1. The Break Field



Work Around

None

Affected Silicon Revisions

Rev. A	Rev. B	Rev. C
X	X	-

2.4 ADC

2.4.1 Comparison Between ADC Inputs and Voltage References

In the analog comparator module, comparing any ADC input (ADC[10..0]) with voltage references (2.56V, 1.28V, 1.10V, 0.64V or 0.32V) fails.

Regardless, AIN1 input can be compared with the voltage references, and any ADC input can be compared with the AIN0 input.

Work Around

Do not use this configuration.

Affected Silicon Revisions

Rev. A	Rev. B	Rev. C
x	-	-

2.4.2 Register Bits of DIDR1

ADC8D, ADC9D and ADC10D (digital input disable) initially located at bit 4 up to 6 are instead located at bit 0 up to 2. These register bits are also in write-only mode.

Work Around

Allow for the change in bit locations and the access mode restriction.

Affected Silicon Revisions

Rev. A	Rev. B	Rev. C
X	-	-

3. Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (www.microchip.com/mymicrochip/filehandler.aspx?ddocname=en590544).

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

3.1 Errata Section in Data Sheet is no Longer Valid

A clarification for the Errata section in the device data sheet has been made.

The errata content has been moved to a separate document, *ATtiny87/167 Automotive Silicon Errata and Data Sheet Clarifications* (this document).

For the latest errata, see the Silicon Errata Issues section of this document.

3.2 Interrupts

3.2.1 Interrupt Vectors in ATtiny87/167 Automotive

A clarification for the source names of the Interrupt vectors has been made to comply with the header file naming convention.

Table 3-1.	Reset and	Interrupt \	Vectors in	ATtiny87/167	Automotive
		•			

Vector Nb.	. Program Address		Source	Interrupt Definition
	ATtiny87	ATtiny167		
1	0x0000	0x0000	RESET	External Pin, Power-on Reset, Brown-out Reset and Watchdog System Reset
2	0x0001	0x0002	INT0	External Interrupt Request 0
3	0x0002	0x0004	INT1	External Interrupt Request 1
4	0x0003	0x0006	PCINT0	Pin Change Interrupt Request 0
5	0x0004	0x0008	PCINT1	Pin Change Interrupt Request 1
6	0x0005	0x000A	WDT	Watchdog Time-out Interrupt
7	0x0006	0x000C	TIMER1_CAPT	Timer/Counter1 Capture Event
8	0x0007	0x000E	TIMER1_COMPA	Timer/Counter1 Compare Match A
9	0x0008	0x0010	TIMER1_COMPB	Timer/Counter1 Compare Match B
10	0x0009	0x0012	TIMER1_OVF	Timer/Counter1 Overflow
11	0x000A	0x0014	TIMER0_COMPA	Timer/Counter0 Compare Match A
12	0x000B	0x0016	TIMER0_OVF	Timer/Counter0 Overflow
13	0x000C	0x0018	LIN_TC	LIN/UART Transfer Complete
14	0x000D	0x001A	LIN_ERR	LIN/UART Error
15	0x000E	0x001C	SPI_STC	SPI Serial Transfer Complete
16	0x000F	0x001E	ADC	ADC Conversion Complete
17	0x0010	0x0020	EE_READY	EEPROM Ready
18	0x0011	0x0022	ANA_COMP	Analog Comparator

ATtiny87/167 Automotive

Data Sheet Clarifications

continued				
Vector Nb.	Program	Address	Source	Interrupt Definition
	ATtiny87	ATtiny167		
19	0x0012	0x0024	USI_START	USI Start Condition Detection
20	0x0013	0x0026	USI_OVF	USI Counter Overflow

3.3 LIN/UART - Local Interconnect Network Controller or UART

3.3.1 Baud Rate Generator

A clarification has been made for the equations in the Baud Rate Generator section.

The baud rate is defined to be the transfer rate in bits per second (bps):

- BAUD: Baud rate (in bps)
- fclk_{i/o}: System I/O clock frequency
- LDIV[11..0]: Contents of LINBRRH & LINBRRL registers (0-4095), the pre-scaler receives clk_{i/o} as input clock
- LBT[5..0]: Least significant bits of LINBTR register- (0-63) is the number of samplings in a LIN or UART bit (default value 32)

Equation for calculating baud rate: BAUD = fclk_{i/o} / (LBT[5..0] x (LDIV[11..0] + 1))

Equation for setting LINDIV value: LDIV[11..0] = (fclk_{i/o} / (LBT[5..0] x BAUD)) - 1

Note that in reception, a majority vote on three samplings is made.

3.4 Package Marking Information

Legend	: XXX Y YY WW NNN @3	Customer-specific information or Microchip part number Year code (last digit of calendar year) Year code (last 2 digits of calendar year) Week code (week of January 1 is week '01') Alphanumeric traceability code Pb-free JEDEC [®] designator for Matte Tin (Sn)			
Note:	In the event the full Microchip part number cannot be marked on one line, it w be carried over to the next line, thus limiting the number of availab characters for customer-specific information.				

ATtiny87/167 Automotive

Example

AMEL

O 2126547

2126C TH

TINY87-A15SZ

Data Sheet Clarifications

3.4.1 20-Pin SOIC





3.4.2 20-Pin TSSOP

General



Example



3.4.3 32-Pin VQFN



Example



4. Document Revision History

Note: The document revision is independent of the silicon revision.

4.1 Revision History

Doc Rev.	Date	Comments	
A	09/2021	 nitial release of this document Errata content moved from the data sheet and restructured to the new document template 	
		 Data sheet clarifications added: 3.1 Errata Section in Data Sheet is no Longer Valid Interrupts: 3.2.1 Interrupt Vectors in ATtiny87/167 Automotive LIN/UART: 3.3.1 Baud Rate Generator Package Marking: 3.4 Package Marking Information 	

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip products:

- · Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code
 protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright
 Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable" Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

Legal Notice

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet- Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, NVM Express, NVMe, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, Symmcom, and Trusted Time are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

[©] 2021, Microchip Technology Incorporated and its subsidiaries. All Rights Reserved.

ISBN: 978-1-5224-8769-2

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Corporate Office	Australia - Sydney	India - Bangalore	Austria - Wels
2355 West Chandler Blvd.	Tel: 61-2-9868-6733	Tel: 91-80-3090-4444	Tel: 43-7242-2244-39
Chandler, AZ 85224-6199	China - Beiiing	India - New Delhi	Fax: 43-7242-2244-393
Tel: 480-792-7200	Tel: 86-10-8569-7000	Tel: 91-11-4160-8631	Denmark - Copenhagen
Fax: 480-792-7277	China - Chengdu	India - Pune	Tel: 45-4485-5910
Technical Support:	Tel: 86-28-8665-5511	Tel: 91-20-4121-0141	Fax: 45-4485-2829
www.microchip.com/support	China - Chongging	Japan - Osaka	Finland - Espoo
Web Address:	Tel: 86-23-8980-9588	Tel: 81-6-6152-7160	Tel: 358-9-4520-820
www.microchip.com	China - Dongguan	Japan - Tokvo	France - Paris
Atlanta	Tel: 86-769-8702-9880	Tel: 81-3-6880- 3770	Tel: 33-1-69-53-63-20
Duluth. GA	China - Guangzhou	Korea - Daegu	Fax: 33-1-69-30-90-79
Tel: 678-957-9614	Tel: 86-20-8755-8029	Tel: 82-53-744-4301	Germany - Garching
Fax: 678-957-1455	China - Hangzhou	Korea - Seoul	Tel: 49-8931-9700
Austin, TX	Tel: 86-571-8792-8115	Tel: 82-2-554-7200	Germany - Haan
Tel: 512-257-3370	China - Hong Kong SAR	Malavsia - Kuala Lumpur	Tel: 49-2129-3766400
Boston	Tel: 852-2943-5100	Tel: 60-3-7651-7906	Germany - Heilbronn
Westborough MA	China - Naniing	Malaysia - Penang	Tel: 49-7131-72400
Tel: 774-760-0087	Tel: 86-25-8473-2460	Tel: 60-4-227-8870	Germany - Karlsruhe
Fax: 774-760-0088	China - Qingdao	Philippines - Manila	Tel: 49-721-625370
Chicago	Tel: 86-532-8502-7355	Tel: 63-2-634-9065	Germany - Munich
Itasca II	China - Shanghai	Singapore	Tel: 49-89-627-144-0
Tel: 630-285-0071	Tel: 86-21-3326-8000	Tel: 65-6334-8870	Fax: 49-89-627-144-44
Eax: 630-285-0075	China - Shenyang	Taiwan - Hsin Chu	Germany - Rosenheim
Dallas	Tel: 86-24-2334-2829	Tel: 886-3-577-8366	Tel: 49-8031-354-560
Addison TX	China - Shenzhen	Taiwan - Kaobsiung	Israel - Ra'anana
Tel: 972-818-7423	Tel: 86-755-8864-2200	Tel: 886-7-213-7830	Tel: 972-9-744-7705
Fax: 972-818-2924	China - Suzhou	Taiwan - Tainei	Italy - Milan
Detroit	Tel: 86-186-6233-1526	Tel: 886-2-2508-8600	Tel: 39-0331-742611
Novi MI	China - Wuhan	Thailand - Bangkok	Fax: 39-0331-466781
Tel: 248-848-4000	Tel: 86-27-5980-5300	Tel: 66-2-694-1351	Italy - Padova
Houston TX	China - Xian	Vietnam - Ho Chi Minh	Tel: 39-049-7625286
Tel: 281-894-5983	Tel: 86-29-8833-7252	Tel: 84-28-5448-2100	Netherlands - Drunen
Indiananolis	China - Xiamen	101. 04 20 0440 2100	Tel: 31-416-690399
Noblesville IN	Tel: 86-592-2388138		Fax: 31-416-690340
Tel: 317-773-8323	China - Zhuhai		Norway - Trondheim
Eav: 317-773-5453	Tel: 86-756-3210040		Tel: 47-72884388
Tel: 317-536-2380	101. 00-700-02 100-0		Poland - Warsaw
			Tel: 48-22-3325737
Mission Vielo CA			Romania - Bucharest
Tel: 0/0-/62-0523			Tel: 40-21-407-87-50
Fax: 949-462-9608			Spain - Madrid
Tel: 951-273-7800			Tel: 31-91-708-08-90
Raleigh NC			Fax: 34-91-708-08-91
Tel: 010-844-7510			Sweden - Gothenberg
New York NY			Tel: 46-31-704-60-40
Tel: 631-435-6000			Sweden - Stockholm
San Jose CA			Tel: 46-8-5090-4654
Tel: 408-735-0110			IIK - Wokingham
Tel: 408-436-4270			Tel: 11-118-021-5800
Canada Taranta			Eav: 44 119 001 5000
			Гах. 44-110-921-382U
101. 303-033-1300 East 005 605 2079			
1 an. 303-033-2010		[