



Product Change Notification / SYST-28PKOP667

Date:

29-Dec-2021

Product Category:

Computing Embedded Controllers

PCN Type:

Document Change

Notification Subject:

ERRATA - MEC170x Silicon Errata and Data Sheet Clarification

Affected CPNs:

[SYST-28PKOP667_Affected_CPN_12292021.pdf](#)

[SYST-28PKOP667_Affected_CPN_12292021.csv](#)

Notification Text:

SYST-28PKOP667

Microchip has released a new Product Documents for the MEC170x Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [MEC170x Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change:

Added Data Sheet Clarification # 18.- PWR_INV bit is always read/write.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 29 Dec 2021

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

MEC170x Silicon Errata and Data Sheet Clarification

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

MEC1701H-C1-SZ
MEC1701H-C1-SZ-TR
MEC1701Q-C2-SZ
MEC1701Q-C2-TN
MEC1703K-F2-SZ
MEC1703K-F3-SZ
MEC1703K-P2-X/XY
MEC1703K-P2-XY
MEC1703K-P3-X/XY
MEC1703K-P3-XY
MEC1703Q-B2-I/TN
MEC1703Q-B2-TN
MEC1703Q-C2-TN
MEC1703Q-C2-XY
MEC1703Q-F2-SZ
MEC1704Q-C2-I/SZ
MEC1705Q-C2-I/SZ

MEC170x

Silicon Errata and Data Sheet Clarification

TABLE 1: SILICON IDENTIFICATION

Part Number	Silicon Identifier	Functional Revision C	Functional Revision E	Functional Revision F
MEC1701	Device ID ⁽¹⁾	2Dh	2Dh	2Dh
	Revision ID for Silicon Revision ⁽²⁾	82h	84h	85h
	PIS ⁽³⁾ Version/Revision	C1	C2	C2
MEC1703	Device ID ⁽¹⁾	2Eh	2Eh	2Eh
	Revision ID for Silicon Revision ⁽²⁾	82h	84h	85h
	PIS ⁽³⁾ Version/Revision	F1	F2	F2
MEC1704	Device ID ⁽¹⁾	33h	33h	33h
	Revision ID for Silicon Revision ⁽²⁾	82h	84h	85h
	PIS ⁽³⁾ Version/Revision	C1	C2	C2
MEC1705	Device ID ⁽¹⁾	32h	32h	32h
	Revision ID for Silicon Revision ⁽²⁾	82h	84h	85h
	PIS ⁽³⁾ Version/Revision	C1	C2	C2

Note 1: The Device ID is visible as an 8-bit number at Plug and Play Configuration Index 20h.
2: The HW Revision Number is visible as an 8-bit number at Plug and Play Configuration Index 21h.
3: Product Identification System (PIS) is defined in the Product Data Sheet.

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾		
				C	E	F
SMB Controller	SMB Master	1.	SMBus Master Controller violates Bus Idle Time between STO and STA in Byte mode only	X	X	X
Boot ROM	Crisis Recovery	2.	May enter crisis recovery mode in error	X	X	X
JTAG Pins	Pins	3.	GPIO145 & GPIO146 input disabled in SWD mode	X	X	X
EEPROM Controller	TEST	4.	For MEC1703 and MEC1705, Test Register at address 0x4000_2C1C needs to be programmed to 0x00060101	X	X	X
ESPI	ESPI	5.	MAFS flash transfers should be to/from 4-byte aligned SRAM buffer starting addresses	X	X	X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.
2: Please refer to the description below to know a list of parts that are affected.

TABLE 2: SILICON ISSUE SUMMARY (CONTINUED)

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾		
				C	E	F
ROM API's	ROM API's	6.	Some API's were removed		X	X
Boot ROM	Boot ROM	7.	The Boot ROM may not successfully load Application Code.	X	X	
ESPI	ESPI	8.	Host needs to follow recommendations while changing the Plug and Play base address	X	X	X
VBAT	VBAT	9.	High I _{BAT} current on coin cell insertion	X	X	X ⁽²⁾
PCR	RESETI#	10.	Glitch on RESETI# pin during VTR power up.	X	X	X
Note 1: Only those issues indicated in the last column apply to the current silicon revision.						
Note 2: Please refer to the description below to know a list of parts that are affected.						

Silicon Errata Issues

1. Module: SMBus 2.0 Host Controller

DESCRIPTION

SMBus Master Controller violates Bus Idle Time between STO and STA in Byte mode only. This issue only occurs in a multi-master environment.

Under firmware control, it is possible to generate a new command on the bus before the Bus Idle time expires, thereby violating the SMBus Idle time.

END USER IMPLICATIONS

The SMBus Master Controller may generate a START condition too soon. The two consequences of this scenario are that another master will issue a transaction that will get corrupted, which is handled by the lost arbitration mechanism, or the MEC170x master will unfairly claim the bus too often.

Work Around

There are two solutions:

- Use the Network Layer instead of Byte mode. This anomaly does not apply to the SMBus Network Layer operation.
- If firmware polls the nBB bit to indicate not busy before asserting the PIN bit and writing the data register, the SMBus Controller will not violate the Bus Idle time.

2. Module: Crisis Recovery Mode

DESCRIPTION

The Boot ROM turns on the internal pull-up on GPIO045 (PVT_STRAP) pin during initialization, then processes the eFuse settings and samples the GPIO045 input value. It is supposed to sample the pin after waiting a minimum of 1 ms to determine if it should abort the standard SPI Flash load process and boot from the Crisis Recovery SPI Flash over the Private SPI Flash interface. However, the boot code turns on the pull-up, does the eFuse processing and samples the pin immediately without delay. Depending on the external capacitance, this pin may not have enough time to rise to a high-level and may be misinterpreted as low and enter crisis recovery mode in error.

END USER IMPLICATIONS

The device may enter crisis recovery mode in error.

Work Around

Implement external pull-up for normal operation.

3. Module: GPIO145 and GPIO146 Inputs Disabled When JTAG Enabled

DESCRIPTION

GPIO145 and GPIO146 inputs are disabled when JTAG enabled and the JTAG debugger is connected in both 4-wire JTAG mode and 2-wire SWD mode.

END USER IMPLICATIONS

- Cannot use SMB09 when JTAG is enabled and JTAG debugger is connected if device is configured for 2-wire SWD test mode.
- Cannot use GPIO145 and GPIO146 inputs when JTAG is enabled and JTAG debugger is connected if device is configured for 2-wire SWD test mode.

Work Around

None.

4. Module: EEPROM Controller

DESCRIPTION

The test register at address 0x4000_2C1C needs to be written to 0x00060101 by the application code during initialization before accessing EEPROM for MEC1703 and MEC1705.

END USER IMPLICATIONS

- EEPROM access may be impacted.

Work Around

During application initialization, the user needs to write the value of 0x00060101 to EEPROM Controller TEST register at address 0x4000_2C1C, before accessing EEPROM.

5. Module: ESPI

DESCRIPTION

All MAFS flash transfers must be to/from 4-byte aligned SRAM buffer starting addresses. The low-order 2 bits of the BUFFER ADDRESS register are reserved and must be written as zeros.

END USER IMPLICATIONS

- Customers are required to start all MAFS flash transfers to/from 4-byte aligned SRAM buffer starting addresses.

Work Around

Start MAFS flash transfers to/from 4-byte aligned SRAM buffer starting addresses.

6. Module: ROM API's

DESCRIPTION

Some APIs have been removed from the Functional Revision E devices.

The "version" API return value can be used to determine the version number of the ROM that corresponds to the functional revision of the device as shown in [Table 3](#) below.

MEC170x

TABLE 3: ROM VERSION NUMBER

Functional Revision	Version API Return Value	Boot ROM Revision	ROM API Manual
C	0x00280032	A1	MEC2016_Rom_A1_API_Manual.docx
E	0x00400232	B0	MEC2016_Rom_B0_API_Manual.pdf

The APIs in [Table 4](#) have been removed from the Functional Revision E devices. Note that all APIs from the Functional Revision C devices, except for those in the [Table 4](#), are present in the Functional Revision E devices.

The replacement for the removed API is shown in the [Table 4](#), if applicable. Please refer to the appropriate ROM API Manual for the device. Note that the replacement API may not be a direct replacement; please refer to the manual for the correct usage of each API.

TABLE 4: REPLACEMENT API'S

No	API in Functional Revision C	Replacement API in Functional Revision E
1	sha_init	api_sha_direct_init
2	sha_update	api_sha_direct_update
3	sha_final	api_sha_direct_finalize
4	sha12_init	api_sha256_init
5	sha12_update	api_sha256_update
6	sha12_finalize	api_sha256_finalize
7	sha35_init	api_sha512_init
8	sha35_update	api_sha512_update
9	sha35_finalize	api_sha512_finalize
10	pke_write_scm32	api_pke_copy_to_scm2
11	rsa_load_key	api_pke_rsa_load_key
12	rsa_load crt_params	api_pke_rsa_load crt_key
13	rsa_encrypt	api_pke_rsa_crypt
14	rsa_decrypt	api_pke_rsa_crypt
15	qmspi_cfg_spi_cmd	None. Refer to the QMSPI source code for example QMSPI accesses.
16	qmspi_read_fifo	None. Refer to the QMSPI source code for example QMSPI accesses.
17	qmspi_start_dma	None. Refer to the QMSPI source code for example QMSPI accesses.

END USER IMPLICATIONS

- The APIs listed in the [Table 4](#) above are not present in the Functional Revision E devices. The replacement for the removed API is shown in the [Table 4](#), if applicable. Refer to the appropriate ROM API Manual for the device.

Work Around

Use the version API as described above in [Table 3](#) to determine the version of the device, if required. Use the Replacement APIs in the [Table 4](#) above for functional revision E parts.

7. Module: Boot ROM

DESCRIPTION

The Boot ROM may generate a Load Failure condition for a limited number of valid images in error. If the failure occurs on the TAG0 image, the Boot ROM will attempt to load the TAG1 image. If the failure occurs on the TAG1 image, the Boot ROM will go to the Load Failure exit state.

This error has been found on a very small subset of images and is dependent on a deterministic synchronous timing event that is dependent on image size and SPI Flash acquisition timing.

Identifying Timing Failure: If this timing failure occurred, then the value "0x0D21" will be in the ROM Event log. Please refer to Boot ROM Addendum for Boot ROM Event Log information.

END USER IMPLICATIONS

- Boot may fail when using different SPI frequency or SPI Mode for the same payload.

Work Around

Recommendations to solve this problem:

- The firmware image is padded to be 64 byte aligned. Pad image with an additional 64 bytes to change size of image.
- Total image (Application binary + trailer for encryption and \ or authentication, if enabled) to be loaded from SPI, should reside only in code SRAM space.
- For larger SRAM devices, for all SPI frequencies, recommended safest SPI operation is QUAD mode.
- If you still sees the Boot code failure, please get in touch with the Microchip support team.

8. Module: eSPI

DESCRIPTION

When a new 16-bit Plug and Play Base Address (INDEX/DATA I/O address) is being written by the Host BIOS directly, the eSPI block does not wait until both bytes of the new address have been written before changing it. Instead, each byte of the new address takes effect immediately when written. In the worst case, with unusual address assignments, this could make the INDEX/DATA registers inaccessible after the first byte has been written.

HOST/BIOS NEEDS TO FOLLOW BELOW RECOMMENDATIONS WHILE CHANGING THE BASE ADDRESS AT RUNTIME

Work Around

For the BIOS to change the Base Address at Runtime, there are two recommended alternatives:

Use only EC Firmware to change the Plug and Play Base Address of the device. The Host BIOS should make a request to Application Firmware to accomplish this, and wait until it has received an acknowledgment from Firmware before accessing the Plug and Play registers again.

1. If the Host needs to change the Base Address by using Plug and Play accesses itself, then it must still write both bytes of the Base Address register, but it should not change the upper (second) byte by doing so.
2. Strongly recommended is to keep the Base Address at one of the legacy addresses 002Eh or 004Eh recognized by the Host Chipset hardware. Otherwise, as implied above, at least keep it within I/O address range 0000h through 00FFh, if this is where EC firmware has initially placed it.

9. Module: VBAT

DESCRIPTION

There could be a high I_{BAT} current on new coin cell insertion. During initial VBAT power rising, the VBAT circuit can enter a high current state causing a voltage drop across the 1K UL resistor. This affects all 128 and 144 pin packages. This issue is not present in the 169 pin packages.

END USER IMPLICATIONS

- Under these conditions, the VBAT power on can stall in this high current state, with the VBAT on device pin between 0.7 and 1.2V.


Work Around

When inserting the coin-cell follow the below procedure.

Insert the coin cell and then apply VTR (i.e +3VALW). This enables VBAT low-power operation. A high I_{BAT} will not return on subsequent VTR power cycles.

Referring to the RTC Battery circuit shown in [Figure 1](#), applying VTR via the +3.3V_RTC_LDO signal, powers RTC_Cell (which is connected to VBAT of MEC170x) directly (without a series 1k resistor and hence no IR drop from the applied VTR), raising VBAT (RTC_Cell) to greater than 2.0 volts. This takes VBAT out of the “high current” region discussed above enabling normal VBAT low power operation.

FIGURE 1: HIGH IBAT CURRENT DURING COIN CELL INSERTION



10. Module: PCR

Glitch on RESETI# pin during VTR power up.

DESCRIPTION

During VTR Power-Up, the RESETI# pin may drive out a pulse for a very short period of time.

END USER IMPLICATIONS

- RESETI# pin should not be connected directly to critical pins of PCH such as RSRMRST# or DSW_PWROK or any other logic that may be impacted by this glitch.

Work Around

Isolate the RESETI# pin from other logic as needed. (i.e. use a buffer to drive the pin).

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet.

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

TABLE 5: DATA SHEET CLARIFICATION SUMMARY

Module	Item Number	Issue Summary
ESPI	1.	Maximum ESPI clock frequency
ESPI	2.	eSPI MAFS-Configuration Flash Erase needs a non-zero Transfer Length
WDT	3.	WDT_STATUS bit is Reserved
EFUSE	4.	The ATE Mode bit is located in EFUSE Byte 35
PIS	5.	Version/Revision B added
Device ID	6.	The Device ID for MEC1705Q-C2-SZ is 32h and Revision ID is 84h
WDT	7.	WDT_Count is reset on RESET_SYS
WDT	8.	WDT Event Count Register is not programmed by Boot ROM, but needs to be programmed by application firmware.
PCR	9.	VBAT_RESET_STATUS in Power Clock and Reset block indicates status of RESET_VBAT
PCR	10.	JTAG_RESET_STATUS in Power Clock and Reset block is replaced with JTAG_RST# and indicates current value of JTAG_RST# pin
PCR	11.	Wake Only interrupt example and explanation
Pin Configuration	12.	In Table2-3 and Figure21-2, nSYS_RST should be read as RESET_SYS
PCR	13.	VTR_RESET_STATUS bit Power Clock and Reset block indicates is renamed to RESET_SYS_STATUS
Electrical Specification	14.	In Table 50-11: VTR SUPPLY CURRENT, I_VTR, EC_CLK is gated Off for Light Sleep condition.
RC_ID	15.	TABLE 34-2, TABLE 34-3, TABLE 34-4 are Sample RC values for 24MHz system clock and CLOCK_SET field in the RC_ID Control Register is set to '1'
Mailbox	16.	Section 16.12.4 SMI INTERRUPT MASK REGISTER bit definition are updated.
Pins	17.	All pins in VBAT power domain are not glitch protected.
PCR	18.	PWR_INV bit is always read/write

1. Module: ESPI

This section captures update to ESPI_CLK clock frequencies supported.

ESPI CLOCK FREQUENCIES

The Boot ROM configures the ESPI hardware to default the maximum ESPI_CLK frequency as 50 MHz. This can be changed by customer application code downloaded from SPI Flash to support the maximum 66 MHz clock frequency. However, the ESPI GPIO Pin Control 2 register must be updated to select 12mA with a fast slew rate.

2. Module: ESPI

This section demonstrates eSPI MAFS-Configuration Flash Erase needs a non-zero Transfer Length.

ESPI MAFS-CONFIGURATION FLASH ERASE OPERATION

In Master Attached Flash configuration, before performing an Erase operation, it is necessary to write a non-zero value into the Flash Access Channel Transfer Length Register, which is in the eSPI I/O Component register set at offset 290h. For Erase, the exact value is not important except that it must be non-zero, and a value of '1' is suggested for the sake of code efficiency.

If this is not done, then if zero appears in that register, any Erase command will terminate immediately with the BAD_REQUEST error status bit set, and the requested Erase will not be performed.

3. Module: WDT

This section clarifies which WDT status bit must be used for detecting watchdog timer events.

WDT TIMER EVENTS

The WDT_STATUS bit documented in the WDT Control register is a Reserved bit and cannot be used to detect watchdog timer events.

Bit[5] WDT located in the Power-Fail and Reset Status register in the VBAT Register Bank must be used as the WDT Status bit.

4. Module: EFUSE

This section clarifies where the ATE Mode bit is located in the EFUSE block.

ATE MODE BIT IS LOCATED AT BYTE 35 BIT 7 OF EFUSE MODULE

The ATE Mode bit is located in EFUSE Byte 35 Bit[7]: ATE Mode =0

1=Normal

0=ATE Mode

If ATE Mode bit has not been programmed (i.e., blank parts) then the Boot ROM will perform the following steps:

1. Enable 4-wire JTAG
2. Halt Processor

If ATE Mode bit is set, Boot ROM will initialize the device and then begin the SPI Port Selection process defined in the Boot ROM document.

5. Module: Product Information System (PIS)

This section adds another entry for the Version/Revision.

B# B = UNPROVISIONED OTP - CUSTOMER NEEDS TO PROVISION, # = VERSION REVISION NUMBER

Version/Revision: B# B = Unprovisioned OTP, # = Version Revision Number

6. Module: Device ID

This section clarifies the Device ID and Revision ID for MEC1705Q-C2-SZ.

REVISION ID AND DEVICE ID OF MEC1705Q-C2-SZ

For MEC1705Q-C2-SZ, the Device ID is 32h and Revision ID is 84h.

7. Module: WDT

This section clarifies which Reset clears the WDT Count.

WDT COUNT RESET

The WDT_COUNT documented in the WDT Count Register is reset by RESET_SYS and not RESET_SYS_nWDT.

8. Module: WDT

This section clarifies programming of WDT EVENT COUNT Register.

WDT EVENT COUNT REGISTER IS NOT PROGRAMMED BY BOOT ROM

The WDT Event Count Register in EC Subsystem block with offset address 28h has following definition. This field is cleared to 0 on a reset triggered by the main power on reset, but not on a reset triggered by the Watchdog Timer. This field may be used by application firmware to monitor WDT activity. The application firmware must manually increment this register to indicate the number of times a WDT event fired since the chip was last reset by a RESET_SYS_nWDT event.

The recommended procedure is as follows:

1. Check WDT bit located in Power-Fail and Reset Status Register. If WDT = 1, first clear WDT status bit in Power-Fail and Reset Status Register and then increment WDT Event Count register.
2. Enable WDT using the WDT Activation Mechanism defined in Watchdog Timer (WDT) data sheet chapter.

9. Module: PCR

The VBAT_RESET_STATUS (bit 5) in PCR Power Reset Status Register indicates RESET_VBAT status and not RESET_VTR.

10. Module: PCR

JTAG_RESET_STATUS bit in PCR Power Reset Status Register is renamed to JTAG_RST# and indicates the current value of JTAG_RST# pin.

JTAG RESET STATUS IS REPLACED WITH JTAG_RST# AND INDICATES STATUS OF JTAG_RST# PIN

The JTAG_RESET_STATUS (bit 7) in PCR Power Reset Status Register is replaced with the JTAG_RST# and indicates the status of JTAG_RST# pin. This is a Read Only bit.

0 = JTAG_RST# pin is low

1 = JTAG_RST# pin is high

Note: This bit always reflects the state of the JTAG_RST# pin even when Boundary Scan Enabled.

11. Module: PCR

This section clarifies Wake-Only Events in Section 4.7.4.1 and gives an example and explanation.

WAKE-ONLY INTERRUPT IN GIRQ22 JUST GENERATES CLOCK FOR THE RESPECTIVE BLOCK AND DO NOT WAKE THE PROCESSOR

The Wake-Only Events and interrupts are responsible for waking up the respective blocks from where the Event or interrupt becomes active, but will not enable the clock to the processor.

For example, when RSMRST is high and there is a desire to wake from an ESPI cycle, GIRQ22[9] is the correct wake source to use. When Chip is asleep and there is a ESPI cycle, the falling edge of the CS will cause the chips clock to turn on the ESPI block, but not the processor itself. Upon conclusion of the ESPI cycle, if no ESPI interrupt was generated (i.e. most cycles), then the clock to the ESPI block will go off, and the chip will go back to sleep. If the ESPI cycle creates an interrupt to the processor (i.e. downstream wire or downstream OOB packet for example), then an processor interrupt will be generated if enabled and the clock will remain on and the processor can service the interrupt and the processor can put the chip back to sleep when it has completed its work.

Note: The ESPI Reset itself is NOT a wake event. If wake from ESPI reset is required, then the GPIO interrupt for the ESPI reset pin can be used as a wake event.

12. Module: Pin Configuration

nSYS_RST in TABLE 2-3 heading and FIGURE 21-2 should be read as RESET_SYS.

13. Module: PCR

The VTR_RESET_STATUS (bit 6) in PCR Power Reset Status Register is replaced with RESET_SYS_STATUS and indicates the status of RESET_SYS. This R/WC bit is set any time the RESET_SYS signal is asserted.

14. Module: Electrical Specification

POWER CONSUMPTION IN LIGHT SLEEP

Table 50-11, VTR SUPPLY CURRENT, I_VTR incorrectly indicates the EC_CLK frequency is 12MHz in Light Sleep. The EC_CLK is gated Off (0 MHz) in Light sleep condition.

15. Module: RC_ID

Section 34.11 Time Constants in MEC170x Data Sheet incorrectly states following statement “In the following tables, the CLOCK_SET field in the RC_ID Control Register is set to ‘0’, so the time base for measuring the rise time is 48MHz, the speed of the system clock”. The correct speed of the system clock is 24MHz for the count value listed in Table 34-2, Table 34-3 and Table 34-4.

SYSTEM CLOCK USED TO MEASURE COUNT IS 24MHZ

The correct statement for Section 34.11 is listed below.

“This section lists a set of R and C values which can be connected to the RC_ID pin. Note that rise time generally follow RC time Tau. Firmware should use the Max and Min Counts in the tables to create quantized states.

In the following tables, the CLOCK_SET field in the RC_ID Control Register is set to ‘1’, so the time base for measuring the rise time is 24MHz, the speed of the system clock. All capacitor values are $\pm 10\%$ and all resistor values are $\pm 5\%$.

Minimum and maximum count values are suggested ranges, calculated to provide reasonable margins around the nominal rise times. Rise times have been confirmed by laboratory measurements.”

16. Module: Mailbox

Section 16.12.4 SMI INTERRUPT MASK REGISTER in MEC170x Data Sheet had incorrect description of the register bits.

UPDATED SECTION 16.12.4 SMI INTERRUPT MASK REGISTER

The updated section 16.12.4 is given below:

16.12.4 SMI Interrupt Mask Register

Offset	10Ch			
MBX_INDEX	03h			
Bits	Description	Type	Default	Reset Event
7:1	EC_SWI_EN EC Software Interrupt Enable. Each bit in this field that is ‘1b’ enables the generation of SERIRQ interrupts when the corresponding bit in the EC_SWI field in the SMI Interrupt Source Register is ‘1b’.	R/W	0h	RESET_SYS
0	EC_WR_EN EC Mailbox Write.Interrupt Enable. If this bit is ‘1b’, the bit EC_WR in the SMI Interrupt Source Register is enabled for the generation of SERIRQ or nSMI events.	R/W	0h	RESET_SYS

17. Module: Pins

All pins on VBAT power rail are not glitch protected.

UPDATED SECTION 2.5.8 MEC1701/MEC1703-128 WFBGA-TF, SECTION 2.5.9 MEC1705/MEC1704/MEC1701/MEC1703 144 WFBGA-SZ, SECTION 2.5.10 MEC1701 169 WFBGA-TN, SECTION 2.5.11 MEC1703 169 WFBGA-TN AND SECTION 2.5.12 MEC1703 169 WFBGA-XY

GPIO pins that are in VBAT power rail are not glitch protected. This includes BGPO[5:0], VCI_IN[4:0]#, VCI_OUT, XTAL1 and XTAL2. Some of these GPIO pins in VBAT power rail have been wrongly marked as glitch protected in above sections. Also BGPO pins are not glitch protected. This is a correction in Section 2.5.3 GLITCH PROTECTION and BGPO GLITCH PROTECTION.

18. Module: PCR

PWR_INV bit is always read/write irrespective of VCC_PWRGD state.

In MEC170x Data Sheet, Section 4.9.9 "POWER RESET CONTROL REGISTER" describes PWR_INV bit at bit position [0]. This bit is always Read/Write irrespective of VCC_PWRGD.

APPENDIX A: DOCUMENT REVISION HISTORY

Revision	Description
DS80000704K (12-14-21)	Added Data Sheet Clarification # 18 . - PWR_INV bit is always read/write.
DS80000704J (04-09-21)	Added Errata # 10 . - Glitch on RESETI# pin during VTR power up.
	Added Data Sheet Clarification # 17 . - Pins in VBAT Power Rail are not glitch protected.
DS80000704H (11-24-20)	Added Data Sheet Clarification # 16 . - Section 16.12.4 SMI INTERRUPT MASK REGISTER bit definition are updated.
DS80000704G (10-07-19)	Added Silicon Revision F. Added Silicon Summary Issue # 8 . Recommendations for changing the base address by Host BIOS at runtime.
DS80000704F (03-06-19)	Added Silicon Summary Issue # 7 . - The Boot ROM may not successfully load Application Code.
	Removed Silicon Summary Issue # 4 - Boot ROM for UPD feature does not disable Basic Timer 16 instance 1. This is fixed.
	Updated Silicon Summary Issue # 2 . - Description of the bug updated to be more exact.
	Updated Table 1 , "Silicon Identification," on page 1 with Revision number (register at address 0x400FFF21) with 0x82 for Silicon revision C and 0x84 for Silicon revision E.
DS80000704E (03-19-18)	Removed Silicon Summary Issue # 8 . - Some QMSPI APIs do not function correctly and merged the API's with Silicon Summary Issue # 6 . - Some API's were removed.
	Added Data Sheet Clarification # 15 . - TABLE 34-2, TABLE 34-3, TABLE 34-4 are Sample RC values for 24MHz system clock and CLOCK_SET field in the RC_ID Control Register is set to '1'.
	Added Data Sheet Clarification # 6 . - The Device ID for MEC1705Q-C2-SZ is 32h and Revision ID is 84h.
	Added Data Sheet Clarification # 7 . - WDT_Count is reset on RESET_SYS.
	Added Data Sheet Clarification # 8 . - WDT Event Count Register is not programmed by Boot ROM, but needs to be programmed by application firmware.
	Added Data Sheet Clarification # 9 . - VBAT_RESET_STATUS in Power Clock and Reset block indicates status of RESET_VBAT.
	Added Data Sheet Clarification # 10 . - JTAG_RESET_STATUS in Power Clock and Reset block indicates should be JTAG_RST#.
	Added Data Sheet Clarification # 11 . - Wake Only interrupt example and explanation.
	Added Data Sheet Clarification # 12 . - In Table 2-3 and Figure 21-2, nSYS_RST should be read as RESET_SYS.
	Added Data Sheet Clarification # 13 . - VTR_RESET_STATUS bit Power Clock and Reset block indicates is renamed to RESET_SYS_STATUS.
	Added Data Sheet Clarification # 14 . - In Table 50-11: VTR SUPPLY CURRENT, I_VTR, EC_CLK is gated off in Light Sleep condition.
	Added Silicon Summary Issue # 6 . - Some API's were removed.
	Added Silicon Summary Issue # 8 . - Some QMSPI APIs do not function correctly.
DS80000704D (01-11-18)	Added Data Sheet Clarification # 4 . - The ATE Mode bit is located in EFUSE Byte 35.
	Added Data Sheet Clarification # 5 . - Version/Revision B added to Product Information System.
DS80000704C (10-05-17)	Added Silicon Summary Issue # 4 and 5 .
	Added column for Function Rev E to Table 2 , "Silicon Issue Summary," on page 1 Added Silicon Summary Issue # 4 .
DS80000704B (01-30-17)	Added column for Function Rev C to Table 2 , "Silicon Issue Summary," on page 1 .
	Added Data Sheet Clarification # 2 . - eSPI MAFS-Configuration Flash Erase needs a non-zero Transfer Length. Added Data Sheet Clarification # 3 . - WDT_STATUS bit is Reserved.
DS80000704A (07-15-16)	Initial release.

THE MICROCHIP WEB SITE

Microchip provides online support via our WWW site at www.microchip.com. This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

CUSTOMER CHANGE NOTIFICATION SERVICE

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at www.microchip.com. Under "Support", click on "Customer Change Notification" and follow the registration instructions.

CUSTOMER SUPPORT

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Field Application Engineer (FAE)
- Technical Support

Customers should contact their distributor, representative or field application engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

Technical support is available through the web site at: <http://www.microchip.com/support>

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is “unbreakable”. Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at <https://www.microchip.com/en-us/support/design-help/client-support-services>.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maxStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-B, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, NVM Express, NVMe, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, Symmcom, and Trusted Time are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2021, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN: 9781522494911

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX
Tel: 512-257-3370

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Novi, MI
Tel: 248-848-4000

Houston, TX
Tel: 281-894-5983

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453
Tel: 317-536-2380

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608
Tel: 951-273-7800

Raleigh, NC
Tel: 919-844-7510

New York, NY
Tel: 631-435-6000

San Jose, CA
Tel: 408-735-9110
Tel: 408-436-4270

Canada - Toronto
Tel: 905-695-1980
Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733

China - Beijing
Tel: 86-10-8569-7000

China - Chengdu
Tel: 86-28-8665-5511

China - Chongqing
Tel: 86-23-8980-9588

China - Dongguan
Tel: 86-769-8702-9880

China - Guangzhou
Tel: 86-20-8755-8029

China - Hangzhou
Tel: 86-571-8792-8115

China - Hong Kong SAR
Tel: 852-2943-5100

China - Nanjing
Tel: 86-25-8473-2460

China - Qingdao
Tel: 86-532-8502-7355

China - Shanghai
Tel: 86-21-3326-8000

China - Shenyang
Tel: 86-24-2334-2829

China - Shenzhen
Tel: 86-755-8864-2200

China - Suzhou
Tel: 86-186-6233-1526

China - Wuhan
Tel: 86-27-5980-5300

China - Xian
Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai
Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444

India - New Delhi
Tel: 91-11-4160-8631

India - Pune
Tel: 91-20-4121-0141

Japan - Osaka
Tel: 81-6-6152-7160

Japan - Tokyo
Tel: 81-3-6880-3770

Korea - Daegu
Tel: 82-53-744-4301

Korea - Seoul
Tel: 82-2-554-7200

Malaysia - Kuala Lumpur
Tel: 60-3-7651-7906

Malaysia - Penang
Tel: 60-4-227-8870

Philippines - Manila
Tel: 63-2-634-9065

Singapore
Tel: 65-6334-8870

Taiwan - Hsin Chu
Tel: 886-3-577-8366

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600

Thailand - Bangkok
Tel: 66-2-694-1351

Vietnam - Ho Chi Minh
Tel: 84-28-5448-2100

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4485-5910
Fax: 45-4485-2829

Finland - Espoo
Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching
Tel: 49-8931-9700

Germany - Haan
Tel: 49-2129-3766400

Germany - Heilbronn
Tel: 49-7131-72400

Germany - Karlsruhe
Tel: 49-721-625370

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Rosenheim
Tel: 49-8031-354-560

Israel - Ra'anana
Tel: 972-9-744-7705

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Padova
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Norway - Trondheim
Tel: 47-7288-4388

Poland - Warsaw
Tel: 48-22-3325737

Romania - Bucharest
Tel: 40-21-407-87-50

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Gothenberg
Tel: 46-31-704-60-40

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820