



Customer Information Notification

202302020I : Release of Errata Document Revision "6" for LS1012A

Note: This notice is NXP Company Proprietary.

Issue Date: Mar 25, 2023 **Effective date:** Mar 26, 2023

Here is your personalized notification about a NXP general announcement.
For detailed information we invite you to [view this notification online](#)

Management summary

Release of Errata Document Revision "6" for LS1012A Device.

Change Category

<input type="checkbox"/> Wafer Fab Process	<input type="checkbox"/> Assembly Process	<input type="checkbox"/> Product Marking	<input type="checkbox"/> Test Process	<input type="checkbox"/> Design
<input type="checkbox"/> Wafer Fab Materials	<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Equipment	<input checked="" type="checkbox"/> Errata
<input type="checkbox"/> Wafer Fab Location	<input type="checkbox"/> Assembly Location	<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Location	<input type="checkbox"/> Electrical spec./Test coverage
<input type="checkbox"/> Firmware <input type="checkbox"/> Other				

PCN Overview

Description

The following changes have been made to the LS1012A Device Errata document:

The following errata were added:

- A-051238 - Hot plug-in/out on SATA Port Multiplier Ports (PMP) may not be detected
- A-050565 - A glitch on I/O pins during VDD core supply ramp up and ramp down

The following errata were revised:

- A-050428 - Speculative AT instruction using out-of-context translation regime could cause subsequent request to generate an incorrect translation
- A-010650 - I2C controller is unable to generate clocks when SDA is low
- A-009149 - USB 2.0 protocol data pins USB_D_M and USB_D_P do not support IEEE 1149.1
- A-007728 - The process of clearing the FTMx_SC[TOF] bit does not work as expected under a certain condition when the FTM counter reaches FTM_MOD value
- A-011218 - eDMA may not work with SPI
- A-009798 - USB high speed squelch threshold adjustment

Reason

Notify customer of the errata document release.

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality

Additional information

Additional documents: [view online](#)

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name	Safwan Raad
Position	Apps Manager
e-mail address	safwan.raad@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

NXP Semiconductors
High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2023 NXP Semiconductors. All rights reserved.