



Product Change Notification / SYST-01PBDY542

Date:

02-May-2023

Product Category:

Motor Drivers

PCN Type:

Document Change

Notification Subject:

ERRATA - MCP8025A/6 Silicon Errata and Data Sheet Clarification

Affected CPNs:

[SYST-01PBDY542_Affected_CPN_05022023.pdf](#)

[SYST-01PBDY542_Affected_CPN_05022023.csv](#)

Notification Text:

SYST-01PBDY542

Microchip has released a new Errata for the MCP8025A/6 Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [MCP8025A/6 Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change: Initial release of this document.

Impacts to Data Sheet: None

Change Implementation Status: Complete

Date Document Changes Effective: 02 May 2023

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

MCP8025A/6 Silicon Errata and Data Sheet Clarification

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

MCP8025A-115E/MP
MCP8025A-115E/PT
MCP8025A-115H/MP
MCP8025A-115H/MPVAO
MCP8025A-115H/PT
MCP8025AT-115E/MP
MCP8025AT-115E/PT
MCP8025AT-115H/MP
MCP8025AT-115H/MPV05
MCP8025AT-115H/MPVAO
MCP8025AT-115H/PT
MCP8026-115E/MP
MCP8026-115E/MPB3
MCP8026-115E/PT
MCP8026-115E/PTVB3
MCP8026-115H/MP
MCP8026-115H/PT
MCP8026T-115E/MP
MCP8026T-115E/MPB3
MCP8026T-115E/PT
MCP8026T-115E/PTVB3
MCP8026T-115H/MP
MCP8026T-115H/PT
MCP8026T-115H/PTVAO

MCP8025A/6

Silicon Errata and Data Sheet Clarification

The functionality of the MCP8025A/6 devices is described in the Device Data Sheet (DS20005905), except for the anomalies described below.

1. Module: V_{BOOT} Not Ready

When CE toggles from a logic '0' to a logic '1', V_{BOOT} must attain 10.8V before the driver outputs will be enabled. If the PWM inputs change state before V_{BOOT} attains 10.8V, the driver outputs will not change and no driver Fault will be issued.

Fix/Work Around:

When setting CE = 1 from Standby mode, allow time for the V_{BOOT} capacitor to charge up to 10.8V. Typical time is 250 μ s.

Devices:

All

2. Module: PWM Pulse Width = Driver Dead-Time Pulse Width

When the PWM input pulse width is the same as the driver programmed dead time, a dead-time race condition may occur that forces both driver outputs to go low until both PWM inputs go low again. Normally, the PWM pulse width is longer than the dead time in order to generate an output pulse equal to PWM_PULSEWIDTH - DEAD TIME. However, some systems allow the PWM pulse width to be smaller than the driver dead time, knowing that there will be no driver output.

Fix/Work Around:

Set up host minimum PWM pulse width to be at least 50 ns larger or smaller than driver dead-time setting.

Devices:

All

3. Module: Motor Driver Lock

It has been detected that the motor driver may be locked after a momentary drop of V_{DD} below the minimum operating voltage or after enabling the driver output when using low V_{GS} threshold

MOSFETs ($V_{GS} < 1.1V$). The issue was traced back to the high-side driver operation at voltages below the minimum operating voltage.

Fix/Work Around:

None.

Devices:

MCP8026 – Date codes prior to YYWW = 1635

4. Module: External MOSFET DUVLO and OCP Detection

These detection functions could flag an inexistent motor driver undervoltage or power MOSFET overcurrent Fault when a DE2 message was sent to enable the functions while the motor was running.

Fix/Work Around:

Stop the motor before enabling the external MOSFET UVLO and OCP protection, and try to keep the blanking time as long as the motor application allows.

Devices:

MCP8025A – All date codes

MCP8026 – Date codes prior to YYWW = 1635

5. Module: External MOSFET DUVLO and OCP Fault

When a resistor is used in series with the VBx bootstrap pins, an external MOSFET undervoltage Fault and/or Overcurrent Protection Fault may occur. This is caused by the voltage drop across the resistor when the complementary driver transistors switch state. The switching overlap may draw enough current to lower the voltage long enough to trigger the Fault. Increasing the bootstrap capacitance and charge time will provide more energy storage.

Fix/Work Around:

When a series VBx bootstrap resistor is used with short duration OFF time duty cycles (< 8%), the value should be kept below 4 ohms.

Devices:

All

6. Module: Buck Overvoltage

It has been observed that the buck output voltage may exceed the target voltage for less than 1.5 ms, after power-up, under certain power-up scenarios. The issue is caused by an unintended current that may flow into the FB pin, causing an additional voltage drop across the resistor R1 (high-side of resistor divider), from the buck output to the FB pin. The overvoltage has only been observed on an application with no resistive load on the +5V LDO output to discharge the 5V LDO capacitor to 0V before the system is powered up again, but it cannot be excluded that other applications may also be affected.

Fix/Work Around:

The overvoltage will be minimized if the resistor selection for the low-side of the resistor voltage divider (R2) is 620 ohms or less. More information on R2 may be found in Section 5.1.3.3 "Setting the Buck Output Voltage" of the MCP8025A/6 Device Data Sheet (DS20005905).

Devices:

MCP8025A – Date codes prior to YYWW = 2240
MCP8026 – Date codes prior to YYWW = 2240

7. Module: Minimum Fault Clearing Pulse Width

It is detected that the minimum Fault clearing pulse-width parameter is too narrow for the CE pin input filter. The correct minimum Fault clearing pulse width is 4 μ s.

Fix/Work Around:

The host should generate a minimum Fault clearing pulse width of 4 μ s.

Devices:

All

8. Module: Start-up DE2 Message

A STAT1 message with the BORW bit set is sent one time by the MCP802X device upon start-up. The message is immediately sent when either the CE pin goes high or when the DE2 pin goes low. This may cause a collision with a host message.

Fix/Work Around:

Pulse the CE pin low-high-low at start-up before sending any messages to the MCP802X device. This triggers the MCP802X to send the BORW message and prevent any collision.

Devices:

All

9. Module: Buck Start-up Issue

It has been detected that when V_{DD} rises faster than 0.083 [V/ μ s], the driver could enter Sleep mode.

Fix/Work Around:

Keep V_{DD} slew rate slower than 0.083 [V/ μ s]. If this is not possible, the device could leave Sleep mode via the CE or LIN signals.

Devices:

All

10. Module: POR Triggered on Standby and V_{DD} Step-down

It has been detected that when having V_{DD} over the charge pump activation threshold – and then reducing V_{DD} back to below this value during standby mode – at the next CE activation the part will trigger a POR. This is caused by the CP capacitor charging with a voltage greater than the actual V_{DD} and in the next startup the part is trying to start the CP circuit. The CP2 pin is connected to V_{DD} before the CP1 connection to GND and the negative voltage applied may affect the internal circuitry. After 1-3 trials, the driver will start successfully.

Fix/Work Around:

Keep the V_{DD} constant during Standby mode (or an additional discharging circuit may be added on CP2 pin if it is required by the system).

It is recommended to keep the CP capacitor lower than 220 nF.

Devices:

MCP8025A – Date codes prior to YYWW = 2240
MCP8026 – Date codes prior to YYWW = 2240

APPENDIX A: REVISION HISTORY

Revision A (May 2023)

- Initial release of this document.

MCP8025A/6

NOTES:

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
 - Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
 - Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
 - Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable" Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.
-

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at <https://www.microchip.com/en-us/support/design-help/client-support-services>.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2023, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN: 978-1-6683-2393-9

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta
Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX
Tel: 512-257-3370

Boston
Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago
Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas
Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit
Novi, MI
Tel: 248-848-4000

Houston, TX
Tel: 281-894-5983

Indianapolis
Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453
Tel: 317-536-2380

Los Angeles
Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608
Tel: 951-273-7800

Raleigh, NC
Tel: 919-844-7510

New York, NY
Tel: 631-435-6000

San Jose, CA
Tel: 408-735-9110
Tel: 408-436-4270

Canada - Toronto
Tel: 905-695-1980
Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733

China - Beijing
Tel: 86-10-8569-7000

China - Chengdu
Tel: 86-28-8665-5511

China - Chongqing
Tel: 86-23-8980-9588

China - Dongguan
Tel: 86-769-8702-9880

China - Guangzhou
Tel: 86-20-8755-8029

China - Hangzhou
Tel: 86-571-8792-8115

China - Hong Kong SAR
Tel: 852-2943-5100

China - Nanjing
Tel: 86-25-8473-2460

China - Qingdao
Tel: 86-532-8502-7355

China - Shanghai
Tel: 86-21-3326-8000

China - Shenyang
Tel: 86-24-2334-2829

China - Shenzhen
Tel: 86-755-8864-2200

China - Suzhou
Tel: 86-186-6233-1526

China - Wuhan
Tel: 86-27-5980-5300

China - Xian
Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai
Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444

India - New Delhi
Tel: 91-11-4160-8631

India - Pune
Tel: 91-20-4121-0141

Japan - Osaka
Tel: 81-6-6152-7160

Japan - Tokyo
Tel: 81-3-6880-3770

Korea - Daegu
Tel: 82-53-744-4301

Korea - Seoul
Tel: 82-2-554-7200

Malaysia - Kuala Lumpur
Tel: 60-3-7651-7906

Malaysia - Penang
Tel: 60-4-227-8870

Philippines - Manila
Tel: 63-2-634-9065

Singapore
Tel: 65-6334-8870

Taiwan - Hsin Chu
Tel: 886-3-577-8366

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600

Thailand - Bangkok
Tel: 66-2-694-1351

Vietnam - Ho Chi Minh
Tel: 84-28-5448-2100

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4485-5910
Fax: 45-4485-2829

Finland - Espoo
Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching
Tel: 49-8931-9700

Germany - Haan
Tel: 49-2129-3766400

Germany - Heilbronn
Tel: 49-7131-72400

Germany - Karlsruhe
Tel: 49-721-625370

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Rosenheim
Tel: 49-8031-354-560

Israel - Ra'anana
Tel: 972-9-744-7705

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Padova
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Norway - Trondheim
Tel: 47-7288-4388

Poland - Warsaw
Tel: 48-22-3325737

Romania - Bucharest
Tel: 40-21-407-87-50

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Gothenberg
Tel: 46-31-704-60-40

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820