



## Product Change Notification / SYST-29LANR577

---

### Date:

30-Jan-2024

### Product Category:

32-Bit Microcontrollers

### PCN Type:

Document Change

### Notification Subject:

PIC32MK General Purpose and Motor Control GPG/MCJ with CAN FD Family Silicon Errata and Data Sheet Clarifications

### Affected CPNs:

[SYST-29LANR577\\_Affected\\_CPN\\_01302024.pdf](#)

[SYST-29LANR577\\_Affected\\_CPN\\_01302024.csv](#)

### Notification Text:

SYST-29LANR577

Microchip has released a new Document for the PIC32MK General Purpose and Motor Control GPG/MCJ with CAN FD Family Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at [PIC32MK General Purpose and Motor Control GPG/MCJ with CAN FD Family Silicon Errata and Data Sheet Clarifications](#).

**Notification Status:** Final

**Description of Change:** The following new Data Sheet Clarification was added: • Packaging

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 30 Jan 2024

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## Attachments:

[PIC32MK General Purpose and Motor Control GPG/MCJ with CAN FD Family Silicon Errata and Data Sheet Clarifications](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

PIC32MK0512MCJ064-E/R4X  
PIC32MK0512MCJ064-E/PT  
PIC32MK0512MCJ064-I/R4X  
PIC32MK0512MCJ064-I/PT  
PIC32MK0512MCJ064T-I/R4X  
PIC32MK0512MCJ064T-I/PT  
PIC32MK0512MCJ064T-E/R4X  
PIC32MK0512MCJ064T-E/PT  
PIC32MK0512MCJ048-E/7MX  
PIC32MK0512MCJ048-E/Y8X  
PIC32MK0512MCJ048-I/7MX  
PIC32MK0512MCJ048-I/Y8X  
PIC32MK0512MCJ048T-I/7MX  
PIC32MK0512MCJ048T-I/Y8X  
PIC32MK0512MCJ048T-E/7MX  
PIC32MK0512MCJ048T-E/Y8X  
PIC32MK0256MCJ048-E/7MX  
PIC32MK0256MCJ048-E/Y8X  
PIC32MK0256MCJ048-I/7MX  
PIC32MK0256MCJ048-I/Y8X  
PIC32MK0256MCJ048T-I/7MX  
PIC32MK0256MCJ048T-I/Y8X  
PIC32MK0256MCJ048T-E/7MX  
PIC32MK0256MCJ048T-E/7MXV01  
PIC32MK0256MCJ048T-E/Y8X  
PIC32MK0512GPG064-E/R4X  
PIC32MK0512GPG064-E/PT  
PIC32MK0512GPG064-I/R4X  
PIC32MK0512GPG064-I/PT  
PIC32MK0512GPG064T-I/R4X  
PIC32MK0512GPG064T-I/PT  
PIC32MK0512GPG064T-E/R4X  
PIC32MK0512GPG064T-E/PT  
PIC32MK0512GPG048-E/7MX  
PIC32MK0512GPG048-E/Y8X  
PIC32MK0512GPG048-I/7MX  
PIC32MK0512GPG048-I/Y8X  
PIC32MK0512GPG048T-I/7MX  
PIC32MK0512GPG048T-I/Y8X  
PIC32MK0512GPG048T-E/7MX  
PIC32MK0512GPG048T-E/Y8X  
PIC32MK0256GPG064-E/R4X  
PIC32MK0256GPG064-E/PT  
PIC32MK0256GPG064-I/R4X  
PIC32MK0256GPG064-I/PT  
PIC32MK0256GPG064T-I/R4X

PIC32MK0256GPG064T-I/PT  
PIC32MK0256GPG064T-E/R4X  
PIC32MK0256GPG064T-E/PT  
PIC32MK0256GPG048-E/7MX  
PIC32MK0256GPG048-E/Y8X  
PIC32MK0256GPG048-I/7MX  
PIC32MK0256GPG048-I/Y8X  
PIC32MK0256GPG048T-I/7MX  
PIC32MK0256GPG048T-I/Y8X  
PIC32MK0256GPG048T-E/7MX  
PIC32MK0256GPG048T-E/Y8X  
PIC32MK0256MCJ064-E/R4X  
PIC32MK0256MCJ064-E/PT  
PIC32MK0256MCJ064-I/R4X  
PIC32MK0256MCJ064-I/PT  
PIC32MK0256MCJ064T-I/R4X  
PIC32MK0256MCJ064T-I/PT  
PIC32MK0256MCJ064T-E/R4X  
PIC32MK0256MCJ064T-E/PT



# PIC32MK GPG/MCJ

## PIC32MK General Purpose and Motor Control GPG/MCJ with CAN FD Family Silicon Errata and Data Sheet Clarifications

### PIC32MK (GPG/MCJ) Family Errata

The PIC32MK family of devices that you have received conform functionally to the device data sheet, PIC32MK General Purpose and Motor Control (GPG/MCJ) with CAN FD Family Data Sheet (DS60001570C), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in the following table. The silicon issues are summarized in the Table of Contents following this section.

The errata described in this document will be addressed in future revisions of the PIC32MK family silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current.

**Table 1. PIC32MK Family Silicon Device Identification**

Part Number	Device Identification (DEVID[27:0])	Revision ID (DEVID[31:28])	
		A1	A2
PIC32MK0512MCJ064	0x6300053	0x1	0x2
PIC32MK0512MCJ048	0x6301053		
PIC32MK0256MCJ064	0x6304053		
PIC32MK0256MCJ048	0x6305053		
PIC32MK0512GPG064	0x6318053		
PIC32MK0512GPG048	0x6319053		
PIC32MK0256GPG064	0x631C053		
PIC32MK0256GPG048	0x631D053		

Data Sheet clarifications and corrections (if applicable) are located in [Data Sheet Clarifications](#), following the discussion of silicon issues.

## Table of Contents

PIC32MK (GPG/MCJ) Family Errata .....	1
1. Silicon Errata Issues Summary.....	3
2. Silicon Errata Issues.....	4
2.1. Oscillator.....	4
2.2. ADC.....	4
2.3. I <sup>2</sup> C.....	4
2.4. Flash.....	5
3. Data Sheet Clarifications.....	6
4. Revision History.....	7
The Microchip Web Site.....	8
Customer Change Notification Service.....	8
Customer Support.....	8
Microchip Devices Code Protection Feature.....	8
Legal Notice.....	9
Trademarks.....	9
Quality Management System Certified by DNV.....	9
Worldwide Sales and Service.....	10

## 1. Silicon Errata Issues Summary

The following errata issues are to be noted for the current device data sheet, PIC32MK General Purpose and Motor Control (GPG/MCJ) with CAN FD Family (DS60001570C).

**Table 1-1. Silicon Errata Summary**

Module	Feature	Item #	Issue Summary	Affected Revisions	
				A1	A2
Oscillator	Hardware Clock Source Selection	2.1.1	Clock source selection in hardware, that is, using the Fuse Configuration register (FNOSC <2:0> bits (DEVCFG1 <2:0>)) does not work.	X	
ADC	Scan mode	2.2.1	Shared ADC7 on high Offset and Gain Error in Scan mode.	X	
I <sup>2</sup> C	Speed	2.3.1	I <sup>2</sup> C Host module does not meet low period of the SCL Clock (t <sub>LOW</sub> ) parameter from I <sup>2</sup> C specification for clock frequency >= 400 kHz.	X	
I <sup>2</sup> C	Client	2.3.2	The 7-bit address that matches the 10-bit upper address value (111_10xx) is not accepted regardless of the STRICT bit setting.	X	
FLASH	RTSP	2.4.1	RTSP of Configuration Words is not functional.	X	X

## 2. Silicon Errata Issues

The following issues apply to the PIC32MK GPG/MCJ family of devices.

### Notes:

- An 'X' indicates the issue is present in this revision of silicon.
- Cells with a dash ('-') indicate that this silicon revision does not exist for this issue.
- Blank cells indicate an issue has been corrected or does not exist in this revision of silicon.

### 2.1 Oscillator

#### 2.1.1 Hardware Clock Source Selection

After a Brown-out Reset (BOR), the system clock source may default to FRC instead of the clock source defined using the Fuse Configuration register (FNOSC<2:0> bits (DEVCFG1<2:0>)).

#### Workaround:

Upon any reset, verify if the Current Clock Source Selection register (COSC<2:0> bits (OSCCON<14:12>)) match the clock source selected using the Fuse Configuration register (FNOSC<2:0> bits (DEVCFG1<2:0>)). If the clock sources do not match, perform a software clock switch to the desired clock source. For additional information on software clock switching, refer to Section 42. *Oscillators with Enhanced PLL (DS60001250)*, subsection 42.3.7.2 *Oscillator Switching Sequence* in the "PIC32 Family Reference Manual".

#### Affected Revisions:

A1	A2						
X							

### 2.2 ADC

#### 2.2.1 Scan Mode

Shared ADC 7 has high offset and gain error up to 38 LSB in ADC7 Scan mode, as defined in the ADCCSS1/ADCCSS2 registers.

#### Workaround:

Increase the user-defined SMAC<9:0> bits (ADCCON2<25:16>) sample time register value by 4  $T_{AD}$ . This will reduce the ADC7 throughput that the user must consider, but it will reduce the gain and offset to less than 4 LSB in 12-bit mode.

#### Affected Revisions:

A1	A2						
X							

### 2.3 I<sup>2</sup>C

#### 2.3.1 Speed

The I<sup>2</sup>C Host module does not meet low period of the SCL clock ( $t_{LOW}$ ) parameter from I<sup>2</sup>C specification for clock frequency  $\geq 400$  kHz.

#### Workaround:

None.



### Affected Revisions:

A1	A2						
X							

### 2.3.2 Client

The 7-bit address that matches the 10-bit upper address value (111\_10xx) is not accepted regardless of the STRICT bit setting.

#### Workaround:

None

### Affected Revisions:

A1	A2						
X							

## 2.4 Flash

### 2.4.1 RTSP

Run-Time Self Programming (RTSP) of Configuration Words is not functional.

#### Workaround:

None

### Affected Revisions:

A1	A2						
X	X						

### **3. Data Sheet Clarifications**

The following typographic corrections and clarifications are to be noted for the current device data sheet, PIC32MK General Purpose and Motor Control (GPG/MCJ) with CAN FD Family (DS60001570**C**), and are showed in **BOLD** type.

Currently there are no known issues to report.

## **4. Revision History**

### **Revision C - July 2022**

The SPI, I<sup>2</sup>S, and I<sup>2</sup>C standards use the terminology "Master" and "Slave". The equivalent Microchip terminology used in this document is "Host" and "Client" respectively. These terms have been updated throughout this document for this revision.

The following silicon errata issues were added:

- [FLASH: 2.4.1 RTSP](#)

### **Revision B - June 2020**

Addition of A1 silicon revision.

The following silicon errata issues were added:

- Oscillator: [2.1.1 Hardware Clock Source Selection](#)
- ADC Scan Mode
- I<sup>2</sup>C Speed Reference and I<sup>2</sup>C Client Reference

### **Revision A - May 2019**

This is the initial released version of this document.

## The Microchip Web Site

---

Microchip provides online support via our web site at [www.microchip.com/](http://www.microchip.com/). This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

## Customer Change Notification Service

---

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at [www.microchip.com/](http://www.microchip.com/). Under "Support", click on "Customer Change Notification" and follow the registration instructions.

## Customer Support

---

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Field Application Engineer (FAE)
- Technical Support

Customers should contact their distributor, representative or Field Application Engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

Technical support is available through the web site at: [www.microchip.com/support](http://www.microchip.com/support)

## Microchip Devices Code Protection Feature

---

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as "unbreakable."

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

## Legal Notice

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

## Trademarks

---

The Microchip name and logo, the Microchip logo, AnyRate, AVR, AVR logo, AVR Freaks, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, Helder, JukeBlox, KeeLoq, Klear, LANCheck, LINK MD, maXStylus, maXTouch, MediaLB, megaAVR, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, Prochip Designer, QTouch, SAM-BA, SpyNIC, SST, SST Logo, SuperFlash, tinyAVR, UNI/O, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

ClockWorks, The Embedded Control Solutions Company, EtherSynch, Hyper Speed Control, HyperLight Load, IntelliMOS, mTouch, Precision Edge, and Quiet-Wire are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, memBrain, Mindi, MiWi, motorBench, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQL, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2019, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-6683-0938-4

## Quality Management System Certified by DNV

---

### ISO/TS 16949

Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.

## Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
<b>Corporate Office</b> 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Fax: 480-792-7277 Technical Support: <a href="http://www.microchip.com/support">http://www.microchip.com/support</a> Web Address: <a href="http://www.microchip.com">www.microchip.com</a>	<b>Australia - Sydney</b> Tel: 61-2-9868-6733 <b>China - Beijing</b> Tel: 86-10-8569-7000 <b>China - Chengdu</b> Tel: 86-28-8665-5511 <b>China - Chongqing</b> Tel: 86-23-8980-9588 <b>China - Dongguan</b> Tel: 86-769-8702-9880 <b>China - Guangzhou</b> Tel: 86-20-8755-8029 <b>China - Hangzhou</b> Tel: 86-571-8792-8115 <b>China - Hong Kong SAR</b> Tel: 852-2943-5100 <b>China - Nanjing</b> Tel: 86-25-8473-2460 <b>China - Qingdao</b> Tel: 86-532-8502-7355 <b>China - Shanghai</b> Tel: 86-21-3326-8000 <b>China - Shenyang</b> Tel: 86-24-2334-2829 <b>China - Shenzhen</b> Tel: 86-755-8864-2200 <b>China - Suzhou</b> Tel: 86-186-6233-1526 <b>China - Wuhan</b> Tel: 86-27-5980-5300 <b>China - Xian</b> Tel: 86-29-8833-7252 <b>China - Xiamen</b> Tel: 86-592-2388138 <b>China - Zhuhai</b> Tel: 86-756-3210040	<b>India - Bangalore</b> Tel: 91-80-3090-4444 <b>India - New Delhi</b> Tel: 91-11-4160-8631 <b>India - Pune</b> Tel: 91-20-4121-0141 <b>Japan - Osaka</b> Tel: 81-6-6152-7160 <b>Japan - Tokyo</b> Tel: 81-3-6880-3770 <b>Korea - Daegu</b> Tel: 82-53-744-4301 <b>Korea - Seoul</b> Tel: 82-2-554-7200 <b>Malaysia - Kuala Lumpur</b> Tel: 60-3-7651-7906 <b>Malaysia - Penang</b> Tel: 60-4-227-8870 <b>Philippines - Manila</b> Tel: 63-2-634-9065 <b>Singapore</b> Tel: 65-6334-8870 <b>Taiwan - Hsin Chu</b> Tel: 886-3-577-8366 <b>Taiwan - Kaohsiung</b> Tel: 886-7-213-7830 <b>Taiwan - Taipei</b> Tel: 886-2-2508-8600 <b>Thailand - Bangkok</b> Tel: 66-2-694-1351 <b>Vietnam - Ho Chi Minh</b> Tel: 84-28-5448-2100	<b>Austria - Wels</b> Tel: 43-7242-2244-39 Fax: 43-7242-2244-393 <b>Denmark - Copenhagen</b> Tel: 45-4450-2828 Fax: 45-4485-2829 <b>Finland - Espoo</b> Tel: 358-9-4520-820 <b>France - Paris</b> Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79 <b>Germany - Garching</b> Tel: 49-8931-9700 <b>Germany - Haan</b> Tel: 49-2129-3766400 <b>Germany - Heilbronn</b> Tel: 49-7131-67-3636 <b>Germany - Karlsruhe</b> Tel: 49-721-625370 <b>Germany - Munich</b> Tel: 49-89-627-144-0 Fax: 49-89-627-144-44 <b>Germany - Rosenheim</b> Tel: 49-8031-354-560 <b>Israel - Ra'anana</b> Tel: 972-9-744-7705 <b>Italy - Milan</b> Tel: 39-0331-742611 Fax: 39-0331-466781 <b>Italy - Padova</b> Tel: 39-049-7625286 <b>Netherlands - Drunen</b> Tel: 31-416-690399 Fax: 31-416-690340 <b>Norway - Trondheim</b> Tel: 47-72884388 <b>Poland - Warsaw</b> Tel: 48-22-3325737 <b>Romania - Bucharest</b> Tel: 40-21-407-87-50 <b>Spain - Madrid</b> Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 <b>Sweden - Gothenberg</b> Tel: 46-31-704-60-40 <b>Sweden - Stockholm</b> Tel: 46-8-5090-4654 <b>UK - Wokingham</b> Tel: 44-118-921-5800 Fax: 44-118-921-5820
<b>Atlanta</b> Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455 <b>Austin, TX</b> Tel: 512-257-3370 <b>Boston</b> Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088 <b>Chicago</b> Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075 <b>Dallas</b> Addison, TX Tel: 972-818-7423 Fax: 972-818-2924 <b>Detroit</b> Novi, MI Tel: 248-848-4000 <b>Houston, TX</b> Tel: 281-894-5983 <b>Indianapolis</b> Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380 <b>Los Angeles</b> Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 <b>Raleigh, NC</b> Tel: 919-844-7510 <b>New York, NY</b> Tel: 631-435-6000 <b>San Jose, CA</b> Tel: 408-735-9110 Tel: 408-436-4270 <b>Canada - Toronto</b> Tel: 905-695-1980 Fax: 905-695-2078			