



## Product Change Notification / SYST-17AFLW716

---

### Date:

22-Jul-2024

### Product Category:

8-Bit Microcontrollers

### PCN Type:

Document Change

### Notification Subject:

PIC16(L)F18326/18346 Family Silicon Errata and Data Sheet Clarifications

### Affected CPNs:

[SYST-17AFLW716\\_Affected\\_CPN\\_07222024.pdf](#)

[SYST-17AFLW716\\_Affected\\_CPN\\_07222024.csv](#)

### Notification Text:

SYST-17AFLW716

Microchip has released a new Document for the PIC16(L)F18326/18346 Family Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at [PIC16\(L\)F18326/18346 Family Silicon Errata and Data Sheet Clarifications](#).

**Notification Status:** Final

**Description of Change:**

Added Silicon rev. A4.

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity.

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 22 Jul 2024

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## **Attachments:**

**PIC16(L)F18326/18346 Family Silicon Errata and Data Sheet Clarifications**

Please contact your local **Microchip sales office** with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our **PCN home page** select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the **PCN FAQ** section.

If you wish to change your PCN profile, including opt out, please go to the **PCN home page** select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

PIC16F18326-E/7NVAO  
PIC16F18326-E/P  
PIC16F18326-E/SL  
PIC16F18326-E/SLVAO  
PIC16F18326-E/ST  
PIC16F18326-E/STVAO-VW  
PIC16F18326-E/JQ  
PIC16F18326-E/JQVAO  
PIC16F18326-I/P  
PIC16F18326-I/SL  
PIC16F18326-I/ST  
PIC16F18326-I/JQ  
PIC16F18326T-I/7NV02  
PIC16F18326T-I/SL  
PIC16F18326T-I/ST  
PIC16F18326T-I/JQ  
PIC16F18326T-E/7NV05  
PIC16F18326T-E/7NV08  
PIC16F18326T-E/7NV08-BW  
PIC16F18326T-E/7NVAO  
PIC16F18326T-E/SLVAO  
PIC16F18326T-E/ST  
PIC16F18326T-E/STV01  
PIC16F18326T-E/STVAO  
PIC16F18326T-E/JQVAO  
PIC16LF18326-E/P  
PIC16LF18326-E/SL  
PIC16LF18326-E/ST  
PIC16LF18326-E/STVAO  
PIC16LF18326-E/JQ  
PIC16LF18326-E/JQVAO  
PIC16LF18326-I/P  
PIC16LF18326-I/SL  
PIC16LF18326-I/ST  
PIC16LF18326-I/JQ  
PIC16LF18326T-I/7N  
PIC16LF18326T-I/7NV03  
PIC16LF18326T-I/7NVAO  
PIC16LF18326T-I/SL  
PIC16LF18326T-I/ST  
PIC16LF18326T-I/JQ024  
PIC16LF18326T-I/JQ  
PIC16LF18326T-E/7NVAO  
PIC16LF18326T-E/STVAO  
PIC16LF18326T-E/JQVAO  
PIC16F18346-E/SS

PIC16F18346-E/SSV10  
PIC16F18346-E/SSVAO  
PIC16F18346-E/SO  
PIC16F18346-E/P  
PIC16F18346-E/GZ  
PIC16F18346-E/GZVAO  
PIC16F18346-I/SSC03  
PIC16F18346-I/SS  
PIC16F18346-I/SSVAO  
PIC16F18346-I/MLC01  
PIC16F18346-I/ML  
PIC16F18346-I/SO  
PIC16F18346-I/P  
PIC16F18346-I/PREL  
PIC16F18346-I/GZC01  
PIC16F18346-I/GZ  
PIC16F18346T-I/6NXV06  
PIC16F18346T-I/SSC03  
PIC16F18346T-I/SS  
PIC16F18346T-I/SSVAO  
PIC16F18346T-I/SSVAO-VW  
PIC16F18346T-I/MLC01  
PIC16F18346T-I/ML  
PIC16F18346T-I/MLV07  
PIC16F18346T-I/SO  
PIC16F18346T-I/GZC01  
PIC16F18346T-I/GZ  
PIC16F18346T-I/GZVAO  
PIC16F18346T-E/SS  
PIC16F18346T-E/SSV09  
PIC16F18346T-E/SSVAO  
PIC16F18346T-E/MLVAO  
PIC16F18346T-E/GZ  
PIC16LF18346-E/SS  
PIC16LF18346-E/SSVAO  
PIC16LF18346-E/SO  
PIC16LF18346-E/P  
PIC16LF18346-E/GZ  
PIC16LF18346-I/SS  
PIC16LF18346-I/SO  
PIC16LF18346-I/P  
PIC16LF18346-I/GZ  
PIC16LF18346T-I/SS  
PIC16LF18346T-I/SO  
PIC16LF18346T-I/GZ025  
PIC16LF18346T-I/GZ026  
PIC16LF18346T-I/GZ  
PIC16LF18346T-E/SS  
PIC16LF18346T-E/SSVAO

PIC16LF18346T-E/MLVAO

PIC16LF18346T-E/GZ

PIC16LF18346T-E/GZVAO

## PIC16(L)F18326/18346 Family Silicon Errata and Data Sheet Clarifications

The PIC16(L)F18326/18346 family devices that you have received conform functionally to the current device data sheet (DS40001839F), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).


The errata described in this document will be addressed in future revisions of the PIC16(L)F18326/18346 silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (**A4**).

Data Sheet clarifications and corrections start on [page 5](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate website ([www.microchip.com](http://www.microchip.com)).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. For MPLAB X IDE, select *Window > Dashboard* and click the **Refresh Debug Tool Status** icon (  ).
5. Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

**Note:** If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC16(L)F18326/18346 silicon revisions are shown in [Table 1](#).

**TABLE 1: SILICON DEVREV VALUES**

Part Number	Device ID <sup>(1)</sup>	Revision ID for Silicon Revision <sup>(2)</sup>			
		A1	A2	A3	A4
PIC16F18326	30A4h	2001h	2002h	2003h	2003h
PIC16LF18326	30A6h	2001h	2002h	2003h	2003h
PIC16F18346	30A5h	2001h	2002h	2003h	2003h
PIC16LF18346	30A7h	2001h	2002h	2003h	2003h

**Note 1:** The Device IDs (DEVID and DEVREV) are located at addresses 8006h and 8005h, respectively. They are shown in hexadecimal in the format "DEVID DEVREV".

- 2:** Refer to the "PIC16(L)F183XX Memory Programming Specification" (DS40001738) for detailed information on Device and Revision IDs for your specific device.

**TABLE 2: SILICON ISSUE SUMMARY**

Module	Feature	Item Number	Issue Summary	Affected Revisions <sup>(1)</sup>			
				A1	A2	A3	A4
Oscillators	Fail-Safe Clock Monitor (FSCM)	1.1	The FSCM may fail to trigger with 4x PLL enabled.	X			
Host Synchronous Serial Port Module (MSSP2)	I <sup>2</sup> C Communication	2.1	Acknowledge failure on LF devices only.	X			
Electrical Specifications	VDD Parameter	3.1	VDDMIN specifications are changed for LF devices only.	X	X	X	X
	ADC Offset Error	3.2	ADC Offset Error specification changed.	X	X	X	X
	FVR Accuracy	3.3	FVR output voltage may be higher than specified in the data sheet.	X	X	X	X

**Note 1:** Only those issues indicated in the last column apply to the current silicon revision.

## Silicon Errata Issues

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (**A4**).

### 1. Module: Oscillators

#### 1.1 Fail-Safe Clock Monitor (FSCM)

The Fail-Safe Clock Monitor may fail to trigger with the loss of the external clock signal when the 4x PLL is enabled. This includes all external clock modes: LP, XT, HS, ECL, ECM and ECH.

##### Work around

None.

##### Affected Silicon Revisions

A1	A2	A3	A4				
X							

### 2. Module: Host Synchronous Serial Port Module (MSSP2)

#### 2.1 I<sup>2</sup>C Communication

When using the MSSP2 to perform I<sup>2</sup>C communication and the voltage for VDD is above 3.0 volts, the Acknowledge signal (ACK) does not always occur after the second address byte is received, as expected. This issue exhibits itself when the MSSP2 is configured either for 7-bit or 10-bit addressing and in either Host or Client mode.

The issue occurs more frequently when using 10-bit addressing in Client mode and the lower address bits (A7-A0) are transmitted by the Host on the SDA line.

##### Work around

Do not exceed 3.0 volts on VDD when using LF device.

##### Affected Silicon Revisions

A1	A2	A3	A4				
X							



## 3. Module: Electrical Specifications

### 3.1 VDD Parameter

VDDMIN at -40°C to +25°C = 2.3V.

#### Work around

None.

#### Affected Silicon Revisions

A1	A2	A3	A4				
X	X	X	X				

**TABLE 3: SUPPLY VOLTAGE**

PIC16LF18326/18346			Standard Operating Conditions (Unless Otherwise Stated)				
Param. No.	Sym.	Characteristic	Min.	Typ.†	Max.	Units	Conditions
D002	VDD		1.8	—	3.6	V	Fosc ≤ 16 MHz, +25°C < TA ≤ +125°C
D002	VDD		2.3	—	3.6	V	Fosc ≤ 16 MHz, -40°C ≤ TA ≤ +25°C
			2.5	—	3.6	V	Fosc > 16 MHz

### 3.2 ADC Offset Error

The table containing the Offset Error specification (AD04:E0FF) for the Analog-to-Digital Converter is modified. The updated value for Offset Error specification is +/- 3.0 LSB.

#### Work around

None.

#### Affected Silicon Revisions

A1	A2	A3	A4				
X	X	X	X				

### 3.3 Fixed Voltage Reference (FVR) Accuracy

At temperatures below -20°C, the output voltage for the FVR may be greater than the levels specified in the data sheet. This will apply to all three gain amplifier settings (1X, 2X, 4X). The affected parameter numbers found in the data sheet are:

- FVR01 (1X gain setting)
- FVR02 (2X gain setting)
- FVR03 (4X gain setting)

#### Work around

None.

#### Affected Silicon Revisions

A1	A2	A3	A4				
X	X	X	X				

## Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS40001839F):

<b>Note:</b> Corrections are shown in <b>bold</b> . Where possible, the original bold text formatting has been removed for clarity.
-------------------------------------------------------------------------------------------------------------------------------------

None.

## **APPENDIX A: DOCUMENT REVISION HISTORY**

### **Rev G Document (07/2024)**

Added Silicon rev. A4.

### **Rev F Document (09/2021)**

Added Silicon issue 3.3 FVR Accuracy.

### **Rev E Document (11/2020)**

Updated Table 2; added Table 3 and Section 3.2 ADC Offset Error.

### **Rev D Document (01/2020)**

Added Silicon rev. A3.

Data Sheet Clarifications:

Removed Modules 1 and 2 (Data Sheet updated).

### **Rev C Document (01/2017)**

Silicon Errata Issues:

Added Silicon rev. A2.

Data Sheet Clarifications:

Changed Module 1 Memory to Analog-to-Digital.

### **Rev B Document (01/2017)**

Data Sheet Clarifications:

Added Module 2: Comparator.

### **Rev A Document (08/2016)**

Initial release of this document.

---

**Note the following details of the code protection feature on Microchip products:**

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
  - Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
  - Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
  - Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable" Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.
- 

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at <https://www.microchip.com/en-us/support/design-help/client-support-services>.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

For information regarding Microchip's Quality Management Systems, please visit [www.microchip.com/quality](http://www.microchip.com/quality).

**Trademarks**

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleeer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricon, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, TimeCesium, TimeHub, TimePictra, TimeProvider, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, EyeOpen, GridTime, IdealBridge, iGAT, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, MarginLink, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, mSiC, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, Power MOS IV, Power MOS 7, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, Turing, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2024, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN: 978-1-6683-4903-8

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Austin, TX**  
Tel: 512-257-3370

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Novi, MI  
Tel: 248-848-4000

**Houston, TX**  
Tel: 281-894-5983

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453  
Tel: 317-536-2380

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608  
Tel: 951-273-7800

**Raleigh, NC**  
Tel: 919-844-7510

**New York, NY**  
Tel: 631-435-6000

**San Jose, CA**  
Tel: 408-735-9110  
Tel: 408-436-4270

**Canada - Toronto**  
Tel: 905-695-1980  
Fax: 905-695-2078

### ASIA/PACIFIC

**Australia - Sydney**  
Tel: 61-2-9868-6733

**China - Beijing**  
Tel: 86-10-8569-7000

**China - Chengdu**  
Tel: 86-28-8665-5511

**China - Chongqing**  
Tel: 86-23-8980-9588

**China - Dongguan**  
Tel: 86-769-8702-9880

**China - Guangzhou**  
Tel: 86-20-8755-8029

**China - Hangzhou**  
Tel: 86-571-8792-8115

**China - Hong Kong SAR**  
Tel: 852-2943-5100

**China - Nanjing**  
Tel: 86-25-8473-2460

**China - Qingdao**  
Tel: 86-532-8502-7355

**China - Shanghai**  
Tel: 86-21-3326-8000

**China - Shenyang**  
Tel: 86-24-2334-2829

**China - Shenzhen**  
Tel: 86-755-8864-2200

**China - Suzhou**  
Tel: 86-186-6233-1526

**China - Wuhan**  
Tel: 86-27-5980-5300

**China - Xian**  
Tel: 86-29-8833-7252

**China - Xiamen**  
Tel: 86-592-2388138

**China - Zhuhai**  
Tel: 86-756-3210040

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444

**India - New Delhi**  
Tel: 91-11-4160-8631

**India - Pune**  
Tel: 91-20-4121-0141

**Japan - Osaka**  
Tel: 81-6-6152-7160

**Japan - Tokyo**  
Tel: 81-3-6880-3770

**Korea - Daegu**  
Tel: 82-53-744-4301

**Korea - Seoul**  
Tel: 82-2-554-7200

**Malaysia - Kuala Lumpur**  
Tel: 60-3-7651-7906

**Malaysia - Penang**  
Tel: 60-4-227-8870

**Philippines - Manila**  
Tel: 63-2-634-9065

**Singapore**  
Tel: 65-6334-8870

**Taiwan - Hsin Chu**  
Tel: 886-3-577-8366

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600

**Thailand - Bangkok**  
Tel: 66-2-694-1351

**Vietnam - Ho Chi Minh**  
Tel: 84-28-5448-2100

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4485-5910  
Fax: 45-4485-2829

**Finland - Espoo**  
Tel: 358-9-4520-820

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Garching**  
Tel: 49-8931-9700

**Germany - Haan**  
Tel: 49-2129-3766400

**Germany - Heilbronn**  
Tel: 49-7131-72400

**Germany - Karlsruhe**  
Tel: 49-721-625370

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Rosenheim**  
Tel: 49-8031-354-560

**Israel - Hod Hasharon**  
Tel: 972-9-775-5100

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Padova**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Norway - Trondheim**  
Tel: 47-7288-4388

**Poland - Warsaw**  
Tel: 48-22-3325737

**Romania - Bucharest**  
Tel: 40-21-407-87-50

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Gothenberg**  
Tel: 46-31-704-60-40

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820