


MULTITURN BUSHING MOUNT POTENTIOMETER

CONTACT WIRE WOUND ANGLE SENSOR

HP-18 series

RoHS compliant



FEATURES

- Contact Wire Wound Angle Sensor (Multi-turns Sensor)
- Effective Electrical Travel : 3600° (10-turns)
- Independent Linearity : $\pm 0.25\%$
- Bushing Mount
- This unit is used with counting dial D-12, H-22, H-46 and DM-15

MATERIAL

- Housing : Nylon, Copper Alloy
- Shaft : Stainless Steel

STANDARD SPECIFICATIONS

Electrical characteristics

| | |
|---------------------------------------|--------------------------------|
| Effective Electrical Travel | 3600° |
| Total Resistance Tolerance | $\pm 5\%$ |
| Independent Linearity | $\pm 0.25\%$ |
| Rated Dissipation | 2 W (40°C) |
| Insulation Resistance | 1000 M Ω min. / 500 VDC |
| Dielectric Strength | 1500 VAC/1 Minute |
| Temperature Coefficient of Resistance | 50 ppm/K max. |
| End Output Voltage | 0.1% max. |
| Equivalent Noise Resistance | 100 Ω max. |

Mechanical characteristics

| | |
|-------------------------|--------------------|
| Total Mechanical Travel | 3600 ± 10 , 0° |
| Torque | 8.5 mN·m max. |
| Net weight | Approx. 19 g |
| Stoper Strength | 450 mN·m min. |
| Bucklash | 1° max. |


TOTAL RESISTANCE

| Total Resistance | Resolution | Input Voltage |
|------------------|------------|---------------|
| 1 k Ω | 0.029% | 40 V (40°C) |
| 2 k Ω | 0.023% | 60 V (40°C) |
| 5 k Ω | 0.025% | 80 V (40°C) |
| 10 k Ω | 0.020% | 100 V (40°C) |
| 20 k Ω | 0.019% | 150 V (40°C) |


HP-18

POTENTIOMETERS

■ OUTPUT CHARACTERISTICS




■ SCHEMATIC



■ OUTLINE DIMENSIONS

(Unit:mm)



<Accessories>

M9 Nut, Internal toothed lock washer
1 piece each

■ HANDLING INSTRUCTION

- Winding resistance may oxidize and cause sliding noise even if this sensor is unused for a long time.
- Miswiring might cause burnout of the resistive element.
- To reduce sliding noise, the load resistance should be more than 100 times and less than 1000 times of the total resistance.
- Slight continuous vibration such as dither might cause the lifetime of the sensor.
- To avoid damage to the stopper, do not rotate the shaft at the end with excessive force.