

Piezo Vibration Sensors VS Series


Application Note

***Patrik Kalbermatten, Associate Director, Tokyo
MSA PBU
YAGEO GROUP***




Classification of Vibration Sensors

- A vibration sensor is a sensor that measures the periodic movement of an object.
- Vibration sensors are roughly classified into three types: displacement sensor, velocity sensor, and acceleration sensor.




Frequency Range of Vibration Sensors

- Accelerometers are attracting attention, especially in the high frequency range, for monitoring mechanical vibrations.






Principle of Piezoelectric Vibration Sensors

- The piezoelectric effect is a phenomenon in which an electric field is generated when mechanical energy is applied to ceramics.



Types of Piezoelectric Vibration Sensors

- Piezoelectric vibration sensors are roughly divided into three types of structures.
- Each has its own characteristics and can be used according to the purpose.
- KEMET uses a bending type.

Bending Type	Share Type	Compressed Type
		
<ul style="list-style-type: none"> • Small size • High sensitivity • Simple structure 	<ul style="list-style-type: none"> • Small effect of external noise 	<ul style="list-style-type: none"> • High strength • High resonance frequency and high sensitivity
<ul style="list-style-type: none"> • Low resonance frequency 	<ul style="list-style-type: none"> • Complex structure • Difficult to reduce height 	<ul style="list-style-type: none"> • Susceptible to external noise

Features of KEMET Vibration Sensors

- Vibration in a wide frequency band can be collected in real time with high sensitivity.

Proprietary Technology

- Composition optimization of ceramic materials
- Mechanism to increase vibration




Features

- High sensitivity and wide frequency band
- Voltage output through the built-in amplifier
- Small size and low profile


Achieves high sensitivity and wide frequency band

Detection Acceleration Area



Example of Measurement Environment


- Monitor the status of FA equipment and structures on the network and perform "visualization".



Sensor Mounting Location

- The frequency performance of the sensor is highly dependent on the method of installation.


Object to be Measured: Motor



NOT OK



Curved surface



Uneven surface



Foreign matter
pinched

* In this case, it may affect the frequency characteristics.



OK




Flat surface

How to Attach the Sensor?


- The frequency performance of the sensor is highly dependent on the method of installation.
- Select the fixing method according to the measurement frequency.




Magnet on uneven surface




Magnet on flat surface



Thin double-sided tape




Screw fixing



If you need to measure up to high frequency, we recommend fixing with screws.

How to Wire Cables?


- Please use the following with caution in order to obtain correct measurement and stable data.
 - Secure the cables at appropriate intervals to minimize cable vibration.
 - Select the cable layout and fixing so that tension is not applied.
 - Do not bend the cable more than necessary (keep the minimum bending radius).



Displacement, Velocity and Acceleration

- The relationship between displacement, velocity and acceleration changes with frequency.
 - The higher the frequency, the easier it is to measure because the same displacement produces higher velocities and accelerations.
 - Acceleration sensor is suitable for high frequency measurement such as motor.

Displacement



Let $[x]$ be the displacement at a certain time $[t]$.

Displacement	$x = A \sin(\omega t)$
---------------------	------------------------


Speed	$v = x' = A \cdot 2 \pi f \cdot \cos(\omega t)$
--------------	---

Acceleration	$v = x'' = -A \cdot (2 \pi f)^2 \cdot \sin(\omega t)$
---------------------	---


$\omega = \text{angular frequency (Hz)} = 2 \pi f$

$f = \text{vibration frequency (Hz)}$

Connection Example with VS-JV Type



Connection Example



- Connect to SG when FG and SG separation is not required.
- When separating FG and SG, open or connect to FG.
- When separating, please consider noise when connecting.

When Measuring Vibrations?

① Is offset voltage (~1.5 V) present?

- In normal conditions you should see 1.5V output.
- Tap the area around the sensor and you should see AC waveform representing mechanical stimulus.

② If no offset voltage present?


- Tap the area around the sensor, expect to see AC waveform representing mechanical input stimulus.
- If no AC waveform present, check data logger and connector (confirm good connection).
- If AC waveform present but no DC offset, check settings of data logger.

③ Is there any power supply noise?


- If a large output is generated at 0/60 Hz during connection, it is considered that power supply noise is superimposed.
- Noise varies greatly depending on the operating environment, so consider ground connection in advance.

- The connection of the shielded wire has a large effect, so check it carefully (SG, FG, floating, etc.).


Waveform Checkpoint



FFT Example of Vibration Sensor



Connection Checkpoint



Temperature Characteristics


Vibration Sensor VS-JV10A

Applied waveform:

Sin 1 kHz / 0.1 V

Measuring instrument:


DS2000 / onosokki



Typical example

Connection Diagram for VS-JV10A

Sensor



Cable




M8 JACK

Lead Wire



Standard PN: VSC-030PURS4-M8D-01

Lead Wire



DC Power Supply 5 V

- Stabilized power supply, etc.
- Current consumption: approx. 0.35 mA.
- If the power supply is unstable, please insert a smoothing.
- Capacitor (about 100 μ F) between Vin and GND.

Measuring Equipment

- FFT, oscilloscope, A/D (\rightarrow PC), etc.
- ※ or terminate with 100 k Ω or more


Pin Assignment

Pin Assignment	Symbol	Function
1	V_{IN}	Power input
2	V_{OUT}	Sensor output
3	SG	Signal ground
4	N.C.	N/A

Connection

Pin Assignment	Wire Color	Symbol	Function ¹
1	Brown	V_{IN}	Power input
2	White	V_{OUT}	Sensor output
3	Blue	SG	Signal ground
4	Black	N.C.	N/A
Other conductor	Shield	FG	Frame ground

Output Example for VS-JV10A



- When the vibration sensor receives vibration, it outputs a voltage proportional to the amount of vibration.
- The acceleration value is obtained based on the offset voltage.
For example, if an instantaneous value is 2 V,


Output voltage: $2 - 1.5 = 0.5$ (V)

Multiplying that value by the sensitivity gives the resulting acceleration.


Acceleration: $0.5 / 0.01 = 50$ (m/s^2)

Sensitivity: 10 mV (mV/m/s^2)

Connection Diagram for VS-BV203-B




Pin Assignment



※ Connector: **SHR-03V-S-B**

Output Example for **VS-BV203-B**



When the vibration sensor receives vibration, it outputs a voltage proportional to the amount of vibration.

The acceleration value is obtained based on the offset voltage.

For example, if an instantaneous value is 2V,

Output voltage: $2 - 1.65 = 0.35 \text{ (V)}$


Multiplying that value by the sensitivity gives the resulting acceleration.

Acceleration: $0.35 / 0.02 = 17.5 \text{ (m/s}^2\text{)}$


Sensitivity: $20 \text{ mV (mV/m/s}^2\text{)}$


Measurement Example ① Pump

- We measured the vibration waveforms of two pumps with different operating sounds.
- A difference was found in the vibration waveform between the two pumps.
- Since vibration is large at high frequencies, the worn part of the bearing may have deteriorated.




- Measure two pumps with different operating sounds.






Measurement Example ② Motor

- While driving the motor, loosen the fixed part of the bearing.
- Many peaks occur around 500 Hz to 1 kHz.
- There was a difference in the vibration level in a specific frequency band.




FFT Analysis



Measurement Example ③ Bearing


- Comparison of waveforms with and without bearing ball damage.




The general usage is to set the threshold value based on the output difference between normal and abnormal equipment.

Time Axis
FFT Waveform

Normal Bearing



Abnormal Bearing



Measurement Example ④ Fan

- The vibration of the air supply / exhaust fan was measured for half a year.
- By using VB-2405B, it is possible to measure even at a low sampling frequency.


Air Supply / Exhaust Fan

Measurement Condition

Measurement interval: 2 hrs

Sampling: 0.441 ms

One measurement time: about 3.5s



Constitution Sensor

Connection unit

Sequencer



Magnet fixing



Equipment Used


Sensor VS-JV10A

Magnet VM-03


Cable VSC-100PURS4-M8D-01

Connection unit VB-2405B


Sequencer analog unit FX Series



Examples of Damage to Rotating Machines






Fast Fourier Transform (FFT) Output



Frequency Band (Hz)	Damaged Part	Damage Details	Detection Sensor
3k~10k	Bearing	Abrasion, burnout	Vibration , acoustic sound, heat
1k~5k	Gear	Missing tooth, gears do not mesh	Vibration , acoustic
50~200	Coupling	Misalignment	Vibration , heat
30~100	Rotating equipment	Unbalance	Vibration
10~50	Fixed base	Rattle, loose fixing bolt	Vibration

Product Lineup

Part Number		Acceleration Measuring Range
VS-JV10A		$\pm 100 \text{ m/s}^2$ maximum 10 mV/m/s ² sensitivity
VS-JV02A		$\pm 500 \text{ m/s}^2$ maximum 2 mV/m/s ² sensitivity
VS-BV203-B <i>with cable integrated</i>		$\pm 50 \text{ m/s}^2$ maximum 20 mV/m/s ² sensitivity

Accessories

- Cable VSC-100PURS4-M8D-01



- Magnet base VM-03



- Attachment VA-01



VS-JV Evaluation Kits

VS-JV02A-K01

or

VS-JV10A-K01



VS-JV02A-K03

or


VS-JV10A-K03



VS-JV02A-K02

or

VS-JV10A-K02



VS-JV02A-K04

or

VS-JV10A-K04

