



## Product Change Notification - SYST-19TQDD495

---

**Date:**

20 Nov 2018

**Product Category:**

USB Hubs

**Affected CPNs:****Notification subject:**

ERRATA - USB253x/USB3x13/USB46x4 Silicon Errata and Data Sheet Clarification

**Notification text:**

SYST-19TQDD495

Microchip has released a new DeviceDoc for the USB253x/USB3x13/USB46x4 Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [USB253x/USB3x13/USB46x4 Silicon Errata and Data Sheet Clarification](#).

**Notification Status:** Final

**Description of Change:** Added new erratum 15.

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 20 Nov 2018

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

**Attachment(s):**

[USB253x/USB3x13/USB46x4 Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

**Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

USB2532-1080AEN  
USB2532-1080AEN-TR  
USB2532-1081AEN  
USB2532-1081AEN-TR  
USB2532I-1080AEN  
USB2532I-1080AENTR  
USB2532I-1081AEN  
USB2532I-1081AEN-TR  
USB2533-1080AEN  
USB2533-1080AEN-TR  
USB2533-1081AEN  
USB2533-1081AEN-TR  
USB2533I-1080AEN  
USB2533I-1080AENTR  
USB2533I-1081AEN  
USB2533I-1081AEN-TR  
USB2534-1050AEN  
USB2534-1050AEN-TR  
USB2534-1051AEN  
USB2534-1051AEN-TR  
USB2534-1080AEN  
USB2534-1080AEN-TR  
USB2534-1081AEN  
USB2534-1081AEN-TR  
USB2534I-1050AEN  
USB2534I-1050AENTR  
USB2534I-1051AEN  
USB2534I-1051AEN-TR  
USB2534I-1080AEN  
USB2534I-1080AENTR  
USB2534I-1081AEN  
USB2534I-1081AEN-TR  
USB3613-1080XY-TR  
USB3613-1081XY-TR  
USB3613I-1080XY-TR  
USB3613I-1081XY-TR  
USB3813-1080XY-TR  
USB3813-1081XY-TR  
USB3813I-1080XY-TR  
USB3813I-1081XY-TR  
USB4604-1051HN  
USB4604-1051HN-TR  
USB4604-1070HN  
USB4604-1070HN-TR  
USB4604-1080HN  
USB4604-1080HN-TR

USB4604-1081HN  
USB4604-1081HN-TR  
USB4604I-1051HN  
USB4604I-1051HN-TR  
USB4604I-1070HN  
USB4604I-1070HN-TR  
USB4604I-1080HN  
USB4604I-1080HN-TR  
USB4604I-1081HN  
USB4604I-1081HN-TR  
USB4624-1051HN-TR  
USB4624-1070HN  
USB4624-1070HN-TR  
USB4624-1080HN  
USB4624-1080HN-TR  
USB4624-1081HN  
USB4624-1081HN-TR  
USB4624I-1051HN  
USB4624I-1051HN-TR  
USB4624I-1070HN  
USB4624I-1070HN-TR  
USB4624I-1080HN  
USB4624I-1080HN-TR  
USB4624I-1081HN  
USB4624I-1081HN-TR



# USB253x/USB3x13/USB46x4

## Silicon Errata and Data Sheet Clarification

This document describes known silicon errata for the USB253x/USB3x13/USB46x4 family of devices, which includes the following:

- USB2532
- USB2533
- USB2534
- USB3613
- USB3813
- USB4604
- USB4624

A summary of USB253x/USB3x13/USB46x4 silicon errata and the affected revisions is provided in [Table 1](#).

**TABLE 1: SILICON ISSUE SUMMARY**

Item Number	Silicon Issue Summary	Affected Revisions
1.	<a href="#">Minor Current Spike when Hibernating or Entering S3 Suspend</a>	All
2.	<a href="#">Upstream Battery Charger Detection</a>	All
3.	<a href="#">VDD33 Output Voltage</a>	All
4.	<a href="#">SE1 Super High Current Voltage Level Lower than Specification</a>	All
5.	<a href="#">SE1 Super High Current Comparator</a>	All
6.	<a href="#">SE1 Charger Detection</a>	All
7.	<a href="#">High Speed Split Transactions to Full Speed Endpoints</a>	All
8.	<a href="#">Microchip UCS100x Usage</a>	All
9.	<a href="#">LPM Compatibility with Port Remap and Port Disable</a>	All
10.	<a href="#">USB Device Reconnection Error in Windows 8 and Windows Server 2013</a>	All
11.	<a href="#">Hub fails USBCV Chapter 9 test 9.21</a>	-1080, -1070, -1050
12.	<a href="#">Hub fails EL_42 SYNC Truncation</a>	-1080, -1070, -1050
13.	<a href="#">Hub Startup Timing</a>	All
14.	<a href="#">Repeating byte pattern may cause bit loss</a>	All
15.	<a href="#">FlexConnect via SMBus enumeration issue</a>	USB2532, USB2533, USB2534

# USB253x/USB3x13/USB46x4

---

## Silicon Errata Issues

### Module 1: Minor Current Spike when Hibernating or Entering S3 Suspend

#### DESCRIPTION

When some hosts enter suspend, the VBUS voltage will slowly decay rather than completely shutting off. This decay can cause the VBUS detection input to oscillate when the VBUS voltage hovers near the digital threshold. The USB253x/USB3x13/USB46x4 will then exit the suspend state and draw typical configured current until the 3ms of inactivity on the DP/DM pins will place the device back into suspend.

#### END USER IMPLICATIONS

There may be a temporary increase in the current consumption after the end users device has entered suspend mode.

#### Work Around

Since this issue is based on the decay of the host systems' VBUS, the Device can do nothing to prevent this. This is a temporary condition based on the VBUS voltage and the voltage divider resistances used, lower resistances can reduce the time of this occurrence but not remove it completely.

#### PLAN

This erratum is not planned to be corrected in a future revision.

### Module 2: Upstream Battery Charger Detection

#### DESCRIPTION

The USB253x/USB3x13/USB46x4 requires a device reset to restart upstream battery charger detection. This can be done by toggling RESET\_B.

#### END USER IMPLICATIONS

If the self powered device detects one type of charger, and then connects to another type of charger without restarting the USB253x/USB3x13/USB46x4, the device will not update the battery charger detection register.

#### Work Around

If using the battery charger detection feature the RESET\_N pin must be driven low when VBUS is not present and driven high when VBUS is detected. This will help conserve power by putting the Hub into the STANDBY state and it will ensure that the charger detection will update at every plug-in.

#### PLAN

This erratum is not planned to be corrected in a future revision.

# USB253x/USB3x13/USB46x4

---

## Module 3: VDD33 Output Voltage

### DESCRIPTION

When the USB253x/USB3x13/USB46x4 draws ~150mA of current in single supply VBAT mode, the voltage on VDD33 can drop below 2.8V when VBAT is 2.9V at 85C. This voltage is used as the Full Speed pull up reference and the reference supply for other analog blocks.

### END USER IMPLICATIONS

The end user could experience problems with Full Speed communication using 5m cables and long PCB traces. This is an uncommon occurrence and would only happen if the other ports were running full traffic at a rate to consume >150mA of current.

#### Work Around

The USB253x/USB3x13/USB46x4 only draws >150mA of current during high traffic transmission of High Speed data on the downstream ports. Reduce the cable length, or set VBAT to 3V or higher.

### PLAN

This erratum is not planned to be corrected in a future revision.

## Module 4: SE1 Super High Current Voltage Level Lower than Specification

### DESCRIPTION

When a downstream port has battery charging enabled in High Current or Super High Current charging mode, the voltages of the 2.0V and 2.7V outputs can be ~20mV less than the minimum inferred from the *iPod Accessory Protocol Standard Specification r32*. The minimum is calculated from the 5V+/-10% supply combined with a 75k/49.9k+/-1% voltage divider, giving 1.77V and 2.39V. This can occur when VBAT is 2.9V at 85C temperatures.

### END USER IMPLICATIONS

An external device may not charge at the maximum current when the system when VBAT is 2.9V.

#### Work Around

VBAT must be greater than 3.0V if this feature is used.

### PLAN

This erratum is not planned to be corrected in a future revision.

## Module 5: SE1 Super High Current Comparator

### DESCRIPTION

The USB253x/USB3x13/USB46x4 comparator was tested to have a minimum detection threshold of 600mV at low voltages and the 85C temperature range. This is greater than the 550mV potential difference between DP and DM in high current chargers.

### END USER IMPLICATIONS

The USB253x/USB3x13/USB46x4 could report the wrong type of charger if the charger DP voltage is at the maximum level of the 2V specification and the DM voltage is at the minimum level of the 2.7V specification.

#### Work Around

There is no known workaround.

### PLAN

This erratum is not planned to be corrected in a future revision.

# USB253x/USB3x13/USB46x4

---

## Module 6: SE1 Charger Detection

### DESCRIPTION

Voltages above 2.23V on both DP and DM can cause the charger detect algorithm to detect the wrong type of charger. This is because the USB4604/USB4624 and USB3813 also use the DP/DM voltage levels at startup to disable the ports.

### END USER IMPLICATIONS

A wide variety of SE1 chargers were tested with the USB4604/USB4624 and USB3813 without any issue. At startup weak 15k resistors are used prevent this issue from happening, but if the voltages on DP and DM are driven with stronger drivers that overcome the 15k pull down resistors the upstream port could be disabled at POR, or the upstream battery charger detection state machine could return the wrong data.

#### **Work Around**

If battery charger detection is enabled on the USB4604/USB4624 or USB3813, Microchip recommends that the hub be powered and out of standby before a charger is connected. If operating in SMBus Slave mode, the charger detection can be restarted any time during the SOC configuration stage.

### PLAN

This erratum is not planned to be corrected in a future revision.

## Module 7: High Speed Split Transactions to Full Speed Endpoints

### DESCRIPTION

If a High Speed split transaction exceeds 288 bytes per microframe to a single downstream port the Transaction Translator of the USB253x/USB3x13/USB46x4 can be corrupted if another HS data packet is sent before the Full Speed packets downstream have completed.

### END USER IMPLICATIONS

The corrupted data would be caught by the USB error checks in most applications causing the host to resend the data to the device, so it would not be noticed by the end user. But if the data is not checked by the device, and streamed to a speaker for example, the corrupted data can negatively impact the performance of the device.

#### **Work Around**

The throughput limits of FS devices is 288 bytes per microframe, a host driver must not schedule more than 288 bytes per microframe going to the same FS device.

### PLAN

This erratum is not planned to be corrected in a future revision.

## Module 8: Microchip UCS100x Usage

### DESCRIPTION

The UCS1002 is an I<sup>2</sup>C controlled power switch for the downstream VBUS. The USB4604/USB4624 and USB253x devices are able to communicate and control this switch through I<sup>2</sup>C by pulling up on the PRTPWR1 and OCS1\_N pins. The Flex Connect feature will not work with the UCS1002 in this mode.

### END USER IMPLICATIONS

The Flex Connect feature cannot be used with the UCS I<sup>2</sup>C control feature.

#### **Work Around**

The UCS1002 will have to be configured to communicate through digital line control instead of I<sup>2</sup>C, or use the UCS1001.

### PLAN

This erratum is not planned to be corrected in a future revision.

# USB253x/USB3x13/USB46x4

---

## Module 9: LPM Compatibility with Port Remap and Port Disable

### DESCRIPTION

Whenever the physical USB port does not match the logical port reported to the Hub, LPM functionality must be disabled. This includes using the Port Remap feature or disabling a port.

### END USER IMPLICATIONS

If LPM is enabled while any physical port does not match its logical port, the final device will fail the Chapter 9 LPM tests. All other compliance tests will pass.

#### **Work Around**

If the Port Remap feature is used, the user must disable the LPM support. This can be done through ProTouch or by setting bit 1 of configuration register 3104h (HUB\_CTL).

When disabling ports, always start at the highest port number. For example, disable port 4 before disabling port 3. This will prevent any remapping of the ports that can create this anomaly.

### PLAN

This erratum is not planned to be corrected in a future revision.

## Module 10: USB Device Reconnection Error in Windows 8 and Windows Server 2013

### DESCRIPTION

There is an issue that affects the USB253x/USB3x13/USB46x4 when used with Windows 8 or Windows Server 2013. This issue occurs when a USB device is connected to a USB downstream port on the hub, the USB device is safely removed from the USB port, and a device (the same device or difference device) is then reconnected to the same downstream port of the hub. In this scenario, Windows does not detect the USB device. This issue occurs because the USB port is disabled after the device was safely removed from the port.

### END USER IMPLICATIONS

A Windows 8 or Windows Server 2013 user may not be able to reconnect devices on USB downstream ports without rebooting Windows.

#### **Work Around**

To resolve this issue, install the Windows RT, Windows 8, and Windows Server 2012 update rollup 2845533, or install a hotfix that is described at <http://support.microsoft.com/kb/2830154>.

### PLAN

This is a Windows software issue and will not be addressed in a future revision of the device.



# USB253x/USB3x13/USB46x4

---

## Module 11: Hub fails USBCV Chapter 9 test 9.21

### DESCRIPTION

This failure is result of the LPM ECN released 9/28/2011. Per this ECN, previously reserved bits in the USB2 Extension Descriptor were allocated to BESL/HIRD support and recommended BESL values. Because the default values of these bits were previously set to 0 in the USB253x/USB3x13/USB46x4 products, the BESL/HIRD test will fail. Note, the part does support the LPM features, the descriptor just needs to be updated.

### END USER IMPLICATIONS

The USB-IF Chapter 9 tests will fail compliance, and LPM enabled hosts will not utilize the rapid suspend/resume features when communicating with the Hub.

#### Work Around

This errata is fixed in the -1081 and -1051 versions of the device.

To correct this situation in -1080, -1070, and -1050 devices, the following configuration registers need to be changed through OTP or SMBus:

Register 3128h is the register for bits 7:0 in the bmAttributes of the USB 2.0 Extension Descriptor. Bits 1 and 2 must be set to pass the test. Bits 3 and 4 signal if the parts has BESL and Deep BESL recommendations. An example passing value would be 0x0Eh.

Register 3129h is the register for bits 15:8 in the bmAttributes of the USB 2.0 Extension Descriptor. These are recommended values for the host to use when implementing LPM. A recommended value would be 04h.

### PLAN

This erratum is corrected in the -1081 and -1051 versions of the device.

## Module 12: Hub fails EL\_42 SYNC Truncation

### DESCRIPTION

The hubs contains a feature that turns off the USB clocks when no traffic is present on the USB lines. This reduces the Idle power consumption but not the maximum power consumption reported in the datasheet. This feature can sometimes cause the hub to truncate 4-6 SYNC pulses when enabled. This feature is enabled by default on -1080, -1070, and -1050 devices.

### END USER IMPLICATIONS

With the power saving feature enabled, the host may not communicate with devices in the 5th tier of a USB hub network.

#### Work Around

This feature is disabled by default in the -1081 and -1051 versions of the device.

To disable this feature in -1080, -1070, and -1050 devices through SMBus, write 00h to runtime register E9h. To disable this feature through OTP, the following configuration commands need to be added through SMBus or USB: **80 44 2B 01 00 FF**.

### PLAN

This erratum is corrected with -1081 part type; contact Microchip for availability.

## Module 13: Hub Startup Timing

### DESCRIPTION

The hub software has a startup variable that has no default value. This can cause the startup timing to be random between 10ms and 210ms.

### END USER IMPLICATIONS

Systems that attempt to communicate with the hub via SMBus less than 200ms after RESET may randomly receive a failure.

#### **Work Around**

Systems should wait a minimum of 220ms before communicating with the hub via SMBus to guarantee communication.

### PLAN

This erratum is not planned to be corrected in a future revision.

## Module 14: Repeating byte pattern may cause bit loss

### DESCRIPTION

When a byte pattern with 6 ones and 1 zero is repeated numerous times, consecutively, there is a chance that the repeater may miss one of the bits when receiving the signal.

### END USER IMPLICATIONS

Under standard operating protocol, the device or host will ignore the corresponding bad CRC packet and retry the packet, which often results in successful data transfer. The issue is a result of the clock recovery circuit in combination with clock delta's between the USB device and hub. Generally this clock difference is temporary, and the hub will recover and successfully repeat the data packet. This issue has not been observed when the content of the USB data packet is compressed (i.e., H264, MPEG2, MPEG3, JPEG, etc).

#### **Work Around**

Because the issue is temporary, setting the host to increase the number of times it retries a packet before issuing an error and resetting the USB device can reduce the impact to the end user. Because the retries are less than 125us apart, there is minimal impact on the timing.

### PLAN

This erratum is planned to be corrected in a future revision.

# USB253x/USB3x13/USB46x4

---

## Module 15: FlexConnect via SMBus enumeration issue

### DESCRIPTION

The USB253x requires a particular sequence of commands in order to allow it to flex and enumerate properly when initiating FlexConnect via SMBus.

### END USER IMPLICATIONS

If a particular sequence is not followed, the hub may not enumerate properly on a newly flexed host. Also, not following the sequence will prevent the user from swapping between the flexed and unflexed states.

#### **Work Around**

To resolve this issue, the following sequence must be followed:

Address: 0x2D W 00 00 05 00 01 31 8E 83/81 // Enable FlexConnect with/without flex mode

Address: 0x2D W 99 37 00

Address: 0x2D W 00 00 05 00 01 30 EE 80 // Ensure the clock stay on during suspend

Address: 0x2D W 99 37 00

Address: 0x2D W AA 55 00 // Attach (At this point, the device on port 1 will enumerate.)

Address: 0x2C W FF 40 // Page 2 of runtime register set

Address: 0x2C W 8E 82/80 // Unflex, thus P0 is upstream

Address: 0x2C W 8E 83/81 // Flex, thus P1 is upstream

Once this sequence is followed, the user is able to swap the upstream port by performing a write.

### PLAN

This erratum is isolated to only the USB253x devices and is not planned to be corrected in a future revision.

# USB253x/USB3x13/USB46x4

---

## APPENDIX A: DOCUMENT REVISION HISTORY

REVISION LEVEL	DESCRIPTION
DS80000583E (10-29-18)	Added new erratum 15.
DS80000583D (08-22-17)	Added new erratum 14.
DS80000583C (06-02-16)	Added new errata 11, 12, and 13. Added errata summary table with links and affected revision information. Updated document formatting for consistency with Microchip standards.
DS80000583B (05-16-14)	Updated anomaly 9 to include information on port disable.
DS80000583A (09-24-13)	replaces the previous SMSC version 1.2
Revision 1.2 (07-24-13)	Added anomaly 10, fixed misc. typos and grammatical errors
Revision 1.1 (05-31-13)	Updated anomalies, added anomalies 8 and 9
Revision 1.0 (04-05-13)	Initial release

# USB253x/USB3x13/USB46x4

---

## THE MICROCHIP WEB SITE

Microchip provides online support via our WWW site at [www.microchip.com](http://www.microchip.com). This web site is used as a means to make files and information easily available to customers. Accessible by using your favorite Internet browser, the web site contains the following information:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQ), technical support requests, online discussion groups, Microchip consultant program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

## CUSTOMER CHANGE NOTIFICATION SERVICE

Microchip's customer notification service helps keep customers current on Microchip products. Subscribers will receive e-mail notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, access the Microchip web site at [www.microchip.com](http://www.microchip.com). Under "Support", click on "Customer Change Notification" and follow the registration instructions.

## CUSTOMER SUPPORT

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Field Application Engineer (FAE)
- Technical Support

Customers should contact their distributor, representative or field application engineer (FAE) for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in the back of this document.

**Technical support is available through the web site at: <http://microchip.com/support>**

# USB253x/USB3x13/USB46x4

---

## Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specification contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is one of the most secure families of its kind on the market today, when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods used to breach the code protection feature. All of these methods, to our knowledge, require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Most likely, the person doing so is engaged in theft of intellectual property.
- Microchip is willing to work with the customer who is concerned about the integrity of their code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of their code. Code protection does not mean that we are guaranteeing the product as “unbreakable.”

Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

Information contained in this publication regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION, INCLUDING BUT NOT LIMITED TO ITS CONDITION, QUALITY, PERFORMANCE, MERCHANTABILITY OR FITNESS FOR PURPOSE. Microchip disclaims all liability arising from this information and its use. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

## Trademarks

The Microchip name and logo, the Microchip logo, AnyRate, AVR, AVR logo, AVR Freaks, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, Heldo, JukeBlox, KeeLoq, Klear, LANCheck, LINK MD, maXStylus, maXTouch, MediaLB, megaAVR, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, Prochip Designer, QTouch, SAM-BA, SpyNIC, SST, SST Logo, SuperFlash, tinyAVR, UNI/O, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

ClockWorks, The Embedded Control Solutions Company, EtherSynch, Hyper Speed Control, HyperLight Load, IntellIMOS, mTouch, Precision Edge, and Quiet-Wire are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, EtherGREEN, In-Circuit Serial Programming, ICSP, INICnet, Inter-Chip Connectivity, JitterBlocker, KlearNet, KlearNet logo, memBrain, Mindi, MiWi, motorBench, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, SAM-ICE, Serial Quad I/O, SMART-I.S., SQI, SuperSwitcher, SuperSwitcher II, Total Endurance, TSHARC, USBCheck, VariSense, ViewSpan, WiperLock, Wireless DNA, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

Silicon Storage Technology is a registered trademark of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2018, Microchip Technology Incorporated, All Rights Reserved.

ISBN: 9781522438366

**QUALITY MANAGEMENT SYSTEM**  
**CERTIFIED BY DNV**  
**== ISO/TS 16949 ==**

*Microchip received ISO/TS-16949:2009 certification for its worldwide headquarters, design and wafer fabrication facilities in Chandler and Tempe, Arizona; Gresham, Oregon and design centers in California and India. The Company's quality system processes and procedures are for its PIC® MCUs and dsPIC® DSCs, KEELOQ® code hopping devices, Serial EEPROMs, microperipherals, nonvolatile memory and analog products. In addition, Microchip's quality system for the design and manufacture of development systems is ISO 9001:2000 certified.*



## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

#### Atlanta

Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

#### Austin, TX

Tel: 512-257-3370

#### Boston

Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

#### Chicago

Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

#### Dallas

Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

#### Detroit

Novi, MI  
Tel: 248-848-4000

#### Houston, TX

Tel: 281-894-5983

#### Indianapolis

Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453  
Tel: 317-536-2380

#### Los Angeles

Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608  
Tel: 951-273-7800

#### Raleigh, NC

Tel: 919-844-7510

#### New York, NY

Tel: 631-435-6000

#### San Jose, CA

Tel: 408-735-9110  
Tel: 408-436-4270

#### Canada - Toronto

Tel: 905-695-1980  
Fax: 905-695-2078

### ASIA/PACIFIC

**Australia - Sydney**  
Tel: 61-2-9868-6733

**China - Beijing**  
Tel: 86-10-8569-7000

**China - Chengdu**  
Tel: 86-28-8665-5511

**China - Chongqing**  
Tel: 86-23-8980-9588

**China - Dongguan**  
Tel: 86-769-8702-9880

**China - Guangzhou**  
Tel: 86-20-8755-8029

**China - Hangzhou**  
Tel: 86-571-8792-8115

**China - Hong Kong SAR**  
Tel: 852-2943-5100

**China - Nanjing**  
Tel: 86-25-8473-2460

**China - Qingdao**  
Tel: 86-532-8502-7355

**China - Shanghai**  
Tel: 86-21-3326-8000

**China - Shenyang**  
Tel: 86-24-2334-2829

**China - Shenzhen**  
Tel: 86-755-8864-2200

**China - Suzhou**  
Tel: 86-186-6233-1526

**China - Wuhan**  
Tel: 86-27-5980-5300

**China - Xian**  
Tel: 86-29-8833-7252

**China - Xiamen**  
Tel: 86-592-2388138

**China - Zhuhai**  
Tel: 86-756-3210040

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444

**India - New Delhi**  
Tel: 91-11-4160-8631

**India - Pune**  
Tel: 91-20-4121-0141

**Japan - Osaka**  
Tel: 81-6-6152-7160

**Japan - Tokyo**  
Tel: 81-3-6880-3770

**Korea - Daegu**  
Tel: 82-53-744-4301

**Korea - Seoul**  
Tel: 82-2-554-7200

**Malaysia - Kuala Lumpur**  
Tel: 60-3-7651-7906

**Malaysia - Penang**  
Tel: 60-4-227-8870

**Philippines - Manila**  
Tel: 63-2-634-9065

**Singapore**  
Tel: 65-6334-8870

**Taiwan - Hsin Chu**  
Tel: 886-3-577-8366

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600

**Thailand - Bangkok**  
Tel: 66-2-694-1351

**Vietnam - Ho Chi Minh**  
Tel: 84-28-5448-2100

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4450-2828  
Fax: 45-4485-2829

**Finland - Espoo**  
Tel: 358-9-4520-820

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Garching**  
Tel: 49-8931-9700

**Germany - Haan**  
Tel: 49-2129-3766400

**Germany - Heilbronn**  
Tel: 49-7131-67-3636

**Germany - Karlsruhe**  
Tel: 49-721-625370

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Rosenheim**  
Tel: 49-8031-354-560

**Israel - Ra'anana**  
Tel: 972-9-744-7705

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Padova**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Norway - Trondheim**  
Tel: 47-7288-4388

**Poland - Warsaw**  
Tel: 48-22-3325737

**Romania - Bucharest**  
Tel: 40-21-407-87-50

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Gothenberg**  
Tel: 46-31-704-60-40

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820