





## Required Calibration & Adjustment Tools






# Setting the Home Position

1



Install the Laser Adjustment Tool (SCS-LAT)

2




Lock the SCS-LAT into place

3



Move the vacuum nozzle to a spot roughly centered over the SCS-LAT

4




Manually drive head down until nozzle is approximately 2mm above SCS-LAT




5



Center the vacuum nozzle over cone at the center of the SCS-LAT




Top View






# Crosshair Laser Setup

1



Install the Laser Adjustment Tool (SCS-LAT)

2




Lock the SCS-LAT

3




Press Home Button

4




Remove the laser assembly cover

5



Activate Laser Crosshair









6



Adjust the crosshair laser (SCS-CALM).  
Ensure the laser is flush with the bottom of the bracket



Laser Radiation Warning  
Do not stare into the beam or view directly with optical instruments.  
Laser components are sealed and replaced in their entirety.






# Calibrating the Laser Height Sensor (SCS-HSLM)

1




Press Home Button

2



Load PCBA into Board Holder

4



Go to Motion Control Screen



Jog head to right limit



Press Min Z Button









The reflow head is stopping below the normal height, please check if PCBA is correctly loaded.

OK



Laser Radiation Warning  
Do not stare into the beam or view directly with optical instruments.  
Laser components are sealed and replaced in their entirety.



**11**




0.05

Use the keypad to enter **0.05** next to the Adjust Relative Position Icon





Press Adjust Relative Position Icon



+




=




0.1mm



>0.1mm







Press and Hold. Repeat **10**

**12**





Press Save Work Surface Location Icon



“Has the vacuum nozzle been positioned 0.1mm above the reference?”

YES






“Click yes to save the current position as the plane of operation.

YES

Part 2

13




0.5

Use the keypad to enter **0.5** next to the Adjust Relative Position Icon

14




Press Adjust Relative Position Icon



0.65 mm  
0.60 mm  
0.55 mm  
0.50 mm  
0.45 mm

0.6-0.65mm


15








M3

Remove the laser assembly cover

16



Verify laser position, center of nozzle



21



Press Motion Control Icon

22



Press Get Absolute Position Icon & Record the Value

23



Press Read Analog Value Icon & Record the Value

24





Use the keypad to enter **0.6** next to the Adjust Relative Position Icon

25



Press Adjust Relative Position Icon

26



Press and hold the TUNE button for 3 sec until "TUNE" blinks, then release

27




"t-P1" appears

28



Press Up button for 3 sec

29 



Press Down a until motor stops

30 



Press Get Absolute Position Icon


31

22 

---

30   ±75

Compare Get Absolute Position from step 22 to Get Absolute Position from step 30



0.6 - 0.65mm

32 



Press Read Analog Value Icon & Record the Value

33

23 

---

32   ±8

Compare Read Analog Value from step 23 to Read Analog Value from step 32



 Step 22 = Step 30 ±75

 Step 23 = Step 32 ±8

Calibration Complete



 Step 22 ≠ Step 30 ±75


 Step 23 ≠ Step 32 ±8

Repeat 13



## External Thermocouple Calibration

- Required:
- K type thermocouple simulator



K type thermocouple tester



Set knob to 250°C



1




- Left click the thermocouple calibration icon

2



- The current temperature will be displayed

3




- Plug the K type thermocouple tester into the matching external thermcouple connector

4



- Right click the thermocouple to calibrate selected thermocouple.

5




- The current temperature will be displayed
- Left to cycle to next thermocouple
- Repeat until each thermocouple has been calibrated.




## Reflow Blower Calibration Setup



5400-0020




9025-9000



SCS-AFF

1



Go to Motion Control Screen

2




Press Home Button

3











Attach SRN-11 to nozzle assembly

4







Load SCS-AFF onto 9025-9000





 The reflow blower has four settings: low, medium, high, and cool






## Focus Blower Setup




5400-0020



NZA-SRS-CAL

1




Go to Motion Control Screen

2




Press Home Button

3



Install NZA-SRS-CAL

4




Install 5400-0020 into NZA-SRS-CAL

5



Power on the 5400-0020

6



Go to the Setup & Calibration Screen

7



Access Airflow Adjustment



The focus blower has two settings: active and cool

8




Press Reflow Blower Icon

9



Access Airflow Adjustment

10



Adjust

11




Save Settings



## Surround Blower Setup




5400-0020



9025-9000




9025-0560




7050-2262

1



Install cover

2




Go to Motion Control Screen

3






Press Home Button

4



Load 9025-9000 into Board Holder





The focus blower has two settings: active and cool

**9**



1x - Active  
2x - Cool


Press Reflow Blower Icon

**10**



Access Airflow Adjustment

**11**



Active 2m/s  
Cool 7m/s  
Tolerance ±0.1

Adjust

**12**















Save Settings



# Reflow Heater Calibration

- Required:
- Heater Calibration Kit; SCS-CALKIT










# Focus Heater Calibration



5300-0017




9025-9000




Go to Motion Control Screen









Press Home Button



Load 9025-9000 into Board Holder




Connect probe to TC1







## Surround Heater Calibration




- Required:
  - Heater Calibration Kit; SCS-CALKIT







5300-0017




9025-9000







# Glue Remover Calibration




APR-MRS Demo PCB




UBS-SCS

1




Go to Motion Control Screen

2



Install under board support

3



Load PCBA into Board Holder

4













Press Min Z Button

5



Adjust Z-axis until 1.75mm above reference





**15**

1

2 Set 1.27

Set Motion Control Parameters

**16**

Activate Laser Crosshair

**17**

Center pad area over the preheater using crosshair laser

**18**

Move crosshair laser to Start Location

**19**

Save Start Location

**20**

Press Min Z Button

**21**

Go to the Setup & Calibration Screen

22 



Activate Glue Remover Calibration

23 







If the unit begins moving and pulsing air (as it would during normal operation,) verify that the glue scraping button is selected, as described in step 15. **The glue remover calibration test will only work if the glue removal function has been activated.**

24 



Reposition the glue scraper as shown in the following pictures.

Record the direction and number of button clicks.

X-axis adjustment

Y-axis adjustment

C

25

# of button clicks



0.25mm



\*Direction



X-axis Value

\*Direction



= -1



= 1

26

# of button clicks Calibration



0.25mm



\*Direction



Y-axis Value

\*Direction



= -1



= 1

27

25

Scraper Gap

X  mm

26

Y  mm

Z  mm

Width  mm

Enter values from 25 & 26

28




Save Settings

29



Deactivate Glue Remover

30



Go to Motion Control Screen

31




Go to Start Location

32



Press Min Z Button

33




Go to the Setup & Calibration Screen

34





Activate Glue Remover Calibration

35








12 months or as needed





# Solder Path Cleaning



**5**

Press the Open Profile Icon

**6**

Profiles

Name
> mydir
> new_dir
> Screenshots
> test_dir4
cpy_glue_abc.rem
default.rem
f1.rem

Select the CleanSCS.rem

**7**

Press the Open Icon

**8**

Run the Profile

**9**

Clean the vacuum tube.  
Tube will be **hot**.

**10**

Stop the Profile

**11**

Allow System to Cool

