

Customer Information Notification

Issue Date: 08-Nov-2020 Effective Date: 09-Nov-2020 Dear Emma Tempest,

Here's your personalized quality information concerning products Premier Farnell PLC purchased from NXP. For detailed information we invite you to <u>view this</u> notification online

This notice is NXP Company Proprietary.

202010017I



QUALITY

onungo outogo	• •			
[] Wafer Fab	[] Assembly	[] Product Marking	[]Test	[] Design
Process	Process		Location	
[] Wafer Fab	[] Assembly	[] Mechanical Specification	[]Test Process	[X] Errata
Materials	Materials			
[] Wafer Fab	[] Assembly	[]	[]Test	[] Electrical spec./Test
Location	Location	Packing/Shipping/Labeling	Equipment	coverage
[] Firmware	[] Other			

KL03Z(1N86K) Errata Update to Rev.10

Description

NXP Semiconductors announces that the KL03Z(1N86K) Errata have been updated to new revisions: KL03Z_1N86K Rev. 10.

There provides a detailed description of the changes:

Added following errata:

1. ERR008992, AWIC: Early NMI wakeup not detected upon entry to stop mode from VLPR mode

- 2. ERR008777, I2C: Address match wake-up from low-power mode cannot receive data
- 3. ERR009308, I2C: I2C does not hold bus between byte transfers in receive and may result in lost data

4. ERR009457, Kinetis Flashloader/ ROM Bootloader: The peripheral auto-detect code in bootloader can falsely detect presence of SPI host causing non-responsive bootloader

5. ERR008010, LLWU: CMP flag in LLWU_Fx register cleared by multiple CMP out toggles when exiting LLSx or VLLSx modes.

6. ERR010527, LPUART: Setting and immediately clearing SBK bit can result in transmission of two break characters

The updated Errata for KL03Z(1N86K) can be found at:

https://www.nxp.com/products/processors-and-microcontrollers/arm-microcontrollers/general-purposemcus/kl-series-cortex-m0-plus/kinetis-kl0x-48-mhz-entry-level-ultra-low-power-microcontrollers-mcusbased-on-arm-cortex-m0-plus-core:KL0x?fpsp=1&tab=Documentation_Tab Reason The Errata have been updated to provide additional technical clarification on some device features. **Identification of Affected Products** Product identification does not change

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No impact on form, fit, function, reliability or quality.

Andrew Su

Additional information

Affected products and sales history information: see attached file

Additional documents: view online

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please <u>contact NXP "Global Quality</u> <u>Support Team"</u>.

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name

Position Systems Engineer

e-mail address yong.su@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

View Notification	Subscription	<u>Support</u>		
NXP Privacy Policy Terms of Use				

NXP Semiconductors

High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2010 NXP Semiconductors. All rights reserved.