



## Product Change Notification / SYST-07ZPGG679

---

**Date:**

12-Jul-2021

**Product Category:**

8-bit Microcontrollers

**PCN Type:**

Document Change

**Notification Subject:**

ERRATA - ATmega4808/4809 Silicon Errata and Data Sheet Clarification Revision

**Affected CPNs:**

[SYST-07ZPGG679\\_Affected\\_CPN\\_07122021.pdf](#)

[SYST-07ZPGG679\\_Affected\\_CPN\\_07122021.csv](#)

**Notification Text:**

SYST-07ZPGG679

Microchip has released a new Product Documents for the ATmega4808/4809 Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [ATmega4808/4809 Silicon Errata and Data Sheet Clarification](#).

**Notification Status:** Final

**Description of Change:**

- 1) "Affected Silicon Revisions" of erratum 2.9.3 CCMP and CNT Registers Operate as 16-Bit Registers in 8-Bit PWM Mode is corrected
- 2) Added Errata: 2.6.2 The CCL Must be Disabled to Change the Configuration of a Single LUT
- 3) Added data sheet clarifications: 3.1 Ordering Information - Automotive Ordering Codes Are Available on Request

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 12 Jul 2021

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## **Attachments:**

[ATmega4808/4809 Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## **Terms and Conditions:**

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

ATMEGA4809-MF  
ATMEGA4809-MF-VAO  
ATMEGA4808-XF  
ATMEGA4808-MF-VAO  
ATMEGA4808-MF  
ATMEGA4809-PF  
ATMEGA4808-AF  
ATMEGA4809-AF  
ATMEGA4809-AF-VAO  
ATMEGA4809-MU  
ATMEGA4808-XU  
ATMEGA4808-MU  
ATMEGA4808-AU  
ATMEGA4809-AU  
ATMEGA4809-MUR  
ATMEGA4808-XUR  
ATMEGA4808-MUR  
ATMEGA4808-AUR  
ATMEGA4809-AUR  
ATMEGA4809-MFR  
ATMEGA4809-MFR-VAO  
ATMEGA4808-XFR  
ATMEGA4808-XFR-VAO  
ATMEGA4808-MFR-VAO  
ATMEGA4808-MFR  
ATMEGA4808-AFR  
ATMEGA4808-AFR-VAO  
ATMEGA4809-AFR  
ATMEGA4809-AFR-V01  
ATMEGA4809-AFR-VAO



# ATmega4808/4809

---

---

## ATmega4808/4809 Silicon Errata and Data Sheet Clarification

---

---

The ATmega4808/4809 devices of the megaAVR® 0-series you have received conform functionally to the current device data sheet ([www.microchip.com/DS40002173](http://www.microchip.com/DS40002173)), except for the anomalies described in this document. The errata described in this document will likely be addressed in future revisions of the ATmega4808/4809 devices.

**Notes:**

- This document summarizes all the silicon errata issues from all revisions of silicon, previous as well as current
- Refer to the Device/Revision ID section in the current device data sheet ([www.microchip.com/DS40002173](http://www.microchip.com/DS40002173)) for more detailed information on Device Identification and Revision IDs for your specific device, or contact your local Microchip sales office for assistance

Table of Contents

..... 1

1. Silicon Issue Summary.....3

2. Silicon Errata.....5

    2.1. Errata Details.....5

    2.2. Device.....5

    2.3. CPUINT.....5

    2.4. PORTMUX.....6

    2.5. ADC.....6

    2.6. CCL.....7

    2.7. RTC.....7

    2.8. TCA.....8

    2.9. TCB.....8

    2.10. USART.....9

3. Data Sheet Clarifications.....11

    3.1. Ordering Information - Automotive Ordering Codes Are Available on Request.....11

4. Document Revision History.....12

    4.1. Revision History.....12

    4.2. Appendix - Obsolete Revision History.....12

The Microchip Website.....14

Product Change Notification Service.....14

Customer Support.....14

Microchip Devices Code Protection Feature.....14

Legal Notice.....15

Trademarks.....15

Quality Management System.....16

Worldwide Sales and Service.....17

## 1. Silicon Issue Summary

### Legend

- Erratum is not applicable.
- X Erratum is applicable.

### Errata Overview

Peripheral	Short Description	Valid for Silicon Revision
		Rev. B <sup>(1)</sup>
DEVICE	2.2.1 Writing the OSCLOCK Fuse in FUSE.OSCCFG to '1' Prevents Automatic Loading of Calibration Values	X
CPUINT	2.3.1 Interrupt Level 1 Does Not Work	X
PORTMUX	2.4.1 SPI SS Pin is Connected to Pin Even if SPI is Configured to Have No Port Connection	X
ADC	2.5.1 One Extra Measurement Performed After Disabling ADC Free-Running Mode	X
	2.5.2 Pending Event Stuck When Disabling the ADC	X
	2.5.3 ADC Functionality Cannot be Ensured with CLKADC Above 1.5 MHz and a Setting of 25% Duty Cycle	X
	2.5.4 ADC Performance Degrades with CLKADC Above 1.5 MHz and VDD < 2.7V	X
CCL	2.6.1 D-latch is Not Functional	X
	2.6.2 The CCL Must be Disabled to Change the Configuration of a Single LUT	X
RTC	2.7.1 Any Write to the RTC.CTRLA Register Resets the RTC and PIT Prescaler	X
TCA	2.8.1 Restart Will Reset Counter Direction in NORMAL and FRQ Mode	X
TCB	2.9.1 The TCA Restart Command Does Not Force a Restart of TCB	X
	2.9.2 Minimum Event Duration Must Exceed the Selected Clock Period	X
	2.9.3 CCMP and CNT Registers Operate as 16-Bit Registers in 8-Bit PWM Mode	X

# ATmega4808/4809

## Silicon Issue Summary

.....continued		
Peripheral	Short Description	Valid for Silicon Revision
		Rev. B <sup>(1)</sup>
USART	<a href="#">2.10.1 TXD Pin Override Not Released When Disabling the Transmitter</a>	X
	<a href="#">2.10.2 Open-Drain Mode Does Not Work When TXD is Configured as Output</a>	X
	<a href="#">2.10.3 Start-of-Frame Detection Can Unintentionally Be Triggered in Active Mode</a>	X

**Note:**

1. This revision is the initial release of the silicon.

## 2. Silicon Errata

### 2.1 Errata Details

- Erratum is not applicable.
- X Erratum is applicable.

### 2.2 Device

#### 2.2.1 Writing the OSCLOCK Fuse in FUSE.OSCCFG to '1' Prevents Automatic Loading of Calibration Values

Writing the OSCLOCK fuse in FUSE.OSCCFG to '1' prevents the automatic loading of calibration values from the signature row. The device will run with an uncalibrated OSC20M oscillator.

##### Work Around

Do not use OSCLOCK for locking the oscillator calibration value. The oscillator calibration value can be locked by writing LOCK in CLKCTRL.OSC20MCALIBB to '1'.

##### Affected Silicon Revisions

Rev. B
X

### 2.3 CPUINT

#### 2.3.1 Interrupt Level 1 Does Not Work

Interrupt Level 1 may fail to execute correctly by executing the Reset vector rather than the intended interrupt vector. This only applies to the following products and is limited to date codes older than 1914 (week 14 of 2019).

- ATMEGA4809-AF
- ATMEGA4809-AFR
- ATMEGA4809-AU
- ATMEGA4809-AUR
- ATMEGA4809-MF
- ATMEGA4809-MFR
- ATMEGA4809-MU
- ATMEGA4809-MUR
- ATMEGA4809-PF

##### Work Around

Use Interrupt Level 0 instead of Interrupt Level 1.

##### Affected Silicon Revisions

Rev. B
X



## 2.4 PORTMUX

### 2.4.1 SPI $\overline{SS}$ Pin is Connected to Pin Even if SPI is Configured to Have No Port Connection

The SPIn  $\overline{SS}$  pin is connected even if NONE is selected in the SPIn field in PORTMUX.TWISPIROUTE. If SPIn is operating in Host mode and the  $\overline{SS}$  pin goes low, or input is disabled, the SPIn will exit Host mode.

#### Work around

Write the SSD bit in SPIn.CTRLB to '1' to ignore the  $\overline{SS}$  signal.

#### Affected Silicon Revisions

Rev. B
X

## 2.5 ADC

### 2.5.1 One Extra Measurement Performed After Disabling ADC Free-Running Mode

The ADC may perform one additional measurement after clearing ADCn.CTRLA.FREERUN.

#### Work Around

Write ADCn.CTRLA.ENABLE to '0' to stop the Free-Running mode immediately.

#### Affected Silicon Revisions

Rev. B
X

### 2.5.2 Pending Event Stuck When Disabling the ADC

If the ADC is disabled during an event-triggered conversion, the event will not be cleared.

#### Work Around

Clear ADC.EVCTRL.STARTEI and wait for the conversion to complete before disabling the ADC.

#### Affected Silicon Revisions

Rev. B
X

### 2.5.3 ADC Functionality Cannot be Ensured with $CLK_{ADC}$ Above 1.5 MHz and a Setting of 25% Duty Cycle

The ADC functionality cannot be ensured if  $CLK_{ADC} > 1.5$  MHz with ADCn.CALIB.DUTYCYC set to '1'.

#### Work around

If ADC is operated with  $CLK_{ADC} > 1.5$  MHz, ADCn.CALIB.DUTYCYC must be set to '0' (50% duty cycle).

#### Affected Silicon Revisions

Rev. B

X
---

### 2.5.4 ADC Performance Degrades with CLK<sub>ADC</sub> Above 1.5 MHz and V<sub>DD</sub> < 2.7V

The ADC INL performance degrades if CLK<sub>ADC</sub> > 1.5 MHz and ADCn.CALIB.DUTYCYC set to '0' for V<sub>DD</sub> < 2.7V.

#### Work Around

None.

#### Affected Silicon Revisions

Rev. B
--------

X
---

## 2.6 CCL

### 2.6.1 D-latch is Not Functional

The CCL D-latch is not functional.

#### Work Around

None.

#### Affected Silicon Revisions

Rev. B
--------

X
---

### 2.6.2 The CCL Must be Disabled to Change the Configuration of a Single LUT

To reconfigure a LUT, the CCL peripheral must be disabled (write ENABLE in CCL.CTRLA to '0'). Writing ENABLE to '0' will disable all the LUTs, and affects the LUTs not under reconfiguration.

#### Work Around

None

#### Affected Silicon Revisions

Rev. B
--------

X
---

## 2.7 RTC

### 2.7.1 Any Write to the RTC.CTRLA Register Resets the RTC and PIT Prescaler

Any write to the RTC.CTRLA register resets the 15-bit prescaler resulting in a longer period on the current count or period.

#### Work Around

None.

**Affected Silicon Revisions**

Rev. B
X

**2.8 TCA****2.8.1 Restart Will Reset Counter Direction in NORMAL and FRQ Mode**

When the TCA is configured to the NORMAL or FRQ mode (WGMODE in TCAn.CTRLB is '0x0' or '0x1'), a RESTART command or Restart event will reset direction to default. The default is counting upwards.

**Work Around**

None.

**Affected Silicon Revisions**

Rev. B
X

**2.9 TCB****2.9.1 The TCA Restart Command Does Not Force a Restart of TCB**

The TCA restart command does not force restarting the TCB when TCB is running in SYNCUPD mode. TCB is restarted only after a TCA OVF.

**Work Around**

None.

**Affected Silicon Revisions**

Rev. B
X

**2.9.2 Minimum Event Duration Must Exceed the Selected Clock Period**

Event detection will fail if TCBn receives an input event with a high/low period shorter than the period of the selected clock source (CLKSEL in TCBn.CTRLA). This applies to the TCB modes (CNTMODE in TCBn.CTRLB) *Time-Out Check* and *Input Capture Frequency and Pulse-Width Measurement* mode.

**Work Around**

Ensure that the high/low period of input events is equal to or longer than the selected clock source (CLKSEL in TCBn.CTRLA) period.

**Affected Silicon Revisions**

Rev. B
X

**2.9.3 CCMP and CNT Registers Operate as 16-Bit Registers in 8-Bit PWM Mode**

When the TCB operates in 8-bit PWM mode (CNTMODE in TCBn.CTRLB is '0x7'), the low and high bytes for the CNT and CCMP registers operate as 16-bit registers for read and write. They cannot be read or written independently.

**Work Around**

Use 16-bit register access. Refer to the data sheet for further information.

**Affected Silicon Revisions**

Rev. B
X

**2.10 USART****2.10.1 TXD Pin Override Not Released When Disabling the Transmitter**

The USART will not release the TXD pin override if:

- The USART transmitter is disabled by writing the TXEN bit in USART.CTRLB to '0' while the USART receiver is disabled (RXEN in USART.CTRLB is '0')
- Both the USART transmitter and receiver are disabled at the same time by writing the TXEN and RXEN bits in USART.CTRLB to '0'

**Work Around**

There are two possible work arounds:

- Make sure the receiver is enabled (RXEN in USART.CTRLB is '1') while disabling the transmitter (writing TXEN in USART.CTRLB to '0')
- Writing to any register in the USART after disabling the transmitter will start the USART for long enough to release the pin override of the TXD pin

**Affected Silicon Revisions**

Rev. B
X

**2.10.2 Open-Drain Mode Does Not Work When TXD is Configured as Output**

When the USART TXD pin is configured as an output, it can drive the pin high regardless of whether the Open-Drain mode is enabled or not.

**Work Around**

Configure the TXD pin as an input by writing the corresponding bit in PORTx.DIR to '0' when using Open-Drain mode.

**Affected Silicon Revisions**

Rev. B
X

**2.10.3 Start-of-Frame Detection Can Unintentionally Be Triggered in Active Mode**

The Start-of-Frame Detection feature enables the USART to wake up from Standby sleep mode upon data reception.

The Start-of-Frame Detector can unintentionally be triggered when the Start-of-Frame Detection Enable (SFDEN) bit in the USART Control B (USARTn.CTRLB) register is set, and the device is in Active mode. If the Receive Data (RXDATA) registers are read while receiving new data, the Receive Complete Interrupt Flag (RXCIF) in the USARTn.STATUS register is cleared. This results in the Start-of-Frame Detector being triggered and falsely detecting the following falling edge as a start bit. When the Start-of-Frame Detector detects a start condition, the frame reception is restarted, resulting in corrupt received data.

Note that the USART Receive Start Interrupt Flag (RXSIF) always is '0' when in Active mode. No interrupt will be triggered.

### Work Around

Disable Start-of-Frame Detection by writing '0' to the Start-of-Frame Detection Enable (SFDEN) bit in the USART Control B (USARTn.CTRLB) register when the device is in Active mode. Enable it again by writing the bit to '1' before transitioning to Standby sleep mode. This work around depends on a protocol preventing a new incoming frame when re-enabling Start-of-Frame Detection. Re-enabling Start-of-Frame Detection, while a new frame is already incoming, will result in corrupted received data.

### Affected Silicon Revisions

Rev. B
X

### **3. Data Sheet Clarifications**

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet ([www.microchip.com/DS40002173](http://www.microchip.com/DS40002173)).

**Note:** Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

#### **3.1 Ordering Information - Automotive Ordering Codes Are Available on Request**

**Note:** Automotive-grade ordering codes (VAO suffix) are set up on request and may not be listed in “Table 34-1. Available Product Numbers” of the data sheet.

## 4. Document Revision History

**Note:** The document revision is independent of the silicon revision.

### 4.1 Revision History

Doc Rev.	Date	Comments
C	07/2021	<ul style="list-style-type: none"> <li>• “Affected Silicon Revisions” of erratum <a href="#">2.9.3 CCMP and CNT Registers Operate as 16-Bit Registers in 8-Bit PWM Mode</a> is corrected</li> <li>• Added Errata:               <ul style="list-style-type: none"> <li>– <a href="#">2.6.2 The CCL Must be Disabled to Change the Configuration of a Single LUT</a></li> </ul> </li> <li>• Added data sheet clarifications:               <ul style="list-style-type: none"> <li>– <a href="#">3.1 Ordering Information - Automotive Ordering Codes Are Available on Request</a></li> </ul> </li> </ul>
B	02/2021	<ul style="list-style-type: none"> <li>• Added new errata:               <ul style="list-style-type: none"> <li>– Device: <a href="#">4.1 Revision History</a></li> <li>– TCA: <a href="#">2.8.1 Restart Will Reset Counter Direction in NORMAL and FRQ Mode</a></li> <li>– TCB: <a href="#">2.9.3 CCMP and CNT Registers Operate as 16-Bit Registers in 8-Bit PWM Mode</a></li> <li>– USART:                   <ul style="list-style-type: none"> <li>• <a href="#">2.10.2 Open-Drain Mode Does Not Work When TXD is Configured as Output</a></li> <li>• <a href="#">2.10.3 Start-of-Frame Detection Can Unintentionally Be Triggered in Active Mode</a></li> </ul> </li> </ul> </li> <li>• New hold place for CPUINT errata: After Device errata</li> </ul>
A	01/2020	<ul style="list-style-type: none"> <li>• Document               <ul style="list-style-type: none"> <li>– Change document structure from one document for the entire megaAVR 0-series to one document per data sheet:                   <ul style="list-style-type: none"> <li>• from: megaAVR-0-series-Errata-and-Clarification-80000777C.pdf</li> <li>• to: ATmega4808_4809-Errata-and-Clarification-DS80000867A.pdf</li> </ul> </li> <li>– Updated document template</li> </ul> </li> <li>• Errata               <ul style="list-style-type: none"> <li>– The ADC errata, ADC Functionality Cannot be Ensured with ADCCLK Above 1.5 MHz for All Conditions, has been split into two separate erratas and rewritten</li> </ul> </li> </ul>

### 4.2 Appendix - Obsolete Revision History

**Note:** Due to document structure change from a single megaAVR 0-series to one document per data sheet, the following history from [www.microchip.com/DS80000777](http://www.microchip.com/DS80000777) is provided as reference.

Doc Rev.	Date	Comments
C	08/2019	<ul style="list-style-type: none"> <li>• New Errata:               <ul style="list-style-type: none"> <li>– CPUINT: Interrupt Level 1 Does Not Work</li> </ul> </li> </ul> <p><b>Note:</b> Only applicable to ATmega4808/4809 for specific date codes.</p>

# ATmega4808/4809

## Document Revision History

.....continued

Doc Rev.	Date	Comments
B	07/2019	<ul style="list-style-type: none"><li>• Document<ul style="list-style-type: none"><li>– Adding variants with 16 KB and 8 KB Flash</li><li>– Adding 40-pin variant of ATmega4809</li><li>– Changing document title</li><li>– Adding section "Data Sheet Clarifications"</li></ul></li><li>• New Errata:<ul style="list-style-type: none"><li>– PORTMUX: SPI SS is Connected to Pin Even if SPI is Configured to Have No Port Connection</li><li>– TCB: Minimum Event Duration Must Exceed Selected Clock Period</li><li>– USART: TXD Pin Override Not Released When Disabling the Transmitter</li></ul></li><li>• Erratum for TCA removed: Issuing a restart will clear the direction bit - the data sheet is describing this correctly.</li></ul>
A	02/2018	<ul style="list-style-type: none"><li>• Initial document release.</li></ul>



## The Microchip Website

---

Microchip provides online support via our website at [www.microchip.com/](http://www.microchip.com/). This website is used to make files and information easily available to customers. Some of the content available includes:

- **Product Support** – Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** – Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** – Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

## Product Change Notification Service

---

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to [www.microchip.com/pcn](http://www.microchip.com/pcn) and follow the registration instructions.

## Customer Support

---

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: [www.microchip.com/support](http://www.microchip.com/support)

## Microchip Devices Code Protection Feature

---

Note the following details of the code protection feature on Microchip devices:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner and under normal conditions.
- There are dishonest and possibly illegal methods being used in attempts to breach the code protection features of the Microchip devices. We believe that these methods require using the Microchip products in a manner outside the operating specifications contained in Microchip's Data Sheets. Attempts to breach these code protection features, most likely, cannot be accomplished without violating Microchip's intellectual property rights.
- Microchip is willing to work with any customer who is concerned about the integrity of its code.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable." Code protection is constantly evolving. We at Microchip are committed to continuously improving the code protection features of our products. Attempts to break Microchip's code protection feature may be a violation of the Digital Millennium Copyright Act. If such acts allow unauthorized access to your software or other copyrighted work, you may have a right to sue for relief under that Act.

---

## Legal Notice

---

Information contained in this publication is provided for the sole purpose of designing with and using Microchip products. Information regarding device applications and the like is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL OR CONSEQUENTIAL LOSS, DAMAGE, COST OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION. Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

---

## Trademarks

---

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, chipKIT, chipKIT logo, CryptoMemory, CryptoRF, dsPIC, FlashFlex, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PackeTime, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, FlashTec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICKit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SMART-I.S., storClad, SQL, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2021, Microchip Technology Incorporated, Printed in the U.S.A., All Rights Reserved.

ISBN: 978-1-5224-8414-1

## **Quality Management System**

---

For information regarding Microchip's Quality Management Systems, please visit [www.microchip.com/quality](http://www.microchip.com/quality).

## Worldwide Sales and Service

AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
<p><b>Corporate Office</b> 2355 West Chandler Blvd. Chandler, AZ 85224-6199 Tel: 480-792-7200 Tel: 480-792-7277 Technical Support: <a href="http://www.microchip.com/support">www.microchip.com/support</a> Web Address: <a href="http://www.microchip.com">www.microchip.com</a></p> <p><b>Atlanta</b> Duluth, GA Tel: 678-957-9614 Fax: 678-957-1455</p> <p><b>Austin, TX</b> Tel: 512-257-3370</p> <p><b>Boston</b> Westborough, MA Tel: 774-760-0087 Fax: 774-760-0088</p> <p><b>Chicago</b> Itasca, IL Tel: 630-285-0071 Fax: 630-285-0075</p> <p><b>Dallas</b> Addison, TX Tel: 972-818-7423 Fax: 972-818-2924</p> <p><b>Detroit</b> Novi, MI Tel: 248-848-4000</p> <p><b>Houston, TX</b> Tel: 281-894-5983</p> <p><b>Indianapolis</b> Noblesville, IN Tel: 317-773-8323 Fax: 317-773-5453 Tel: 317-536-2380</p> <p><b>Los Angeles</b> Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800</p> <p><b>Raleigh, NC</b> Tel: 919-844-7510</p> <p><b>New York, NY</b> Tel: 631-435-6000</p> <p><b>San Jose, CA</b> Tel: 408-735-9110 Tel: 408-436-4270</p> <p><b>Canada - Toronto</b> Tel: 905-695-1980 Fax: 905-695-2078</p>	<p><b>Australia - Sydney</b> Tel: 61-2-9868-6733</p> <p><b>China - Beijing</b> Tel: 86-10-8569-7000</p> <p><b>China - Chengdu</b> Tel: 86-28-8665-5511</p> <p><b>China - Chongqing</b> Tel: 86-23-8980-9588</p> <p><b>China - Dongguan</b> Tel: 86-769-8702-9880</p> <p><b>China - Guangzhou</b> Tel: 86-20-8755-8029</p> <p><b>China - Hangzhou</b> Tel: 86-571-8792-8115</p> <p><b>China - Hong Kong SAR</b> Tel: 852-2943-5100</p> <p><b>China - Nanjing</b> Tel: 86-25-8473-2460</p> <p><b>China - Qingdao</b> Tel: 86-532-8502-7355</p> <p><b>China - Shanghai</b> Tel: 86-21-3326-8000</p> <p><b>China - Shenyang</b> Tel: 86-24-2334-2829</p> <p><b>China - Shenzhen</b> Tel: 86-755-8864-2200</p> <p><b>China - Suzhou</b> Tel: 86-186-6233-1526</p> <p><b>China - Wuhan</b> Tel: 86-27-5980-5300</p> <p><b>China - Xian</b> Tel: 86-29-8833-7252</p> <p><b>China - Xiamen</b> Tel: 86-592-2388138</p> <p><b>China - Zhuhai</b> Tel: 86-756-3210040</p>	<p><b>India - Bangalore</b> Tel: 91-80-3090-4444</p> <p><b>India - New Delhi</b> Tel: 91-11-4160-8631</p> <p><b>India - Pune</b> Tel: 91-20-4121-0141</p> <p><b>Japan - Osaka</b> Tel: 81-6-6152-7160</p> <p><b>Japan - Tokyo</b> Tel: 81-3-6880-3770</p> <p><b>Korea - Daegu</b> Tel: 82-53-744-4301</p> <p><b>Korea - Seoul</b> Tel: 82-2-554-7200</p> <p><b>Malaysia - Kuala Lumpur</b> Tel: 60-3-7651-7906</p> <p><b>Malaysia - Penang</b> Tel: 60-4-227-8870</p> <p><b>Philippines - Manila</b> Tel: 63-2-634-9065</p> <p><b>Singapore</b> Tel: 65-6334-8870</p> <p><b>Taiwan - Hsin Chu</b> Tel: 886-3-577-8366</p> <p><b>Taiwan - Kaohsiung</b> Tel: 886-7-213-7830</p> <p><b>Taiwan - Taipei</b> Tel: 886-2-2508-8600</p> <p><b>Thailand - Bangkok</b> Tel: 66-2-694-1351</p> <p><b>Vietnam - Ho Chi Minh</b> Tel: 84-28-5448-2100</p>	<p><b>Austria - Wels</b> Tel: 43-7242-2244-39 Fax: 43-7242-2244-393</p> <p><b>Denmark - Copenhagen</b> Tel: 45-4485-5910 Fax: 45-4485-2829</p> <p><b>Finland - Espoo</b> Tel: 358-9-4520-820</p> <p><b>France - Paris</b> Tel: 33-1-69-53-63-20 Fax: 33-1-69-30-90-79</p> <p><b>Germany - Garching</b> Tel: 49-8931-9700</p> <p><b>Germany - Haan</b> Tel: 49-2129-3766400</p> <p><b>Germany - Heilbronn</b> Tel: 49-7131-72400</p> <p><b>Germany - Karlsruhe</b> Tel: 49-721-625370</p> <p><b>Germany - Munich</b> Tel: 49-89-627-144-0 Fax: 49-89-627-144-44</p> <p><b>Germany - Rosenheim</b> Tel: 49-8031-354-560</p> <p><b>Israel - Ra'anana</b> Tel: 972-9-744-7705</p> <p><b>Italy - Milan</b> Tel: 39-0331-742611 Fax: 39-0331-466781</p> <p><b>Italy - Padova</b> Tel: 39-049-7625286</p> <p><b>Netherlands - Drunen</b> Tel: 31-416-690399 Fax: 31-416-690340</p> <p><b>Norway - Trondheim</b> Tel: 47-72884388</p> <p><b>Poland - Warsaw</b> Tel: 48-22-3325737</p> <p><b>Romania - Bucharest</b> Tel: 40-21-407-87-50</p> <p><b>Spain - Madrid</b> Tel: 34-91-708-08-90 Fax: 34-91-708-08-91</p> <p><b>Sweden - Gothenberg</b> Tel: 46-31-704-60-40</p> <p><b>Sweden - Stockholm</b> Tel: 46-8-5090-4654</p> <p><b>UK - Wokingham</b> Tel: 44-118-921-5800 Fax: 44-118-921-5820</p>