



## Customer Information Notification

202112019I : NTM88xxxx Product Family Pre-Charge Function

**Note:** This notice is NXP Company Proprietary.

**Issue Date:** Dec 16, 2021 **Effective date:** Dec 17, 2021

Here is your personalized notification about a NXP general announcement.

For detailed information we invite you to [view this notification online](#)

### Management summary

For the NTM88xxxx product family, communication of a gap in test coverage, where the RF transmitter Pre-charge function may not operate as expected.

### Change Category

<input type="checkbox"/> Wafer Fab Process	<input type="checkbox"/> Assembly Process	<input type="checkbox"/> Product Marking	<input type="checkbox"/> Test Process	<input type="checkbox"/> Design
<input type="checkbox"/> Wafer Fab Materials	<input type="checkbox"/> Assembly Materials	<input type="checkbox"/> Mechanical Specification	<input type="checkbox"/> Test Equipment	<input type="checkbox"/> Errata
<input type="checkbox"/> Wafer Fab Location	<input type="checkbox"/> Assembly Location	<input type="checkbox"/> Packing/Shipping/Labeling	<input type="checkbox"/> Test Location	<input checked="" type="checkbox"/> Electrical spec./Test coverage
<input type="checkbox"/> Firmware	<input type="checkbox"/> Other			

## PCN Overview

### Description

For the NTM88xxxx product family, a use-case condition has exposed a gap in test coverage, where the RF transmitter Pre-charge function may not operate as expected.

### Reason

For the NTM88xxxx product family, the User Manual UM11227 section 10.16.11.12 describes the Pre-charging of the RF voltage regulator external stability capacitor, which is connected on customer circuit boards at the sensor pin 12 labelled "VREG". When the Pre-charge function is enabled, the external VREG capacitor is charged just prior to each scheduled RF transmission. However, sensors shipped prior to 10 December 2021 received an inadequate test of the Pre-charge function, such that the external capacitor may not be Pre-charged as expected. As a result, some sensors may not trigger the RF transmission if the Pre-charge is enabled, or the temperature-based adjustments to Periodic Wake-up, Medium Frequency Oscillator, and/or Free Running counts may not be executed.

### Identification of Affected Products

Product identification does not change

Some NTM88xxxx product shipped prior to 10 December 2021.

### Anticipated Impact on Form, Fit, Function, Reliability or Quality

Some NTM88xxxx product, shipped prior to 10 December 2021, may not trigger the RF transmission if the Pre-charge is enabled, or the temperature-based adjustments to Periodic Wake-up, Medium Frequency Oscillator, and/or Free Running counts may not be executed.

### Additional information

Additional documents: [view online](#)

### Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

**Name** Matt Muddiman  
**Position** System Engineer  
**e-mail address** [matt.muddiman@nxp.com](mailto:matt.muddiman@nxp.com)

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

**About NXP Semiconductors**

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply .

NXP Semiconductors  
 High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006- 2021 NXP Semiconductors. All rights reserved.

Changed Orderable Part#	12NC	Product Type	Product Description	Package Outline	Package Description	Product Status	Customer Specific Indicator	New Orderable Part#	12NC New	Product Type New	Product Description New
NTM88H055T1	935396482528	NTM88H055T1	TPMS 4X4 900kPa X axis	HQFN24FAMWF	SOT1931-1(D)	RFS	No				
NTM88H065T1	935396483528	NTM88H065T1	TPMS 4X4 900kPa X axis	HQFN24FAMWF	SOT1931-1(D)	RFS	No				
NTM88H135T1	935400231528	NTM88H135T1	TPMS 4X4 900kPa XZ axis	HQFN24FAMWF	SOT1931-1(D)	RFS	No				
NTM88H145T1	935400233528	NTM88H145T1	TPMS 4X4 900kPa XZ axis	HQFN24FAMWF	SOT1931-1(D)	ASM	No				
NTM88H155T1	935404318528	NTM88H155T1	TPMS 4X4 900kPa XZ axis	HQFN24FAMWF	SOT1931-1(D)	RFS	No				
NTM88H075T1	935407575528	NTM88H075T1	TPMS 4X4 900kPa X axis	HQFN24FAMWF	SOT1931-1(D)	ASM	No				
NTM88H125T1	935407576528	NTM88H125T1	TPMS 4X4 900kPa XZ axis	HQFN24FAMWF	SOT1931-1(D)	ASM	No				
NTM88H127T1	935417611528	NTM88H127T1	TPMS 4X4 900kPa XZ axis	HQFN24FAMWF	SOT1931-1(D)	ASM	No				
NTM88J127T1	935417612528	NTM88J127T1	TPMS 4X4 900kPa XZ axis	HQFN24FAMWF	SOT1931-1(D)	ASM	No				
NTM88H077T1	935420512528	NTM88H077T1	TPMS 4X4 900kPa X axis	HQFN24FAMWF	SOT1931-1(D)	ASM	No				
NTM88J135T1	935420513528	NTM88J135T1	TPMS 4X4 1100kPa XZ axis	HQFN24FAMWF	SOT1931-1(D)	ASM	No				
NTM88H025T1	935433337528	NTM88H025T1	TPMS 4X4 900kPa Z axis	HQFN24FAMWF	SOT1931-1(D)	ASM	No				