

Product Change Notification / SYST-25USRC973

D	a	t	۵	•
u	a	L	ᆮ	•

05-Sep-2022

Product Category:

8-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - PIC16F17126/46 Silicon Errata and Datasheet Clarifications

Affected CPNs:

SYST-25USRC973_Affected_CPN_09052022.pdf SYST-25USRC973_Affected_CPN_09052022.csv

Notification Text:

SYST-25USRC973

Microchip has released a new Errata for the PIC16F17126/46 Silicon Errata and Datasheet Clarifications of devices. If you are using one of these devices please read the document located at PIC16F17126/46 Silicon Errata and Datasheet Clarifications.

Notification Status: Final

Description of Change: Added new silicon revision B2; updated datasheet revision letter; added silicon issue 1.3.1.

Impacts to Data Sheet: None

Change Implementation Status: Complete

Date Document Changes Effective: 05 Sep 2022

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices:: N/A

Attachments:	
PIC16F17126/46 Silicon Errata and Datasheet Clarifications	
Please contact your local Microchip sales office with questions or concerns regarding this no	tification
	tilication.
Ferms and Conditions:	
f you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at oun name page select register then fill in the required fields. You will find instructions about regis Microchips PCN email service in the PCN FAQ section.	
f you wish to <u>change your PCN profile, including opt out,</u> please go to the <u>PCN home page</u> se and sign into your myMicrochip account. Select a profile option from the left navigation bar a the applicable selections.	

SYST-25USRC973 - ERRATA - PIC16F17126/46 Silicon Errata and Datasheet Clarifications

Affected Catalog Part Numbers (CPN)

PIC16F17146-I/6N

PIC16F17126-I/7N

PIC16F17126-I/P

PIC16F17126-I/SL

PIC16F17126-I/ST

PIC16F17146-I/SS

PIC16F17146-I/SO

PIC16F17146-I/P

Date: Sunday, September 04, 2022

PIC16F17126/46

PIC16F17126/46 Silicon Errata and Datasheet Clarifications

The PIC16F17126/46 devices that you have received conform functionally to the current device data sheet (DS40002343**D**), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in the table below.

The errata described in this document will be addressed in future revisions of the PIC16F17126/46 silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current.

Table 1. Silicon Device Identification

Part Number	Device ID	Revision ID		
rait Nullibei	Device iD	В0	B2	
PIC16F17126	0x30E0	0xA040	0xA042	
PIC16F17146	0x30E1	0xA040	0xA042	



Important: Refer to the **Device/Revision ID** section in the device data sheet for more detailed information on Device Identification and Revision IDs for your specific device.

Silicon Issue Summary

Table 2. Silicon Issue Summary

Module	Feature	Item	Jacua Summany	Affected Revisions		
Module	reature	No.	Issue Summary	В0	B2	
Analog-to-Digital Converter with Computation (ADCC)	Double Sample Conversions	1.1.1	An unexpected acquisition time is added between the first and second conversions.	Х		
Host Synchronous Serial Port (MSSP)	I ² C Start and Stop Interrupt Function	1.2.1	A race condition can cause the Start and/or Stop flags to be set when I ² C is enabled.	Х		
Configuration Words (CONFIG)	Sleep	1.3.1	Waking from Sleep may cause unexpected behavior.	Х		

Note: Only those issues indicated in the last column apply to the current silicon revision.

1. Silicon Errata Issues



Notice: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the bold font in the following tables apply to the current silicon revision.

1.1 Module: Analog-to-Digital Converter with Computation (ADCC)

1.1.1 Double Sample Conversions

When enabling a Double Sample Conversion (DSEN = 1), with no Precharge time (ADPRE = 0) and no Acquisition time (ADACQ = 0), the maximum number of cycles of acquisition time is inserted prior to the second conversion. The first conversion will be performed as expected with no Precharge time and no Acquisition time. It is only between the first and second conversions where a maximum number of cycles of Acquisition time is performed unexpectedly.

Work around

- Method 1: Disable Double Sample Conversion (DSEN = 0) and perform two single conversions back to back.
- Method 2: If adding acquisition time is acceptable, then select no Precharge time, along with the desired Acquisition time.

Affected Silicon Revisions

В0	B2			
X				

1.2 Module: MSSP

1.2.1 The I²C Start and/or Stop Flags May Be Set When I²C Is Enabled

When I²C is enabled, erroneous Start and/or Stop conditions may be detected. This can generate erroneous I²C interrupts if enabled.

Work around

Use the following procedure to correctly detect the Start and Stop conditions:

- 1. Disable the Start and Stop conditions interrupt functions.
- 2. Enable the I²C module.
- 3. Wait 250 ns + six instructions cycles (F_{OSC}/4).
- 4. Clear the Start and Stop conditions interrupt flags.
- 5. Enable the Start and Stop conditions interrupt functions if used.

```
SSPxCON3bits.SCIE = 0;  // Disable Start condition interrupt
SSPxCON3bits.PCIE = 0;  // Disable Stop condition interrupt
SSPxCON1bits.SSPEN = 1;  // Enable I2C

Delay();  // Wait for 250 ns + 6 instruction cycles (Fosc/4)
PIRxbits.SSPxIF = 0;  // Clear the MSSP interrupt flag
SSPxCON3bits.SCIE = 1;  // Enable Start condition interrupt if used
SSPxCON3bits.PCIE = 1;  // Enable Stop condition interrupt if used
```

Affected	Silicon	Revisions
----------	---------	-----------

В0	B2			
X				

1.3 Module: Configuration Words (CONFIG)

1.3.1 Waking from Sleep May Cause Unexpected Behavior

Waking from Sleep may cause unexpected behavior.

Work around

Do not use the SLEEP instruction. If clock switching is available and there is a need for reduced current consumption, switch to the slowest system clock.

Affected Silicon Revisions

В0	B2			
X				

2. **Data Sheet Clarifications**

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS40002343**D**):

Note:

Corrections are shown in bold. Where possible, the original bold text formatting has been removed for clarity.

2.1 None

There are no known data sheet clarifications as of this publication date.

Appendix A: Revision History 3.

Doc Rev.	Date	Comments
В	8/2022	Added new silicon revision B2; updated datasheet revision letter; added silicon issue 1.3.1.
Α	3/2022	Initial release of this document.

Microchip Information

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- Product Support Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- General Technical Support Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- Business of Microchip Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- **Technical Support**

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable". Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

Legal Notice

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded

by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet- Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, Anyln, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2022, Microchip Technology Incorporated and its subsidiaries. All Rights Reserved.

ISBN: 978-1-6683-0853-0

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



Worldwide Sales and Service

AMERICAS ASIA/RACIFIC ASIA/RACIFIC EUROPE 2355 West Chandler Blvd Tel: 61-2-9868-6733 India - Bangafore Tel: 43-7242-2244-39 Tel: 43-7242-2244-39 Chandler, AZ 55/24-6199 China - Beejing India - New Dehi Fex: 43-7242-2244-39 Tel: 43-7242-2244-39 Fax: 480-792-7270 Tel: 86-10-8669-7000 Tel: 91-11-4160-8331 Dommark - Copenhagen Fax: 480-792-7277 China - Chengdu India - Pune Tel: 48-4485-5910 Tachicial Support: Tel: 86-22-8809-5886 Tel: 91-12-01-12-10-141 Fex: 45-4485-2829 Www.microtip.com China - Chongqiing Japan - Tokyo Final 68-68-2829 Allanta Tel: 86-876-8702-980 Tel: 81-3-6880-3770 Tel: 33-16-85-56-20 Fax: 678-98-79-961 Tel: 86-876-8702-980 Tel: 81-3-6880-3770 Tel: 32-16-95-36-20 Fax: 678-98-71-455 China - Hangrhou Korea - Daegu Fex: 33-16-93-99-97 Tel: 678-95-79-961 Tel: 68-86-78-7892-8115 Tel: 82-25-47-400 Tel: 42-9-893-7900 Tel: 678-96-98-70-95 Tel: 68-87-18-872-815 Tel: 82-25-47-400 Tel: 42-22-22-27-200 Tel: 678-98-78-78-78-78-				
2355 West Chandler Blvd. Chandler, AZ 82224-199 China - Beigling Tel: 480-792-7270 Tel: 480-792-7277 China - Chengdu Tel: 86-10-8568-7000 Tel: 86-10-8568-70	AMERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
Chandler, AZ 85224-8199 Tell: 480-792-7277 Tell: 480-8698-8000 Tell: 480-292-8900 Tell: 480-292-9900 T	Corporate Office	Australia - Sydney	India - Bangalore	Austria - Wels
Tel: 48-07-92-7200	2355 West Chandler Blvd.	Tel: 61-2-9868-6733	Tel: 91-80-3090-4444	Tel: 43-7242-2244-39
Fax: 480-792-7277	Chandler, AZ 85224-6199	China - Beijing	India - New Delhi	Fax: 43-7242-2244-393
Technical Support	Tel: 480-792-7200	Tel: 86-10-8569-7000	Tel: 91-11-4160-8631	Denmark - Copenhagen
New Microchip cond Sepo	Fax: 480-792-7277	China - Chengdu	India - Pune	Tel: 45-4485-5910
Web Address:	Technical Support:	Tel: 86-28-8665-5511	Tel: 91-20-4121-0141	Fax: 45-4485-2829
Atlanta	www.microchip.com/support	China - Chongqing	Japan - Osaka	Finland - Espoo
Atlanta	Web Address:	Tel: 86-23-8980-9588	Tel: 81-6-6152-7160	Tel: 358-9-4520-820
Duluth, CA	www.microchip.com	China - Dongguan	Japan - Tokyo	France - Paris
Tel: 68-08-79-614	Atlanta	Tel: 86-769-8702-9880	Tel: 81-3-6880- 3770	Tel: 33-1-69-53-63-20
Fax: 678-957-1455	Duluth, GA	China - Guangzhou	Korea - Daegu	Fax: 33-1-69-30-90-79
Austin, TX	Tel: 678-957-9614	Tel: 86-20-8755-8029	Tel: 82-53-744-4301	Germany - Garching
Tel: 512-257-3370	Fax: 678-957-1455	China - Hangzhou	Korea - Seoul	Tel: 49-8931-9700
Boston	Austin, TX	Tel: 86-571-8792-8115	Tel: 82-2-554-7200	Germany - Haan
Westborough, MA	Tel: 512-257-3370	China - Hong Kong SAR	Malaysia - Kuala Lumpur	Tel: 49-2129-3766400
Tel: 774-760-0087	Boston	Tel: 852-2943-5100	Tel: 60-3-7651-7906	Germany - Heilbronn
Tel: 774-76-0087	Westborough, MA	China - Nanjing	Malaysia - Penang	Tel: 49-7131-72400
Tel: 86-532-8502-7355	=	Tel: 86-25-8473-2460	Tel: 60-4-227-8870	Germany - Karlsruhe
Itasca, IL	Fax: 774-760-0088	China - Qingdao	Philippines - Manila	Tel: 49-721-625370
Itasca, IL	Chicago	Tel: 86-532-8502-7355	Tel: 63-2-634-9065	Germany - Munich
Tel: 630-285-0071 Fax: 630-285-0075 China - Shenyang Dallas Tel: 86-24-233-28-29 Addison, TX China - Shenyhen Tel: 86-24-2334-2829 Addison, TX China - Shenyhen Tel: 86-24-2334-2829 Tel: 86-357-8366 Tel: 48-8031-354-560 Israel - Ra'aman Tel: 49-8031-354-560 Israel - Ra'aman Tel: 49-8031-354-560 Tel: 48-84-8-200 Tel: 86-75-8864-2200 Tel: 886-3-77-8380 Tel: 91-9-844-7510 Rei - Shenyhen Taiwan - Kaohsiung Israel - Ra'aman Tel: 49-8-8031-354-560 Italy - Milan Tel: 91-9-844-7510 Rei - Shenyhen Taiwan - Taipei Tel: 88-8-721-37830 Tel: 89-8-881-3216 Tel: 88-8-8-8-8-8-33-1526 Tel: 88-8-8-22508-8600 Tel: 39-8-48-8100 Tel: 86-27-980-5300 Tel: 68-28-893-31526 Tel: 86-28-893-37-252 Tel: 86-28-893-37-252 Tel: 86-28-893-37-252 Tel: 86-28-893-37-252 Tel: 31-773-8323 Tel: 31-773-8323 Tel: 31-773-8323 Tel: 31-773-8323 Tel: 31-773-8323 Tel: 31-773-8323 Tel: 31-73-80-2380 Los Angeles Los Angeles Los Angeles Rei - Shenyhen Taiwan - Taipei Tel: 88-756-3210040 Tel: 919-844-7510 Rei - Shenyhen Taiwan - Taipei Tel: 88-756-3210040 Tel: 919-844-7510 Rei - Shenyhen Tel: 48-8-8-900-4654 Tel: 48-31-704-60-40 Tel: 49-3-470-40-04 Tel: 48-37-38-9110 Tel: 48-48-4270 Tel: 48-48-4270 Tel: 48-48-4270 Tel: 48-48-4270 Tel: 99-69-51-980	_	China - Shanghai	Singapore	-
Dallas	Tel: 630-285-0071	Tel: 86-21-3326-8000		Fax: 49-89-627-144-44
Dallas	Fax: 630-285-0075	China - Shenyang	Taiwan - Hsin Chu	Germany - Rosenheim
Tel: 972-818-7423 Tel: 86-755-8864-2200 China - Suzhou Tel: 86-86-2-5980-8600 Tel: 86-86-2-5980-5300 Tel: 86-2-698-8600 Tel: 86-2-698-8600 Tel: 86-2-698-8600 Tel: 39-0331-742611 Tel: 39-0331-742611 Tel: 39-0331-742611 Tel: 248-848-4000 Tel: 86-27-5980-5300 Tel: 66-2-694-1351 Tel: 86-28-94-9583 Tel: 86-29-833-7252 Tel: 86-39-2388138 Tel: 317-773-8323 China - Zhuhai Tel: 317-773-5453 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 99-844-7510 New York, NY Tel: 919-844-7510 New York, NY Tel: 68-2-69-4-1351 Tel: 86-2-694-1351 Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 34-2-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 66-31-704-60-40 Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-735-9110 Tel: 408-735-9110 Tel: 905-695-1980	Dallas		Tel: 886-3-577-8366	-
Tel: 972-818-7423 Tel: 972-818-7423 Tel: 86-755-8864-2200 China - Suzhou Tel: 86-86-32-31526 Tel: 86-86-32-31526 Tel: 86-86-32-31526 Tel: 86-86-22-31-742611 Tel: 248-848-4000 Tel: 36-27-5980-5300 Tel: 36-2-698-8600 Tel: 39-0331-742611 Tel: 39-031-742611 Tel: 39-0331-742611 Tel: 39-039-31-742611 Tel: 39-039-31-742611 Tel: 39-039-31-742611 Tel: 39-039-31-742611 Tel: 39-039-31-742611 Tel: 39-039-31-742611 Tel: 39-031-74261 Tel: 39-031-74260 Tel: 39-031-74261 Tel: 39-031-	Addison, TX	China - Shenzhen	Taiwan - Kaohsiung	Israel - Ra'anana
Detroit Tel: 86-186-6233-1526 Tel: 886-2-2508-8600 Tel: 39-0331-742611 Novi, MI China - Wuhan Tel: 86-27-5980-5300 Tel: 66-2-694-1351 Italy - Padova Houston, TX China - Xian Vietnam - Ho Chi Minh Tel: 39-049-7625286 Tel: 86-29-8833-7252 Tel: 86-29-8833-7252 Tel: 86-29-8833-7252 Tel: 86-29-8833-7252 Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340 Tel: 31-773-5453 Tel: 86-592-2388138 Tel: 86-592-2388138 Tel: 317-773-5453 Tel: 86-756-3210040 Tel: 31-416-690340 Tel: 48-22-3325737 Romania - Bucharest Tel: 49-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-91110 Tel: 408-735-91110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 905-705-705-705-7	Tel: 972-818-7423	Tel: 86-755-8864-2200		Tel: 972-9-744-7705
Detroit Tel: 86-186-6233-1526 Tel: 886-2-2508-8600 Tel: 39-0331-742611 Novi, MI China - Wuhan Tel: 86-27-5980-5300 Tel: 66-2-694-1351 Italy - Padova Houston, TX China - Xian Vietnam - Ho Chi Minh Tel: 39-049-7625286 Tel: 86-29-8833-7252 Tel: 86-29-8833-7252 Tel: 86-29-8833-7252 Tel: 86-29-8833-7252 Tel: 84-28-5448-2100 Netherlands - Drunen Tel: 31-416-690399 Fax: 31-416-690340 Tel: 31-773-5453 Tel: 86-592-2388138 Tel: 86-592-2388138 Tel: 317-773-5453 Tel: 86-756-3210040 Tel: 31-416-690340 Tel: 48-22-3325737 Romania - Bucharest Tel: 49-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-91110 Tel: 408-735-91110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 905-705-705-705-7	Fax: 972-818-2924	China - Suzhou	Taiwan - Taipei	Italy - Milan
Novi, MI	Detroit	Tel: 86-186-6233-1526	•	· ·
Houston, TX	Novi, MI	China - Wuhan		Fax: 39-0331-466781
Houston, TX	Tel: 248-848-4000	Tel: 86-27-5980-5300		Italy - Padova
Tel: 281-894-5983 ITel: 86-29-8833-7252 China - Xiamen Noblesville, IN Tel: 86-592-2388138 China - Zhuhai Tel: 317-773-5453 Tel: 86-756-3210040 Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-90 Fax: 34-91-708-08-91 Tel: 46-31-708-08-91 Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Canada - Toronto Tel: 905-695-1980	Houston, TX	China - Xian	Vietnam - Ho Chi Minh	_
Noblesville, IN Tel: 86-592-2388138 China - Zhuhai Tel: 317-773-8323 Tel: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Tel: 47-72884388 Tel: 48-22-3325737 Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Tel: 46-31-704-60-40 Tel: 46-31-704-60-40 Tel: 408-735-9110 Tel: 408-436-4270 Tel: 905-695-1980	•	Tel: 86-29-8833-7252	Tel: 84-28-5448-2100	Netherlands - Drunen
Tel: 317-773-8323	Indianapolis	China - Xiamen		Tel: 31-416-690399
Fax: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Poland - Warsaw Tel: 48-22-3325737 Romania - Bucharest Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 86-756-3210040 Tel: 48-22-3325737 Romania - Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 408-735-9110 Tel: 408-735-9110 Tel: 408-735-9110 Tel: 408-136-4270 Tel: 905-695-1980	Noblesville, IN	Tel: 86-592-2388138		Fax: 31-416-690340
Fax: 317-773-5453 Tel: 86-756-3210040 Tel: 47-72884388 Tel: 317-536-2380 Poland - Warsaw Los Angeles Tel: 48-22-3325737 Mission Viejo, CA Romania - Bucharest Tel: 949-462-9523 Tel: 40-21-407-87-50 Fax: 949-462-9608 Spain - Madrid Tel: 951-273-7800 Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 408-735-6000 Sweden - Stockholm Tel: 408-735-9110 UK - Wokingham Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820		China - Zhuhai		Norway - Trondheim
Los Angeles Tel: 48-22-3325737 Mission Viejo, CA Romania - Bucharest Tel: 949-462-9523 Tel: 40-21-407-87-50 Fax: 949-462-9608 Spain - Madrid Tel: 951-273-7800 Tel: 34-91-708-08-90 Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 UK - Wokingham Tel: 408-436-4270 Fax: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820	Fax: 317-773-5453	Tel: 86-756-3210040		
Mission Viejo, CA Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Roward - Gothen Bucharest Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Tel: 34-91-708-08-91 Tel: 34-91-708-08-91 Tel: 46-31-704-60-40 Sweden - Gothenberg Tel: 46-31-704-60-40 Tel: 46-8-5090-4654 UK - Wokingham Tel: 408-436-4270 Fax: 44-118-921-5820	Tel: 317-536-2380			Poland - Warsaw
Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	Los Angeles			Tel: 48-22-3325737
Tel: 949-462-9523 Fax: 949-462-9608 Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 40-21-407-87-50 Spain - Madrid Tel: 34-91-708-08-90 Fax: 34-91-708-08-91 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	Mission Viejo, CA			Romania - Bucharest
Tel: 951-273-7800 Raleigh, NC Tel: 919-844-7510 New York, NY Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Tel: 34-91-708-08-90 Fax: 34-91-708-08-90 Fax: 34-91-708-08-90 Sweden - Gothenberg Tel: 46-31-704-60-40 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800	<u>=</u>			Tel: 40-21-407-87-50
Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820 Tel: 905-695-1980 Tel: 44-118-921-5820	Fax: 949-462-9608			Spain - Madrid
Raleigh, NC Fax: 34-91-708-08-91 Tel: 919-844-7510 Sweden - Gothenberg New York, NY Tel: 46-31-704-60-40 Seeden - Stockholm Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 UK - Wokingham UK - Wokingham Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820	Tel: 951-273-7800			Tel: 34-91-708-08-90
New York, NY Tel: 46-31-704-60-40 Tel: 631-435-6000 Sweden - Stockholm San Jose, CA Tel: 46-8-5090-4654 Tel: 408-735-9110 UK - Wokingham Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Fax: 44-118-921-5820 Tel: 905-695-1980 Fax: 44-118-921-5820				Fax: 34-91-708-08-91
Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	Tel: 919-844-7510			Sweden - Gothenberg
Tel: 631-435-6000 San Jose, CA Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 Sweden - Stockholm Tel: 46-8-5090-4654 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	New York, NY			_
Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	·			Sweden - Stockholm
Tel: 408-735-9110 Tel: 408-436-4270 Canada - Toronto Tel: 905-695-1980 UK - Wokingham Tel: 44-118-921-5800 Fax: 44-118-921-5820	San Jose, CA			Tel: 46-8-5090-4654
Tel: 408-436-4270 Tel: 44-118-921-5800 Canada - Toronto Tel: 905-695-1980 Tel: 905-695-1980				UK - Wokingham
Canada - Toronto Fax: 44-118-921-5820 Tel: 905-695-1980 Fax: 44-118-921-5820				
Tel: 905-695-1980				
Fax: 905-695-2078	Fax: 905-695-2078			