

### **Customer Information Notification**

202207020I: MKW40Z/30Z/20Z Reference Manual Update to Rev 1.4.1

**Note:** This notice is NXP Company Proprietary.

Issue Date: Oct 04, 2022 Effective date: Oct 05, 2022

Here is your personalized notification about a NXP general announcement. For detailed information we invite you to view this notification online

#### **Management summary**

Reference Manual (RM) update for the MKW40Z/30Z/20Z to revision 1.4.1.

### **Change Category**

[ ]Wafer Fab Process	[]Assembly Process	[]Product Marking	[]Test Process	[]Design
[ ]Wafer Fab Materials	[ ]Assembly Materials	[ ]Mechanical Specification	[]Test Equipment	[]Errata
[ ]Wafer Fab Location	[ ]Assembly Location	[]Packing/Shipping/Labeling	[]Test Location	[]Electrica spec./Test coverage
[]Firmware	[X]Other: Re	eference Manual		

# **PCN** Overview

# **Description**

NXP Semiconductors announces a Reference Manual (RM) update for the MKW40Z/30Z/20Z to revision 1.4.1. The Chapter 56 included in the updated document provides a detailed description of the changes.

Changes are summarized below.

### Reference Manual Changes:

- 1. Removed the DTEST\_PAGE bitfield from the XCVR\_DTEST\_CTRL register.
- 2. Added I2C1 interrupt at 0x0000\_0064 in Table 3-6. Interrupt vector assignment in Chip Configuration.
- 3. DCDC\_REG2[DCDC\_LOOPCTRL\_EN\_RCSCALE] added at bit[10:9]. Also updated bit field descriptions of the registers in DCDC Converter(DCDC).
- 4. Removed test registers: C12, S2 and T3 in Multipurpose Clock Generator (MCG).
- 5. Updated register information in Universal Asynchronous Receiver/Transmitter (UART0).
- 6. Updated access value of Key Size(KS) register to RO in LP Trusted Cryptography (LTC).
- 7. Removed test register Radio System Integration Module(RSIM).

8. Updated access values of the following registers to RW: XCVR\_PLL\_HPM\_CAL\_CTRL, XCVR\_PLL\_LD\_HPM\_CAL1, and XCVR\_PLL\_LD\_HPM\_CAL2 in Transceiver Registers.
9. Updated access value of the BLE\_RF\_REGS\_BLE\_PART\_ID register to RO in BLE RF Registers.
10. Updated access value of ZLL\_SAM\_MATCH register to RO and access value of ZLL\_FILTERFAIL\_CODE register to RW in Zigbee Registers.

The MKW40Z/30Z/20Z Reference Manual revision 1.4 is attached to this notice, and can be found at:

https://www.nxp.com/products/wireless/multiprotocol-mcus/kinetis-kw40z-2-4-ghz-dual-mode-bluetooth-low-energy-and-802-15-4-wireless-radio-microcontroller-mcu-based-on-arm-cortex-m0-plus-core:KW40Z?fpsp=1&#documentation

#### Reason

The Reference Manual has been updated to correct errors and / or provide additional technical clarification on some device features.

#### **Identification of Affected Products**

Product identification does not change

## Anticipated Impact on Form, Fit, Function, Reliability or Quality

No Impact on form, fit, function, reliability or quality

### Additional information

Additional documents: view online

### **Contact and Support**

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly:

Name H.C Zhu

Position Product Engineer

e-mail

address <u>hongchao.zhu@nxp.com</u>

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

#### **About NXP Semiconductors**

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your

organization. This message has been automatically distributed. Please do not reply .

NXP Semiconductors

High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006- 2022 NXP Semiconductors. All rights reserved.