



Product Change Notification / SYST-14KFNM046

Date:

17-Mar-2023

Product Category:

8-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - PIC16(L)F1782/1783 Family Silicon Errata and Data Sheet Clarification

Affected CPNs:

[SYST-14KFNM046_Affected_CPN_03172023.pdf](#)

[SYST-14KFNM046_Affected_CPN_03172023.csv](#)

Notification Text:

SYST-14KFNM046

Microchip has released a new Errata for the PIC16(L)F1782/1783 Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [PIC16\(L\)F1782/1783 Family Silicon Errata and Data Sheet Clarification](#).

Notification Status: Final

Description of Change: Updated Table 2; Added sections 6.3 and 6.4; Other minor corrections.

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 17 Mar 2023

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

[PIC16\(L\)F1782/1783 Family Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

PIC16F1783-E/SP
PIC16F1783-E/ML
PIC16F1783-E/SS
PIC16F1783-E/SO
PIC16F1783-E/MV
PIC16F1783-I/SP
PIC16F1783-I/ML
PIC16F1783-I/SS
PIC16F1783-I/SO
PIC16F1783-I/SOC02
PIC16F1783-I/SOC04
PIC16F1783-I/MV
PIC16F1783T-I/ML
PIC16F1783T-I/SS
PIC16F1783T-I/SO
PIC16F1783T-I/SOC02
PIC16F1783T-I/SOC04
PIC16F1783T-I/MV024
PIC16F1783T-I/MV
PIC16F1783T-E/MLVAO
PIC16F1783T-E/SS
PIC16F1783T-E/SSV01
PIC16F1783T-E/SSVAO
PIC16F1783T-E/MV
PIC16F1782-E/SP
PIC16F1782-E/ML
PIC16F1782-E/SS
PIC16F1782-E/SO
PIC16F1782-E/MV
PIC16F1782-E/MVVAO
PIC16F1782-I/SP
PIC16F1782-I/ML
PIC16F1782-I/SS
PIC16F1782-I/SSVAO
PIC16F1782-I/SO
PIC16F1782-I/MV
PIC16F1782T-I/ML
PIC16F1782T-I/SS
PIC16F1782T-I/SO
PIC16F1782T-I/MV
PIC16F1782T-E/ML
PIC16F1782T-E/MVVAO
PIC16LF1783-E/SP
PIC16LF1783-I/SP
PIC16LF1783-I/ML
PIC16LF1783-I/SSC01

PIC16LF1783-I/SS
PIC16LF1783-I/SO
PIC16LF1783-I/MV
PIC16LF1783T-I/ML
PIC16LF1783T-I/SSC01
PIC16LF1783T-I/SS
PIC16LF1782-E/SP
PIC16LF1782-E/ML
PIC16LF1782-E/SO
PIC16LF1782-I/SP
PIC16LF1782-I/SS
PIC16LF1782-I/SO
PIC16LF1782-I/MV
PIC16LF1782T-I/SS

PIC16(L)F1782/1783 Family Silicon Errata and Data Sheet Clarification

The PIC16(L)F1782/1783 family devices that you have received conform functionally to the current Device Data Sheet (DS400001579E), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).


The errata described in this document will be addressed in future revisions of the PIC16(L)F1782/1783 silicon.

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (**B4**).

Data Sheet clarifications and corrections start on page 11, following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers, and emulation tools, which are available at the Microchip corporate web site (www.microchip.com).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
 - a) For MPLAB IDE 8, select *Programmer > Reconnect*.
 - b) For MPLAB X IDE, select *Window > Dashboard* and click the **Refresh Debug Tool Status** icon ().
5. Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

Note: If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various PIC16(L)F1782/1783 silicon revisions are shown in [Table 1](#).

TABLE 1: SILICON DEVREV VALUES

Part Number	DEVICE ID[13:0] ^{(1),(2)}		
	DEV[8:0]	REV[4:0] Silicon Revision	
		B2	B4
PIC16F1782	01 0111 000	0 0110	0 1000
PIC16LF1782	01 0111 001	0 0110	0 1000
PIC16F1783	01 0110 010	0 0110	0 1000
PIC16LF1783	01 0111 010	0 0110	0 1000

- Note 1:** The Device ID is located in the configuration memory at address 8006h.
- 2:** Refer to the “PIC16(L)F178X Memory Programming Specification” (DS41457) for detailed information on Device and Revision IDs for your specific device.

PIC16(L)F1782/1783

TABLE 2: SILICON ISSUE SUMMARY

Module	Feature	Item Number	Issue Summary	Affected Revisions ⁽¹⁾	
				B2	B4
ADC	Fosc/2	1.1	Fosc/2 not functional.	X	
ADC	Offset	1.2	Time between conversions affects offset.	X	
ADC	INL (12-bit mode)	1.3	INL is ± 4 LSb.	X	
ADC	FRC	1.4	ADC not functional if using FRC with Fosc < 2 MHz.	X	
Op Amp	Offset	2.1	Offset increases when Common mode < 200 mV.	X	
Comparator	Low-Power mode	3.1	Improper Low-Power mode operation.	X	X
Comparator	Typical Offset Performance mode	3.2	Normal Speed mode.	X	
Data EEPROM	Endurance	4.1	Limited to 10k cycles, VDD < 2.3V, PIC16LF1782/1783.	X	
HF Internal Oscillator	Clock Switching	5.1	Clock switching can cause a single corrupted instruction.	X	
PSMC	Rising Edge Input	6.1	Period and falling edge race condition.	X	X
PSMC	Auto-shutdown	6.2	Failure to auto-restart after shutdown from comparator.	X	
PSMC	Auto-shutdown	6.3	The PSMC fails to Auto-Restart under certain conditions.	X	X
PSMC	Auto-shutdown	6.4	The PxASE bit may be stuck high in Auto-Shutdown mode.	X	X
Low-Dropout (LDO) Voltage Regulator	Low-Power Sleep	7.1	Unexpected Resets may occur at ambient temperatures below 0°C.	X	X
FVR	FVR Module	8.1	Use of FVR module can cause device to Reset.	X	X
PFM	PFM Self-Write	9.1	PFM self-write will not work depending on clock selection.		X

Note 1: Only those issues indicated in the last column apply to the current silicon revision.

Silicon Errata Issues

Note: This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (**B4**).

1. Module: ADC

1.1 Operation with FOSC/2

The ADC is not functional when the ADCS[2:0] bits of ADCON1 select the FOSC/2 frequency.

Work around

Use the FRC selection which provides a valid TAD time, regardless of the system clock frequency.

Affected Silicon Revisions

B2	B4							
X								

1.2 ADC Offset

The offset error exceeds the data sheet specification when the time between conversions is greater than 100 us.

Work around

The time dependent error is insignificant when the time between conversions is less than 100 us. When the time between conversions is greater than 100 us, take two back-to-back ADC conversions and discard the results of the first conversion.

Affected Silicon Revisions

B2	B4							
X								

PIC16(L)F1782/1783

1.3 ADC INL (12-bit mode)

The ADC linearity is ± 4 LSB for the 12-bit mode. Below are typical INL graphs in 12-bit mode (See [Figure 1](#) and [Figure 2](#)).

Work around

None.

Affected Silicon Revisions

B2	B4						
X							

FIGURE 1: ADC 12-BIT MODE, SINGLE-ENDED INL, $V_{DD} = 3.0V$, $T_{AD} = 4 \mu s$, $25^{\circ}C$, TYPICAL MEASURED VALUES





FIGURE 2: ADC 12-BIT MODE, SINGLE-ENDED INL, $V_{DD} = 5.5V$, $T_{AD} = 4 \mu s$, $25^{\circ}C$, TYPICAL MEASURED VALUES



1.4 Incorrect Readings if using Fosc < 2 MHz

The ADC is not functional if using FRC with Fosc frequencies less than 2 MHz.

Work around

Use frequencies greater than 2 MHz for correct ADC functionality.

Affected Silicon Revisions

B2	B4						
X							

2. Module: Op Amp

2.1 Offset at Low Common Mode

The op amp offset at Common mode input voltages below 200 mV increases with respect to temperature. Below are typical graphs showing the increase in offset (See [Figure 3](#), [Figure 4](#) and [Figure 5](#)).


Work around

None.

Affected Silicon Revisions


B2	B4						
X							

FIGURE 3: OP AMP TYPICAL OFFSET VOLTAGE AT 25°C, HIGH GBWP MODE (OPAxSP = 1), VDD = 3.6V, 0V ≤ CMV ≤ 5.5V




PIC16(L)F1782/1783

**FIGURE 4: OP AMP TYPICAL OFFSET VOLTAGE AT LOW VCM, 85°C,
HIGH GBWP MODE (OPAxSP = 1), V_{DD} = 3.6V, 0V ≤ CMV ≤ 0.5V**



**FIGURE 5: OP AMP TYPICAL OFFSET VOLTAGE AT 85°C,
HIGH GBWP MODE (OPAxSP = 1), V_{DD} = 3.6V, 0.5V ≤ CMV ≤ 3.5V**



3. Module: Comparator

3.1 No Low-Power, No Low-Speed Mode

The comparator operation in Low-Power, Low-Speed mode ($CxSP = 0$) may not perform properly.

Work around

Use the comparator in High Power mode.

Affected Silicon Revisions

B2	B4						
X	X						

3.2 Typical Offset Performance

CMRR performance for the range of $V_{SS} + 1V$ to $V_{DD} - 1V$ is better than specified in the data sheet.


Work around

See [Figure 6](#) and [Figure 7](#).

Affected Silicon Revisions


B2	B4						
X							

FIGURE 6: COMPARATOR INPUT OFFSET, TYPICAL MEASURED VALUES, NORMAL SPEED MODE ($CxSP = 1$), $V_{DD} = 5.5V$, PIC16F1782/1783 ONLY



PIC16(L)F1782/1783

FIGURE 7: COMPARATOR INPUT OFFSET, TYPICAL MEASURED VALUES, NORMAL SPEED MODE (CxSP = 1), VDD = 3.2V



4. Module: Data EEPROM

4.1 Endurance of the Data EEPROM is 10k

The write/erase endurance of the data EE memory is limited to 10k cycles when VDD < 2.3V. This errata applies to the PIC16LF1782/1783 only.

Work around

Use an error correction method that stores data in multiple locations.

Affected Silicon Revisions

B2	B4						
X							

5. Module: HF Internal Oscillator

5.1 Clock Switching

When switching clock sources between INTOSC clock source and an external clock source, one corrupted instruction may be executed after the switch occurs.

This issue affects Two-Speed Start-up operation.

Work around

When switching from an external oscillator clock source, first switch to 16 MHz HFINTOSC. Once running at 16 MHz HFINTOSC, configure IRCF to run at desired internal oscillator frequency.

When switching from an internal oscillator (INTOSC) to an external oscillator clock source, first switch to HFINTOSC High-Power mode (8 MHz or 16 MHz). Once running from HFINTOSC, switch to the external oscillator clock source.

Affected Silicon Revisions

B2	B4						
X							

6. Module: PSMC

6.1 Rising Edge Inhibit

When the period and falling edge sources are from the same asynchronous input, then a race condition may occur where the period is detected before the falling edge. When this occurs, then the falling edge properly terminates the cycle but subsequent rising edge inputs are ignored.

Work around

To configure the PSMC for fixed off-time and variable frequency, set the following:

- Period = Asynchronous feedback
- Rising Event = Synchronous @ PSMCxPH = 0
- Falling Event = Synchronous @ PSMCxDC = Off Time
- Output inverted so drive time is from falling event to period event.

Affected Silicon Revisions

B2	B4						
X	X						

6.2 Auto-Restart

When auto-shutdown is configured for auto-restart and the shutdown source is a comparator, then auto-restart may fail to occur after the shutdown condition ceases.

Work around

Enable the zero-latency filter of the comparator used for auto-shutdown.

Affected Silicon Revisions

B2	B4						
X	X						

6.3 The PSMC Fails to Auto-Restart Under Certain Conditions

Under the following conditions, the PSMC may fail to Auto-Restart:

- Ambient temperature is above 50°C
- PSMC clock frequency is above 32 MHz
- PSMC Operating mode = Push-pull output
- PSMCxPHH = 0 and PSMCxPHL = 0

Work around

- Select a PSMC clock source that is less than or equal to 32 MHz
- Delay the rising and falling events by increasing the value of the PSMCxPHL and PSMCxDC by 0x01 or higher value
- When the auto-shutdown source deasserts, toggle the PSMCxEN bit to restart the PSMC output

Affected Silicon Revisions

B2	B4						
X	X						

6.4 The PxASE Bit May be Stuck High in Auto-Shutdown Mode

When Auto-Shutdown is configured for Auto-Restart, the PxASE bit may be stuck high when the Auto-Shutdown source deasserts. When this occurs, the PSMC outputs will get stuck in their shutdown states and will not be able to start.

Work around

When the Auto-Shutdown source deasserts, toggle the PSMCxEN bit to restart the PSMC outputs.

Affected Silicon Revisions

B2	B4						
X	X						

7. Module: Low-Dropout (LDO) Voltage Regulator

7.1 Low-Power Sleep mode at ambient temperatures below 0°C

Under the following conditions:

- ambient temperatures below 0°C
- while in Sleep mode
- VREGCON configured for Low-Power Sleep mode (VREGPM = 1)

On very rare occasions, the LDO voltage will drop below the minimum V_{DD}, causing unexpected device Resets.

PIC16(L)F1782/1783

Work around

For applications that operate at ambient temperatures below 0°C, use the LDO voltage regulator in Normal-Power mode (VREGPM = 0).

Affected Silicon Revisions

B2	B4						
X	X						

8. Module: FVR

8.1 FVR Module

When using the FVR module, if the gain amplifier outputs are set via the CDAFVR or ADFVR bits in FVRCON while the module is disabled (FVREN = 0), the internal oscillator frequency may shift, device current consumption can increase, and a Brown-out Reset may occur. Additionally, after the FVREN is enabled, a switch from 4x to 1x can also cause a Reset.

Work around

Set the FVREN bit of FVRCON to enable the module prior to adjusting the amplifier output selections with the CDAFVR and ADFVR bits. Always set the amplifier output selections to off ('00') before disabling the FVR module.

When switching from 4x to 1x, first switch from 4x to 2x and then from 2x to 1x.

Affected Silicon Revisions

B2	B4						
X	X						

9. Module: PFM Self-Writes

9.1 PFM

Writes to the PFM will not execute if the device's clock source is HS, ECH, or the Internal oscillator is at either 8 MHz or 16 MHz. The DFM is unaffected.

Work around

To write to the PFM, the clock source must be one of the following settings: Internal oscillator set to 4 MHz or lower, ECM, ECL, XT, External RC, LP or T1OSC.

Affected Silicon Revisions

B2	B4						
	X						

Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS400001579E):

<p>Note: Corrections are shown in bold. Where possible, the original bold text formatting has been removed for clarity.</p>

None.

PIC16(L)F1782/1783

APPENDIX A: DOCUMENT REVISION HISTORY

Rev A Document (03/2012)

Initial release of this document.

Rev B Document (07/2012)

Added MPLAB X IDE; Added Silicon Revision B4;
Updated Module 6.1; Added Modules 6.2, 7, 8 and 9.

Rev C Document (09/2012)

Removed Silicon Revision B4 from Module 4, Data
EEPROM.

Rev D Document (05/2014)

Added Module 1.4; Other minor corrections.

Rev E Document (03/2023)

Updated Table 2; Added sections 6.3 and 6.4; Other
minor corrections.

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable" Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at <https://www.microchip.com/en-us/support/design-help/client-support-services>.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Klear, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet-Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2012-2023, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN: 978-1-6683-2160-7



MICROCHIP

Worldwide Sales and Service

AMERICAS

Corporate Office
2355 West Chandler Blvd.
Chandler, AZ 85224-6199
Tel: 480-792-7200
Fax: 480-792-7277
Technical Support:
<http://www.microchip.com/support>
Web Address:
www.microchip.com

Atlanta

Duluth, GA
Tel: 678-957-9614
Fax: 678-957-1455

Austin, TX

Tel: 512-257-3370

Boston

Westborough, MA
Tel: 774-760-0087
Fax: 774-760-0088

Chicago

Itasca, IL
Tel: 630-285-0071
Fax: 630-285-0075

Dallas

Addison, TX
Tel: 972-818-7423
Fax: 972-818-2924

Detroit

Novi, MI
Tel: 248-848-4000

Houston, TX

Tel: 281-894-5983

Indianapolis

Noblesville, IN
Tel: 317-773-8323
Fax: 317-773-5453
Tel: 317-536-2380

Los Angeles

Mission Viejo, CA
Tel: 949-462-9523
Fax: 949-462-9608
Tel: 951-273-7800

Raleigh, NC

Tel: 919-844-7510

New York, NY

Tel: 631-435-6000

San Jose, CA

Tel: 408-735-9110
Tel: 408-436-4270

Canada - Toronto

Tel: 905-695-1980
Fax: 905-695-2078

ASIA/PACIFIC

Australia - Sydney
Tel: 61-2-9868-6733

China - Beijing
Tel: 86-10-8569-7000

China - Chengdu
Tel: 86-28-8665-5511

China - Chongqing
Tel: 86-23-8980-9588

China - Dongguan
Tel: 86-769-8702-9880

China - Guangzhou
Tel: 86-20-8755-8029

China - Hangzhou
Tel: 86-571-8792-8115

China - Hong Kong SAR
Tel: 852-2943-5100

China - Nanjing
Tel: 86-25-8473-2460

China - Qingdao
Tel: 86-532-8502-7355

China - Shanghai
Tel: 86-21-3326-8000

China - Shenyang
Tel: 86-24-2334-2829

China - Shenzhen
Tel: 86-755-8864-2200

China - Suzhou
Tel: 86-186-6233-1526

China - Wuhan
Tel: 86-27-5980-5300

China - Xian
Tel: 86-29-8833-7252

China - Xiamen
Tel: 86-592-2388138

China - Zhuhai
Tel: 86-756-3210040

ASIA/PACIFIC

India - Bangalore
Tel: 91-80-3090-4444

India - New Delhi
Tel: 91-11-4160-8631

India - Pune
Tel: 91-20-4121-0141

Japan - Osaka
Tel: 81-6-6152-7160

Japan - Tokyo
Tel: 81-3-6880-3770

Korea - Daegu
Tel: 82-53-744-4301

Korea - Seoul
Tel: 82-2-554-7200

Malaysia - Kuala Lumpur
Tel: 60-3-7651-7906

Malaysia - Penang
Tel: 60-4-227-8870

Philippines - Manila
Tel: 63-2-634-9065

Singapore
Tel: 65-6334-8870

Taiwan - Hsin Chu
Tel: 886-3-577-8366

Taiwan - Kaohsiung
Tel: 886-7-213-7830

Taiwan - Taipei
Tel: 886-2-2508-8600

Thailand - Bangkok
Tel: 66-2-694-1351

Vietnam - Ho Chi Minh
Tel: 84-28-5448-2100

EUROPE

Austria - Wels
Tel: 43-7242-2244-39
Fax: 43-7242-2244-393

Denmark - Copenhagen
Tel: 45-4485-5910
Fax: 45-4485-2829

Finland - Espoo
Tel: 358-9-4520-820

France - Paris
Tel: 33-1-69-53-63-20
Fax: 33-1-69-30-90-79

Germany - Garching
Tel: 49-8931-9700

Germany - Haan
Tel: 49-2129-3766400

Germany - Heilbronn
Tel: 49-7131-72400

Germany - Karlsruhe
Tel: 49-721-625370

Germany - Munich
Tel: 49-89-627-144-0
Fax: 49-89-627-144-44

Germany - Rosenheim
Tel: 49-8031-354-560

Israel - Ra'anana
Tel: 972-9-744-7705

Italy - Milan
Tel: 39-0331-742611
Fax: 39-0331-466781

Italy - Padova
Tel: 39-049-7625286

Netherlands - Drunen
Tel: 31-416-690399
Fax: 31-416-690340

Norway - Trondheim
Tel: 47-7288-4388

Poland - Warsaw
Tel: 48-22-3325737

Romania - Bucharest
Tel: 40-21-407-87-50

Spain - Madrid
Tel: 34-91-708-08-90
Fax: 34-91-708-08-91

Sweden - Gothenberg
Tel: 46-31-704-60-40

Sweden - Stockholm
Tel: 46-8-5090-4654

UK - Wokingham
Tel: 44-118-921-5800
Fax: 44-118-921-5820