

Product Change Notification / SYST-27NPXN861

١ ـ	1	_	
ıa	т	Δ	۰
		·	

29-Jun-2023

Product Category:

8-bit Microcontrollers

PCN Type:

Document Change

Notification Subject:

ERRATA - AVR64EA28/32/48 Silicon Errata and Data Sheet Clarifications

Affected CPNs:

SYST-27NPXN861_Affected_CPN_06292023.pdf SYST-27NPXN861_Affected_CPN_06292023.csv

Notification Text:

SYST-27NPXN861

Microchip has released a new Errata for the AVR64EA28/32/48 Silicon Errata and Data Sheet Clarifications of devices. If you are using one of these devices please read the document located at AVR64EA28/32/48 Silicon Errata and Data Sheet Clarifications.

Notification Status: Final

Description of Change:

Added errata:

- 2.2.3. Write Operation Lost if Consecutive Writes to Specific Address Spaces
- 2.4.2. Flash-Self Programming Failing When Flash Read During Programming Removed errata:
- NVMCTRL: Flash Page Erase/Write Operation Non-Functional

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 29 Jun 2023

NOTE: Please be advised that this is a change to the document only the product has not been changed. Markings to Distinguish Revised from Unrevised Devices: N/A
Attachments:
AVR64EA28/32/48 Silicon Errata and Data Sheet Clarifications
Please contact your local Microchip sales office with questions or concerns regarding this notification.
Terms and Conditions:
If you wish to <u>receive Microchip PCNs via email</u> please register for our PCN email service at our <u>PCN</u> home page select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the <u>PCN FAQ</u> section.
If you wish to <u>change your PCN profile</u> , <u>including opt out</u> , please go to the <u>PCN home page</u> select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

SYST-27NPXN861 - ERRATA - AVR64EA28/32/48 Silicon Errata and Data Sheet Clarifications

Affected Catalog Part Numbers (CPN)

AVR64EA28-I/SP

AVR64EA28-I/SS

AVR64EA28-I/STX

AVR64EA28T-I/SS

AVR64EA32-I/PT

AVR64EA32-I/RXB

AVR64EA32T-I/PT

AVR64EA32T-I/RXB

AVR64EA48-I/6LX

AVR64EA48-I/PT

AVR64EA48T-I/6LX

AVR64EA48T-I/6LXC01

AVR64EA48T-I/PT

Date: Wednesday, June 28, 2023

Silicon Errata and Data Sheet Clarifications

AVR64EA28/32/48



The AVR64EA28/32/48 devices you have received conform functionally to the current device data sheet (www.microchip.com/DS40002443), except for the anomalies described in this document. The errata described in this document will likely be addressed in future revisions of the AVR64EA28/32/48 devices.

Notes:

- This document summarizes all the silicon errata issues from all the silicon revisions, previous and current
- Refer to the Device/Revision ID section in the current device data sheet (www.microchip.com/DS40002443)
 for more detailed information on Device Identification and Revision IDs for your specific device, or contact
 your local Microchip sales office for assistance

1. Silicon Issue Summary

Legend

- Erratum is not applicable.
- X Erratum is applicable.

Peripheral	Short Description	Valid for Silicon Revision
		Rev. B1 ⁽¹⁾
Device	2.2.1. NVM Programming Does Not Work Below 2.7V	X
	2.2.2. Reduced Flash Endurance for VDD Below BODLEVEL3	X
	2.2.3. Write Operation Lost if Consecutive Writes to Specific Address Spaces	X
CRCSCAN	2.3.1. Running CRC Scan on Part of The Flash is Non-Functional	X
NVMCTRL	2.4.1. Flash Multi Page Erase Non-Functional from UPDI	X
	2.4.2. Flash-Self Programming Failing When Flash Read During Programming	X
USART	2.5.1. Receiver Non-Functional after Detection of Inconsistent Synchronization Field	X

Note:

1. This revision is the initial release of the silicon.



2. Silicon Errata Issues

2.1 Errata Details

- Erratum is not applicable.
- X Erratum is applicable.

2.2 Device

2.2.1 NVM Programming Does Not Work Below 2.7V

Performing an erase or write operation when V_{DD} is below 2.7V may fail. Recommending to make sure that V_{DD} is above 2.7V before starting an erase or a write operation. Alternatively, BOD can be enabled with a level set to BODLEVEL2 or higher.

Work Around

None.

Affected Silicon Revisions

Rev. B1
X

2.2.2 Reduced Flash Endurance for V_{DD} Below BODLEVEL3

If operating at V_{DD} below BODLEVEL3, Flash endurance is reduced to 1k erase/write cycles. The reduction is independent of the V_{DD} level during erase/write.

Work Around

None

Affected Silicon Revisions

Rev. B1
X

2.2.3 Write Operation Lost if Consecutive Writes to Specific Address Spaces

An ST/STD/STS instruction to address > = 64 followed by an ST/STD instruction to address < 64 or SLPCTRL.CTRLA will cause loss of the last write.

Work Around

To avoid loss of write operation, use one of the following workarounds depending on address space:

- Insert a NOP instruction before writing to address < 64, or use the OUT instruction instead of ST/STD
- Insert a NOP instruction before writing to SLPCTRL.CTRLA

Affected Silicon Revisions



2.3 CRCSCAN - Cyclic Redundancy Check Memory Scan

2.3.1 Running CRC Scan on Part of The Flash is Non-Functional

- Running CRC scan on the boot section does not work if FUSE.BOOTSIZE is different from 0x00
- Running CRC scan on the boot and application section does not work if FUSE.CODESIZE is different from 0x00



· Running CRC scan on the entire Flash works

Work Around

None

Affected Silicon Revisions

Rev. B1
X

2.4 NVMCTRL - Nonvolatile Memory Controller

2.4.1 Flash Multi Page Erase Non-Functional from UPDI

Performing a Flash multi-page erase (writing the CMD bitfield in NVMCTRL.CTRLA to FLMPERn) from UPDI does not work on the boot section. It is not recommended to use multi-page erase on any Flash section.

Work Around

Use Flash page erase (writing the CMD bitfield in NVMCTRL.CTRLA to 0x08).

Affected Silicon Revisions



2.4.2 Flash-Self Programming Failing When Flash Read During Programming

If data are read from the Flash NRWW section while the Flash RWW section is being written to or erased (Flash Page Write or Flash Page Erase), the erase or write may fail. Instruction fetch from the Flash NRWW section does not affect erase or write operation to the Flash RWW section.

Work Around

Alternative 1: RWW functionality not needed

• Do not use flash self-programming when executing from the NRWW section

Alternative 2: RWW functionality needed

- Enable BOD in continuous mode (in FUSE.BODCFG, set bitfield LVL to BODLEVEL1 or higher and bitfield ACTIVE to 0x3)
- Do not use the Flash Page Erase and Page Write operation (writing the CMD bitfield in NVMCTRL.CTRLA to 0×05). Execute Flash Page Erase and Flash Page Write as two separate operations instead.

Affected Silicon Revisions

Rev. B1
X

2.5 USART - Universal Synchronous and Asynchronous Receiver and Transmitter

2.5.1 Receiver Non-Functional after Detection of Inconsistent Synchronization Field

The USART Receiver becomes non-functional when the Inconsistent Synchronization Field Interrupt Flag (ISFIF) in the Status (USARTn.STATUS) register is set. The ISFIF interrupt flag is set when the Receiver Mode (RXMODE) bit field in the Control B (USARTn.CTRLB) register is configured to Generic Auto-Baud (GENAUTO) or LIN Constrained Auto-Baud (LINAUTO) mode, and the received synchronization frame does not conform to the conditions described in the data sheet. Clearing the flag does not re-enable the USART Receiver.



Work Around

When the ISFIF interrupt flag is set, disable and re-enable the USART Receiver by first writing a '0' and then a '1' to the Receiver Enable (RXEN) bit in the Control B (USARTn.CTRLB) register.

Affected Silicon Revisions

Rev. B1	
Х	



3. Data Sheet Clarifications

Note the following typographic corrections and clarifications for the latest version of the device data sheet (www.microchip.com/DS40002443).

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

3.1 Electrical Characteristics - RSTCTRL and BOD

A clarification has been made to change the Brown-out Detect Voltage (V_{BOD}) in the *Reset, WDT, Oscillator Start-up Timer, Power-up Timer, Brown-out Detector Specifications* table.

Table 35-15. Reset, WDT, Oscillator Start-up Timer, Power-up Timer, Brown-out Detector Specifications

Symbol	Description	Min.	Typ. †	Max.	Unit	Conditions
t _{RST} *	RESET pin pulse-width low to ensure a Reset	2.5	_	_	μs	
R _{RST_UP} *	RESET pin pull-up resistor	_	35		kΩ	
T _{OST} *	Oscillator start-up timer period ⁽¹⁾	_	1024		cycles	
			1.75	_	V	BODLEVEL0
			1.90	2.10	V	BODLEVEL1
V_{BOD+}	Brown-out Detect Voltage, rising slope ⁽²⁾	_	2.60	2.80	V	BODLEVEL2
			4.30	4.60	V	BODLEVEL3
		1.62	1.75		V	BODLEVEL0
	(2)	1.80	1.90		V	BODLEVEL1
V_{BOD}	Brown-out Detect Voltage, falling slope ⁽²⁾	2.43	2.60		V	BODLEVEL2
		4.05	4.30		V	BODLEVEL3
V_{BOD_HYS}	Brown-out Detect hysteresis	_	25	_	mV	
t _{BOD_ST}	Brown-out Detect start-up time from sleep	_	30		μs	
t _{BOD}	BOD sampling time when used in Sampling mode	_	1/f _{BOD}	_	ms	
t _{BOD_RST}	Brown-out Reset response time	_	4	_	μs	$V_{DD} = V_{BOD} - 0.1V$

[†] Data in the "Typ." column is at $T_A = 25$ °C and $V_{DD} = 3.0$ V unless otherwise specified. These parameters are not tested and are for design guidance only.

Notes:

- 1. By design, the Oscillator Start-up Timer (T_{OST}) counts the first 1024 cycles, independent of frequency.
- 2. VDD and GND must be capacitively decoupled as close to the device as possible to ensure these voltage tolerances. Recommended values are 0.1 µF and 0.01 µF in parallel.



^{*} These parameters are characterized but not tested in production.

4. Document Revision History

Note: The document revision is independent of the silicon revision.

4.1 Revision History

Doc. Rev.	Date	Comments
В	06/2023	Added errata:
		• 2.2.3. Write Operation Lost if Consecutive Writes to Specific Address Spaces
		2.4.2. Flash-Self Programming Failing When Flash Read During Programming
		Removed errata: NVMCTRL: Flash Page Erase/Write Operation Non-Functional
Α	02/2023	Initial document release



Microchip Information

The Microchip Website

Microchip provides online support via our website at www.microchip.com/. This website is used to make files and information easily available to customers. Some of the content available includes:

- Product Support Data sheets and errata, application notes and sample programs, design resources, user's guides and hardware support documents, latest software releases and archived software
- **General Technical Support** Frequently Asked Questions (FAQs), technical support requests, online discussion groups, Microchip design partner program member listing
- **Business of Microchip** Product selector and ordering guides, latest Microchip press releases, listing of seminars and events, listings of Microchip sales offices, distributors and factory representatives

Product Change Notification Service

Microchip's product change notification service helps keep customers current on Microchip products. Subscribers will receive email notification whenever there are changes, updates, revisions or errata related to a specified product family or development tool of interest.

To register, go to www.microchip.com/pcn and follow the registration instructions.

Customer Support

Users of Microchip products can receive assistance through several channels:

- Distributor or Representative
- Local Sales Office
- Embedded Solutions Engineer (ESE)
- Technical Support

Customers should contact their distributor, representative or ESE for support. Local sales offices are also available to help customers. A listing of sales offices and locations is included in this document.

Technical support is available through the website at: www.microchip.com/support

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is "unbreakable".
 Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

Legal Notice

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure



that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Trademarks

The Microchip name and logo, the Microchip logo, Adaptec, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, Quiet- Wire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, Anyln, AnyOut, Augmented Switching, BlueSky, BodyCom, Clockstudio, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, IntelliMOS, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, KoD, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, Omniscient Code Generation, PICDEM, PICDEM.net, PICkit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchroPHY, Total Endurance, Trusted Time, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, and Symmcom are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.



© 2023, Microchip Technology Incorporated and its subsidiaries. All Rights Reserved.

ISBN: 978-1-6683-2663-3

Quality Management System

For information regarding Microchip's Quality Management Systems, please visit www.microchip.com/quality.



Worldwide Sales and Service

MERICAS	ASIA/PACIFIC	ASIA/PACIFIC	EUROPE
orporate Office	Australia - Sydney	India - Bangalore	Austria - Wels
355 West Chandler Blvd.	Tel: 61-2-9868-6733	Tel: 91-80-3090-4444	Tel: 43-7242-2244-39
handler, AZ 85224-6199	China - Beijing	India - New Delhi	Fax: 43-7242-2244-393
el: 480-792-7200	Tel: 86-10-8569-7000	Tel: 91-11-4160-8631	Denmark - Copenhagen
ax: 480-792-7277	China - Chengdu	India - Pune	Tel: 45-4485-5910
echnical Support:	Tel: 86-28-8665-5511	Tel: 91-20-4121-0141	Fax: 45-4485-2829
ww.microchip.com/support	China - Chongqing	Japan - Osaka	Finland - Espoo
eb Address:	Tel: 86-23-8980-9588	Tel: 81-6-6152-7160	Tel: 358-9-4520-820
ww.microchip.com	China - Dongguan	Japan - Tokyo	France - Paris
tlanta	Tel: 86-769-8702-9880	Tel: 81-3-6880- 3770	Tel: 33-1-69-53-63-20
uluth, GA	China - Guangzhou	Korea - Daegu	Fax: 33-1-69-30-90-79
el: 678-957-9614	Tel: 86-20-8755-8029	Tel: 82-53-744-4301	Germany - Garching
ax: 678-957-1455	China - Hangzhou	Korea - Seoul	Tel: 49-8931-9700
ustin, TX	Tel: 86-571-8792-8115	Tel: 82-2-554-7200	Germany - Haan
el: 512-257-3370	China - Hong Kong SAR	Malaysia - Kuala Lumpur	Tel: 49-2129-3766400
oston	Tel: 852-2943-5100	Tel: 60-3-7651-7906	Germany - Heilbronn
estborough, MA	China - Nanjing	Malaysia - Penang	Tel: 49-7131-72400
el: 774-760-0087	Tel: 86-25-8473-2460	Tel: 60-4-227-8870	Germany - Karlsruhe
ax: 774-760-0088	China - Qingdao	Philippines - Manila	Tel: 49-721-625370
hicago	Tel: 86-532-8502-7355	Tel: 63-2-634-9065	Germany - Munich
asca, IL	China - Shanghai	Singapore	Tel: 49-89-627-144-0
el: 630-285-0071	Tel: 86-21-3326-8000	Tel: 65-6334-8870	Fax: 49-89-627-144-44
ax: 630-285-0075	China - Shenyang	Taiwan - Hsin Chu	Germany - Rosenheim
allas	Tel: 86-24-2334-2829	Tel: 886-3-577-8366	Tel: 49-8031-354-560
ddison, TX	China - Shenzhen	Taiwan - Kaohsiung	Israel - Ra'anana
l: 972-818-7423	Tel: 86-755-8864-2200	Tel: 886-7-213-7830	Tel: 972-9-744-7705
x: 972-818-2924	China - Suzhou	Taiwan - Taipei	Italy - Milan
etroit	Tel: 86-186-6233-1526	Tel: 886-2-2508-8600	Tel: 39-0331-742611
ovi, MI	China - Wuhan	Thailand - Bangkok	Fax: 39-0331-466781
el: 248-848-4000	Tel: 86-27-5980-5300	Tel: 66-2-694-1351	Italy - Padova
ouston, TX	China - Xian	Vietnam - Ho Chi Minh	Tel: 39-049-7625286
l: 281-894-5983	Tel: 86-29-8833-7252	Tel: 84-28-5448-2100	Netherlands - Drunen
dianapolis	China - Xiamen		Tel: 31-416-690399
bblesville, IN	Tel: 86-592-2388138		Fax: 31-416-690340
l: 317-773-8323	China - Zhuhai		Norway - Trondheim
x: 317-773-5453	Tel: 86-756-3210040		Tel: 47-72884388
l: 317-536-2380			Poland - Warsaw
s Angeles			Tel: 48-22-3325737
ssion Viejo, CA			Romania - Bucharest
l: 949-462-9523			Tel: 40-21-407-87-50
x: 949-462-9608			Spain - Madrid
l: 951-273-7800			Tel: 34-91-708-08-90
aleigh, NC			Fax: 34-91-708-08-91
el: 919-844-7510			Sweden - Gothenberg
ew York, NY			Tel: 46-31-704-60-40
el: 631-435-6000			Sweden - Stockholm
in Jose, CA			Tel: 46-8-5090-4654
el: 408-735-9110			UK - Wokingham
l: 408-436-4270			Tel: 44-118-921-5800
150 150 1270			Fax: 44-118-921-5820
ınada - Toronto			