



## Product Change Notification / SYST-06XKDI494

---

### Date:

07-Jul-2023

### Product Category:

16-Bit - Microcontrollers and Digital Signal Controllers

### PCN Type:

Document Change

### Notification Subject:

ERRATA - dsPIC33CK1024MP710 Family Silicon Errata and Data Sheet Clarification

### Affected CPNs:

[SYST-06XKDI494\\_Affected\\_CPN\\_07072023.pdf](#)

[SYST-06XKDI494\\_Affected\\_CPN\\_07072023.csv](#)

### Notification Text:

SYST-06XKDI494

Microchip has released a new Errata for the dsPIC33CK1024MP710 Family Silicon Errata and Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [dsPIC33CK1024MP710 Family Silicon Errata and Data Sheet Clarification](#).

**Notification Status:** Final

**Description of Change:**

- Added silicon errata issue 7 (Reset)

**Impacts to Data Sheet:** None

**Reason for Change:** To Improve Productivity

**Change Implementation Status:** Complete

**Date Document Changes Effective:** 07 Jul 2023

**NOTE:** Please be advised that this is a change to the document only the product has not been changed.

**Markings to Distinguish Revised from Unrevised Devices:** N/A

## Attachments:

[dsPIC33CK1024MP710 Family Silicon Errata and Data Sheet Clarification](#)

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

## Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

DSPIC33CK1024MP705-E/M7  
DSPIC33CK512MP705-E/M7  
DSPIC33CK256MP705-E/M7  
DSPIC33CK1024MP706-E/MR  
DSPIC33CK512MP706-E/MR  
DSPIC33CK256MP706-E/MR  
DSPIC33CK1024MP706-E/PT  
DSPIC33CK512MP706-E/PT  
DSPIC33CK256MP706-E/PT  
DSPIC33CK1024MP710-E/PT  
DSPIC33CK512MP710-E/PT  
DSPIC33CK256MP710-E/PT  
DSPIC33CK1024MP710-E/PTVAO  
DSPIC33CK1024MP708-E/PT  
DSPIC33CK512MP708-E/PT  
DSPIC33CK256MP708-E/PT  
DSPIC33CK1024MP708-E/PTVAO  
DSPIC33CK1024MP705-E/PT  
DSPIC33CK512MP705-E/PT  
DSPIC33CK256MP705-E/PT  
DSPIC33CK1024MP705-I/M7  
DSPIC33CK512MP705-I/M7  
DSPIC33CK256MP705-I/M7  
DSPIC33CK1024MP706-I/MR  
DSPIC33CK512MP706-I/MR  
DSPIC33CK256MP706-I/MR  
DSPIC33CK1024MP706-I/PT  
DSPIC33CK512MP706-I/PT  
DSPIC33CK256MP706-I/PT  
DSPIC33CK1024MP710-I/PT  
DSPIC33CK512MP710-I/PT  
DSPIC33CK256MP710-I/PT  
DSPIC33CK1024MP708-I/PT  
DSPIC33CK512MP708-I/PT  
DSPIC33CK256MP708-I/PT  
DSPIC33CK1024MP705-I/PT  
DSPIC33CK512MP705-I/PT  
DSPIC33CK256MP705-I/PT  
DSPIC33CK1024MP705-H/M7  
DSPIC33CK512MP705-H/M7  
DSPIC33CK256MP705-H/M7  
DSPIC33CK1024MP706-H/MR  
DSPIC33CK512MP706-H/MR  
DSPIC33CK256MP706-H/MR  
DSPIC33CK1024MP706-H/PT  
DSPIC33CK512MP706-H/PT

DSPIC33CK256MP706-H/PT  
DSPIC33CK1024MP710-H/PT  
DSPIC33CK512MP710-H/PT  
DSPIC33CK256MP710-H/PT  
DSPIC33CK1024MP708-H/PT  
DSPIC33CK512MP708-H/PT  
DSPIC33CK256MP708-H/PT  
DSPIC33CK1024MP705-H/PT  
DSPIC33CK512MP705-H/PT  
DSPIC33CK256MP705-H/PT  
DSPIC33CK1024MP705T-I/M7  
DSPIC33CK512MP705T-I/M7  
DSPIC33CK256MP705T-I/M7  
DSPIC33CK1024MP706T-I/MR  
DSPIC33CK512MP706T-I/MR  
DSPIC33CK256MP706T-I/MR  
DSPIC33CK1024MP706T-I/PT  
DSPIC33CK512MP706T-I/PT  
DSPIC33CK256MP706T-I/PT  
DSPIC33CK1024MP710T-I/PT  
DSPIC33CK512MP710T-I/PT  
DSPIC33CK256MP710T-I/PT  
DSPIC33CK1024MP708T-I/PT  
DSPIC33CK512MP708T-I/PT  
DSPIC33CK256MP708T-I/PT  
DSPIC33CK1024MP705T-I/PT  
DSPIC33CK512MP705T-I/PT  
DSPIC33CK256MP705T-I/PT  
DSPIC33CK1024MP705T-E/M7  
DSPIC33CK512MP705T-E/M7  
DSPIC33CK256MP705T-E/M7  
DSPIC33CK1024MP706T-E/MR  
DSPIC33CK512MP706T-E/MR  
DSPIC33CK256MP706T-E/MR  
DSPIC33CK1024MP706T-E/PT  
DSPIC33CK512MP706T-E/PT  
DSPIC33CK256MP706T-E/PT  
DSPIC33CK1024MP710T-E/PT  
DSPIC33CK512MP710T-E/PT  
DSPIC33CK256MP710T-E/PT  
DSPIC33CK1024MP710T-E/PTVAO  
DSPIC33CK1024MP708T-E/PT  
DSPIC33CK512MP708T-E/PT  
DSPIC33CK256MP708T-E/PT  
DSPIC33CK1024MP705T-E/PT  
DSPIC33CK512MP705T-E/PT  
DSPIC33CK256MP705T-E/PT

---

## dsPIC33CK1024MP710 Family Silicon Errata and Data Sheet Clarification

---

The dsPIC33CK1024MP710 family devices that you have received conform functionally to the current Device Data Sheet (DS70005496B), except for the anomalies described in this document.

The silicon issues discussed in the following pages are for silicon revisions with the Device and Revision IDs listed in [Table 1](#). The silicon issues are summarized in [Table 2](#).


The errata described in this document will be addressed in future revisions of the dsPIC33CK1024MP710 silicon.

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated in the last column of [Table 2](#) apply to the current silicon revision (A1).

Data Sheet clarifications and corrections start on [page 5](#), following the discussion of silicon issues.

The silicon revision level can be identified using the current version of MPLAB® IDE and Microchip's programmers, debuggers and emulation tools, which are available at the Microchip corporate website ([www.microchip.com](http://www.microchip.com)).

For example, to identify the silicon revision level using MPLAB IDE in conjunction with a hardware debugger:

1. Using the appropriate interface, connect the device to the hardware debugger.
2. Open an MPLAB IDE project.
3. Configure the MPLAB IDE project for the appropriate device and hardware debugger.
4. Based on the version of MPLAB IDE you are using, do one of the following:
  - a) For MPLAB IDE 8, select *Programmer > Reconnect*.
  - b) For MPLAB X IDE, select *Window > Dashboard* and click the **Refresh Debug Tool Status** icon (  ).
5. Depending on the development tool used, the part number *and* Device Revision ID value appear in the **Output** window.

**Note:** If you are unable to extract the silicon revision level, please contact your local Microchip sales office for assistance.

The DEVREV values for the various dsPIC33CK1024MP710 silicon revisions are shown in [Table 1](#).

# dsPIC33CK1024MP710

**TABLE 1: SILICON DEVREV VALUES**

Device	Device ID <sup>(1)</sup>	Revision ID for Silicon Revision	Device	Device ID <sup>(1)</sup>	Revision ID for Silicon Revision
		A1			A1
<b>dsPIC33CK1024MP710 Family with CAN FD</b>			<b>dsPIC33CK1024MP710 Family without CAN FD</b>		
dsPIC33CK1024MP710	0xA065	0x0001	dsPIC33CK1024MP410	0xA025	0x0001
dsPIC33CK1024MP708	0xA064		dsPIC33CK1024MP408	0xA024	
dsPIC33CK1024MP706	0xA063		dsPIC33CK1024MP406	0xA023	
dsPIC33CK1024MP705	0xA062		dsPIC33CK1024MP405	0xA022	
dsPIC33CK512MP710	0xA055		dsPIC33CK512MP410	0xA015	
dsPIC33CK512MP708	0xA054		dsPIC33CK512MP408	0xA014	
dsPIC33CK512MP706	0xA053		dsPIC33CK512MP406	0xA013	
dsPIC33CK512MP705	0xA052		dsPIC33CK512MP405	0xA012	
dsPIC33CK256MP710	0xA045		dsPIC33CK256MP410	0xA005	
dsPIC33CK256MP708	0xA044		dsPIC33CK256MP408	0xA004	
dsPIC33CK256MP706	0xA043		dsPIC33CK256MP406	0xA003	
dsPIC33CK256MP705	0xA042		dsPIC33CK256MP405	0xA002	

**Note 1:** The Device IDs (DEVID and DEVREV) are located at the last two implemented addresses of configuration memory space. They are shown in hexadecimal in the format "DEVID DEVREV".

# dsPIC33CK1024MP710

**TABLE 2: SILICON ISSUE SUMMARY**

Module	Feature	Item Number	Issue Summary	Affected Revisions <sup>(1)</sup>
				A1
I <sup>2</sup> C	Idle	1.	Address cannot be received in Idle mode.	X
CPU	DIV.SD Instruction	2.	Overflow bit is not getting set when an overflow occurs.	X
I <sup>2</sup> C	Collision Detection	3.	Bus collision is not detected during Host reception if there is a Start/Stop condition.	X
I <sup>2</sup> C	Client Mode	4.	Unexpected Client interrupt if there is a Stop bit in the 9th clock, followed by a Start bit.	X
I <sup>2</sup> C	Client Mode	5.	When data hold is enabled and software sends a NACK, a Client interrupt is asserted if there are more bytes on the bus.	X
ADC	Differential-Mode	6.	Errors may occur when enabling Differential-mode when F <sub>SRC</sub> is greater than 50 MHz.	X

**Note 1:** Only those issues indicated in the last column apply to the current silicon revision.

# dsPIC33CK1024MP710

## Silicon Errata Issues

**Note:** This document summarizes all silicon errata issues from all revisions of silicon, previous as well as current. Only the issues indicated by the shaded column in the following tables apply to the current silicon revision (**A1**).

### 1. Module: I<sup>2</sup>C

In Client mode, an address cannot be received when the device is in Idle and the module is set for discontinue in Idle (I2CSIDL = 1).

#### Work around

None.

#### Affected Silicon Revisions

A1								
X								

### 2. Module: CPU

When using the Signed 32/16-bit Division instruction, DIV.SD, the Overflow bit may not always get set when an overflow occurs.

#### Work around

Test for, and handle, Overflow conditions outside of the DIV.SD instruction.

#### Affected Silicon Revisions

A1								
X								

### 3. Module: I<sup>2</sup>C

Bus collision detection can fail during a Start/ Stop condition when a Host is receiving data from a Client. This condition can occur in a noisy environment or hot swapping I<sup>2</sup>C.

#### Work around

None.

#### Affected Silicon Revisions

A1								
X								

### 4. Module: I<sup>2</sup>C

An unexpected Client interrupt will occur if the Host sends a NACK and a Stop bit, followed by a Start bit in the ACK phase (9th clock) during Client transmit.

#### Work around

Software should ignore the Client interrupt that is asserted after sending a NACK.

#### Affected Silicon Revisions

A1								
X								

### 5. Module: I<sup>2</sup>C

In Client mode with DHEN = 1 (Data Hold Enable), if software sends a NACK, the Client interrupt is asserted if there are any bytes on the bus.

#### Work around

Software should ignore the Client interrupt that is asserted after sending a NACK.

#### Affected Silicon Revisions

A1								
X								

### 6. Module: ADC

When operating ADC with an Input Frequency (F<sub>SR</sub>) above 50 MHz, conversion errors may occur when enabling Differential-mode (DIFFx = 1).

#### Work around

During initialization of the ADC to write the ADMODxL/H registers, use a slower input frequency of 50 MHz or less. After completion of the 1st conversion of each channel in Differential-mode, Input Frequency, F<sub>SR</sub>, can be increased to the maximum specified in the “**Electrical Characteristics**”.

#### Affected Silicon Revisions

A1								
X								



## Data Sheet Clarifications

The following typographic corrections and clarifications are to be noted for the latest version of the device data sheet (DS70005496B):

<p><b>Note:</b> Corrections are shown in <b>bold</b>. Where possible, the original bold text formatting has been removed for clarity.</p>
---

None.

# dsPIC33CK1024MP710

---

## APPENDIX A: DOCUMENT REVISION HISTORY

Rev A Document (5/2022)

Initial version of this document; issued for revision **A1**.

---

---

**Note the following details of the code protection feature on Microchip products:**

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip product is strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is “unbreakable”. Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

---

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at <https://www.microchip.com/en-us/support/design-help/client-support-services>.

THIS INFORMATION IS PROVIDED BY MICROCHIP "AS IS". MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP'S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer's risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

For information regarding Microchip's Quality Management Systems, please visit [www.microchip.com/quality](http://www.microchip.com/quality).

**Trademarks**

The Microchip name and logo, the Microchip logo, Adaptec, AnyRate, AVR, AVR logo, AVR Freaks, BesTime, BitCloud, CryptoMemory, CryptoRF, dsPIC, flexPWR, HELDO, IGLOO, JukeBlox, KeeLoq, Kleer, LANCheck, LinkMD, maXStylus, maXTouch, MediaLB, megaAVR, Microsemi, Microsemi logo, MOST, MOST logo, MPLAB, OptoLyzer, PIC, picoPower, PICSTART, PIC32 logo, PolarFire, Prochip Designer, QTouch, SAM-BA, SenGenuity, SpyNIC, SST, SST Logo, SuperFlash, Symmetricom, SyncServer, Tachyon, TimeSource, tinyAVR, UNI/O, Vectron, and XMEGA are registered trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

AgileSwitch, APT, ClockWorks, The Embedded Control Solutions Company, EtherSynch, Flashtec, Hyper Speed Control, HyperLight Load, IntelliMOS, Libero, motorBench, mTouch, Powermite 3, Precision Edge, ProASIC, ProASIC Plus, ProASIC Plus logo, QuietWire, SmartFusion, SyncWorld, Temux, TimeCesium, TimeHub, TimePictra, TimeProvider, TrueTime, WinPath, and ZL are registered trademarks of Microchip Technology Incorporated in the U.S.A.

Adjacent Key Suppression, AKS, Analog-for-the-Digital Age, Any Capacitor, AnyIn, AnyOut, Augmented Switching, BlueSky, BodyCom, CodeGuard, CryptoAuthentication, CryptoAutomotive, CryptoCompanion, CryptoController, dsPICDEM, dsPICDEM.net, Dynamic Average Matching, DAM, ECAN, Espresso T1S, EtherGREEN, GridTime, IdealBridge, In-Circuit Serial Programming, ICSP, INICnet, Intelligent Paralleling, Inter-Chip Connectivity, JitterBlocker, Knob-on-Display, maxCrypto, maxView, memBrain, Mindi, MiWi, MPASM, MPF, MPLAB Certified logo, MPLIB, MPLINK, MultiTRAK, NetDetach, NVM Express, NVMe, Omniscient Code Generation, PICDEM, PICDEM.net, PICKit, PICtail, PowerSmart, PureSilicon, QMatrix, REAL ICE, Ripple Blocker, RTAX, RTG4, SAM-ICE, Serial Quad I/O, simpleMAP, SimpliPHY, SmartBuffer, SmartHLS, SMART-I.S., storClad, SQI, SuperSwitcher, SuperSwitcher II, Switchtec, SynchronPHY, Total Endurance, TSHARC, USBCheck, VariSense, VectorBlox, VeriPHY, ViewSpan, WiperLock, XpressConnect, and ZENA are trademarks of Microchip Technology Incorporated in the U.S.A. and other countries.

SQTP is a service mark of Microchip Technology Incorporated in the U.S.A.

The Adaptec logo, Frequency on Demand, Silicon Storage Technology, Symmcom, and Trusted Time are registered trademarks of Microchip Technology Inc. in other countries.

GestIC is a registered trademark of Microchip Technology Germany II GmbH & Co. KG, a subsidiary of Microchip Technology Inc., in other countries.

All other trademarks mentioned herein are property of their respective companies.

© 2022, Microchip Technology Incorporated and its subsidiaries.

All Rights Reserved.

ISBN: 978-1-6683-0490-7



# MICROCHIP

## Worldwide Sales and Service

### AMERICAS

**Corporate Office**  
2355 West Chandler Blvd.  
Chandler, AZ 85224-6199  
Tel: 480-792-7200  
Fax: 480-792-7277  
Technical Support:  
<http://www.microchip.com/support>  
Web Address:  
[www.microchip.com](http://www.microchip.com)

**Atlanta**  
Duluth, GA  
Tel: 678-957-9614  
Fax: 678-957-1455

**Austin, TX**  
Tel: 512-257-3370

**Boston**  
Westborough, MA  
Tel: 774-760-0087  
Fax: 774-760-0088

**Chicago**  
Itasca, IL  
Tel: 630-285-0071  
Fax: 630-285-0075

**Dallas**  
Addison, TX  
Tel: 972-818-7423  
Fax: 972-818-2924

**Detroit**  
Novi, MI  
Tel: 248-848-4000

**Houston, TX**  
Tel: 281-894-5983

**Indianapolis**  
Noblesville, IN  
Tel: 317-773-8323  
Fax: 317-773-5453  
Tel: 317-536-2380

**Los Angeles**  
Mission Viejo, CA  
Tel: 949-462-9523  
Fax: 949-462-9608  
Tel: 951-273-7800

**Raleigh, NC**  
Tel: 919-844-7510

**New York, NY**  
Tel: 631-435-6000

**San Jose, CA**  
Tel: 408-735-9110  
Tel: 408-436-4270

**Canada - Toronto**  
Tel: 905-695-1980  
Fax: 905-695-2078

### ASIA/PACIFIC

**Australia - Sydney**  
Tel: 61-2-9868-6733

**China - Beijing**  
Tel: 86-10-8569-7000

**China - Chengdu**  
Tel: 86-28-8665-5511

**China - Chongqing**  
Tel: 86-23-8980-9588

**China - Dongguan**  
Tel: 86-769-8702-9880

**China - Guangzhou**  
Tel: 86-20-8755-8029

**China - Hangzhou**  
Tel: 86-571-8792-8115

**China - Hong Kong SAR**  
Tel: 852-2943-5100

**China - Nanjing**  
Tel: 86-25-8473-2460

**China - Qingdao**  
Tel: 86-532-8502-7355

**China - Shanghai**  
Tel: 86-21-3326-8000

**China - Shenyang**  
Tel: 86-24-2334-2829

**China - Shenzhen**  
Tel: 86-755-8864-2200

**China - Suzhou**  
Tel: 86-186-6233-1526

**China - Wuhan**  
Tel: 86-27-5980-5300

**China - Xian**  
Tel: 86-29-8833-7252

**China - Xiamen**  
Tel: 86-592-2388138

**China - Zhuhai**  
Tel: 86-756-3210040

### ASIA/PACIFIC

**India - Bangalore**  
Tel: 91-80-3090-4444

**India - New Delhi**  
Tel: 91-11-4160-8631

**India - Pune**  
Tel: 91-20-4121-0141

**Japan - Osaka**  
Tel: 81-6-6152-7160

**Japan - Tokyo**  
Tel: 81-3-6880-3770

**Korea - Daegu**  
Tel: 82-53-744-4301

**Korea - Seoul**  
Tel: 82-2-554-7200

**Malaysia - Kuala Lumpur**  
Tel: 60-3-7651-7906

**Malaysia - Penang**  
Tel: 60-4-227-8870

**Philippines - Manila**  
Tel: 63-2-634-9065

**Singapore**  
Tel: 65-6334-8870

**Taiwan - Hsin Chu**  
Tel: 886-3-577-8366

**Taiwan - Kaohsiung**  
Tel: 886-7-213-7830

**Taiwan - Taipei**  
Tel: 886-2-2508-8600

**Thailand - Bangkok**  
Tel: 66-2-694-1351

**Vietnam - Ho Chi Minh**  
Tel: 84-28-5448-2100

### EUROPE

**Austria - Wels**  
Tel: 43-7242-2244-39  
Fax: 43-7242-2244-393

**Denmark - Copenhagen**  
Tel: 45-4485-5910  
Fax: 45-4485-2829

**Finland - Espoo**  
Tel: 358-9-4520-820

**France - Paris**  
Tel: 33-1-69-53-63-20  
Fax: 33-1-69-30-90-79

**Germany - Garching**  
Tel: 49-8931-9700

**Germany - Haan**  
Tel: 49-2129-3766400

**Germany - Heilbronn**  
Tel: 49-7131-72400

**Germany - Karlsruhe**  
Tel: 49-721-625370

**Germany - Munich**  
Tel: 49-89-627-144-0  
Fax: 49-89-627-144-44

**Germany - Rosenheim**  
Tel: 49-8031-354-560

**Israel - Ra'anana**  
Tel: 972-9-744-7705

**Italy - Milan**  
Tel: 39-0331-742611  
Fax: 39-0331-466781

**Italy - Padova**  
Tel: 39-049-7625286

**Netherlands - Drunen**  
Tel: 31-416-690399  
Fax: 31-416-690340

**Norway - Trondheim**  
Tel: 47-7288-4388

**Poland - Warsaw**  
Tel: 48-22-3325737

**Romania - Bucharest**  
Tel: 40-21-407-87-50

**Spain - Madrid**  
Tel: 34-91-708-08-90  
Fax: 34-91-708-08-91

**Sweden - Gothenberg**  
Tel: 46-31-704-60-40

**Sweden - Stockholm**  
Tel: 46-8-5090-4654

**UK - Wokingham**  
Tel: 44-118-921-5800  
Fax: 44-118-921-5820