



Product Change Notification: SYST-10PYHA836

Date:

15-Apr-2026

Product Category:

8-Bit Microcontrollers

Notification Subject:

AVR32SD20/28/32 Silicon Errata Data Sheet Clarification

Affected CPNs:

[SYST-10PYHA836_Affected_CPN_04152026.pdf](#)

[SYST-10PYHA836_Affected_CPN_04152026.csv](#)

Notification Text:

SYST-10PYHA836

Microchip has released a new Document for the AVR32SD20/28/32 Silicon Errata Data Sheet Clarification of devices. If you are using one of these devices please read the document located at [AVR32SD20/28/32 Silicon Errata Data Sheet Clarification](#).

Notification Status: Final

Description of Change:

- Added mask revision A2
- New errata:
 - ADC - False Overrun Detection
 - ADC - Misleading Busy Status During Initialization Phase

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 15 Apr 2026

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachments:

AVR32SD20/28/32 Silicon Errata Data Sheet Clarification

Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from

Affected Catalog Part Numbers (CPN)

AVR32SD20-E/SS

AVR32SD20-I/SS

AVR32SD20T-E/SS

AVR32SD20T-I/SS

AVR32SD28-E/3LW

AVR32SD28-E/SP

AVR32SD28-E/SS

AVR32SD28-I/3LW

AVR32SD28-I/SP

AVR32SD28-I/SS

AVR32SD28T-E/3LW

AVR32SD28T-E/SS

AVR32SD28T-I/3LW

AVR32SD28T-I/SS

AVR32SD32-E/PT

AVR32SD32-E/QZB

AVR32SD32-I/PT

AVR32SD32-I/QZB

AVR32SD32T-E/PT

AVR32SD32T-E/QZB

AVR32SD32T-I/PT

AVR32SD32T-I/QZB

Introduction

The AVR32SD20/28/32 devices you have received conform functionally to the current device data sheet (www.microchip.com/DS40002629), except for the anomalies described in this document. The errata described in this document will likely be addressed in future revisions of the AVR32SD20/28/32 devices.

Notes:

- This document summarizes all the silicon errata issues from all the silicon revisions, previous and current
- Refer to the Device/Revision ID section in the current device data sheet (www.microchip.com/DS40002629) for more detailed information on Device Identification and Revision IDs for your specific device, or contact your local Microchip sales office for assistance

1. Silicon Issue Summary

Legend

- Erratum is not applicable.
- X Erratum is applicable.

Peripheral	Short Description	Valid for Silicon Revision	
		Rev. A1 ⁽¹⁾	Rev. A2
ADC	False Overrun Detection	X	X
	Misleading Busy Status During Initialization Phase	X	X
TCD	Halting TCD and Waiting for SW Restart Does Not Work if Compare Value A is 0 or Dual Slope Mode is Used	X	X
USART	Receiver Non-Functional after Detection of Inconsistent Synchronization Field	X	X

Note:

1. This revision is the initial release of the silicon.

2. Silicon Errata Issues

2.1. Errata Details

- Erratum is not applicable.
- X Erratum is applicable.

2.2. ADC - Analog-to-Digital Converter

2.2.1. False Overrun Detection

The first conversion after re-enabling the ADC can give a false overrun detection.

Work Around

Read the SAMPLE and RESULT registers before re-enabling the ADC.

Affected Silicon Revisions

Rev. A1	Rev. A2
X	X

2.2.2. Misleading Busy Status During Initialization Phase

When the ADC peripheral is enabled with LOWLAT = '0x1' in the CTRLA register, the initialization phase starts as expected, but the ADCBUSY bit in the STATUS register may be cleared too early. Any conversion started before the initialization phase is complete will be halted, regardless of the ADCBUSY bit. Once the initialization phase is completed, the ADCBUSY bit will operate correctly.

Work Around

Perform a dummy conversion and wait for the RESRDY or SAMPRDY flag in the INTFLAGS register to be set.

Affected Silicon Revisions

Rev. A1	Rev. A2
X	X

2.3. TCD - 12-Bit Timer/Counter Type D

2.3.1. Halting TCD and Waiting for SW Restart Does Not Work if Compare Value A is 0 or Dual Slope Mode is Used

Halting TCD and waiting for software restart (INPUTMODE in TCDn.INPUTCTRLA is '0x7') does not work if compare value A is 0 (CMPASET in TCDn.CMPASET is '0x0') or Dual Slope mode is used (WGMode in TCDn.CTRLB is '0x3').

Work Around

Configure the compare value A (CMPASET in TCDn.CMPASET) to be different from 0 and do not use Dual Slope mode (WGMode in TCDn.CTRLB is not '0x3').

Affected Silicon Revisions

Rev. A1	Rev. A2
X	X

2.4. USART - Universal Synchronous and Asynchronous Receiver and Transmitter

2.4.1. Receiver Non-Functional after Detection of Inconsistent Synchronization Field

The USART Receiver becomes non-functional when the Inconsistent Synchronization Field Interrupt Flag (ISFIF) in the Status (USARTn.STATUS) register is set. The ISFIF interrupt flag is set when the Receiver Mode (RXMODE) bit field in the Control B (USARTn.CTRLB) register is configured to Generic Auto-Baud (GENAUTO) or LIN Constrained Auto-Baud (LINAUTO) mode, and the received synchronization frame does not conform to the conditions described in the data sheet. Clearing the flag does not re-enable the USART Receiver.

Work Around

When the ISFIF interrupt flag is set, disable and re-enable the USART Receiver by first writing a '0' and then a '1' to the Receiver Enable (RXEN) bit in the Control B (USARTn.CTRLB) register.

Affected Silicon Revisions

Rev. A1	Rev. A2
X	X

3. Data Sheet Clarifications

Note the following typographical corrections and clarifications for the latest version of the device data sheet (www.microchip.com/DS40002629).

Note: Corrections are shown in **bold**. Where possible, the original bold text formatting has been removed for clarity.

3.1. None

There are no known data sheet clarifications as of this publication date.

4. Document Revision History

Note: The document revision is independent of the silicon revision.

4.1. Revision History

Doc. Rev.	Date	Comments
B	04/2026	- Added mask revision A2 - New errata: - ADC - False Overrun Detection - ADC - Misleading Busy Status During Initialization Phase
A	02/2025	Initial document release

Microchip Information

Trademarks

The “Microchip” name and logo, the “M” logo, and other names, logos, and brands are registered and unregistered trademarks of Microchip Technology Incorporated or its affiliates and/or subsidiaries in the United States and/or other countries (“Microchip Trademarks”). Information regarding Microchip Trademarks can be found at <https://www.microchip.com/en-us/about/legal-information/microchip-trademarks>.

ISBN: 979-8-3371-3148-1

Legal Notice

This publication and the information herein may be used only with Microchip products, including to design, test, and integrate Microchip products with your application. Use of this information in any other manner violates these terms. Information regarding device applications is provided only for your convenience and may be superseded by updates. It is your responsibility to ensure that your application meets with your specifications. Contact your local Microchip sales office for additional support or, obtain additional support at www.microchip.com/en-us/support/design-help/client-support-services.

THIS INFORMATION IS PROVIDED BY MICROCHIP “AS IS”. MICROCHIP MAKES NO REPRESENTATIONS OR WARRANTIES OF ANY KIND WHETHER EXPRESS OR IMPLIED, WRITTEN OR ORAL, STATUTORY OR OTHERWISE, RELATED TO THE INFORMATION INCLUDING BUT NOT LIMITED TO ANY IMPLIED WARRANTIES OF NON-INFRINGEMENT, MERCHANTABILITY, AND FITNESS FOR A PARTICULAR PURPOSE, OR WARRANTIES RELATED TO ITS CONDITION, QUALITY, OR PERFORMANCE.

IN NO EVENT WILL MICROCHIP BE LIABLE FOR ANY INDIRECT, SPECIAL, PUNITIVE, INCIDENTAL, OR CONSEQUENTIAL LOSS, DAMAGE, COST, OR EXPENSE OF ANY KIND WHATSOEVER RELATED TO THE INFORMATION OR ITS USE, HOWEVER CAUSED, EVEN IF MICROCHIP HAS BEEN ADVISED OF THE POSSIBILITY OR THE DAMAGES ARE FORESEEABLE. TO THE FULLEST EXTENT ALLOWED BY LAW, MICROCHIP’S TOTAL LIABILITY ON ALL CLAIMS IN ANY WAY RELATED TO THE INFORMATION OR ITS USE WILL NOT EXCEED THE AMOUNT OF FEES, IF ANY, THAT YOU HAVE PAID DIRECTLY TO MICROCHIP FOR THE INFORMATION.

Use of Microchip devices in life support and/or safety applications is entirely at the buyer’s risk, and the buyer agrees to defend, indemnify and hold harmless Microchip from any and all damages, claims, suits, or expenses resulting from such use. No licenses are conveyed, implicitly or otherwise, under any Microchip intellectual property rights unless otherwise stated.

Microchip Devices Code Protection Feature

Note the following details of the code protection feature on Microchip products:

- Microchip products meet the specifications contained in their particular Microchip Data Sheet.
- Microchip believes that its family of products is secure when used in the intended manner, within operating specifications, and under normal conditions.
- Microchip values and aggressively protects its intellectual property rights. Attempts to breach the code protection features of Microchip products are strictly prohibited and may violate the Digital Millennium Copyright Act.
- Neither Microchip nor any other semiconductor manufacturer can guarantee the security of its code. Code protection does not mean that we are guaranteeing the product is “unbreakable”. Code protection is constantly evolving. Microchip is committed to continuously improving the code protection features of our products.

Product Page Links

[AVR32SD20](#), [AVR32SD28](#), [AVR32SD32](#)