



PRODUCT BULLETIN
Generic Copy

ISSUE DATE: 21-Feb-2013
NOTIFICATION: 15506
TITLE: I.MX233 ERRATA
EFFECTIVE DATE: 22-Feb-2013

DEVICE(S)

MPN
MCIMX233CAG4B
MCIMX233CAG4C
MCIMX233CJM4B
MCIMX233CJM4BR2
MCIMX233CJM4C
MCIMX233DAG4B
MCIMX233DAG4C
MCIMX233DJM4B
MCIMX233DJM4BR2
MCIMX233DJM4C
MCIMX233DJM4CR2

AFFECTED CHANGE CATEGORIES

- DEVICE SPECIFICATION / ERRATA

DESCRIPTION OF CHANGE

The i.MX233 errata documentation has been updated to include additional errata that have been identified.

Added erratum 5838:

SAIF2 DMA completion IRQ in the APBX DMA module is not connected to the interrupt collector.

The updated errata documentation is attached to this notice and can be found at <http://www.freescale.com>

File name: IMX23CE_Rev4

http://www.freescale.com/webapp/sps/site/prod_summary.jsp?

code=i.MX233&nodeId=018rH3ZrDR780E

REASON FOR CHANGE

The errata documentation for I.MX233 has been updated.

ANTICIPATED IMPACT OF PRODUCT CHANGE(FORM, FIT, FUNCTION, OR RELIABILITY)

No changes have been made to the current production device. The errata describe existing conditions identified on current production devices.

NOTE:

THE CHANGE(S) SPECIFIED IN THIS NOTIFICATION WILL BE IMPLEMENTED ON THE EFFECTIVE DATE LISTED ABOVE. To request further data or inquire about the notification, please enter a [Service Request](#)

For sample inquiries - please go to www.freescale.com

QUAL DATA AVAILABILITY DATE: 25-Jan-2013

QUALIFICATION STATUS: N/A

QUALIFICATION PLAN:

N/A

RELIABILITY DATA SUMMARY:

N/A

ELECTRICAL CHARACTERISTIC SUMMARY:

N/A

CHANGED PART IDENTIFICATION:

N/A

ATTACHMENT(S):

External attachment(s) FOR this notification can be viewed AT:
[15506 IMX23CE Rev4.pdf](#)
