

**CURRENT DATE:** 22-MAY-2013

[Get Email Version](#)

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** Future Electronics  
**LOCATION:** WORLDWIDE  
**CUSTOMER NO:** 0000080100

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785  
**PCN DATE:** 21-MAY-13

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Universal MATE-N-LOK Gold-Plated Contacts

### DESCRIPTION OF CHANGE:

No Change to any product - Correcting lubricant dash-number on production drawing for gold plated parts only - All non-gold-plated parts show correct lubricant dash-number

### REASON FOR CHANGE:

Document clarification. Lubricant dash-number error on production drawing goes back to original drafting of prints - Manufacturing location stated gold-plated parts have always been made with correct lubricant dash-number - This recently discovered error must be corrected - All associated PNs must be bumped a full revision to eliminate any potential future misunderstanding

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED**

**PARTS:** 25-MAY-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS:** NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

Following list contains all the unique parts and drawings /documents listed  
on each of the individual PCN Forms affecting this worldwide customer account.

**CURRENT DATE:** 22-MAY-2013

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** Future Electronics

**LOCATION:** WORLDWIDE

**CUSTOMER NO:** 0000080100

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**PCN DATE:** 21-MAY-13

---

### PARTS BEING MODIFIED

350218-1

350218-2

350218-3  
(Alias Part Numbers:  
"403431893" )

350536-1  
(Alias Part Numbers:  
"403429822" )

350536-2

350536-3  
(Alias Part Numbers:  
"403311541" )

350536-6  
(Alias Part Numbers:  
"402245922" )

350536-7

350537-1  
(Alias Part Numbers:  
"AMPS-0-0350537-1",  
"D60465-000" )

350537-3

350537-6

350561-1  
(Alias Part Numbers:  
"0-0350561-1",  
"CU3085-000",  
"AMPS-0-0350561-1" )

350561-2

350561-3  
(Alias Part Numbers:  
"405331331" )

350561-7

350570-1

350570-2  
(Alias Part Numbers:  
"AMPS-0-0350570-2",  
"F35891-000" )

350570-3  
(Alias Part Numbers:  
"403761786" )

350570-7

350654-1

350687-1

350687-7

350699-1

350851-1  
(Alias Part Numbers:  
"0-0350851-1",  
"2021755",  
"CU3086-000",  
"AMPS-0-0350851-1" )

350922-3

350922-6  
(Alias Part Numbers:  
"403927767" )

350923-3  
(Alias Part Numbers:  
"403980899" )

[Get Email Version](#)

---

---

**CURRENT DATE:** 22-MAY-2013

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** FUTURE ELECTRONICS INC

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** POINTE CLAIRE QUEBEC

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 184927

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Universal MATE-N-LOK Gold-Plated Contacts

### DESCRIPTION OF CHANGE:

No Change to any product - Correcting lubricant dash-number on production drawing for gold plated parts only - All non-gold-plated parts show correct lubricant dash-number

### REASON FOR CHANGE:

Document clarification. Lubricant dash-number error on production drawing goes back to original drafting of prints - Manufacturing location stated gold-plated parts have always been made with correct lubricant dash-number - This recently discovered error must be corrected - All associated PNs must be bumped a full revision to eliminate any potential future misunderstanding

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED**

**PARTS:** 25-MAY-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS:** NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

**CURRENT DATE:** 22-MAY-2013

**TE CONNECTIVITY**

**PRODUCT CHANGE  
NOTIFICATION**

---

**CUSTOMER:** FUTURE ELECTRONICS INC

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** POINTE CLAIRE QUEBEC

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 184927

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

---

**PARTS BEING MODIFIED      CUSTOMER PART NBR**

350218-3  
(Alias Part Numbers:  
"403431893" )

---

---

**CURRENT DATE:** 22-MAY-2013

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** FUTURE ELECTRONICS INC.

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** SINGAPORE

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 1319888

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** TESI (1914) - Tyco Electronics Singapore Pte Ltd.

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Universal MATE-N-LOK Gold-Plated Contacts

### DESCRIPTION OF CHANGE:

No Change to any product - Correcting lubricant dash-number on production drawing for gold plated parts only - All non-gold-plated parts show correct lubricant dash-number

### REASON FOR CHANGE:

Document clarification. Lubricant dash-number error on production drawing goes back to original drafting of prints - Manufacturing location stated gold-plated parts have always been made with correct lubricant dash-number - This recently discovered error must be corrected - All associated PNs must be bumped a full revision to eliminate any potential future misunderstanding

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED**

**PARTS:** 25-MAY-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS:** NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

**CURRENT DATE:** 22-MAY-2013

**TE CONNECTIVITY****PRODUCT CHANGE  
NOTIFICATION**

**CUSTOMER:** FUTURE ELECTRONICS INC.

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** SINGAPORE

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 1319888

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** TESI (1914) - Tyco Electronics Singapore Pte Ltd.

---

**PARTS BEING MODIFIED      CUSTOMER PART NBR**

350218-1

350218-2

350536-1

(Alias Part Numbers:  
"403429822" )

350537-3

350561-1

(Alias Part Numbers:  
"0-0350561-1",  
"CU3085-000",  
"AMPS-0-0350561-1" )

350561-7

350570-3

(Alias Part Numbers:  
"403761786" )

---

---



**CURRENT DATE:** 22-MAY-2013

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** FUTURE ELECTRONICS ASIA  
PACIFIC

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** SINGAPORE

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 2923061

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** TESI (1914) - Tyco Electronics Singapore Pte Ltd.

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Universal MATE-N-LOK Gold-Plated Contacts

### DESCRIPTION OF CHANGE:

No Change to any product - Correcting lubricant dash-number on production drawing for gold plated parts only - All non-gold-plated parts show correct lubricant dash-number

### REASON FOR CHANGE:

Document clarification. Lubricant dash-number error on production drawing goes back to original drafting of prints - Manufacturing location stated gold-plated parts have always been made with correct lubricant dash-number - This recently discovered error must be corrected - All associated PNs must be bumped a full revision to eliminate any potential future misunderstanding

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED**

**PARTS:** 25-MAY-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS:** NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

**CURRENT DATE:** 22-MAY-2013

**TE CONNECTIVITY**

**PRODUCT CHANGE  
NOTIFICATION**

**CUSTOMER:** FUTURE ELECTRONICS ASIA  
PACIFIC

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** SINGAPORE

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 2923061

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** TESI (1914) - Tyco Electronics Singapore Pte Ltd.

---

**PARTS BEING MODIFIED      CUSTOMER PART NBR**

350218-1

350536-1  
(Alias Part Numbers:  
"403429822" )

350536-2

350561-1  
(Alias Part Numbers:  
"0-0350561-1",  
"CU3085-000",  
"AMPS-0-0350561-1" )

350561-7

350570-1

350687-1

---

---

**CURRENT DATE:** 22-MAY-2013

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** FUTURE ELECTRONICS INC

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** SOUTHAVEN

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 1290208

**AGREEMENT NO:** FUTAGR001

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Universal MATE-N-LOK Gold-Plated Contacts

### DESCRIPTION OF CHANGE:

No Change to any product - Correcting lubricant dash-number on production drawing for gold plated parts only - All non-gold-plated parts show correct lubricant dash-number

### REASON FOR CHANGE:

Document clarification. Lubricant dash-number error on production drawing goes back to original drafting of prints - Manufacturing location stated gold-plated parts have always been made with correct lubricant dash-number - This recently discovered error must be corrected - All associated PNs must be bumped a full revision to eliminate any potential future misunderstanding

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED**

**PARTS:** 25-MAY-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS:** NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

**CURRENT DATE:** 22-MAY-2013

**TE CONNECTIVITY****PRODUCT CHANGE  
NOTIFICATION**

**CUSTOMER:** FUTURE ELECTRONICS INC

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** SOUTHAVEN

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 1290208

**AGREEMENT NO:** FUTAGR001

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

---

**PARTS BEING MODIFIED      CUSTOMER PART NBR**

350218-1

350218-2

350218-3  
(Alias Part Numbers:  
"403431893" )

350536-1  
(Alias Part Numbers:  
"403429822" )

350536-2

350536-3  
(Alias Part Numbers:  
"403311541" )

350536-7

350537-1  
(Alias Part Numbers:  
"AMPS-0-0350537-1",  
"D60465-000" )

350537-3

350537-6

350561-1

(Alias Part Numbers:  
"0-0350561-1",  
"CU3085-000",  
"AMPS-0-0350561-1" )

350561-2

350561-3

(Alias Part Numbers:  
"405331331" )

350561-7

350570-1

350570-2

(Alias Part Numbers:  
"AMPS-0-0350570-2",  
"F35891-000" )

350570-3

(Alias Part Numbers:  
"403761786" )

350570-7

350687-7

350699-1

350851-1

(Alias Part Numbers:  
"0-0350851-1",  
"2021755",  
"CU3086-000",  
"AMPS-0-0350851-1" )

350922-3

350922-6  
(Alias Part Numbers:  
"403927767" )

350923-3  
(Alias Part Numbers:  
"403980899" )



**CURRENT DATE:** 22-MAY-2013

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** FUTURE ELECTRONICS UK

**LOCATION:** HAYES

**CUSTOMER NO:** 2833922

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**PCN DATE:** 21-MAY-13

**AGREEMENT NO:**

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Universal MATE-N-LOK Gold-Plated Contacts

### DESCRIPTION OF CHANGE:

No Change to any product - Correcting lubricant dash-number on production drawing for gold plated parts only - All non-gold-plated parts show correct lubricant dash-number

### REASON FOR CHANGE:

Document clarification. Lubricant dash-number error on production drawing goes back to original drafting of prints - Manufacturing location stated gold-plated parts have always been made with correct lubricant dash-number - This recently discovered error must be corrected - All associated PNs must be bumped a full revision to eliminate any potential future misunderstanding

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED**

**PARTS:** 25-MAY-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS:** NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

**CURRENT DATE:** 22-MAY-2013

**TE CONNECTIVITY**

**PRODUCT CHANGE  
NOTIFICATION**

**CUSTOMER:** FUTURE ELECTRONICS UK

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** HAYES

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 2833922

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** RMP (1082) - U.S. Operations on SAP

---

**PARTS BEING MODIFIED      CUSTOMER PART NBR**

350218-1

350536-1  
(Alias Part Numbers:  
"403429822" )

350570-1

350570-3  
(Alias Part Numbers:  
"403761786" )

350699-1

350851-1  
(Alias Part Numbers:  
"0-0350851-1",  
"2021755",  
"CU3086-000",  
"AMPS-0-0350851-1" )

---

**CURRENT DATE:** 22-MAY-2013

**PRODUCT CHANGE**



**TE CONNECTIVITY****NOTIFICATION****CUSTOMER:** FUTURE ELECTRONICS LTD**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785**LOCATION:** EGHAM**PCN DATE:** 21-MAY-13**CUSTOMER NO:** 1273129**AGREEMENT NO:****TE CONNECTIVITY ENTITY:** TELG (1151) - TE Connectivity Solutions GmbH

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**GENERAL PRODUCT DESCRIPTION:**

Universal MATE-N-LOK Gold-Plated Contacts

**DESCRIPTION OF CHANGE:**

No Change to any product - Correcting lubricant dash-number on production drawing for gold plated parts only - All non-gold-plated parts show correct lubricant dash-number

**REASON FOR CHANGE:**

Document clarification. Lubricant dash-number error on production drawing goes back to original drafting of prints - Manufacturing location stated gold-plated parts have always been made with correct lubricant dash-number - This recently discovered error must be corrected - All associated PNs must be bumped a full revision to eliminate any potential future misunderstanding

**ESTIMATE DATE:****LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED****PARTS:** 25-MAY-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED****SHIPMENTS:** NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

**CURRENT DATE:** 22-MAY-2013**TE CONNECTIVITY****PRODUCT CHANGE  
NOTIFICATION****CUSTOMER:** FUTURE ELECTRONICS LTD**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785**LOCATION:** EGHAM**PCN DATE:** 21-MAY-13**CUSTOMER NO:** 1273129**AGREEMENT NO:****TE CONNECTIVITY ENTITY:** TELG (1151) - TE Connectivity Solutions GmbH

---

**PARTS BEING MODIFIED      CUSTOMER PART NBR**

350218-1	350218-1-LF
350218-2	350218-2-LF
350536-1 (Alias Part Numbers: "403429822" )	350536-1-BR-LF, 350536-1-LF
350536-3 (Alias Part Numbers: "403311541" )	350536-3-LF
350536-6 (Alias Part Numbers: "402245922" )	
350537-1 (Alias Part Numbers: "AMPS-0-0350537-1", "D60465-000" )	350537-1-LF
350561-2	350561-2-LF
350570-1	350570-1-LF
350654-1	350654-1-LF

350687-1

350687-1-LF



**CURRENT DATE:** 22-MAY-2013

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** FUTURE ELECTRONICS INC.

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** SINGAPORE

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 1319888

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** HK (0451) - TE Connectivity HK Ltd

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Universal MATE-N-LOK Gold-Plated Contacts

### DESCRIPTION OF CHANGE:

No Change to any product - Correcting lubricant dash-number on production drawing for gold plated parts only - All non-gold-plated parts show correct lubricant dash-number

### REASON FOR CHANGE:

Document clarification. Lubricant dash-number error on production drawing goes back to original drafting of prints - Manufacturing location stated gold-plated parts have always been made with correct lubricant dash-number - This recently discovered error must be corrected - All associated PNs must be bumped a full revision to eliminate any potential future misunderstanding

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED**

**PARTS:** 25-MAY-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS:** NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

**CURRENT DATE:** 22-MAY-2013

**TE CONNECTIVITY****PRODUCT CHANGE  
NOTIFICATION**

**CUSTOMER:** FUTURE ELECTRONICS INC.

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** SINGAPORE

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 1319888

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** HK (0451) - TE Connectivity HK Ltd

---

**PARTS BEING MODIFIED      CUSTOMER PART NBR**

350536-1

(Alias Part Numbers:  
"403429822" )

350561-1

(Alias Part Numbers:  
"0-0350561-1",  
"CU3085-000",  
"AMPS-0-0350561-1" )

350687-1

---

---

**CURRENT DATE:** 22-MAY-2013

## TE CONNECTIVITY

## PRODUCT CHANGE NOTIFICATION

**CUSTOMER:** FUTURE ELECTRONICS  
INCORPORATE

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** CANADA

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 591

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** COLO (0750) - Tyco Electronics Colombia Ltda.

We would like to inform you about the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

### GENERAL PRODUCT DESCRIPTION:

Universal MATE-N-LOK Gold-Plated Contacts

### DESCRIPTION OF CHANGE:

No Change to any product - Correcting lubricant dash-number on production drawing for gold plated parts only - All non-gold-plated parts show correct lubricant dash-number

### REASON FOR CHANGE:

Document clarification. Lubricant dash-number error on production drawing goes back to original drafting of prints - Manufacturing location stated gold-plated parts have always been made with correct lubricant dash-number - This recently discovered error must be corrected - All associated PNs must be bumped a full revision to eliminate any potential future misunderstanding

### ESTIMATE DATE:

**LAST ORDER DATE:**

(OBSOLETE PARTS ONLY)

**LAST SHIP DATE:**

(OBSOLETE PARTS ONLY)

**FIRST DATE TO SHIP CHANGED**

**PARTS:** 25-MAY-2013

(CHANGED PARTS ONLY)

**LAST DATE FOR MIXED**

**SHIPMENTS:** NO MIXED SHIPMENTS

(CHANGED PARTS ONLY)

**CURRENT DATE:** 22-MAY-2013

**TE CONNECTIVITY**

**PRODUCT CHANGE  
NOTIFICATION**

**CUSTOMER:** FUTURE ELECTRONICS  
INCORPORATE

**PRODUCT CHANGE NOTIFICATION NO:** E-13-005785

**LOCATION:** CANADA

**PCN DATE:** 21-MAY-13

**CUSTOMER NO:** 591

**AGREEMENT NO:**

**TE CONNECTIVITY ENTITY:** COLO (0750) - Tyco Electronics Colombia Ltda.

---

**PARTS BEING MODIFIED      CUSTOMER PART NBR**

350536-1  
(Alias Part Numbers:  
"403429822" )

350537-1  
(Alias Part Numbers:  
"AMPS-0-0350537-1",  
"D60465-000" )

350570-1