



No. 70, XingZhong Rd., NeiHu Dist
 Taipei, Taiwan, R.O.C.
 TEL:(886) 2-2792-8000

Product Change Notification

PCN No.	PCN-CF-151104	Dept.	PM2
Project Name	TS8GCF200I	Date	2015/10/13
Subject	CHS setting correction for TS8GCF200I with FBGSSMB flash.		
Refer to	<input checked="" type="checkbox"/> ECN-CF-151104 <input type="checkbox"/> Other: _____	Attachment	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Change Category	<input type="checkbox"/> Marketing Spec <input type="checkbox"/> Test Program and MP tool <input type="checkbox"/> Controller <input type="checkbox"/> Accessory <input type="checkbox"/> Artwork Material <input type="checkbox"/> Mechanism on Appearance <input type="checkbox"/> CD content <input checked="" type="checkbox"/> Firmware <input type="checkbox"/> EOL <input type="checkbox"/> Last time Buy <input type="checkbox"/> Other _____		

I. Description:

CHS setting correction for TS8GCF200I with FBGSSMB flash.

II. Change Comparison:

Comparison	Current	New
ITEM	TS8GCF200I	TS8GCF200I
Flash MfgNo	FBGSSMB-1D04	FBGSSMB-1D04
Flash PN	22-5634	22-5634
Firmware	K0407	K0407
C/H/S	15796/16/63	15798/16/63

III. Affected Model P/N:

TS8GCF200I

IV. Note:

By W/O: C52805