

## **Global Change Notification (GCN)**

**Product Family** USB 3.0 receptacle 10682850 **GCN Number** Series 48395-000x;48397-000x;48398-000x May 04, 2015 Date Issued Reason For Change **Product Component Change** This is to inform valued customer the change on USB3.0 receptacle: 1)Add two Change Description holder on the housing both side to fix housing loose issue; 2)Increase product stability performance; 3)fix the housing loose potential issue. 4) Can perform right away. Internal qualification will be done and ok. Molex product series impacted as enclosed part list: 48395-000x,48397-000x,48398-000x. Shell slot is short to fix the HSG, need extension Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message. Reason For Short Notice Exception 8D Corrective Action Changes Assessment Of Change Internal qualification done. (How Product Will Be Qualified & Validated) Internal Molex Qualification Date April 15, 2015 (Planned Date Information Available) Sample Availability Date April 15, 2015 (Changed Part) Date of Implementation May 05, 2015 Method of Identifying Change Date code. Recommended Replacement Parts n/a Last Time Buy Date for Obsolete Parts Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com