






STRAIGHT PUSH PULL PLUG SOLDER TYPE FOR CABLE .141

PAGE 1/3 ISSUE 09-02-17A SERIES NEX10 PART NUMBER R180052017







All dimensions are in mm.



COMPONENTS	MATERIALS	PLATING (μm)	
5 1	PD400	222	
Body	BRASS.	BBR	
Center contact	BRASS.	SILVER	
Outer contact	BERYLLIUM COPPER	SILVER	
Insulator	PTFE		
Gasket	SILICONE RUBBER		
Others parts	BRASS.	BBR	
-	-	-	
-	-	-	



Technical Data Sheet

STRAIGHT PUSH PULL PLUG SOLDER TYPE FOR CABLE .141

PAGE 2/3	ISSUE 09-02-17A	SERIES NEX10	PART NUMBER R180052017
-----------------	------------------------	--------------	-------------------------------

PACKAGING

50	Contact us	Contact us
Standard	Unit	Other

ELECTRICAL CHARACTERISTICS

Impedance 50 Ω Frequency 0-18 GHz **VSWR** 1.02* 0.0200 x F(GHz) Maxi Insertion loss 0.05 √F(GHz) dB Maxi RF leakage NA - F(GHz)) dB Maxi - (Voltage rating Veff Maxi 500 Dielectric withstanding voltage 1500 Veff mini Insulation resistance 5000 $M\Omega$ mini

MECHANICAL CHARACTERISTICS

Center contact retention

Axial force - Mating End NA N mini Axial force - Opposite end NA N mini N.cm mini NA Torque

Recommended torque

300 Mating N.cm Panel nut NA N.cm Clamp nut NA N.cm A/F clamp nut 0.0000 mm

Mating life 100 Cycles mini g

Weight 12.8380

ENVIRONMENTAL

Operating temperature -55~+125 °C Hermetic seal NA Atm.cm3/s Panel leakage NA

SPECIFICATION

CABLE ASSEMBLY

Stripping	а	b	С	d	е	f
mm	3.5	0	0	0	0.85	0

Assembly instruction: NA

Recommended cable(s)

RG 402

Characteristics indicated on this data sheet are those that can be achieved with the highest performance cable. Intrinsic limitations of the cable may diminish the performance of the

Cable retention

- pull off 200 N mini - torque NA N.cm

TOOLING

Part Number	Description	Hexagon

OTHER CHARACTERISTICS

IP68(1m,24h) mated condition Return loss for interface:






STRAIGHT PUSH PULL PLUG SOLDER TYPE FOR CABLE .141


PAGE 3/3 ISSUE 09-02-17A SERIES NEX10 PART NUMBER R180052017

COMPONENTS
BODY





CENTER CONTACT



1

- -Strip the cable with the cable stripping tool.
- -Clean the cable



3

- -Introduce the cable into the body until contact with the body shoulder.
- -Place the sub-assembly on assembly jig
- -Solder body on the cable.
- -Let assembly cool down before removing it from the jig.

2

- -Insert center contact until the cable
- -Solder center contact

