

HellermannTyton

6/18/2018

Re: Change Notification

To our valued Customer:

HellermannTyton continually evaluates our manufacturing and supply chain to provide you with quality service at a reasonable price. To better serve your business, we inform you of the following change in:

Type		
<input checked="" type="checkbox"/> Production/assembly location	<input type="checkbox"/> Material	<input type="checkbox"/> End of Life w/ replacement
<input type="checkbox"/> Part Number	<input type="checkbox"/> Packaging	<input type="checkbox"/> End of Life w/o replacement
<input checked="" type="checkbox"/> Country of Origin	<input type="checkbox"/> Point of Purchase	<input type="checkbox"/> Additional tool/refurbishment
<input type="checkbox"/> Design (fit, form, function)	<input type="checkbox"/> Point of Pick up	<input type="checkbox"/> Cost/Lead Time
<input type="checkbox"/> Engineering record (non-fit, form, function)	<input type="checkbox"/> Supply Chain	<input type="checkbox"/> Process
Additional Information		
From: HellermannTyton Milwaukee 6701 W. Good Hope Road Milwaukee, WI 53224, USA	To: HellermannTyton Monterrey Av. Internacional – 140-A VYNMSA General Escobedo, Nuevo Leon, 66053 Mexico	
Scope		
HT PN	Customer PN	Change Effective*
CTAM10C2	75Y0479	12/13/2018
CTAM110C2	74Y9745	12/13/2018
CTAM110C3VT	-	12/13/2018
CTAM20C2	75Y0482	12/13/2018
CTAM210C2	75Y0484	12/13/2018
CTM210C2	75Y0499	11/29/2018
CTM30C2	75Y0501	11/29/2018
CTM310C2	75Y0503	11/29/2018
CTM40C2	75Y0505	11/29/2018
CTM410C2	75Y0507	11/29/2018
TM1SF0C2	75Y3257	12/13/2018
TM1SF10C2	75Y3259	12/13/2018
PBM0C2	75Y1911	12/28/2018
PBM10C2	75Y1913	12/28/2018
CTT20R9C2	75Y0512	11/8/2018
T18MR0C2	75Y3509	11/8/2018
T18MR0M4	75Y3510	11/8/2018
T18MR9C2	75Y3511	11/8/2018
HDM3120HIRC2	75Y1053	1/8/2019
IT18FL9C2	75Y1116	11/8/2018
IT18FL9L4	75Y1117	11/8/2018
RT250XL0X2	75Y2916	3/23/2019
RT250XL9X2	75Y2917	3/23/2019
T250L0X2	75Y3578	3/23/2019
T250XL0X2	75Y3587	3/23/2019
126-00049	75Y4105	3/5/2019
HDM250HIRC2	75Y1051	10/23/2018
T30MR0C2	75Y3603	2/8/2019
T30MR0M4	75Y3604	2/8/2019

T30MR9C2	75Y3605	2/8/2019
T30RSF0M4	75Y3607	2/8/2019
T30RSF9C2	75Y3608	2/8/2019
T50RDH0UVC2	75Y3728	3/5/2019
T50RSF0C2	75Y3731	3/5/2019
T50RSF9C2	75Y3733	3/5/2019
RT250M0X2	75Y2911	3/23/2019
RT250R0X2	80Y1486	3/23/2019
RT250R9X2	75Y2913	3/23/2019
RT250S0X2	75Y2914	3/23/2019
RT255R0HIRX2	75Y2918	3/23/2019
RT255S0HIRX2	75Y2919	3/23/2019
T250S9X2	75Y3586	3/23/2019
T255M0HIRX2	75Y3589	3/23/2019
T255R0HIRX2	75Y3590	3/23/2019

*Effective date is subject to change based on availability

We ask that you please acknowledge this notification by 6/27/2018, informing us if a new PPAP is required. If we do not receive a response, we assume the change can be executed as planned without further notice. For additional information or assistance please contact your HellermannTyton Customer Service Representative. We appreciate your support in this change.

Thank you for your business,

Todd Franz
Quality Project Administrator
Office: 414 355 1130 x 8656
Email: tfranz@htamericas.com