

Customer Information Notification

Issue Date: 08-Aug-2019 Effective Date: 09-Aug-2019 Dear Emma Tempest,

Here's your personalized quality information concerning products Premier Farnell PLC purchased from NXP. For detailed information we invite you to <u>view this</u> notification online

This notice is NXP Company Proprietary.

201907005I



QUALITY

Change Category				
[]Wafer Fab Process	[] Assembly	[] Product Marking	[] Test Location	[] Design
[] Wafer Fab Materials	Process [] Assembly Materials	[] Mechanical Specification	[]Test Process	[X] Errata
[]Wafer Fab Location	[] Assembly Location	[] Packing/Shipping/Labeling	[] Test gEquipment	[X] Electrical spec./Test coverage
[] Firmware	[] Other			
i.MXRT1015&1020 Errata				
and Data Sheet Update to				
Rev.1				

Description

_ _ _

NXP Semiconductors announces errata and data sheet update for both i.MXRT1015&RT1020 to revision 1. The revision history included in the updated documents provides a detailed description of the changes. Changes are summarized below.

For RT1015&RT1020 both Industrial and Consumer Chip Errata: Added following 5 errata:

- * ERR011572
- * ERR050130
- * ERR050144
- * ERR050101
- * ERR050194

For RT1015 both Industrial and Consumer DS, Data Sheet Changes:

1. Updated the SNVS descriptions in the Table 2, i.MX RT1015 modules list

2. Updated the Section 4.8.1, LPSPI timing parameters

For RT1020 both Industrial and Consumer DS, Data Sheet Changes:

1. Added analog descriptions in the Section 1.1, Features

2. Added ADC channel number in the Table 1, The comparison between 100 LQFP and 144 LQFP package

3. Updated the RT website link in the Section 1.2, Ordering information

4. Updated the ADC descriptions in the Figure 2, "i.MX RT1020 system block diagram

5. Updated the RAM size, SNVS descriptions, and USB descriptions in the Table 3, i.MX RT1020 modules list

6. Updated the on-chip termination values of JTAG_TCK and JTAG_MOD in the Table 5, JTAG controller interface summary

7. Removed the USB_OTG2_VBUS from the Table 8, Absolute maximum ratings, Table 11, Operating ranges, and Section 4.2.1.1, Power-up sequence

8. Changed 528 MHz PLL to System PLL in the Table 17, System PLLs electrical parameters

9. Changed 480 MHz PLL to USB PLL in the Table 19, USB PLLs electrical parameters

10. Updated the Section 4.8.1, LPSPI timing parameters

11. Added the Figure 32, "Minimum Sample Time Vs Ras (Cas = 2pF)", Figure 33, "Minimum Sample Time Vs Ras (Cas = 5 pF)", and Figure 34, "Minimum Sample Time Vs Ras (Cas = 10 pF)" in the Section 4.7.2, A/D converter

The i.MXRT1015 errata revision 1 is attached to this notice, and can be found at: <u>https://www.nxp.com/docs/en/errata/IMXRT1015CE.pdf</u>

The i.MXRT1020 errata revision 1 is attached to this notice, and can be found at: <u>https://www.nxp.com/docs/en/errata/IMXRT1020CE.pdf</u>

The i.MXRT1015 data sheet revision 1 is attached to this notice, and can be found at: https://www.nxp.com/products/processors-and-microcontrollers/arm-based-processors-and-mcus/i.mxapplications-processors/i.mx-rt-series/i.mx-rt1015-crossover-processor-with-arm-cortex-m7-core:i.MX-RT1015?&tab=Documentation_Tab&linkline=Data-Sheet

The i.MXRT1020 data sheet revision 1 is attached to this notice, and can be found at:

https://www.nxp.com/products/processors-and-microcontrollers/arm-based-processors-and-mcus/i.mxapplications-processors/i.mx-rt-series/i.mx-rt1020-crossover-processor-with-arm-cortex-m7-core:i.MX-RT1020?&tab=Documentation_Tab&linkline=Data-Sheet

Reason

The errata were added for additional technical clarification on some device features.

The data sheets have been updated to correct errors and / or provide additional technical clarification on some device features.

Identification of Affected Products

Product identification does not change

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No impact on form, fit, function, reliability or quality.

Data Sheet Revision

A new datasheet will be issued

Additional information

Affected products and sales history information: see attached file Additional documents: view online

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please <u>contact NXP "Global Quality</u> <u>Support Team"</u>.

0

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

For specific questions on this notice or the products affected please contact our specialist directly: Yang Wang Name

Position **Product Engineer** e-mail address

yang.wang 9@nxp.com

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team. **About NXP Semiconductors**

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

View Notification	Subscription	<u>Support</u>
NXP Privacy Policy Terms of Use		

NXP Semiconductors

High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006-2010 NXP Semiconductors. All rights reserved.