

**EOL-237640**

Product Obsolescence Notification

Issue Date: September 23, 2021

Dear Customer:

Broadcom regrets to announce the immediate obsolescence of the following products, as Broadcom's wafer supplier is discontinuing the manufacture of wafers for these products. Broadcom will not be able to accept any new orders under the obsoleted part numbers.

Broadcom Part Numbers	Description	Suggested Replacement
B50610C1KMLG	Single Gigabit Phy	B50612EB1KMLG, B50210EB1KMLG
BCM54610C1HKFBG	Single Gigabit Phy	BCM54612EB1KFBG, BCM54213PEB1KMLG
BCM54610C1IFBG	Single Gigabit Phy	BCM54612EB1IFBG, BCM54213PEB1IMLG
BCM54610C1IMLG	Single Gigabit Phy	BCM54612EB1IMLG, BCM54210EB1IMLG
BCM54610C1KFBG	Single Gigabit Phy	BCM54612EB1KFBG, BCM54213PEB1KMLG
BCM54610C1KMLG	Single Gigabit Phy	BCM54612EB1KMLG, BCM54210EB1KMLG
B50640EB2KFBG	Quad GPHY with EEE +1588	BCM54640B0KFBG, B50140B0KFBG
B50680EB2KFBG	GPHY with EEE	BCM54680B0KFBG, B50280C1KFBG, B50180B0KFBG
B50682EB2KFBG*	GPHY with EEE +1588	BCM54182B0KQLEG
BCM52681EB2IFBG	10/100 FE PHY with EEE + 1588	BCM52681B1IFBG
BCM54640EB2IFBG	Quad GPHY with EEE +1588	BCM54640B0IFBG, BCM54140B0IFBG
BCM54640EB2KFBG	Quad GPHY with EEE +1588	BCM54640B0KFBG, BCM54140B0KFBG
BCM54680EB2IFBG	GPHY with EEE	BCM54680B0IFBG, BCM54180B0IFBG
BCM54680EB2KFBG	GPHY with EEE	BCM54680B0KFBG, BCM54280C1KFBG, BCM54180B0KFBG
BCM54682EB2KFBG	GPHY with EEE +1588	BCM54182B0KQLEG
BCM54685EB2IPBG	Octal GPHY with EEE +1588	BCM54685B0IPBG, BCM54185B0IFBG



Broadcom Part Numbers	Description	Suggested Replacement
BCM54685EB2KPBG	Octal GPHY with EEE +1588	BCM54685B0KPBG, BCM54185B0KFBG
BCM54880EB2IFBG	GPHY with EEE 1588	BCM54880B0IFBG, BCM54280C1KFBG, BCM54180B0IFBG
BCM54880EB2KFBG	GPHY with EEE 1588	BCM54880B0KFBG, BCM54280C1KFBG, BCM54180B0KFBG

* This EOL letter replaces EOL-149092 for B50682EB2KFBG

Please contact your Broadcom Sales Representative for questions or concerns.

Please contact your Broadcom Field Sales Engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.