

Product Change Notification

Product Category _____ OUTLETS _____ 20230529-1

Product Group _____ ROAR _____

ISSUE DATE: _____ ☒ 29 May-23

IMPACTED REGIONS: ☒ NA ☒ EMEA ☒ LATAM ☐ DISCONTINUATION

REASON FOR CHANGE: ☒ OTHER

DESCRIPTION OF CHANGE: (Required)

The rear gasket of the water resistant faceplates will be replaced due to supply challenges, a minor visual change will be noticed after installation. New gastket will be slightly larger than previous one. Part number will not change and product application will not be affected.



IMPACTED PART NUMBERS AND REPLACEMENT PART NUM+A13:G32BERS: (where applicable)

[Reference Page 2 / Linked PDF](#)

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*	2023	5	31

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	AUSTRALIA: 1-800 7263848 AUS-Customer-Service@panduit.com	CHINA: 800-820-1900 CHN-CustomerService@panduit.com	HONG KONG: 800-965768 CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) 000 800 6500369 (Mobile) IND-Customer_Service@panduit.com	INDONESIA: 001 803 65 7571 SGP-Customer_Service@panduit.com	JAPAN: +81-3-6863-6000 JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	MALAYSIA 1800 801435 SGP-Customer_Service@panduit.com	SINGAPORE: 1-800-7263848 SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	THAILAND: 001-800-65-6385 SGP-Customer_Service@panduit.com	
LATIN AMERICA	BRAZIL 08000562613 (Toll Free)	MEXICO: +52-33-37776000 x80520 01 800 360 86 00 (Toll Free)	OTHER LA COUNTRIES: Phone USA 1-708-532-1800

	BRA-custservice@panduit.com	MEX-customerservice@panduit.com	TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	EMEA: +44 208 6017219 EMEA-CustomerServices@panduit.com

Impacted Part Numbers
CFPWR4CIG
CFPWR4CL
CFPWR4CEI/N