

Product Series Involved

94 Series, 95 Series, and 97 Series Relay Sockets

Type of Change

Major

Key Change

Obsolescence of old socket part numbers.


Scope

Over the years, with advancement of new designs, improved characteristics and production, Finder is obsoleting a few older sockets. The already established new versions will replace the old versions with no change to wiring configurations.

Product Change Notification




Current Part Numbers



94.92.3
94.92.30
94.94.3
94.94.30
95.55
95.55.3
95.93.3
95.93.30
95.95.3
95.95.30
97.51 / 97.51.3
97.51.7
97.52 / 97.52.3

Note: The above part numbers may be followed by SMA or SPA

New Part Numbers



94.02
94.02.0
94.04
94.04.0
95.P5
95.P5
95.03
95.03.0
95.05
95.05.0
97.P1
97.P1.7
97.P2

No change to electrical and wiring configuration.

Note: If using suppression module 99.80 it is necessary to update to newer version 99.02 for the 94 and 95 Series numbers.

Timing

As of May 30th no orders for the older sockets will be accepted. All affected part numbers are easily replaced with the newer versions noted above.

Questions? Contact us at 770-271-4431 or www.finder-us.com