



Product Change Notice 574

Issued January 23, 2015

Please acknowledge this PCN within 30 days of receipt. Lack of acknowledgement within 30 days constitutes acceptance of these changes. After acknowledgement, lack of additional response within 90 days of initial receipt constitutes acceptance. Please send acknowledgement or comments to documentcontrol@coilcraft.com.

Products Affected

XPL2010 series

Description of Change

A white dot is being added on top of the part to indicate the inside lead. Parts will be oriented in the tape as shown.

Reason for Change

Various customers have requested a way to determine the inside lead to aid in their manufacturing processes.

How to Identify Change


New (color dot)



Old (no dot)



Orientation in tape



Expected Impact Due to Change

No impact to form, fit or function of component. This will provide a visual indication of inside lead.

Implementation Date

July 1, 2015

Contact

Document Control Manager, documentcontrol@coilcraft.com, 1-847-639-6400, Fax 1-847-639-1469