


Product Change Notice

Change Description	Implementation of mountingfoot version 3 for TopJob-S series 2004, 2010 and 2016 Both conditions can be used mixed
	Current mountingfoot: 
	New mountingfoot 2- and 3-conductor Series 2004: 
	New mountingfoot 4-conductor Series 2004: 
	New mountingfoot 2- and 3-conductor Series 2010 and 2016: 

Affected Part Numbers:

2004-1201	2004-1304	2004-1411_1000-0400	2016-1202
2004-1202	2004-1305	2004-1411_1000-0401	2016-1204
2004-1203	2004-1306	2010-1201	2016-1207
2004-1204	2004-1307	2010-1202	2016-1208
2004-1205	2004-1311_1000-0400	2010-1203	2016-1301
2004-1206	2004-1311_1000-0400	2010-1204	2016-1302
2004-1207	2004-1311_1000-0401	2010-1205	2016-1303
2004-1209	2004-1401	2010-1207	2016-1304
2004-1211	2004-1402	2010-1208	2016-1305
2004-1211_1000-0400	2004-1403	2010-1301	2016-1306
2004-1211_1000-0401	2004-1404	2010-1302	2016-1307
2004-1211_1000-0703	2004-1405	2010-1303	
2004-1301	2004-1406	2010-1304	
2004-1302	2004-1407	2010-1307	
2004-1303	2004-1408	2016-1201	

Reason for change:

Improved mounting under cold conditions
Improved dismounting under any condition

Changes dated 30-08-17

This change will be integrated in the next six to twelve months. In this frame of time mixed delivery is possible.