

N° 051/20

Dear Customer,

With this INFINEON Technologies Information Note we would like to inform you about the following

Change of tube packing affecting various packages at backend production site at Tijuana, Mexico

Infineon Technologies AG
Postal Address Headquarters: Am Campeon 1-15, D-85579 Neubiberg, Phone +49 (0)89 234-0
Chairman of the Supervisory Board: Dr. Wolfgang Eder
Management Board: Dr. Reinhard Ploss (CEO), Dr. Helmut Gassel, Jochen Hanebeck, Dr. Sven Schneider
Registered Office: Neubiberg
Commercial Register: München HRB 126492

N° 051/20

Change of tube packing affecting various packages at backend production site at Tijuana, Mexico

► **Products affected:**

Please refer to attached affected product list 1_cip05120.xlsx



► **Detailed Change Information:**

Subject: Standardized inner box quantity for all tube packages.

- Reason:**
- As part of the "One Interface to the Customer" (OITC) initiative and data migration to the Infineon system, alignment needs to be done to have a consistent standard tube packing quantity for former International Rectifier (IRF) packages.
 - Contact Sales Representatives or Customer Logistics Management for details on specific parts.

Description:

	<u>Old</u>	<u>New</u>
Minimum order quantity (MoQ) change to standardize number of tubes per inner box packing as specified in below table.		
TO247 Long Lead	■ 750 pcs	■ 400 pcs
TO247 Short Lead	■ 1000 pcs	■ 400 pcs
TO220 / TO263 / TO273	■ 3000 pcs	■ 1000 pcs
TO274 Long Lead	■ 750 pcs	■ 400 pcs
TO274 Short Lead	■ 1000 pcs	■ 400 pcs

N° 051/20

- **Product Identification:** Identification by the quantity is available on labels



- **Impact of Change:**

Infineon does not see any negative impact on quality, function and reliability as it is only a logistical change.

There is no change in form, fit and function except standardization of packing and order quantity. Please change the minimum ordering quantity in your system.

- **Attachments:**

Affected product list 1_cip05120.xlsx

- **Intended start of delivery:**

15-July-2020

A mixed delivery during the transition phase up to 4 weeks might occur.

If you have any questions, please do not hesitate to contact your local Sales office.