



10-May-2021

PCN #:P-21-020898

Subject:Devices as described in below list.

Description of Change: Adding Prop 65 label, further information below. No fit, form or function change.

Reason: Product [improvement.In](#) 1986, California, in the United States of America (USA), enacted the Safe Drinking Water and Toxic Enforcement Act into California state law. This Act, generally referred to as Proposition 65 (Prop 65), is broad law that applies to any company operating in California, selling products in California, or manufacturing products that may be sold in or brought into California. Online channels are now used to sell TE products which means products could ultimately be sold or brought into California. To ensure compliance with Proposition 65 requirements, we have made the decision to include warnings on these products. You will see Proposition 65 warnings on these products from 24 May 2021. Customers should evaluate the environment in which they intend to supply or utilise these products and make their own determination regarding their obligations under Proposition 65 to employees, consumers or other individuals in California.

Key Dates:

Contact By Date:24-May-2021

Implementation Date:24-May-2021

| Product Affected | Alias Part Number |
|------------------|------------------------------------|
| 390299-000 | "3-1192930-5", "DK-621-0439-4P" |
| 740425-000 | "3-1195779-0", "DK-621-0433R-1P" |
| 468675-000 | "4-1193512-9" |
| 120331N001 | "4-1201210-5", "RTD-50-M-04CS2834" |
| F87962-000 | "9-1201725-5" |
| 037359-000 | "6-1190288-6", "DK-621-0087-1P" |
| 361727-000 | "7-1192712-6", "DK-621-0438-3P" |

| Product Affected | Alias Part Number |
|-------------------------|--|
| 168825-000 | "1-1191229-7" |
| 432582-000 | "4-1193253-1", "DK-621-0051-1P" |
| 019439-000 | "6-1190151-7", "DK-621-0433-1P" |
| 915480-000 | "6-1199172-7", "DK-621-0435-2UP" |
| 127200-000 | "9-1199171-0" |
| 960799-000 | "1-1197434-2", "DK-621-0548-2P" |
| 026279-000 | "9-1190203-9", "PTD-50-83-S" |
| 905341-000 | "8-1197034-3", "RTD-75-S-04" |
| EP3803-000 | |
| 020929-000 | "1190163-6", "DK-3716-F221-CP" |
| 175929-000 | "1-1191279-4", "DK-621-0088-2S" |
| 903331-000 | "2-1197020-7", "RBD-75-L-02" |
| 544155-000 | "4-1194268-6", "D-150-9133" |
| A35141-000 | "6-1201422-0", "MK-0020-100" |
| 143981-000 | "9-1191040-2", "DK-621-0434-1S" |
| 289851-000 | "7-1192197-3", "PTD-50-M-01" |
| 879785-000 | "6-1196849-0" |
| 318825N002 | "5-1192418-5", "DK-621-0045-3PCS228" |
| 124675-000 | "3-1190906-8", "DK-621-0436" |
| 963537-000 | "9-1197452-2", "DK-621-0011-PCS1271" |
| 992095-000 | "1197674-4", "PBD-75-M-01" |
| 891382-000 | "7-1200135-9", "DK-621-0047-2PCS228" |
| 228389-000 | "4-1191680-8" |
| E99199-000 | "8-1201725-6" |
| 524907-000 | "8-1194122-7", "DK-621-0433" |
| 121626-000 | "7-1198957-4", "DK-3716-F201-TPCS2789" |
| 327539-000 | "1192478-7", "RTD-50-M-01-H" |
| 023465-000 | "6-1197869-3", "DBHC-0020" |
| 859081-000 | "1-1196694-6", "PBD-75-L-00" |
| 902973N002 | "4-1197017-7", "DK-621-0411-PCS1862" |
| 944889-000 | "5-1197313-6", "D-621-0038" |
| 036958-000 | "4-1190285-7", "D-621-0036" |
| 561366-000 | "2-1194434-8", "DK-621-0050-1S" |
| 525354-000 | "DK-621-0550" |
| 633671-000 | "5-1195012-6", "DK-621-0433-1S" |
| 957740N003 | "2-1197414-0", "DK-621-0046-3PCS258" |
| CX7360-000 | |
| 700513-000 | "9-1195498-3" |
| 947687-000 | "7-1197332-9", "D-150-9134" |
| D36771-000 | "4-1200790-7" |

| Product Affected | Alias Part Number |
|-------------------------|---|
| 500637-000 | "8-1193742-6", "D-621-0012CS1271" |
| EG9719-000 | "D-098-10-01-01" |
| E68466-000 | "8-1201725-3" |
| 719303-000 | "1-1195626-0", "RTD-75-S-01" |
| 379759-000 | "4-1192840-2", "RBD-75-M-04" |
| 459515-000 | "8-1193446-4", "DK-621-0433R-1S" |
| 728269N001 | "6-1201210-1", "RTD-50-L-04CS2834" |
| A11769-000 | "9-1200570-5", "D-150-0321" |
| F49852-000 | "9-1201725-0" |
| 269967N002 | "6-1191992-7", "DK-621-0045-3SCS228" |
| 452071-000 | "6-1193394-0" |
| EG9721-000 | "D-098-10-01-03" |
| 042871-000 | "9-1190328-1", "DK-621-0440-4P" |
| 404843-000 | "5-1193055-0", "D-621-0027CS934" |
| 206165-000 | "2-1191494-8", "DK-621-1639R-4SCS1930" |
| 916221-000 | "4-1197112-7", "PTD-50-S-01" |
| EG9720-000 | "D-098-10-01-02" |
| 014808-000 | "1-1190116-3", "DK-621-0546" |
| 354499-000 | "8-1192661-9", "DK-3716-F101-TP" |
| 638491-000 | "9-1195046-7", "DK-621-0434-1P" |
| D15592-000 | "6-1201725-0" |
| 929221-000 | "2-1197204-7", "DK-621-0087-1S" |
| 312537-000 | "4-1192364-4", "RBD-50-L-01" |
| 954355-000 | "2-1197389-1", "D-621-0002CS064", "4-40001-7728" |
| 711551-000 | "5-1195574-2", "DK-621-0438" |
| 702377-000 | "3-1195511-3", "RTD-50-L-03" |
| 507911-000 | "5-1193977-4" |
| 601107N006 | "5-1200792-2", "D-621-0001CS2866" |
| 969005-000 | "6-1197491-4", "D-621-0012CS1902" |
| 186825-000 | "2-1191356-5", "DK-3716-E102-TS" |
| 660872-000 | "1195210-5" |
| 139255-000 | "9-1191009-1", "DK-621-0411R-S" |
| 018591-000 | "3-1190145-0", "DK-621-0011-S" |
| 610789-000 | "1194830-8", "DK-621-0035-2PCS1271" |
| 536937-000 | "4-1194214-1", "DK-621-0411R-44PCS2326" |
| 648823-000 | "6-1195121-0", "DK-621-0052-1P" |
| 648837-000 | "8-1195121-2", "PBD-50-M-00-MS" |
| 156542-000 | "1-1191131-3", "DK-621-0039-4S" |
| 696255-000 | "8-1195461-3", "B-202-82" |

| Product Affected | Alias Part Number |
|-------------------------|---------------------------------------|
| 912481N001 | "6-1201210-7", "RBD-50-S-00CS2834" |
| 293270N002 | "8-1192222-6", "DK-621-0049-1SCS228" |
| 272199-000 | "6-1192016-4", "DK-621-0434" |
| D29402-000 | "6-1201725-1" |
| 641225-000 | "3-1195068-5" |
| 933981-000 | "7-1197237-1", "DK-621-0440" |
| 943488-000 | "7-1199172-0" |
| 542467-000 | "2-1194253-5", "DK-621-0436-2S" |
| 955933-000 | "1-1197401-7" |
| 499987-000 | "7-1193737-0", "DK-621-0512" |
| 120331-000 | "4-1190875-0", "RTD-50-M-04" |
| 441975-000 | "9-1193322-4", "RTD-75-M-01" |
| 438510-000 | "7-1193295-3", "DK-621-0039-4P" |
| E24799-000 | "6-1200790-5" |
| 724447-000 | "1195663-1", "DK-621-0435-2S" |
| 106881-000 | "6-1190780-1", "DK-621-0550-1S" |
| 549335-000 | "8-1194322-6", "DK-3716-E224-CS" |
| 974435-000 | "4-1197530-3", "DK-3716-F201-TS" |
| 986829-000 | "8-1197621-8", "DK-621-1638-3P" |
| 301528-000 | "4-1199929-4", "D-150-L708-F1" |
| CU2949-000 | |
| 323783-000 | "6-1192450-3", "RTD-50-L-00" |
| 491332-000 | "1193675-8", "DK-621-0051-1S" |
| 971913-000 | "6-1197512-1", "DK-621-0012-P" |
| 223723-000 | "1191648-6", "RTD-50-L-01" |
| 530805N002 | "9-1194168-5", "DK-621-0436-2PCS1104" |
| 157763-000 | "7-1191139-6", "RTD-75-M-00" |
| 842399-000 | "4-1196571-8", "RBD-75-S-01" |
| CM5812-000 | "D-150-9133CS2925" |
| 593035N001 | "5-1201210-6", "RTD-50-M-01CS2835" |
| 947687N001 | "4-1200878-1", "D-150-9134CS2873" |
| 070351-000 | "2-1190529-0", "DK-621-0435-2P" |
| 191045-000 | "7-1191385-3", "DK-621-0411-S" |
| EK4374-000 | |
| 608041-000 | "6-1194809-4", "DK-621-1638-3S" |
| 497293-000 | "2-1193718-6", "D-621-0027" |
| 438915-000 | "5-1193298-0", "DK-621-0411R-P" |
| 362346-000 | "9-1192716-8", "DK-621-0551" |
| 365668-000 | "2-1199172-5" |
| E02554-000 | "7-1201725-1" |

| Product Affected | Alias Part Number |
|-------------------------|---------------------------------------|
| CM8600-000 | |
| 573571-000 | "1-1194553-6", "RTD-50-M-03" |
| 197947-000 | "5-1191434-1", "RBD-75-M-01" |
| 477472N002 | "9-1193575-6", "DK-621-0049-1PCS228" |
| 734977-000 | "1-1195740-4", "DK-621-0412-UP" |
| 601107-000 | "8-1194757-5" |
| 475861-000 | "2-1193564-7", "PTD-50-L-01" |
| 855793-000 | "4-1196670-9", "DK-621-1634-1P" |
| 199653-000 | "2-1191446-3", "DK-621-0411-45S" |
| 800523-000 | "7-1196189-3" |
| 668131-000 | "5-1195261-3", "RTD-50-M-00" |
| 652913-000 | "3-1195153-7", "DK-621-0437-3P" |
| 601108-000 | "9-1194757-0" |
| 485251-000 | "5-1193631-5", "RBD-75-L-01" |
| 911225-000 | "1-1197077-0", "DK-621-1639-4S" |
| 094067-000 | "6-1190689-6", "RTD-75-M-02" |
| F87083-000 | "1-1201174-6", "DK-621-L934-1S" |
| 992021-000 | "5-1197673-1", "RTD-50-M-00-H" |
| 727755-000 | "2-1195687-3" |
| 432582N002 | "4-1193253-4", "DK-621-0051-1P-CS257" |
| 601154-000 | "4-1194758-9", "D-621-0011" |
| 391329-000 | "9-1192936-1", "DK-621-0412-45S" |
| A12306-000 | "3-1201725-7" |
| 641537-000 | "5-1195070-5", "DK-3716-E222-CS" |
| 503123-000 | "1-1193787-5", "DK-621-0412-S" |
| 339341-000 | "1-1192561-2", "RTD-75-L-00" |
| EK3418-000 | |
| 858834-000 | "3-1201190-7", "DK-621-L933-1S" |
| 745177-000 | "8-1195812-7", "DK-621-1635R-2S" |
| 639215-000 | "2-1195052-1", "DK-621-0012-S" |
| 503123N002 | "1-1193787-7", "DK-621-0412-SCS857" |
| 436425-000 | "7-1193280-8", "PBD-50-M-01-MS" |
| 241251-000 | "4-1191772-5", "DK-621-0440-4S" |
| 128469-000 | "5-1190933-3", "RBD-50-M-03" |
| 425653-000 | "9-1193203-9", "RTD-50-P-00" |
| 520077-000 | "8-1194085-5", "PBD-50-M-01" |
| 881889-000 | "1-1196865-9", "RBD-50-L-02" |
| 449453-000 | "3-1193376-3", "D-150-0708-5" |
| 477472-000 | "9-1193575-3", "DK-621-0049-1P" |
| 515159-000 | "3-1194046-2", "DK-621-0090-4S" |

| Product Affected | Alias Part Number |
|-------------------------|--|
| 883641-000 | "3-1196877-8", "RTD-50-S-01" |
| 871693-000 | "6-1196783-2" |
| 383392-000 | "2-1199172-6" |
| 484104-000 | "9-1199923-6" |
| 205863-000 | "1191492-9", "RBD-75-M-03" |
| CM8603-000 | |
| 510241-000 | "6-1194010-6", "DK-621-1635R-2SCS1930" |
| 736953-000 | "1-1195754-6", "DK-621-0089-3S" |
| 601155-000 | "5-1194758-5", "D-621-0012" |
| 385449-000 | "1-1192892-6", "DK-621-0437" |
| 332350-000 | "1-1192511-5" |
| 392221-000 | "7-1197837-6", "DK-621-0412-USCS2682" |
| 526151-000 | "8-1194134-6", "DK-3716-E202-TP" |
| 400675-000 | "5-1193025-1", "DK-3716-E222-CP" |
| 842531N001 | "6-1201210-4", "RTD-50-S-04CS2834" |
| 660873-000 | "1195210-6" |
| 916629-000 | "5-1197812-1", "DK-621-0412-45SCS2682" |
| 847037-000 | "6-1196606-0", "DK-621-0435" |
| 118345-000 | "1-1190861-9", "DK-621-0412-P" |
| C11277-000 | "2-1200790-7" |
| 491952-000 | "5-1193679-1", "DK-621-0050-1P" |
| CY9236-000 | |
| EK2494-000 | "DK-675-0433/0434-A1" |
| 918911-000 | "2-1197131-0", "RBD-75-S-03" |
| 196799-000 | "8-1191426-9", "RTD-75-S-00" |
| 055672-000 | "8-1199171-2" |
| 614637-000 | "6-1194858-4" |
| 407575-000 | "6-1193074-2", "DK-621-1637-3P" |
| 132195-000 | "7-1190960-3", "RBD-50-L-00" |
| 214946-000 | "3-1191552-6", "DK-621-0040-4S" |
| 591691-000 | "1-1194680-9", "RBD-75-S-04" |
| 171071-000 | "6-1191244-9", "DK-3716-E202-TS" |
| 648823N002 | "6-1195121-3", "DK-621-0052-1P-CS259" |
| 581157-000 | "1194605-7" |
| 149527-000 | "3-1191081-3", "DK-621-0412" |
| 154710-000 | "1-1199210-2" |
| 945696-000 | "7-1199172-1", "DK-621-0436-2US" |
| 850359-000 | "4-1196630-4", "RBD-50-S-04" |
| 969729-000 | "8-1197496-9", "DK-621-0439" |
| 811966-000 | "1199995-2", "DK-621-0050-1SCS258" |

| Product Affected | Alias Part Number |
|-------------------------|--|
| 572829-000 | "9-1194547-9", "RBD-50-L-04" |
| 161438N002 | "7-1191165-4", "DK-621-0048-2SCS258" |
| 902973-000 | "4-1197017-5", "DK-621-0411-P" |
| CN1332-000 | |
| 582693-000 | "9-1194615-1" |
| 052247-000 | "6-1190399-9", "PTD-50-M-00" |
| 036977-000 | "6-1190285-8", "DK-3716-E212-TS" |
| 187785-000 | "8-1191362-7", "DK-621-0548" |
| 696254-000 | "8-1195461-0" |
| 139515-000 | "7-1191011-6", "DK-3716-F201-TP" |
| 893543-000 | "9-1196949-9" |
| 718869-000 | "9-1195622-3", "RBD-50-S-03" |
| C54421-000 | "5-1201725-1" |
| 536389-000 | "6-1194210-2", "RBD-50-L-03" |
| 848661-000 | "1196618-7", "RTD-50-P-02" |
| 332350N001 | "1-1192511-6", "D-600-0019CS2731" |
| 461067-000 | "1-1193458-8" |
| 532505-000 | "2-1194181-5", "RBD-50-M-02" |
| EP5547-000 | |
| 857483-000 | "6-1196682-8", "RBD-75-L-00" |
| 905497-000 | "9-1197035-9", "RTD-50-S-00" |
| 511405N001 | "3-1201209-5", "RBD-50-M-01CS2834" |
| 028775-000 | "1190223-6", "DK-621-1435R-2S" |
| 182443-000 | "7-1191325-1" |
| 499725-000 | "7-1193735-3", "D-621-0011CS1271" |
| 863011-000 | "6-1196721-1", "PTD-50-85-S" |
| 014125-000 | "7-1190110-3", "DK-621-0037-3PCS1271" |
| 937549-000 | "1-1197263-2", "PTD-50-92-S" |
| D54598-000 | "6-1201725-5" |
| 734989-000 | "2-1195740-3", "DK-621-0437-3S" |
| CM8606-000 | |
| 014939-000 | "2-1190117-7", "DK-621-0439-4S" |
| 593035-000 | "6-1194689-0", "RTD-50-M-01" |
| 061209-000 | "4-1190463-4", "PBD-75-M-03" |
| 942598-000 | "2-1199152-0", "DK-621-0433-1US" |
| 141275-000 | "9-1191023-4" |
| 541315-000 | "3-1194245-0", "RTD-50-S-03" |
| 842531-000 | "3-1196572-7", "RTD-50-S-04" |
| CS7919-000 | "DK-621-0412R-S" |
| 810685-000 | "9-1196299-4", "DK-621-1633R-1SCS1930" |

| Product Affected | Alias Part Number |
|-------------------------|---------------------------------------|
| 041809N001 | "3-1190320-8", "DK-621-1640-4PCS312" |
| 295997-000 | "4-1192242-8", "DK-621-1636-2P" |
| 900469N001 | "4-1201209-9", "RBD-50-M-00CS2834" |
| 333867-000 | "6-1192522-1", "RTD-75-M-04" |
| 883689-000 | "6-1196877-6", "PBD-50-M-00" |
| 524635-000 | "1194121-1", "RTD-50-L-02" |
| EK1531-000 | "D-621-0008CS2866" |
| 820597-000 | "4-1196398-2", "DK-621-0411R-PCS2326" |
| 931075-000 | "2-1197217-0", "DK-621-0052-1S" |
| 449255-000 | "1193375-8", "RBD-50-S-02" |
| 982910-000 | "3-1197594-1" |
| 161529-000 | "3-1191166-9" |
| 244913-000 | "6-1191796-1", "DK-621-0035-2P" |
| 765475-000 | "1-1195959-1", "RTD-50-S-02" |
| 065039-000 | "1190491-9", "DK-3716-F221-CS" |
| 288705-000 | "5-1192189-2" |
| 530805-000 | "9-1194168-3", "DK-621-0436-2P" |
| 552587-000 | "6-1194367-5", "KHDB-6155" |
| D42234-000 | "4-1200790-8" |
| C20019-000 | "4-1201725-6" |
| 534583-000 | "1-1194196-5", "RBD-75-M-02" |
| 393863-000 | "8-1192954-1", "D-150-9708-5" |
| 707080-000 | "5-1199022-6", "DK-621-0047-2SCS228" |
| 128596-000 | "8-1199150-7", "DK-621-0434-1US" |
| 041809-000 | "3-1190320-7", "DK-621-1640-4P" |
| EG9778-000 | "DK-621-1640-4SCS312" |
| 894401-000 | "7-1196955-7", "D-150-0708-2" |
| 951419-000 | "4-1197357-9", "DK-621-0434-1PCS1104" |
| F45204-000 | "8-1201725-9" |
| 900469-000 | "4-1196999-4", "RBD-50-M-00" |
| 704201-000 | "1-1195524-5" |
| F67524-000 | "9-1201725-3" |
| 363549-000 | "1192726-3", "DK-621-0011-P" |
| 638323-000 | "7-1195045-2" |
| 931075N002 | "2-1197217-3", "DK-621-0052-1SCS259" |
| 580047-000 | "1-1194597-1", "DK-621-0411-US" |
| 631921-000 | "1195000-7", "B-500-600-00" |
| 644749-000 | "7-1195092-5", "DK-621-0411R-44P" |
| 390039-000 | "5-1192928-2", "RTD-75-S-02" |
| 873151-000 | "4-1196794-2", "DK-3716-E224-CP" |

| Product Affected | Alias Part Number |
|-------------------------|--------------------------------------|
| 600363-000 | "1-1194748-8", "PTD-50-82-S" |
| 849185-000 | "7-1196621-0" |
| 457333-000 | "8-1193431-9", "DK-621-1637-3PCS324" |
| 918455-000 | "2-1197128-7", "RBD-75-S-00" |
| 728269-000 | "7-1195690-8", "RTD-50-L-04" |
| 247116-000 | "1-1199151-3", "DK-621-0433-1UP" |
| 191045N002 | "7-1191385-5", "DK-621-0411-SCS1862" |
| 404880-000 | "7-1193055-4", "DK-621-0033-1S" |

The dates on the product change notification (PCN) are best estimate dates determined at the time of issuance. Actual implementation dates may vary from such dates.

The change described in the PCN can be withdrawn, without notice, for any or all of the products identified on the PCN.

TE Connectivity corporate policy is for PCNs to be valid for 60 days and obsolescence notices to be valid for 180 days after date of issue.

For confirmation or additional information on the change, please contact the TE Connectivity Product Information Center at 800-522-6752 or your TE Connectivity Sales Representative.

Alert document created by IHS Markit based on content provided by TE Connectivity.