

Product Change Notice

Alps PCN: LO080921_Disti

Date: August 9, 2021

Type of Change:	Discontinuation of Products
Title of Change:	2021 Notice of Discontinuation – Switches, TACT Switches™, Variable Resistors
Description of Change:	Products will be discontinued due to the following reasons: 1) Demand for this product became very low and we have had very few orders recently. 2) The production equipment (Jigs/tools) get too old, or difficult to purchase materials. 3) We have not received your PO for a long time.
Contact Information:	Sales and Marketing Contact Sales@alps.com Alps Alpine North America, Inc.
Product Affected:	Switches, TACT Switches™, Variable Resistors

AFFECTED ALPS ALPINE PART NUMBERS

Part Number	Suggested Alternative
EC11B15202AN	-
EC11B1524209	-
EC11B15242AF	-
EC11B15242AZ	-
EC11B15242B1	-
EC11E0B2LB01	-
EC11E152T409	-
EC11E152U402	-
EC11E1534408	-
EC11E153440D	-
EC11E1834403	-
EC11E183440C	-
EC11EBB24C03	-
EC11G1560414	-
EC11G1564411	EC11M1565403
EC11G1574402	EC11M1575403
EC11J0920404	-
EC11J0924411	-
EC11J0925403	-
EC11J152040F	-
EC11J1524413	-
EC11J1525402	-
EC11K0920404	-
EC11K0925416	-
EC11K1520406	-
EC11K1524406	-
EC11K1525413	-

Part Number	Suggested Alternative
EC20A1820401	-
EC20A1824401	-
EC45AG520402	-
EC60B1520402	EC50A0920404
EM20B4014000	-
RDC401D07A	-
RDC803001A	-
RDCC010002	-
RK08H11100U3	-
RK08H11100X7	-
RK08H11100XC	-
RK08H1110A04	-
RK08H1120A05	-
RK08H113003G	-
RK08H12100GP	-
RK08H122005A	-
RK08H123002K	-
RK09710ELC07	EC11E15244G1
RK09711100F8	-
RK097111020N	-
RK097111080J	-
RK0971110909	-
RK097111091M	-
RK0971110D57	-
RK0971110D7F	-
RK09711110AL	-
RK0971111Z0P	-

Note: Lack of acknowledgment of this PCN by September 30, 2021 constitutes acceptance of change.

AFFECTED ALPS ALPINE PART NUMBERS

Part Number	Suggested Alternative
RK0971111Z32	-
RK097111202P	-
RK097111202Q	-
RK0971114D0B	-
RK0971114Z07	-
RK097111T064	-
RK097111TD44	-
RK097111TZ17	-
RK0971210097	-
RK09712100AV	-
RK0971210Z2M	-
RK0971214Z06	-
RK097121TD57	-
RK097122008T	-
RK09712200MC	-
RK09712200MT	-
RK09712200MY	-
RK0971221Z05	-
RK0971221Z11	-
RK097122200G	-
RK097122TZ0A	-
RK097221004C	-
RK09D1110C0R	-
RK09D113000F	-
RK09D1130A1L	-
RK09D1130A1N	-
RK09K11100E9	-
RK09K1110A2S	-
RK09K1110AH8	-
RK09K1110B1R	-
RK09K1110B1V	-
RK09K1130A70	-
RK09K1130AAU	-
RK09K1130ACL	-
RK09K1130AH1	-
RK09K1130AJ3	-
RK09K1130AU2	-
RK09K1130AV7	-
RK09K1130BM4	-
RK09K12A0A2K	-
RK09K12A0A6R	-
RK09K12A0B0W	-

Part Number	Suggested Alternative
RK09K12C0A19	-
RK09K12C0A2S	-
RK09K12C0A4D	-
RK09K12C0A8K	-
RK09K12C0A8P	-
RK09L112003P	-
RK09L1120A2S	-
RK09L1120A69	-
RK09L1140A5E	-
RK09L1140A5P	-
RK09L1140A65	-
RK09L1140A66	-
RK09L122002M	-
RK09L1220A1B	-
RK09L124000Z	-
RK09L1240A12	-
RK09L12B0A31	-
RK09L12B0A3Z	-
RK10J11E002Y	-
RK10J11R001Y	-
RK10J11R0A0H	-
RK10J12E0024	-
RK10J12E002L	-
RK1191110001	-
RK1191114001	-
RK1191124001	-
RK11K1110A3D	-
RK11K1120060	-
RK11K1120A31	-
RK11K1120A5T	-
RK11K113002F	-
RK11K1130040	-
RK11K1130A07	-
RK11K1130A0M	-
RK11K1130A2X	-
RK11K114001Z	-
RK11K114003Y	-
RK11K1140A23	-
RK11K1140A2S	-
RK11K1140A4Q	-
RK12L1210C0R	-
RK12L123000E	-

Note: Lack of acknowledgment of this PCN by September 30, 2021 constitutes acceptance of change.

AFFECTED ALPS ALPINE PART NUMBERS

Part Number	Suggested Alternative
RK12L1230C0K	-
RK12L1230C0T	-
RK12L1270009	-
RK12L12C0A0A	-
RK12L12C0C0V	-
RK14J12R0A0C	RK10J12R004R
RK14K1210A1B	-
RK14K1220024	-
RK14K1220A0F	-
RK14K1220A25	-
RK14K1230A0X	-
RK14K1230A2X	-
RK14K1240036	-
RK14K1240062	-
RK14K1240D04	-
RK14K12A0A3C	-
RK14K12B0A0R	-
RK14K12C0A0T	-
RK14K12C0A1S	-
RK14K12D0A18	-
RK1631110TBK	-
RK1631110TT3	-
RK1631110TTU	-
RK1631210AWN	-
RK16312A0BKH	-
RK203111000V	-
RK203111001A	-
RK203111001B	-
RK45B1A00001	-
RK45B1A00002	-
RKJXK1210002	-
RKJXK122000D	-
RKJXK122400Y	-
RKJXM2E13004	-
RKJXS1004001	-
RKJXV1224005	-
RKJXW2014001	-
RKJXY1000006	-
RKJXY100000A	-
RS20H11AA019	-
RS20H11CA00B	-

Part Number	Suggested Alternative
RS301111J00R	-
RS30111A602N	-
RS30111AC00V	-
RS30112AC00J	-
RS4511119A04	-
RS45111ABA02	-
RS451121400A	-
RS60112A600N	-
RS60112A600U	-
RS6011Y1600Q	-
RS6011YA600M	-
RSA0N11S9A0K	-
SDKTA20100	-
SKQUCAA010	SKRHAAE010
SPEG110100	-
SPUP192300	SPUJ191500
SPVL110100	SPVL110102
SPVN110101	SPVN110107
SPVN210101	SPVN210106
SPVQ640100	SPVQ640102
SPVQ850500	SPVQ850501
SPVQ860100	SPVQ860101
SPVQ910201	SPVQ910205
SPVR110100	SPVR110102
SPVR120100	SPVR120102
SPVT110102	SPVT110106
SPVT110201	SPVT110202
SPVT120101	SPVT120103
SPVT120201	SPVT120202
SPVT130101	SPVT130102
SPVT130201	SPVT130202
SPVT140101	SPVT140104
SPVT210101	SPVT210104
SPVT210201	SPVT210202
SPVT220102	SPVT220103
SPVT220201	SPVT220202
SPVT230101	SPVT230103
SPVT230201	SPVT230202
SPVT240101	SPVT240103
SSCW110101	SSCW110102
SSSS212301	SSSS213800

Note: Lack of acknowledgment of this PCN by September 30, 2021 constitutes acceptance of change.

Alps Alpine Sites Affected:	Americas
Last Time Buy:	September 30, 2021
Last Time Ship:	December 31, 2021

Note: Lack of acknowledgment of this PCN by September 30, 2021 constitutes acceptance of change.