

## **Product Bulletin**

Document #:PB24394X1 Issue Date: 07 Oct 2022

| Title of Change:          | Update for <b>PB24394X</b> - To identify specific sites affected with the change including the transition period.  |                                  |  |
|---------------------------|--|----------------------------------|--|
| Effective date:           | 07 Oct 2022  |                                  |  |
| Contact information:      | Contact your local onsemi Sales Office or KrisJudelo.Dayna@onsemi.com  |                                  |  |
| Type of notification:     | This Product Bulletin is for notification purposes only. onsemi will proceed with implementation of this change upon publication of this Product Bulletin. |                                  |  |
| Change Category:          | Test Change  |                                  |  |
| Change Sub-Category(s):   | Shipping/Packaging/Marking   |                                  |  |
| Sites Affected:           |  |                                  |  |
| onsemi Sites              |  | External Foundry/Subcon Sites    |  |
| onsemi Cebu, Philippines  |  | Greatek Electronics Inc., Taiwan |  |
| onsemi Leshan, China      |  | HANA Microelectronics, China     |  |
| onsemi Seremban, Malaysia |  | JCET, China                      |  |

## **Description and Purpose:**


This update to PB24394X is to list all of the affected sites and clarify that the transition period will be until Dec 31,2022.

SOSM and SOT223 package assembled in various listed sites will start to use onsemi Marking Layout Configuration

This is part of the alignment and marking standardization.

For a specific OPN that is build in different sites will now have the same lay out scheme and will just differ on the plant code.

Sample marking change below.



Note: This information is generic. Please refer to device data sheet for actual part marking. Pin1 indicator, Pb–Free indicator, microdot, may or may not be present.

Some products may not follow the Generic Marking.

TEM001796 Rev. D Page 1 of 2



## **Product Bulletin**

Document #:PB24394X1 Issue Date: 07 Oct 2022

## **List of Affected Standard Parts:**

**Note**: Only the standard (off the shelf) part numbers are listed in the parts list. Any custom parts affected by this PCN are shown in the customer specific PCN addendum in the PCN email notification, or on the <u>PCN Customized Portal</u>.

| FDT86256       | FDV301N    | FDV304P     |
|----------------|------------|-------------|
| FFB2227A       | FFB2907A   | FFB5551     |
| FIN1001M5X     | FIN1002M5X | FL3100TSX   |
| FMB2222A       | FMB2227A   | FMB2907A    |
| FMB3904        | FMB3906    | FMB3946     |
| FMB5551        | FMBA06     | FMBA14      |
| FMBM5401       | FMBM5551   | MMBD1505A   |
| MMBD1503A-D87Z | MMBD1501A  | MMBD1405A   |
| MMBD1405       | MMBD1403   | MMBD1401    |
| HUFA75307T3ST  | FZT790A    | FZT649      |
| FXLP34P5X      | FSQ501L    | FSQ500L     |
| FSB749         | FSB660A    | FSB649      |
| FSB560A        | FSB560     | FSA5157P6X  |
| FSA4159P6X     | FSA4157P6X | FSA4157AP6X |
| FMMT549        |            |             |

TEM001796 Rev. D Page 2 of 2