PCN# 20141104001
ISO7241C Data Sheet
Data Sheet Change Notification

Date: 11/20/2014
To: Newark/Farnell PCN

Dear Customer:

This is a notice of change to a product data sheet for a device that is currently offered by Texas Instruments. The details of this change are on the following pages.

We request you acknowledge receipt of this notification within **30** days of the date of this notice.

The proposed first ship date is indicated on page 3 of this notification, unless customer agreement has been reached on an earlier implementation of the change.

This notice does not change the end-of-life status of any product. Should product affected be on a previously issued product withdrawal/discontinuance notice, this notification does not extend the life of that product or change the life time buy offering/discontinuance plan.

For questions regarding this notice, contact your local Field Sales Representative or the PCN Manager (PCN_ww_admin_team@list.ti.com).

Sincerely,

PCN Team
SC Business Services
Phone: +1(214) 480-6037
Fax: +1(214) 480-6659

Products Affected:

The devices listed on this page are a subset of the complete list of affected devices. According to our records, these are the devices that you have purchased within the past twenty-four (24) months. The corresponding customer part number is also listed, if available.

DEVICE	CUSTOMER PART NUMBER
ISO7241CDW	null

Technical details of this Product Change follow on the next page(s).

PCN Number:	20141104001		**PCN Date:**	11/20/2014
Title:	ISO7241C Data Sheet			
Customer Contact:	PCN Manager	**Phone:** +1(214)480-6037	**Dept:**	Quality Services
Proposed 1ˢᵗ Ship Date:	02/20/2015			

Change Type:

☐	Assembly Site	☐	Design	☐	Wafer Bump Site
☐	Assembly Process	☒	Data Sheet	☐	Wafer Bump Material
☐	Assembly Materials	☐	Part number change	☐	Wafer Bump Process
☐	Mechanical Specification	☐	Test Site	☐	Wafer Fab Site
☐	Packing/Shipping/Labeling	☐	Test Process	☐	Wafer Fab Materials
				☐	Wafer Fab Process

PCN Details

Description of Change:

The product datasheet(s) for ISO7241C have been updated as summarized in the following change history.

ISO7240CF, ISO7240C, ISO7240M
ISO7241C, ISO7241M, ISO7242C, ISO7242M

TEXAS INSTRUMENTS

SLLS868P – SEPTEMBER 2007 – REVISED OCTOBER 2014

www.ti.com

Changes from Revision O (November 2012) to Revision P   **Page**

- Added *Pin Configuration and Functions* section, *Handling Rating* table, *Feature Description* section, *Device Functional Modes*, *Application and Implementation* section, *Power Supply Recommendations* section, *Layout* section, *Device and Documentation Support* section, and *Mechanical, Packaging, and Orderable Information* section 1
- Changed ISO7241C minimum supply from 2.8 V to 3.15 V 7

The datasheet number will be changing.

Device Family	Change From:	Change To:
ISO7241C	SLLS868O	**SLLS868P**

These changes may be reviewed at the datasheet links provided.

http://www.ti.com/lit/gpn/iso7241c

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Electrical specification performance changes as indicated above.

Changes to product identification resulting from this PCN:

None.

Product Affected:

ISO7241CDW	ISO7241CDWG4	ISO7241CDWR	ISO7241CDWRG4

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com