# Product Change Notification

**Product Group:** Thin Film/**08-25-17/PCN-TF-002-2017 Rev 0**

# RFCS Product Termination Notice

**DESCRIPTION OF CHANGE:** Discontinuation of RFCS Value Range 0.2 to 0.6 picofarad and RFCS Solder termination options

**CLASSIFICATION OF CHANGE:** Assembly Process/Structure and Form, Fit, Function

**REASON FOR CHANGE:** Production materials and process no longer sustainable for these RFCS values and terminations due to low demand

**EXPECTED INFLUENCE ON QUALITY/RELIABILTY/PERFORMANCE:** There will be no effect on quality, reliability and/or performance.

**PRODUCT CATAGORY:** Hybrids & Substrates

**PART NUMBERS/SERIES/FAMILIES AFFECTED:** RFCS part family. All part numbers affected are listed below/attached

**VISHAY BRAND(s):** Vishay Electro-Films

**TIME SCHEDULE:**
Last Time Buy Date: March 28, 2018
Last Time Shipment Date: September 28, 2018

**SAMPLE AVAILABILITY:** N/A

**PRODUCT IDENTIFICATION:** N/A

**QUALIFICATION DATA:** N/A

**This PCN is considered approved, without further notification, unless we receive specific customer concerns before** October 28, 2017 **or as specified by contract.**

**ISSUED BY:** Andrew Mason, Product Marketing Manager, Vishay Electro-Films, andrew.mason@vishay.com

**For further information, please contact your regional Vishay office.**

**CONTACT INFORMATION:**


**The Americas**
Vishay Americas
One Greenwich Place
Shelton, CT 06484 USA
PH: +1-402-563-6866
FAX: +1-402-563-6296
efi@vishay.com

**Europe**
Vishay Electronic GMBH
Geheimrat-Rosenthal-STR,100
95100 Selb Germany
PH: +49-9287-71-0
FAX: +49-9287-70435
richard.steel@vishay.com

**Asia**
Vishay Intertechnology Asia PTE Ltd
37A Tampines St 92 #07-00
Singapore 528886
PH: +65-6788-6668
FAX: +65-6788-0988
victor.goh@vishay.com

**RFCS Part Numbers to be obsoleted:**

| |
|---|
| RFCS04021000BJTT1 |
| RFCS04021000BJTTS |
| RFCS04021000BJTWS |
| RFCS04021000CBTT1 |
| RFCS04021000CBTTS |
| RFCS04021000CBTWS |
| RFCS04021000CBTWS |
| RFCS04021200BJTT1 |
| RFCS04021200BJTTS |
| RFCS04021200BJTWS |
| RFCS04021200CBTT1 |
| RFCS04021200CBTTS |
| RFCS04021200CBTWS |
| RFCS04021500BJTT1 |
| RFCS04021500BJTTS |
| RFCS04021500BJTWS |
| RFCS04021500CBTT1 |
| RFCS04021500CBTTS |
| RFCS04021500CBTWS |
| RFCS04021800BJTT1 |
| RFCS04021800BJTTS |
| RFCS04021800BJTWS |
| RFCS04021800CBTT1 |
| RFCS04021800CBTTS |
| RFCS04021800CBTWS |
| RFCS04022000DBTT1 |
| RFCS04022000DBTTS |
| RFCS04022000DBTWS |
| RFCS04022200BJTT1 |
| RFCS04022200BJTTS |
| RFCS04022200BJTWS |
| RFCS04022200CJTT1 |
| RFCS04022200CJTTS |
| RFCS04022200CJTWS |
| RFCS04022700BJTT1 |
| RFCS04022700BJTTS |
| RFCS04022700BJTWS |
| RFCS04022700CJTT1 |
| RFCS04022700CJTTS |
| RFCS04022700CJTWS |
| RFCS04022700CKTWS |
| RFCS04023000CBCT1 |
| RFCS04023000CJCT1 |
| RFCS04023000DBTT1 |
| RFCS04023000DBTTS |
| RFCS04023000DBTWS |

| |
|---|
| RFCS04023300CJTT1 |
| RFCS04023300CJTTS |
| RFCS04023300CJTWS |
| RFCS04023900CJTT1 |
| RFCS04023900CJTTS |
| RFCS04023900CJTWS |
| RFCS04024000DBTT1 |
| RFCS04024000DBTTS |
| RFCS04024000DBTWS |
| RFCS04024700CBCT1 |
| RFCS04024700CJCT1 |
| RFCS04024700CJTT1 |
| RFCS04024700CJTTS |
| RFCS04024700CJTWS |
| RFCS04025000DBTT1 |
| RFCS04025000DBTTS |
| RFCS04025000DBTWS |
| RFCS04025600CJTT1 |
| RFCS04025600CJTTS |
| RFCS04025600CJTWS |
| RFCS04026000DBTT1 |
| RFCS04026000DBTTS |
| RFCS04026000DBTWS |
| RFCS04026800CJTT1 |
| RFCS04026800CJTTS |
| RFCS04026800CJTWS |
| RFCS04027000DBTT1 |
| RFCS04027000DBTTS |
| RFCS04027000DBTWS |
| RFCS04028000DBTT1 |
| RFCS04028000DBTTS |
| RFCS04028000DBTWS |
| RFCS04028200CJTT1 |
| RFCS04028200CJTTS |
| RFCS04028200CJTWS |
| RFCS04028200CKTT1 |
| RFCS04029000DBTT1 |
| RFCS04029000DBTTS |
| RFCS04029000DBTWS |
| RFCS04023000DBGWS |
| RFCS04025000DBGWS |