



PRODUCT CHANGE NOTIFICATION

MAGNETICS



Bourns® Model RLB1112V4 Series 400 Volt Radial Inductors

Core Supplier Change

Riverside, California – June 4, 2026 – In order to support continuity of supply after a supplier for the RLB1112V4 Series 400 Volt Radial Inductors abruptly went out of business, effective June 15, 2026, Bourns is changing the core supplier for the affected part numbers listed below. The new supplier has been qualified and is included in the Bourns Authorized Vendor List.

Affected Part Numbers
RLB1112V4-102J
RLB1112V4-152J
RLB1112V4-222J
RLB1112V4-332J
RLB1112V4-472J

The fit, form, function, quality, and reliability of the affected part numbers will remain unchanged. Traceability will be maintained through lot code and date code.

Samples are available upon request. Bourns recommends that customers test the affected part numbers in their specific applications to verify satisfactory performance.

Implementation Dates:

Last date of delivery of products manufactured using cores from the existing supplier: **June 14, 2026**

First date of delivery of products manufactured using cores from the new supplier: **June 15, 2026**

First date code using the above change: **2625**

If you have any questions or need additional information, please feel free to [contact Customer Service/Inside Sales](#).

Users should verify that the described changes will not impact the performance of the product in their specific applications.

IC26082