Product Change Notification

Current Date: 30-Sep-2026

TE Connectivity

Product Change Notification: P-26-031504

PCN Date: 18-SEP-26

Customer: Premier Farnell UK Ltd (PFUK) (101113)

Location: Leeds

Agreement: Agreement Unknown

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
M83513 Microdot Connectors

Description of Changes
Dear Customer, In support of TE Connectivity's commitment to ensuring long-term product availability and continuity of supply, a marking ink change is being implemented following the supplier's discontinuation of the current ink formulation. The replacement ink has undergone a comprehensive engineering evaluation and qualification process. Based on the results, the new ink has been determined to be equivalent to the current ink in terms of material composition, marking functionality, durability, and overall performance characteristics.

Reason for Changes:	
Product improvement.Validation testing, including assessment in accordance with applicable industry and internal requirements, has confirmed that the replacement ink maintains the intended product marking functionality without adverse effects on product quality, reliability, form, fit, function, or performance. This change has been reviewed, validated, and approved through TE Connectivity's established change management and quality assurance processes prior to implementation.	
Estimated Dates:	
Last Order Date (Obsolete Parts Only):	**First Date To Ship** (Changed Parts Only):
	18-SEP-2026
Last Ship Date (Obsolete Parts Only):	**Last Date for Mixed Shipments:** (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1532206-2	NO			MCKS-C2-B-37SS**, 094-6636-0000**			
1532211-2	NO			MCKS-C2-B-21PS**, 094-6335-0000**			
1532212-1	NO		0N808501-1	"094-6425-0000", "MCKS-N1-B-25PS"			