BROADCOM

PCN-312979

Product Change Notice

Issue Date: 28-September-2026

Change Description:
Addition of alternate IC and LED

Parts Affected:
HCNW3120-000E
HCNW3120-00GE
HCNW3120-300E
HCNW3120-500E
HCNW3120-500QE

Description and Extent of Change:
Addition of alternate IC from different wafer fab and alternate LED from different manufacturing site.

Reasons for Change:
To have a dual source for alternate IC and LED as part of Broadcom's Business Continuity Plan.

Effect of Change on Fit, Form, Function, Quality, or Reliability:
All electrical specifications and physical characteristics remain within the datasheet limits. Appropriate electrical characterization and reliability qualifications have been performed on representative products to ensure normal parametric distribution, consistent electrical performance, and reliability.

Effective Date of Change:
Product shipments using this change will begin with date-code starting from 2703 [YYWW] or after. Timing of shipment of the changed part will vary by part number depending on customer demand and inventory levels.

Qualification Data:
Qualification data has been generated and approved.

Software / Firmware Update:
No software or firmware updates are required of this change.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.