PRODUCT CHANGE NOTIFICATION

Product Category COMPUTER PRINTABLES **20260901-2**

Product Group ID AND SAFETY

ISSUE DATE: 01-Sep-26

IMPACTED REGIONS: ☑ NA ☑ EMEA ☑ LATAM ☑ AP

REASON FOR CHANGE: ☑ DISCONTINUATION ☐ OTHER

DESCRIPTION OF CHANGE: (Required)

The old Easy-Mark Plus labeling software part numbers are being discontinued and replaced by new labeling software part numbers. We greatly value and thank you for your ongoing support.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

Reference Page 2 / Linked PDF

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2026	9	1
Old product discontinuation date*	2026	10	1

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

CUSTOMER SERVICE CONTACTS

ASIA PACIFIC	**AUSTRALIA: 1-800 7263848** AUS-CSVM@panduit.com	**CHINA: 400-820-1900** CHN-CustomerService@panduit.com	**HONG KONG: 800-965768** CHN-CustomerService@panduit.com
	INDIA: 000 800 6501844 (Fixed) **000 800 6500369 (Mobile)** SGP-Customer_Service@panduit.com	**INDONESIA: 001 803 65 7571** SGP-Customer_Service@panduit.com	**JAPAN: +81-3-6863-6000** JPN-CS@panduit.com
	KOREA: 02-2182-7300 KOR-CustomerService@panduit.com	**MALAYSIA 1800 801435** SGP-Customer_Service@panduit.com	**SINGAPORE: 1-800-7263848** SGP-Customer_Service@panduit.com
	TAIWAN: 0080 165 1487 SGP-Customer_Service@panduit.com	**THAILAND: 001-800-65-6385** SGP-Customer_Service@panduit.com	
LATIN AMERICA	**BRAZIL 08000562613 (Toll Free)** BRA-custservice@panduit.com	**MEXICO: +52-33-37776000 x80520** **01 800 360 86 00 (Toll Free)** MEX-customerservice@panduit.com	**OTHER LA COUNTRIES:** **Phone USA 1-708-532-1800** TP-CS-INTERNATIONAL@panduit.com
NORTH AMERICA	USA & CANADA: 1-800-777-3300 cs@panduit.com	EMEA	**EMEA: +44 208 6017219** EMEA-CustomerServices@panduit.com

To add a contact or to unsubscribe, please send an email to: PCN@panduit.com

Product Groups

CABLE COPPER, FIBER CABLE AND CONNECTORS

CONVERGED INFRASTRUCTURE

COPPER & NETKEY COPPER, FIBER, CABLE

DATA CENTER SOFTWARE

DC CONNECTIVITY

DUCT AND ABRASION

ID, SAFETY AND ACCESSORIES

IMS SMARTZONE HARDWARE

INDUSTRIALNET COPPER

INDUSTRIALNET FIBER

INDUSTRIALNET OUTLETS

IOT SOFTWARE

IOT SOLUTIONS

MISC

OUTLETS, SURFACE RACEWAY, RACKS, ZONE, CABLE MANAGEMENT

POWER CONNECTORS, GROUNDING AND STEEL

PRE-CONFIGURED IA

TIES AND TERMINALS

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2	Grouping (For Complex only)	Discontinuation Date
EMPLUS-CD	Compatible	EM-DL			01-OCT-2026
EMPLUS-DL	Direct	EM-DL			01-OCT-2026
EMPLUS-2GO	Direct	EM-2GO			01-OCT-2026
EMPLUS-SERVER	Compatible	EM-SERVER-DL			01-OCT-2026
EMPLUS-SL5	Direct	EM-SL5			01-OCT-2026

Replacement Type Definition

DIRECT REPLACEMENT	Exact same part in a different package size, or has any other update that doesn't change the product itself
COMPATIBLE	The replacement part is different in a way that allows it to be used for some applications, but it is not the same part. The difference can be in color, size, material, or performance (like *CAT5 to CAT6), etc.*
COMPLEX	The replacement part(s) are too dissimilar to assume it can easily replace the discontinued part, however Panduit can offer a replacement which may be used in certain applications. Customer Experience should be contacted.
NO REPLACEMENT	No replacement product is available.