




Oct.1.2018 Copyright 2018 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case that the application demands a high level of reliability, such as automotive,
please contact a company representative for further information.



- NOTE
- 1 This product is packaged in tray. (42pcs/tray)
 - 2 Blemish and hit mark can be occurred through out the manufacturing process which doesn't affect quality level. Also, black spot could be observed on the surface of housing.
 - 3 For the contact NO., adjacent two pairs of leads placed back-to-back (4 leads in total) Compose one line.
 - 4 Misalignment absorbing range: ± 0.3mm max.
 - 5 The dimension in parentheses are for references.
 - 6 Lot NO. is indicated at either one of the position as shown.

2	Copper alloy	Contact area: Gold-plating 0.1 μm	4	Polystyrene	
		Lead area: Tin-plating 1.0 μm			
		Under plating: Nickel 1.0 μm			
1	Polyamide	Black UL94V-0	3	Phosphor bronze	Tin-plating 3.0 μm
NO. MATERIAL		FINISH, REMARKS	NO. MATERIAL		FINISH, REMARKS
UNITS mm		SCALE 2 : 1	COUNT		DESCRIPTION OF REVISIONS
DESIGNED		CHECKED	APPROVED		DATE
DRAWN		DESIGNED	DRAWING NO.		EDC3-359165-00
HRS HIROSE ELECTRIC CO., LTD.		CHECKED	PART NO.		FX30B-2S-7. 62DSA
		DESIGNED	CODE NO.		CL570-3504-2-00
		DRAWN			1/2

Oct.1.2018 Copyright 2018 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case that the application demands a high level of reliability, such as automotive,
please contact a company representative for further information.



HRS	DRAWING NO.	EDC3-359165-00
	PART NO.	FX30B-2S-7.62DSA
	CODE NO.	CL570-3504-2-00
		22