


- NOTES
- 1 THE RECOMMENDED CLAMP TORQUE, REF. NO. ⑦ : $3\text{N} \cdot \text{m}$.
LOCTITE 243, HENKEL JAPAN OR EQUIVALENT IS RECOMMENDED TO
PREVENT REF. NO. ⑦ FOR LOOSENING.
 - 2 WHEN MOUNTED ON CHASSIS, BE CAREFUL THAT REFERENCE NO. ⑤ IS FITTED
INTO THE INDICATED GROOVE WITHOUT ANY BITING.

4	DIALLYL PHTHALATE	(BLACK)	UL94V-0			
3	DIALLYL PHTHALATE	(BLACK)	UL94V-0	7	BRASS	NICKEL PLATING
2	COPPER ALLOY	SILVER PLATING	5 μ m min.	6	PHOSPHOR BRONZE	NICKEL PLATING
1	ZINC ALLOY	CROMATE PLATING		5	SILICONE RUBBER	(BLACK)
NO.	MATERIAL	FINISH . REMARKS		NO.	MATERIAL	FINISH . REMARKS

UNITS mm		SCALE 2 : 1		COUNT	DESCRIPTION OF REVISIONS	DESIGNED	CHECKED	DATE
 <div> <div>HIROSE</div> <div>ELECTRIC</div> <div>CO., LTD.</div> </div>		APPROVED : TP. KOMATSU		20210528	DRAWING NO. EDC-111092-76-00			
		CHECED : HY. KOBAYASHI		20210527	PART NO. RM15WTRZA-12S(76)			
		DESIGNED : TY. SUZUKI		20210526	CODE NO. CL0109-1662-6-76			
		DRAWN : KR. SUZUKI		20210519				

5

6

7

8

1